

1977
Photo No. 1. Gatehouse entrance looking east from stone stairway. Note stone pitchers at gable peaks and iron crestings.




Photo No. 2. Gatehouse entrance looking east. Note white marble plinths and free-standing black marble columns.

0 1979



Photo No. 3. Gatehouse looking southeast from promenade. Note cast-iron railing at settling basin perimeter.



Photo No. 4. Statehouse looking southeast.

JUL 1 0 1979



Photo No. 5. Gatehouse looking southeast showing arched sluice opening in foundation.

SEP 10 1979 JUL 1 0 1979



1977
Photo No. 6. Gatehouse looking northeast.




Crescent Hill Reservoir Louisville, Jefferson, Kentucky Elizabeth F. Jones SEP 617 West Jefferson Louisville, Kentucky 40202 JEHNERSON (15 Photo No. 7. Gatehouse and stairway looking northeast.



Crescent Hill Reservoir Louisville, Jefferson, Kentucky Elizabeth F. JonesFP 10 1979 617 West Jefferson Louisville, Kentucky 40202% 1977 Photo No. 8. Superintendent's house looking southwest. Note three separate entries and iron

0 1979

crestings.



Crescent Hill Reservoir Louisville, Jefferson, Kentucky Elizabeth F. Jones SEP 10 1979 617 West Jefferson Louisville, Kentucky 40202 Photo No. 9. Superintendent's house looking west.

JUL 1 0 1979



Crescent Hill Reservoir Louisville, Jefferson, Kentucky Elizabeth F. Jones SEP | 0 1979 Louisville Kentucky 40202 1977 Establication Photo No. 10. Reservoir showing

relationship of superintendent's house (foreground) and gatehouse (center).

0 19/9