



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Ron Markwell, May 1985. Neg. at WI Hist.
Society. View from southwest.

Photo #1 of



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Ron Markwell, May 1985. Neg. at WI Hist.
Society. Close view from southwest.
Photo #2 of



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Joe Johnson, May 1985. Negative at WI
Historical Society. View of hanging gasolier
in dining room.

Photo #. of .

3 97



ALLYN, A. H., HOUSE. 511 E. Walworth Ave.
Delavan, Walworth County, WI. Photo by
Ron Markwell, May 1985. Neg. at WI Hist.
Society. View from northwest.

Photo #4 of 27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.
Delavan, Walworth County, WI. Photo by
Ron Markwell, May 1985. Neg. at WI Hist.
Society. View from north.

Photo #5 of . 27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Joe Johnson, May 1985. Negative at WI
Historical Society. View of east bay in
back parlor.
Photo # of .

6 27



ALLYN, A.H., HOUSE. 511 E. Walworth
Ave., Delavan, Walworth County, WI.
Photo by Ron Markwell, May 1985. Neg.
at WI Hist. Society. View of south
bay of main parlor.
Photo # of .

7 27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Joe Johnston. May 1985. Negative at WI.
Historical Society. View of south bay in
music room.

Photo # of

8 27



ALLYN, A. H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Dan Ziembo, April 1985. Neg. at WI Hist.
Society. View of west central bay (Note
stained glass windows between split chim-
neys and the chimney panel)

Photo #9 of .27



ALLYN, A. H., HOUSE. 511 E . Walworth Ave.
Delavan, Walworth County, WI. Photo by
Dan Ziembo, April 1985. Neg. at WI Hist.
Society. View of west central bay (Note
barge boards, half-timbering, dentiling,
horseshoe window, shingling, and slight
arch above other windows.

Photo #10 of . 27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Dan Ziembo, Dec. 1984. Negative at WI
Historical Society. View of trigger handles
which are found on all doors.
Photo # . . . of . . .

11 27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Dan Ziembo, April 1985. Neg. at WI Hist.
Society. View of west central and southern
bays (Note multi-form dormer bays)

Photo #12 of - d7



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Dan Ziembo, Dec. 1984. Negative at WI
Historical Society. View of handpainted
ceiling in dining room.

Photo # of

13

27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.
Delavan, Walworth County, WI. Photo by
Dan Ziembo, April 1985. Neg. at WI Hist.
Society. View of split chimney stained
glass windows and panel and limestone
moldings and arches.

Photo #14 of .07



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.
Delavan, Walworth County, WI. Photo by
Dan Ziembo, April 1985. Neg. at WI Hist.
Society. View of stylized floral design
on split chimney panel.

Photo #15 of . . . 27



ALLYN, A.H., HOUSE. 511 E. Walworth
Ave., Delavan, Walworth County, WI.
Photo by Dan Ziembo, Dec. 1984. Neg.
at WI Hist. Society. View of carriage
porch entrance and staircase.
Photo # of

16

27



ALLYN, A.H., HOUSE. 511 E. Walworth
Ave., Delavan, Walworth County, WI.
Photo by Dan Ziembo, Dec. 1984. Neg.
at WI Hist. Society. View of detail
of newel post of main staircase.
Photo # of .

17 27



ALLYN, A.H., HOUSE 511 E. Walworth Ave.
Delavan, Walworth County, WI. Photo by
Ron Markwell, May 1985. Neg. at WI Hist.
Society. View from north of the north
and central bays on the east side.
Photo #18 of .27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.
Delavan, Walworth County, WI. Photo by
Ron Markwell, May 1985. Neg. at WI Hist.
Society. View of bracketed rectangular
bay with shingled apron and dentils on
east side.

Photo #19 of .27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.
Delavan, Walworth County, WI. Photo by
Ron Markwell, May 1985. Neg. at WI Hist.
Society. View of overhanging gabled dor-
mer with pendants in east central bay.

Photo #20 of .27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Joe Johnson, May 1985. Negative at WI
Historical Society. Close view of stained
glass window between split chimneys over
fireplace in northwest bedroom.
Photo # of

d1 d7



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Dan Ziembo, Dec. 1984. Negative at WI
Historical Society. View of music room
fireplace and mirror.

Photo # of .
22 27



ALLYN, A.H., HOUSE. 511 E.. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Dan Ziembo, Dec. 1984. Negative at WI
Historical Society. View of fireplace and
mirror in back parlor.
Photo # of

23

27

ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Ron Markwell, May 1985. Neg. at WI Hist.
Society. View of French-cut and embossed
paneled pocket doors of foyer. *glass.*

Photo #24 of .27



ALLYN, A.H., HOUSE. 511 E. Walworth
Ave., Delavan, Walworth County, WI.
Photo by Dan Ziembo, dec. 1984. Neg.
at WI Hist. Society. View of stained
muntined-framed glass and cut and
etched panel in outer carriage en-
trance door.

Photo # of

25

27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Dan Ziembo, Dec. 1984. Negative at WI.
Historical Society. View of detail of
music room fireplace (one of many).
Photo # of .

26

27



ALLYN, A.H., HOUSE. 511 E. Walworth Ave.,
Delavan, Walworth County, WI. Photo by
Dan Ziembo, Dec. 1984. Negative at WI
Historical Society. View of fireplace in
library.

Photo # of .

27

27