	DESCRI	PTION		IDENT		SIH
□ Garneys Step □ Garden □ Source Step □ Garden X Open lend I wed Residential □ Scentered buildings visible from site X Open lend I wed Residential □ Scentered buildings visible from site Commercial Indust Rural □ High buildings density Io migration for sultions and site of the roadway along with other mid 19th century homes in this area. As is common along Palisado Avenue, to the rear is vacant land extending to the Connecticut River. (ovER)	wood Skingle Rail Tin Stare Aspholi shingle Built up Tile Other Aspholi shingle Built up Tile Other 2 + basement 37' x 44' vith 23' x 10' rear addition 1 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 10000 - 10000 - 10000 - 1000 - 1000 - 1000 - 1000 - 1000 - 10000 - 1000 - 100	It Load bearing masonry Structural iron or steel Other Specify Hannord Cable Flat Cable Flat Gambrel Sted Hip Other Specify Moveral'	Ciapbord Axbertos Siding X Brick Other Wood Shingle Axphalt Siding Fieldstone Boord & Borlyn Succo Cobblextone Auminum Concretion Cobblextone Stange Concretion X Control on the standard stan	ial	Ission Imm to be office use on the second	
	COMPILED BY PHOTO	SOURCES	SIGNIFICANCE		DESCRIPTION (Continued)	
- rafif 115 TA BUIL MAC ON STE Reneral Private Deterioration Zoning Explanation	PHOTOGRAPHER Date PHOTOGRAPHER Michael K. O'Leary Vie Michael K. O'Leary West (front) Micharut ON Filt West (front) CHC, Sheet #10 Preston Maynard Date DHALMIZATION Planning Consultant - Town of Windsor P18 Froad Street, Windsor, CT 06095	Windsor Land Records 1869 Map U.S. Census Records: Windsor, 1880 Hartford Suburban Directory: 1915-16 Town of Windsor Assessor's Office		IN INTERICAL OF ARCHITECTURAL IMPORTANCE Example of a French Second Empire style dwelling built in the mid 19th century. Note the ubiquitous mansard roof, and the juxtaposition of the towers. This house	2 story masonry dwelling, has bell-cast mansard roof with corbeled cornice, southwest and northeast corner towers, and asymmetrical plan. The front section has a polygonal bay with mansard roof pierced by pedimented dormers. To the right of the bay is the tower which is 2 stories plus mansard. The rear block has same details as the front section. The tower in the rear has lost its mansard. Fenestra- tion throughout the building is irregular. Most windows have segmental arch opening with segmental window head and cut-stone sill. The entry is on the south side. It used to have a small entry porch but this has been removed. To the rear, south side is a recessed porch.	