

Name: Hearn and Rawlins Mill

Location: Seaford, Delaware

Sussex Count

Photographer: Jean Athan

Date 1/8/77

Location of Megative: Div. of Historical & Cultural Affair: Bureau of Archaeology & Historic Preservation, Hall of Records, Dover, DE 19901
Description:

Southwest side of mill.

MAY 22 1978

Photograph Number: 1

NOV 1 8 1977

5-436

PROPERTY OF THE NATIONAL RESISTER



Name: Hearn and Rawlins Mill

Location: Seaford, Delaware

x County

Photographer: Jean Athan

Date: 9/8/77

Location of Megative: Div. of Historical & Cultural Affairs Bureau of Archaeology & Historic Preservation, Hall of

Records, Dover, DE 19901
Description:

Northwest side of mill.

Photograph Number:


2

NOV 181977

5-436

MAY 2 2 1978

PROPERTY OF THE NATIONAL REGISTER



Location: Seaford, DE

Photographer: Jean Athan

Date: 9-8-77

Location of Negative: Bureau of Arch. & Hist. Preservation

Hall of Records, Dover, DE

Description:


Eastern side of Mill.

Photograph Number: S-436-(3)

NOV 1 8 1977

MAY 2 2 1978

PROPERTY OF THE NATIONAL REGISTER



Location: Alternate Route 13, Seaford, DE

Photographer: Jean Athan Sussex County

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover


Description: View of the overshot iron wheel.

Photograph Number: S-436 (#4)

NOV 1 8 1977

MAY 2 2 1978

## PROPERTY OF THE NATIONAL REGISTER



Sussex County

Location: Alternate Route 13, Seaford, DE

Photographer: Jean Athan

Date: 10/77


Location of Negative: DHCA; B/A&HP; Hall of Records,

Dover

Description: Detail of the overshot iron wheel.

Photograph Number: S-436 (#4A)

NOV 1 8 1977




Location: Alternate Route 13, Seaford, DE

Photographer: Jean Athan
Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of the grinding corn stone.

Photograph Number: S-436 (#5)



Location: Alternate Route 13, Seaford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of the interior truss work on the first level.

Photograph Number: S-436 (#6)

NOV 1 8 1977

MAY 2 2 1978



SUSS#X

Location: Alternate Route 13, Seaford, DE County

Photographer:

Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of the flour packer.

Photograph Number: S-436 (#7)

NOV 181977

MAI 22 1978

