NOV 2 6 1986 Substantive Revis

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource	# BU-7
Bullitt	Cour

10 Shepherdsville 20 Original Floor Plan: Shotgun [NA X X X X X X X X X						
2. Original Owner: Abram Fields 3. Other Names: "Old Stone Bank" 4. Prehistoric Site Building X Object Historic Site Structure Other 5. Location: west side Buckman Street in Shepherdsville 6. Owner's Name: Charles Hamilton & Burlyn Pike Plans Route #5 Shepherdsville, Kentucky 40165 8. Evaluation: 9. Recognition & Date: Nat.Landmark Local Landmark Nat.Register HABS/HAER Highway Marker KY Inventory X KY Landmark Certificate 11. N.R.Status & Date: 11. N.R.Status & Date: 11. N.R.Status & Date: 11. N.R.Stonup: District Name: Primary: Architecture Primary: Architecture Primary: Architecture Primary: Architecture Scood example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-e14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. 14. History: Built ca. 1809. Was said by General Henry Crist Addition Frederal [21] 18. Architect/Builder: Not Knot Known 19. No. of Stories: One It.0 Not Known 19. No. of Stories: One It.0 20. Original Floor Plan: Shotque Shotque Indicate Ind	1. Name of Resource:	16.	Date:		·	
2. Original Owner: Abram Fields 3. Other Names: "Old Stone Bank" 4. Prehistoric Site Building X Object Historic Site Structure Other 5. Location: west side Buckman Street in Shepherdsville 6. Owner's Name: Charles Hamilton & Burlyn Pike Plans Route #5 Shepherdsville, Kentucky 40165 8. Evaluation: 9. Recognition & Date: Nat.Landmark Local Landmark Nat.Register HABS/HAER Highway Marker KY Inventory X KY Landmark Certificate 11. N.R.Status & Date: 11. N.R.Status & Date: 11. N.R.Status & Date: 11. N.R.Stonup: District Name: Primary: Architecture Primary: Architecture Primary: Architecture Primary: Architecture Scood example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-e14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. 14. History: Built ca. 1809. Was said by General Henry Crist Addition Frederal [21] 18. Architect/Builder: Not Knot Known 19. No. of Stories: One It.0 Not Known 19. No. of Stories: One It.0 20. Original Floor Plan: Shotque Shotque Indicate Ind	Bank of the Commonwealth		Original Building	CA 1809	ſ	R
3. Other Names:				0/1. 1005	Ĩ	0
3. Other Names:	Abram Fields	17.	Style:			
## Old Stone Bank** # Prehistoric Site			•	Federal	[21
4. Prehistoric Site Building X Object Historic Site Structure Other 5. Location: west side Buckman Street in Shepherdsville 6. Owner's Name: Charles Hamilton & Burlyn Pike Route #5 Shepherdsville, Kentucky 40165 8. Evaluation: 9. Recognition & Date: Nat.Landmark Local Landmark Nat.Register HABS/HAER Highway Marker KY Inventory X KY Landmark Certificate 10. N.R.Status & Date: IThematic Name: Farly Stone Buildings 12. Historical Theme: Primary: Architecture Secondary: Banking Other: 13. Statement of Significance: Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. Built ca. 1809. Was said by General Henry Crist 18. Architect/Builder: Not Known 19. No. of Stories: One Inc. Shotqun Inc. Story Cable Not Original Floor Plan: Shotqun Inc. Shotqun Inc. Addition: Stone Inc. Stone In	"Old Stone Bank"			reactar	. [
Historic Site	4. Prehistoric Site Building y Object	18.	Architect/Builder:			
10 Shepherdsville 20 Original Floor Plan: Shotgun [NA Shotgun	Historic Site Structure Other			Not Known		•
10 Shepherdsville 20 Original Floor Plan: Shotgun NA X X 22 Roof Form & Material: Original Gable NA X X 22 Roof Form & Material: Original Gable NA X X X X X X X X X	5. Location: west side Buckman Street			0ne]	1.0
Charles Hamilton & Burlyn Pike Charles Hamilton & Charle		20.	Original Floor Plan:			
Charles Hamilton & Burlyn Pike p	'					
7. Owner's Address: Route #5 Shepherdsville, Kentucky 40165 8. Evaluation: 9. Recognition & Date: Nat.Landmark Nat.Register HABS/HAER Highway Marker KY Inventory X KY Landmark Certificate 10. N.R.Status & Date: 11. N.R.Group: District Name: Primary: Architecture Primary: Architecture Primary: Architecture Primary: Architecture Food example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. 10. History: Stone [S] 24. Exterior Material: Stone [S] Stone [S] 25. Foundation Material: None Moved/Rebuilt Additions X 27. Special Features: 10. Major Alterations: None Moved/Rebuilt Additions X 27. Special Features: 12. Historical Theme: Primary: Architecture [030] Secondary: Bank ing [058] Other: 13. Statement of Significance: Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. 14. History: Built ca. 1809. Was said by General Henry Crist	6. Owner's Name:					X
7. Owner's Address: Route #5 Shepherdsville, Kentucky 40165 8. Evaluation: 9. Recognition & Date: Nat.Landmark Nat.Register HABS/HAER Highway Marker KY Inventory X KY Landmark Certificate 10. N.R.Status & Date: 11. N.R.Group: District Name: Mult.Resource Area: Primary: Architecture Primary: Architecture Primary: Architecture Scondary: Banking Other: Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. Condition: Condition	Charles Hamilton & Burlyn Pike	22.		- 0		
Route #5 Shepherdsville, Kentucky 40165 8. Evaluation: [G] 9. Recognition & Date: Nat.Landmark Local Landmark Nat.Register HABS/HAER	L PJ		Gable	Not Orig	<u>inal</u>	
Shepherdsville, Kentucky 40165 8. Evaluation: [G] 9. Recognition & Date: Nat.Landmark Local Landmark Nat.Register HABS/HAER Highway Marker KY Inventory X KY Landmark Certificate 10. N.R.Status & Date: 11. N.R.Group: District Name: [] Additions X 10. Historical Theme: Primary: Architecture Primary: Architecture Secondary: Banking Other: 13. Statement of Significance: Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. [] 14. History: Built ca. 1809. Was said by General Henry Crist 25. Foundation Material: Stone [S] 26. Major Alterations: None Moved/Rebuilt Other 26. Major Alterations: None [S] 27. Special Features: 16. Mojor Alterations: None [S] 28. Outbuildings: None [O] 29. Original Function: Bank [O2A] 30. Present Use: Business [O2A] 31. Condition: [G] 32. Endangered: Yes No X Attach Photos: Roll: 13 Photo Nos:31-35 No. of Slides: X Roll: 13 Photo Nos:31-35 No. of Slides: X		23.	Structural Material:	Ctono	_	.
Stolle				2 roue	<u>l</u>	<u> </u>
9. Recognition & Date: Nat.Landmark Nat.Register Highway Marker KY Inventory KY Landmark Certificate 10. N.R.Status & Date: 11. N.R.Group: District Name: District Name: Primaric Name: Farly Stone Buildings 12. Historical Theme: Primary: Architecture Primary: Architecture Primary: Banking Other: 13. Statement of Significance: Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. Business Stone Stone None Moved/Rebuilt Additions X 27. Special Features: 10. Malterations: None Moved/Rebuilt Additions X 27. Special Features: 10. Outbuildings: None 10. Outbuildings: None 10. Outbuildings: None 10. Original Function: Bank 10. Present Use: Business 10. Attach Photos: Roll: 13 Photo Nos:31-35 No. of Slides: X 31. Attach Photos: Roll: 13 Photo Nos:31-35 No. of Slides: X 32. Endangered: 33. Attach Photos: Roll: 13 Photo Nos:31-35 No. of Slides: X 34. History: Built ca. 1809. Was said by General Henry Crist		24.	Exterior Material:	Stone	Ī	S
Nat.Landmark						
Nat.Register HABS/HAER Highway Marker KY Inventory X KY Landmark Certificate 10. N.R.Status & Date: 11. N.R.Group: District Name: [] Z8. Outbuildings: Mult.Resource Area: [] Z9. Original Function: Primary: Architecture [] Z9. Original Function: Primary: Architecture [] Z9. Original Function: Secondary: Banking [] Z9. Original Function: Other: [] Z9. Original Function: Bank		25.	Foundation Material:			c ·
Highway Marker KY Inventory X Moved/Rebuilt Additions X 27. Special Features: 10. N.R.Status & Date: 11. N.R.Group: District Name: [] 28. Outbuildings: Mult.Resource Area: [] 29. Original Function: Primary: Architecture [030] 30. Present Use: Secondary: Banking [05B] 0ther: [] 31. Condition: 13. Statement of Significance: [Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. [] 14. History: Built ca. 1809. Was said by General Henry Crist		00	Nr			<u> </u>
Additions χ 27. Special Features: 28. Outbuildings: 29. Original Function: 29. Original Function: 29. Original Function: 20. Milt. Resource Area: 29. Original Function: 20. Original Function: 20. Original Function: 20. Original Function: 29. Orig		26.				
10. N.R.Status & Date: 11. N.R.Group: District Name: Mult.Resource Area: Thematic Name: Early Stone Buildings [] 12. Historical Theme: Primary: Architecture Primary: Architecture Secondary: Banking Other: 13. Statement of Significance: Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. Business 12. Special Features: 28. Outbuildings: None 19. 29. Original Function: Bank 10. 30. Present Use: 11. None 12. Endangered: 12. Special Features: 27. Special Features: 28. Outbuildings:				Other		
District Name: Mult.Resource Area: Thematic Name: Farly Stone Buildings[]		97				
District Name: Mult.Resource Area: Thematic Name: Farly Stone Buildings[]	11 N.R. Status & Date:	21.	speciai reatures:			
Mult.Resource Area: []		20	Outhuildings			
Thematic Name: Early Stone Buildings [] 29. Original Function: 12. Historical Theme:		20.	Outbuildings.	None	ſ	0
Primary: Architecture Secondary: Banking Other: 13. Statement of Significance: Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. 12. History: 1030		29	Original Functions			<u>·</u>
Primary: Architecture Secondary: Banking [05B] Other: [05B] 30. Present Use: Business [02A] 31. Condition: [6] 31. Condition: [6] 32. Endangered: Yes No X X X X X X X X X X	12 Historical Theme:	40.	Original Lanction.	Bank	ı()2A
Secondary: Banking [05B] Other: [05B] 13. Statement of Significance: [Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. [I] 14. History: Built ca. 1809. Was said by General Henry Crist		30.	Present Use:			
Other: 13. Statement of Significance: Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. Built ca. 1809. Was said by General Henry Crist 31. Condition: 32. Endangered: 33. Attach Photos: Roll: 13 Photo Nos:31-35 No. of Slides: X	Secondary: Panking [050]	000	11000111 0001	Business	ľ)2A
I Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. Built ca. 1809. Was said by General Henry Crist	Other:	$\overline{31}$.	Condition:			
Good example of dry-stone construction used for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. [] 14. History: Built ca. 1809. Was said by General Henry Crist					ſ	G
for a bank building. The two remaining early stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. 14. History: Built ca. 1809. Was said by General Henry Crist	_	$\overline{32}$.	Endangered:	<u> </u>	čes	·····
stone banks in Kentucky (this and GN-G-14) each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. [] 14. History: Built ca. 1809. Was said by General Henry Crist					_	X
each have the main entrance in the gable end. This one has an unusually wide flat arch spanning a tripartite opening. [] 14. History: Built ca. 1809. Was said by General Henry Crist		33	Attach Photos			
This one has an unusually wide flat arch spanning a tripartite opening. [] 14. History: Built ca. 1809. Was said by General Henry Crist		00.		\$31_35 No. of S	Slides:	. Y
spanning a tripartite opening. [] 14. History: Built ca. 1809. Was said by General Henry Crist			19 111010 1101	701-33 mor or z	114000	^ ^
14. History: Built ca. 1809. Was said by General Henry Crist						
Built ca. 1809. Was said by General Henry Crist						
	14. History:					
ULN CONGRESSMAN (XU4-IXII) TO NAVE DEEN THE	Built ca. 1809. Was said by General Henry Cris (U.S. Congressman 1804-1811) to have been the	st				

first bank in the state. Building was operated as a combined bank and store by Abram Fields,

who was born in 1781.

34.	Prepared by:	Carolyn Murray-Wooley
35.	Organization:	Kentucky Heritage Council
36.	Date:	•
37.	New Survey	January 1984 X X

^{15.} Source of historical information and/or contact person: Wife of S.N. Brooks, descendant of Abram Fields (in Kentucky Heritage Council Files).

Form KHC1985-2 Page 2 of 3 pages

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource # BU-7

38.	UTM Point of Primary Building: Quadrant: Shepherdsville	Zone <u>1 6</u>	Easting 6 1 2 6 4 0	Northing 4 2 0 4 9 4 0		G.I.S. Mod. Coordi.Accuracy	[
41.	UTM Points of Boundary (for N. R. eligible sites only):						
	A	_	\mathbf{r}				
	В.	_	E	•			
-	c	_	F	•			
42.	Total Acreage in Present Property	7:	43. Acre	age included in p	ropose	d N.R. boundary: .1	7 acr
44.	Site Plan (and boundary description	n and ju	stification fo	N.R. sites):			

See Attached

45. Description and House Plan:

One-story, single-cell, dry-stone building, 18 x 30 feet, with gable end entrance, and with one stone room added to west end, 18 x 24 feet. Masonry in regular courses of varying heights on front (east gable end) with 17-voussoir flat arch without keystone, and with skew backs, in center of wall, spanning two windows and one door in center. One window toward rear of room on north side; one door and window in south side, as unit, spanned by 11-voussoir flat arch with keystone and skew backs (filled in to size of one window). Masonry on side walls in broken courses. Interior chimney in west gable end. This section has pegged, beaded frames, trim missing; square wooden window sills; square corner stone door sills. Cellar window (closed) on north side of front door, spanned by six-voussoir flat arch.

Room added to rear (west) of similar construction, has one door, one window on each side, and interior chimney in west gable end. These frames are not beaded.

Interior refinished. Contains original vault with "S Spang and Sons" stamped into door.

Building located at sidewalk bordering the main street of town, one block north of the Salt River which runs through the town.

KENTUCKY HISTORIC RESOURCE INVENTORY SUPPLEMENT BOUNDARY AND LOCATION INFORMATION

Historic Property Name Benking Come	romwealth Site # Bu-7
Multiple Resource/Thematic Nomination T	•
U.T.M. Coordinates - List multiple UTMs A. 16 612640 4204940	
В	E
c	F
Verbal Boundary Description	
	of the M. E. Karner of the
Stone bank, if the furt	of the street, Chence
with struk 75 fl S to B.	<i>V V</i> . ^
N 100 fl & C. thence paralle	
There parelel to B-C, E	
This is the present proper	ly line. I Contributing building
Sketch of Site Plan (Showing outbuildin	gs, structures, landscape features
15 ft	ary as described above.) D N
	- Pidewall
B	A
Buchman Struit	

Official Courthouse Property Reference: