



James Moore House

Woodland, CA

Photo by A. L. Hurtado

Negative at CA OHP

East elevation

#1

JUL 31 1978

NOV 16 1978



James Moore House
Woodland, CA
Photo by A. L. Hurtado
Negative at CA OHP
South elevation
#2

JUL 31 1978

NOV 16 1978



James Moore House
Woodland, CA
Photo by A. L. Hurtado
Negative at CA OHP
West elevation

#3

JUL 31 1978

NOV 16 1978



James Moore House
Woodland, CA
Photo by A. L. Hurtado
Negative at CA OHP
North elevation
#4

JUL 31 1978

NOV 16 1978



James Moore House

Woodland, CA

Photo by A. L. Hurtado

Negative at CA OHP

North elevation, kitchen on west end of
house

#5

JUL 31 1978

NOV 16 1978



James Moore House

Woodland, CA

Photo by A. L. Hurtado

Negative at CA OHP

Detail, balcony railing, north side of house
#6

JUL 31 1978

NOV 16 1978



James Moore House

Woodland, CA

Photo by A. L. Hurtado

Negative at CA OHP

Detail, bracket and gable return, north side
of house

#7

JUL 31 1978

NOV 16 1978



James Moore H ouse

Woodland, CA

JUL 31 1978

Photo by A. L. Hurtado

Negative at CA OHP

Detail, window, north side of house

#8

NOV 16 1978



James Moore House

Woodland, CA

Photo by A. L. Hurtado

Negative at CA OHP

Detail, leaded glass windows, west entry

#10

JUL 31 1978

NOV 16 1978



James Moore House

Woodland, CA

Photo by A. L. Hurtado

Negative at CA OHP

Detail, attice fanlight, north wall

#11

JUL 31 1978

NOV 16 1978



NOV 16 1978

James Moore House

Woodland, CA

Photo by A. L. Hurtado

JUL 31 1978

Negative at CA OHP

Construction detail, wooden tie with metal
bracket to relieve stress in parallel
walls

#12



James Moore House

Woodland, CA

Photo by A. L. Hurtado

Negative at CA OHP

Detail, interior window moulding and base board
showing deterioration and mold.

#13

JUL 31 1978

NOV 16 1978