

Mead Johnson River-Rail-Truck Terminal and Warehouse 1830 West Ohio Street Evansville. Indiana A. B. Casteel; DMD: 3/84

Photo #1: View, looking northwest, of the terminal and warehouse in its riverbank context.



A. B. Casteel; DMD; 3/84

Photo#2: Close-up view, looking northwest, of the terminal and warehouse structures.



A. B. Casteel; DMD; 3/84.

Photo #3: View, looking west, of the terminal and warehouse structures.



A. B. Casteel: DMD; 3/84

Photo #4: View, looking west, of the east elevation of the warehouse.



Mead Johnson River-Rail-Truck Terminal and Warehouse 1830 West Ohio Street and Livia Evansville, Indiana A. B. Casteel; DMD; 3/84

Photo #5: View of the south elevation of the warehouse.



A. B. Casteel; DMD; 3/84

Photo #6: View of the west elevation of the terminal canopy over the riverbank and river.



A. B. Casteel: DMD: 3/84

Photo #7: View of the west elevation of the terminal canopy at the end adjacent to the warehouse.



Mead Johnson River-Rail-Truck Terminal and Warehouse 1830 West Ohio Street Evansville, Indiana A. B. Casteel; DMD; 3/84

Photo #8: View of the south elevation of the 1957 warehouse addition. Note: the original warehouse structure stopped at point where the canopy structure abuts the warehouse structure. The roof line is lower.



A. B. Casteel: DMD: 3/84

Photo #9: View of the west elevation of the warehouse structure.



A. B. Casteel; DMD; 3/84

Photo #10: View of the north elevation

Photo #10: View of the north elevation of the warehouse. 1957 addition in the forground.



Mead Johnson River-Rail Truck Terminal and Warehouse 1830 West Ohio Street 13.65 Evansville, Indiana 1. O.S.A. A. B. Casteel; DMD: 3/84 Photo #11: View of the north elevation of the warehouse. The original structure in the foreground.



1830 West Ohio Street:
Evansville, Indiana

A. B. Gasteel; DMD; 3/84

Photo #12: View of the canopy interior

looking south towards the river.

Mead Johnson River-Rail-Truck

Terminal and Warehouse



Terminal and Warehouse Si keep dead 1830 West Ohio Street ကြည်၍သည် အခု**င်**⊬်း Evansville. Indiana Ad killyar A. B. Casteel; DMD; 3/84 Photo #13: View of the canopy interior looking north at the warehouse structure.

Mead Johnson River-Rail-Truck



A. B. Casteel: DMD: 3/84

Photo #14: Close-up view of one of the electric overhead gantry cranes.




A. B. Casteel: DMD: 3/84

Photo #15: Close-up view of the bisecting railroad tracks under the canopy structure.



Mead Johnson River-Rail-Truck Terminal and Warehouse 1830 West Ohio Street Evansville, Indiana A. B. Casteel: DMD: 3/84

Photo #16: Detail of a part of the superstructure of the canopy/ terminal building.



Mead Johnson River-Rail-Truck Terminal and Warehouse 1830 West Ohio Street Evansville, Indiana A. B. Casteel: DMD: 3/84

Photo #17: Detail of a part of the supersturcture of the canopy/terminal building.



A. B. Casteel; DMD; 3/84

Photo #18: Detail of the oak flooring in the canopy/terminal structure.



A. B. Casteel; DMD; 3/84

Photo #19: Close-up view of the concrete loading/unloading dock used for trucks and to handle items into the warehouse.



Terminal and Warehouse
1830 West Ohio Street
Evansville, Indiana

A. B. Casteel; DMD; 3/84

Mead Johnson River-Rail-Truck

Photo #20: Close-up view of the covered concrete docks used for rail transfer in warehouse operations. This is on the north elevation of the original warehouse.



Mead Johnson River-Rail-Truck Terminal and Warehouse 1830 West Ohio Street Evansville, Indiana A. B. Casteel: DMD: 3/84

Photo #21: Detail of some of the reinforced concrete piers which support the canopy structure.