



Casa Klumb

San Juan, Puerto Rico

Javier Isado / Staff Architect

July 3, 1997

Negative - Puerto Rico SHPO

Facing East - Main facade

Photo # 1



Casa Klumb

San Juan, Puerto Rico

Javier Tsado / Staff Architect

July 3, 1997

Negative - Puerto Rico SHPO

Facing Northeast - Main facade

Photo # 2



Casa Klumb

San Juan, Puerto Rico

Javier Isado / Staff Architect

July 3, 1997

Negative - Puerto Rico, SHPO

Facing Southeast - Main entrance

Photo # 3



Casa Klumb

San Juan, Puerto Rico

Javier Tsado / Staff Architect

July 3, 1997

Negative - Puerto Rico SHPO

Facing Southeast - Entrance ground floor

Photo # 4



Casa Klumb

San Juan, Puerto Rico

Javier Tsado / Staff Architect

July 3, 1997

Negative - Puerto Rico SHPO

Facing Southwest - Dining area

Photo # 5



Casa Klumb

San Juan, Puerto Rico

Javier Isado / Staff Architect

July 3, 1997

Negative - Puerto Rico SHPO

Facing West - Dining area

Photo # 6



Casa Klumb

San Juan, Puerto Rico

Javier Isado / Staff Architect

July 3, 1997

Negative - Puerto Rico SHPO

Facing East - Vegetation Wall

Photo # 7



Casa Klumb

San Juan, Puerto Rico

Javier Isado / Staff Architect

July 3, 1997

Negative - Puerto Rico SHPO

Facing Northwest - Gravel pathway

Photo # 8



Casa Klumb

San Juan, Puerto Rico

Javier Tsado / Staff Architect

July 3, 1997

Negative - Puerto Rico SHPO

Facing South - detail of vernacular
and international style elements
combined

Photo #9