

6. Functions or Use

Historic Functions (enter categories from instructions) DOMESTIC: single dwelling

DOMESTIC: secondary structure

Current Functions (enter categories from instructions) VACANT/NOT IN USE

Description 7.

Architectural Classification (enter categories from instructions)

Other: National Park Service Rustic

					_
Materials	(enter	categories	from	instructions)	

ŝ

foundation sandstone; concrete walls <u>sandstone</u> roof: wood shingles, log other asphalt, concrete, stone

Describe present and historic physical appearance.

Summary

The Saddlehorn Caretaker's Residence and Garage are located at the intersection of Rim Rock Drive and Saddlehorn Loop Road, approximately 5 miles from the west entrance of Colorado National Monument. Both buildings are rectangular, one-story structures designed by the National Park Service and constructed of native red sandstone masonry by the Civilian Conservation Corps in 1935 and 1936. The style exemplifies National Park Service Rustic Architecture. The buildings are in good condition and maintain integrity of location, setting, design, materials, workmanship, feeling, and association from the historic period.

Setting

The buildings are located at the junction of Saddlehorn Loop Road and Rim Rock Drive in the northwest portion of Colorado National Monument. The topography of the 32-square mile park includes the northern rim of the Uncompanyre Plateau with its deeply cut canyons and towering rock formations. Located at the entrance of the monument campground, the residence and garage are set back from the road and shielded by natural vegetation. The area in the vicinity of the residence and garage includes juniper and pinon pine trees, native brush vegetation, as well as natural sandstone cliffs. The area is named for the distinctive sandstone monolith nearby, "Ca-Roo-Nump-Ta-Chee" or "Saddlehorn". Stone curbing lines much of the driveway to the residence and is a contributing feature. The park's headquarters building and visitor center is located about 500 feet to the southwest of the residence and garage. No other buildings are in the immediate vicinity. The Saddlehorn Utilities Area is located about one-quarter mile to the west. (See attached Saddlehorn Headquarters/Campground site map.)

Description

This one-story building is constructed on a concrete Caretaker's Residence (HS-1H): foundation of native red sandstone masonry set in a coursed ashlar pattern. The plan is rectangular with small side wings. The two lower courses of the building are stepped. The entrance is located on the north elevation, a vertical plank wood door with 6-lights and a single light aluminum sash storm door. The entrance stoop is built of large stone blocks and the doorway is sheltered by a gabled roof supported by large rustic carved wood brackets and an undecorated barge board. The rear entrance door is modern with 3 lights and a storm door. All windows are wood casement type with aluminum storm sash. Windows on the north elevation include one triple divided 6-light, one double divided 6-light, and one 4-light; on the east elevation, one double divided 6-light, one 6-light, one 4-light at basement level; on the south elevation, one double divided 6-light, one 4-light, two double divided 4-light (one at basement level), and one 2-light. The recessed, chiseled stone window openings have stone sills and lintels.

い目標書

201
- 14 C
25
22.2
1920
<
nf.

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

RECEIVED

EE	D	2	8	1001
FF.	-	<i>.</i>		1 1 1
	~	<u> </u>	-	1334

NATIONAL REGISTER

Section number <u>7</u> Page <u>2</u>

The east-west oriented roof is gabled, of moderate rise, and is covered with cedar shingles. The main structure at the gable ends has weatherboard wood siding with exposed log purlin ends. Louvered vents are located under each gable. The residence has one offcenter coursed ashlar sandstone chimney. The two small wings at either end of the building have gabled roofs. All wood trim is painted rust color. A detached stone garage (HS-2H) is located to the southwest and is associated with the residence. As a note, while the residence faces north, the original 1934 plans had the building facing south.

The interior of the residence includes a living room, 2 bedrooms, kitchen and bath with a central rear stairway leading to a 3/4 basement that is partitioned to include a bathroom, activity room, laundry, furnace room, coal bin and two closets. The main floor rooms have plastered walls. The bedrooms, living rooms, and hall have wood floors constructed of 1 x 3 fir. The kitchen and bath floors are linoleum. The kitchen and bath were remodeled and the basement was paneled in 1973-1974. While some of the other rooms retain their original configuration and appearance, the overall interior is not considered significant.

With exception of the installation of metal storm sash doors and windows in 1973-74 (replacing 1953 versions), the exterior of the residence has not been modified and retains a high degree of integrity from the historic period. The trim was at one-time painted red; it is not know if this was the original color. The building is in good condition. (See attached Drawing #3003A detail, dated July 1934.)

Caretaker's Garage (HS-2H): The garage for the caretaker's residence is located at the southwest corner of the property. This one-story nearly square structure was constructed in a similar manner as the residence. The foundation of the garage is concrete. The exterior walls are constructed of native sandstone blocks, which are set in a coursed ashlar pattern. The lower courses are stepped. Constructed from massive native red sandstone blocks on a concrete foundation, the opposing side walls of the structure are mirror images of one another, and the placement of blocks in the front and back walls are also symmetrical with reference to their respective centerlines. In a technique called "built by detail," not only were the walls' gross dimensions specified by the architect, but also each component block's shape, size and location.¹ The mirror image of laid stone makes this building distinct and a particularly excellent example of architectural design and building craftsmanship.

The north facade of the garage contains a double, wood paneled overhead door with 5-lights. The gabled roof is covered with cedar shingles with weatherboard siding used on each gable end. A louvered vent is located under each gable. The rafter tails and ridge beams are exposed. All trim is painted rust brown. The cornerstone on the left front exposure

(X) See continuation sheet

¹ The practice of erecting opposing walls that are mirror images of one another was called "built by detail", according to CCC project foreman Sidney W. Johnson as told to Chief Ranger Hank Schoch in the mid-1980s.

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number <u>7</u> Page <u>3</u>

contains a small, informal time capsule. The interior of the garage is a nearly square open, 1-stall room with stone walls, exposed ceiling rafters, and a concrete floor.

Modifications to the garage resulted from the replacement of its doors. Originally, the garage had two wooden overhead doors, constructed of vertical wood planks with three 4light windows on each door. A center support was located between the doors (See Drawing #3021 detail, dated January 1936). The center support was removed and these doors were replaced in 1964 with the double overhead door described above. Removal of a center support changed the interior from a 2-stall to 1-stall garage. The change of garage doors did not significantly impact the design and appearance of the building. It is in good condition and retains sufficient integrity from the historic period to meet National Register criteria.

8. Statement of Significance				
Certifying official has considered the relation to other properties:				
Applicable National Register Criteria Criteria Considerations (Exceptions)	<u>X</u> A <u>B X</u> C <u>D</u> <u>A B C D E F G</u>			
Areas of Significance				
(enter categories from instructions)	Period of Significance Significant Dates <u>1935 - 1944</u> <u>1935; 1936</u>			
ARCHITECTURE				
SOCIAL HISTORY	Cultural Affiliation			
Significant Person	Architect/Builder			
<u>N/A</u>	NATIONAL PARK SERVICE			
	CIVILIAN CONSERVATION CORPS			

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

Summary

The Saddlehorn Caretaker's Residence and Garage have local significance under National Register Criterion A for their association with the Civilian Conservation Corps (CCC) and the Works Progress Administration. They also have local significance under National Register Criterion C for their exemplary representation of National Park Service Rustic Architecture. The materials and architectural design of these resources reflect the philosophy of incorporating natural landscape elements into planning and design. The period of significance for the caretaker's residence and garage dates from 1935 (when the residence was built) to 1944, the end of the historic period as defined by the National Register. Significant dates relate to the date of construction of the residence and the garage. Both buildings were utilized as park employee housing from their construction until about 1988. They are currently vacant.

This nomination is part of the multiple property submission, <u>Colorado National Monument</u>. The Saddlehorn Caretaker's Residence and Garage are associated with the historic context "National Park Service Rustic Architecture and Public Works Construction, 1933-1942". Two other related individual nominations associated with the multiple property submission are the nearby Saddlehorn Utility Area, and the Saddlehorn Comfort Station. The relationship of these three areas is shown on the accompanying site map. While the resources of all three are tied by architectural style, historic context, and period of significance, their distance from each other, topography, and intrusions (Mission 66-era buildings) preclude nominating them as an intact district.

Background History

Designed by architect W. G. Carney of the National Park Service's Western Division of the Branch of Plans and Design and built by the Civilian Conservation Corps, the residence and garage were constructed in 1935 and 1936 respectively with Emergency Conservation Works funding. They were built by craftsmen hired for their skills under the New Deal Relief appropriations. Many of these craftsmen were LEMs (local experienced men), reputed to be stonemasons of Italian descent, that trained a number of the CCC enrollees. The construction was administered by the Public Works Administration and built by contract labor. Sandstone blocks, quarried in Colorado National Monument by CCC men, either from the immediate vicinity or from the Rim Rock Drive construction project, were the primary building material.

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number <u>8</u> Page <u>2</u>

The larger Saddlehorn area, which also included a utility area, campground and CCC camp, was built in response to the need for a permanent base camp for CCC workers, as they were employed in the construction of Rim Rock Drive and other park facilities. In addition, much of the road had been completed by 1938, making the area accessible to visitors and creating a demand for recreational facilities.¹ The garage and residence were the first permanent buildings to be constructed, followed by the campground Comfort Station (HS-3H) and utility area's Roads and Trails Shop (HS-4H) in 1937. A second building, the Oil House (HS-5H), was added to the utility area in 1938; another two buildings were completed in by 1941 (HS-6H and HS-7H).

The Caretaker's Residence/Garage and Saddlehorn Utility Area served to augment the main administrative area of CCC camp NM-2-C, located about one-half mile to the east. A number of CCC camps were established in or near the monument to support the crews working on Rim Rock Drive and other projects. Camp NM-2-C was temporarily established at Monument Canyon trailhead in March of 1933, but was disbanded and moved to Saddlehorn, when the permanent camp was established. (Additional information about the workforce is included in Section E of the Colorado National Monument Multiple Property Submission.)

The earliest plans for buildings to house workers of NM-2-C at Saddlehorn were first laid out by the National Park Service in November 1933. The location of the CCC camp buildings at Saddlehorn was to the east of the caretaker's residence, due south of the Saddlehorn. Up until the time it was built, there had not been a permanent administrative facility for the CCC. A Campground General Plan drawing of September 1934 shows a "Base Ball Field for CCC Camp" as well as a planned tennis court. The drawing also shows the proposed headquarters, utility area, and campgrounds. By June 1935 plans had also been finalized for a park headquarters area that included the CCC administrative and residential area, the caretaker's residence and garage, and a park administration building just north of the residence. (The proposed administration building was never constructed where sited.) The CCC buildings in this camp included an administration building, recreation hall, mess hall, latrine, and 5 barracks. In addition, the 1935 map shows the campground with a baseball field. Plans for the utility area had also been finalized by July 1935. The utility area, proposed on the June drawing to be constructed south of the custodian's residence, was actually built west of it as shown on the July drawing. (Copies of all four maps are attached as documentation. Design and construction drawing numbers are listed in Item 9.)

The CCC program was phased out at the start of World War II. As men were called to military duty, projects were abandoned and camps dispersed. Most work by the CCC within Colorado National Monument had ended by 1941, and the program was completely shut down in 1942. The exact fate of the buildings which the camp NM-2-C occupied has yet to be documented with regard to their dates and method of removal. According to Hank Schoch, the monument's Chief Ranger, at least one was burned as a fire training exercise. By the

(X) See continuation sheet

¹ See <u>Rim Rock Drive Historic District</u> individual nomination, part of the <u>Colorado National Monument</u> multiple property submission.

1.

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number <u>8</u> Page <u>3</u>

early 1960s the only buildings in that area were the latrine/washhouse and several staff residences that may have been moved into the area. When new housing was constructed north of the utility area in the late 1950s and early 1960s as part of MISSION 66, all remaining buildings in the CCC camp area were removed. The CCC camp baseball field has since been turned into a campground parking area. There still remain some foundations and stone walkways that are evidence of the work camp. A large midden (most likely CCC camp related) also exists near the base of a nearby sandstone cliff. The grounds have not been inventoried for historic archeology thus the site's eligibility under criterion D has not been determined.

As the physical remains of CCC base camps are now primarily archeological, the permanent roads and buildings of Colorado National Monument are often the only tangible evidence to visitors that hundreds of men labored there during the Great Depression. The rustic style of architecture displays the history of the development of Colorado National Monument, and also reflects the craftsmanship of the CCC and the LEMs (local experienced men). Employed for various assignments, enrollees of the CCC were essential in the development of many parks and other government facilities. In Colorado National Monument, the CCC, LEMs, and workers from other relief agencies, not only supplied valuable labor in the construction of park facilities for administrative use but, with the construction of Rim Rock Drive, also opened up the park for thousands of visitors.

The Saddlehorn Caretaker's Residence and Garage are excellent examples of the design methodology of National Park Service Rustic Architecture, with its emphasis on the use of natural and native materials. The topography of Colorado National Monument is a spectacular display of carved sandstone monoliths and valleys amongst semi-desert terrain. In the construction of these buildings, architects, landscape architects, and the CCC manipulated native stone and wood supports to blend with the surrounding landscape. Earthtones are the predominant colors, with natural cream to red for the stone and brown and rust for the wood supports. The buildings were designed in such a way as to not intrude on the natural landscape, but to blend with the terrain and to be in harmony with their surroundings. The construction techniques of the CCC are also exemplified in these buildings. Through the use of native materials and stone masonry craftsmanship, the structures reflect the National Park Service's design philosophy of maintaining a sense of rusticity in construction. Unified in design and construction techniques, the Caretaker's Residence and Garage represent the lasting contribution made by public relief projects during the Great Depression, and the rustic architecture design philosophy that prevailed in the National Park Service in the 1930s.

9. Major Bibliographical References

Baume, Lawrence and Mildred Harris, <u>National Register of Historic Places Draft Nomination</u>, <u>Colorado National Monument</u>, National Park Service, Rocky Mountain Regional Office, Denver, 1987.

Good, Albert, <u>Park Structures and Facilities</u>, U.S. Department of the Interior, National Park Service, Branch of Planning, Washington, D.C., 1935.

(X) See continuation sheet

Previous documentation on file (NPS): preliminary determination of individual listing (36 CFR 67) has been requested	
previously listed in the National	Primary location of additional data:
Register	State Historic Preservation Office
-	
X previously determined eligible by	Other State agency
the National Register	<u>X</u> Federal agency
designated a National Historic	Local government
Landmark	University
X_recorded by Historic American	Other
Buildings Survey # <u>CO-74</u>	Specify Repository:
recorded by Historic American	Park files, COLM
Engineering Record #	NPS, Rocky Mountain Regional Office

10. Geographical Data

Acreage of property <u>less than one acre</u>

UTM References

A <u>1/2</u>	<u>6/9/6/0/4/0</u>	<u>4/3/3/0/2/8/0</u>	 <u>/////</u>	<u>/////</u>
Zone	Easting	Northing	Easting	Northing
C _/_ Zone	<u>/////</u> Easting	<u>/////</u> Northing	 <u>/////</u> Easting	<u>//////</u> Northing

Verbal Boundary Description

The Residence and Garage are located approximately 50 feet from Rim Rock Drive, off of the Saddlehorn Loop Road. The northern boundary line follows Saddlehorn Loop Road for 190 feet, to allow inclusion of the Residence's driveway and front landscape. The eastern boundary line extends 250 feet south, to meet with the southern boundary line. The south boundary repeats the 190 foot north boundary line. The west boundary measures 250 feet, to complete a symmetrical rectangle for the boundary.

() See continuation sheet

Boundary Justification

The boundary encompasses the two historically associated buildings and their immediate setting. It excludes the park's headquarters/visitor center (constructed 1963), which is partially screened from view by vegetation.

() See continuation sheet

11. Form Prepared By			
name/title Kathy McKoy, Historian			
organization <u>National Park Service, RMRO</u>	date <u>December 28, 1992; rev.1/94</u>		
street & number <u>12795 W. Alameda Parkway</u>	telephone <u>(303) 969-2878</u>		
city or town <u>Denver</u>	state <u>CO</u> zip code <u>80228</u>		

Tet to

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number 9 Page 2

- Law, Henry, G., Laura E. Soulliere, William C. Tweed, <u>National Park Service Rustic</u> <u>Architecture: 1916-1942</u>, National Park Service, Western Regional Office, Division of Cultural Resource Management, 1977.
- Newspaper Articles, Colorado National Monument 1935-1947, National Park Service, Rocky Mountain Region, Denver, CO.
- Paige, John, C., <u>The Civilian Conservation Corps and the National Park Service</u>, <u>1933-1942: An Administrative History</u>, National Park Service, Department of the Interior, 1985.
- U. S. Department of the Interior, National Park Service, Denver Service Center Technical Information Center files: Drawing Nos. 3003 A and 3021; Topographical Maps Nos. 4948, 3006, 4963, 4970. Denver, CO.
- Williams, Lance, List of Classified Structures survey forms, National Park Service, Rocky Mountain Region, Denver, CO, 1976.

1. · · · ·

<u>____</u>

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number <u>photographs</u> Page <u>1</u>

INDEX TO PHOTOGRAPHS The following information applies to photographs #1-4 listed below: Saddlehorn Historic District, Colorado National Monument 1) Property: 2) Location: Mesa County, Colorado 3) Photographers: Eunice Fedors 4) Date taken: November, 1989 5) Location of negatives: National Park Service, Rocky Mountain Regional Office, Denver, Colorado The property, its location, and location of negatives is the same as above for photo #5, except photographer and date taken are as follows: 3) Photographer: Clayton B. Fraser 4) Date taken: September 1984 PHOTO DESCRIPTIVE NUMBER INFORMATION Caretaker's Residence (HS-1H), view to S 1 2 Caretaker's Residence (HS-1H), view to SE 3 Caretaker's Garage (HS-2H), view to SW Caretaker's Garage (HS-2H), view to S 4 5 Overall view of Caretaker's Residence and Garage, view to SE

United States Department of the Interior National Park Service

National Register of Historic Places **Continuation Sheet**

Section number _____ Page ____

SUPPLEMENTARY LISTING RECORD

Date Listed: 4/21/94 NRIS Reference Number: 94000306

CO Saddlehorn Caretaker's House and Garage, Mesa County State Property Name

Colorado National Monument MPS Multiple Name

This property is listed in the National Register of Historic Places in accordance with the attached nomination documentation

subject to the following exceptions, exclusions, or amendments, notwithstanding the National Park Service certification included in the nomination documentation.


Beth Boland Signature of the Keeper


Date of


Amended Items in Nomination:


The period of significance is 1935-1942. This information was verified by Kathy McKoy, NPS RMRO.


DISTRIBUTION: National Register property file Nominating Authority (without nomination attachment)











Caretaker's Residence, Drawing #3003A, July 1934

