

```
l of 25
Historic View of City Hotel, c. 1880.
One of two 19th century hotels
preceeding Heppner Hotel.
```

```
Oregon Historical Society
1230 SW Park Avenue
Portland, OR 97205
Negative # 24337
```



2 of 25 Historic view of Palace Hotel (1890), c. 1900. One of two 19th century hotels preceeding Heppner Hotel.

Oregon Historical Society 1230 SW Park Avenue Portland, OR 97205 Negative #15780



3 of 25 Historic view of Heppner prior to Flood of 1903. Looking north down Willow Creek Canyon.

Oregon Historical Society 1230 SW Park Avenue Portland, OR 97205 Negative # 25194



4 of 25 Historic view of Heppner after Flood of 1903. Looking north down Willow Creek Canyon.

Oregon Historical Society 1230 SW Park Avenue Portland, OR 97205 Negative # 25193 Happener after the 1903 Flood



5 of 25 Historic view, ca. 1920-1925. North and west elevations. Oregon Historic Society 1230 SW Park Avenue Portland, OR 97205 Negative # 15745



6 of 25 General view of Heppner showing Heppner Hotel at center of town, looking west.



7 of 25 North and west elevations.



8 of 25 West (front) elevation, looking southwesterly along Main Street.

```
David Sykes Photo, 1982
Heppner <u>Gazette-Times</u>
Neg.: Ronnie Belsma
Route 2, Box 2285
Heppner, OR 97836
```



9 of 25 Looking south along Main Street. Hpnner Hotel on left.



10 of 25 West (front) elevation. Looking northeasterly along Main Street.



11 of 25
North and west elevations.



```
Heppner Hotel
124 South Main Street
Heppner, Morrow County, Oregon
```

```
12 of 25
North elevation fronting Willow
Street.
```

```
David Sykes Photo, 1982
Heppner <u>Gazette-Times</u>
Neg.: Ronnie Belsma
Route 2, Box 2285
Heppner, OR 97836
```



```
13 of 25
East and north elevations from
Willow Street.
```



# 14 of 25 South and east elevations.



```
15 of 25
South and east elevations.
```



```
16 of 25
East elevation.
```

```
David Sykes Photo, 1982
Heppner <u>Gazette-Times</u>
Neg.: Ronnie Belsma
Route 2, Box 2285
Heppner, OR 97836
```



### 17 of 25 Interior view of recessed entrance centered in north street face.




18 of 25 Interior view of lobby showing t imber columns and beams.



## 19 of 25 Detail of paneled timber beam, cornice molding and pilaster capital.

## David Sykes Photo, 1982 Heppner <u>Gazette-Times</u>

Neg.: Ronnie Belsma Route 2, Box 2285 Heppner, OR 97836



20 of 25 Detail of terrazzo floor in lobby.



```
21 of 25
Detail of terrazzo floor and border
in lobby.
```

```
David Sykes Photo, 1982
Heppner <u>Gazette-Times</u>
Neg.: Ronnie Belsma
Route 2, Box 2285
Heppner, OR 97836
```



22 of 25 Typical wood work of interior public spaces, paneled timber column and paneled wainscoting.



```
23 of 25
Main stairwell.
```

```
David Sykes Photo, 1982
Heppner <u>Gazette-Times</u>
Neg.: Ronnie Belsma
Route 2, Box 2285
Heppner, OR 97836
```



24 of 25 Second floor hallway .



25 of 25 Third floor hallway.