



Cole's Five Cypress Farm

11221 E. 8-Mile Rd, Stockton, San  
Joaquin County, CA 95212.

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas, CA93908

Approach to house from SW, looking NE  
across lane; setting, garage to right.

1 of 29



*Looney*  
THE STUDIO  
1911

Cole's Five Cypress Farm

11221 E. 8-Mile Rd, Stockton, San  
Joaquin County, CA 95212

Logan Studios, Summer 1905 (copy)

296 Corral de Tierra, Salinas, CA93908

Looking NE at SW facade; shutters still  
on parlor window, original balustrade.

2 of 26



Cole's Five Cypress Farm  
11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212  
Marit P. Evans, Winter 1986  
296 Corral de Tierra, Salinas, CA93908  
Looking NE at SW facade; upper shutters  
on.  
3 of 25

---



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas, CA93908

SW facade, looking NE; aerial removed,  
1919 door in back porch, brick porch.

4 of 29





Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas CA 93908

SE facade, looking NW; enclosed back  
porch, 2 upper windows of room in wing.

5 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Winter 1986

296 Corral de Tierra, Salinas, CA93908

Looking W at E elevation, shows servant  
door, 1919 sleeping porch.

6 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas, CA93908

N. elevation looking SE; 1934 furnace

flue

7 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas CA 93908

Looking NE at front gable elevation

8 of 29





Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas CA 93908

Front door under portico of W. side,

looking E.

9 of 29

---



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas CA 93908

entablature at NW end of portico,

looking up to balcony

10 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Brynhild B. Parker, Summer 1928 (copy)

296 Corral de Tierra, Salinas, CA 93908

S side of portico looking N; original  
balustrade on balcony, porch stoops.

11 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas CA 93908

Balcony over portico, looking E; 1940

balustrade

12 of 29





Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas CA93908

Balcony slider windows at front gable

from SW corner of balcony

13 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212


Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas CA 93908

Detail of entablature above slider

windows from balcony looking up to SE.

14 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212


Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas CA 93908

Cornice Bracket on front gable eave,

looking up at angle from SW on balcony.

15 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Spring 1986

296 Corral de Tierra, Salinas, CA 93908

Cornice bracket showing angle of curves  
to maintain verticality in gable,  
looking up and E.

16 of 29





Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Fall 1986

296 Corral de Tierra, Salinas CA 93908

Entrance door to servants' quarters on  
E. side, looking W.

17 of 24



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Fall 1986

296 Corral de Tierra, Salinas CA 93908

Looking W. at inside front door from  
hallway.

18 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Fall 1986

296 Corral de Tierra, Salinas CA 93908

Front hall stairs, looking S., newel  
post with button, balustrade, mouldings



Cole's Five Cypress Farm  
11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212  
Marit P. Evans, Fall 1986  
296 Corral de Tierra, Salinas CA 93908  
Slider windows at W. wall of upstairs  
master bedroom in front gable.





Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Fall 1986

296 Corral de Tierra, Salinas CA 93908

1919 light fixture in E. wall of up-  
stairs master bedroom (on-off knob

21 of 29

behind)



Cole's Five Cypress Farm


11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Fall 1986

296 Corral de Tierra, Salinas CA 93908

Worn steps leading to separate ser-  
vants' quarters, looking W.

22 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Fall 1986

296 Corral de Tierra, Salinas CA 93908

Looking E. down stairwell of servants'  
quarters to outside.

23 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Fall 1986

296 Corral de Tierra, Salinas CA 93908

E. wall at S. corner of E. bedroom of  
servants' quarters, looking SE.

24 of 29





Cole's Five Cypress Farm

11221 E. 8-Mile Rd., Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Fall 1986

296 Corral de Tierra, Salinas CA 93908

Looking W. out gate under cypress at  
former front entrance.

25 of 29



Cole's Five Cypress Farm  
11221 E. 8-Mile Rd, Stockton, San  
Joaquin County, CA 95212  
Marit P. Evans, Winter 1987  
296 Corral de Tierra, Salinas CA 93908  
W. facade of garage showing 3 sliding  
doors + automatic door 2<sup>d</sup> from right.  
From West, looking East.  
26 out of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd, Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Winter 1987

296 Corral de Tierra, Salinas CA 93908

Pumphouse N of main house outside of  
picket fence. From NW, looking SE.

27 of 29



Cole's Five Cypress Farm

11221 E. 8-Mile Rd, Stockton, San

Joaquin County, CA 95212

Marit P. Evans, Winter 1987

296 Corral de Tierra, Salinas CA 93908

NE corner of tool shed shown, looking

SW from East boundary of property.

.28 of 29





Cole's Five Cypress Farm

11221 E. 8-Mile Rd, Stockton, San  
Joaquin County, CA 95212

Marit P. Evans, Winter 1987

296 Corral de Tierra, Salinas CA 93908

Oak trees + S side of tenant house and  
shed, looking N. from S. boundary of  
29 of 29 property.