



JOHN BUNN HOUSE
East facade
Yamhill, Oregon
Carol Koch, photographer
May 18, 1978
Negative in photographer's
possession
Camera facing West

OCT 16 1979
KOE

Bunn (John Marion) House
285 SW 3rd Street
Yamhill, Yamhill County, Oregon

1 of 6
East elevation and general view
of site from SW 3rd Street

AUG 20 1979

Carol Koch Photo, 1978
1515 Hilyard Ave., No. 23
Eugene, OR 97403



JOHN BUNN HOUSE
~~South~~^{East} facade
Yamhill, Oregon
Carol Koch, photographer
May 18, 1978
Negative in photographer's
possession
Camera facing west

Bunn (John Marion) House
285 SW 3rd Street
Yamhill, Yamhill County, Oregon

2 of 6

East (front) elevation

DOE
OCT 16 1979

AUG 20 1979

Carol Koch Photo, 1978
1515 Hilyard Ave., No. 23
Eugene, OR 97403



JOHN BUNN HOUSE
South facade
Yamhill, Oregon
Carol Koch, photographer
May 18, 1978
Negative in ^{photographer's} possession
Camera facing North

Bunn (John Marion) House
285 SW 3rd Street
Yamhill, Yamhill County, Oregon

Doc
OCT 16 1979

3 of 6
South elevation

AUG 20 1979

Carol Koch Photo, 1978
1515 Hilyard Ave., No. 23
Eugene, OR 97403



JOHN BUNN HOUSE
Back porch
Yamhill, Oregon
Carol Koch, photographer
May 18, 1978
Negative in photographer's
possession
Camera facing Southeast

Bunn (John Marion) House
285 SW 3rd Street
Yamhill, Yamhill County, Oregon

OCT 16 ^{Doc} 1979

4 of 6
West elevation

AUG 20 1979

Carol Koch Photo, 1978
1515 Hilyard Ave., No. 23
Eugene, OR 97403



JOHN BUNN HOUSE
Interior of dormer window
Yamhill, Oregon
Carol Koch, photographer
May 18, 1978
Negative in photographer's
possession
Camera facing Southeast

Bunn (John Marion) House
285 SW 3rd Street
Yamhill, Yamhill County, Oregon

AUG 20 1979

5 of 6

Detail of interior, typical second
story dormer window

OCT 16 1979
^{POE}

Carol Koch Photo, 1978
1515 Hilyard Ave., No. 23
Eugene, OR 97403



JOHN BUNN HOUSE
Side porch
Yamhill, Oregon
Carol Koch, photographer
May 18, 1978
Negative in photographers
possession
camera facing west

Bunn (John Marion) House
285 SW 3rd Street
Yamhill, Yamhill County, Oregon

AUG 20 1979

6 of 6

Close up view of tower bay and porch
at NE corner of house. Originally,
the main entry in center of East

elevation was sheltered by a porch
with deck and railing, which no
longer stands. The deck railing of
this corner porch is missing.

⁰⁰⁸
OCT 16 1979

Carol Koch Photo, 1978
1515 Hilyard Ave., No. 23
Eugene, OR 97403