



#10/15  
Front view, looking northwest.  
Showing porch under construction.  
January 6, 1979

DOE  
DEC 31 1979  
JUN 19 1979

1. Lewis Falkenstein House  
Sarter House
2. Yreka Siskiyou <sup>county</sup> / California
3. Don Carey Jan. 6, 1979  
908 Park Place, Yreka, Calif. 96097



South side view, looking north

Showing south end of porch under constr.

420/15

January 6, 1979

DEC 31 1979  
DOE

JUN 19 1979

1. Lewis Falkenstein House  
Sarter House

2. Yreka Siskiyou <sup>COUNTY</sup> California 96097

3. Don Carey Jan. 6, 1979

908 Park Place, Yreka, Calif. 96097



~~3.7/15~~  
North side view, looking southwest.  
Showing porch on north side under constr.

# 38/15 January 6, 1979

JUN 19 1979

1. Lewis Falkenstein House  
Sarter House

DOE

2. Yreka Siskiyou Co., Calif.

3. Don Carey January 6, 1979  
908 Park Place, Yreka, California 96097



~~4. 5/7~~  
Front view, looking west.

Showing porch under constr., both sides.

January 6, 1979.

JUN 19 1979

1. Lewis Falkenstein House  
Sarter House

DOE

2. Yreka Siskiyou County California

3. Don Carey Jan. 6, 1979

908 Park Place, Yreka, California 96097





Close-up view of front side.

Showing cornice and brackets which appear on front (east), north and south sides.

January 6, 1979.

JUN 19 1979

1. Lewis Falkenstein House  
Sarter House

2. Yreka Siskiyou California

3. Don Carey Jan. 6, 1979

908 Park Place, Yreka, California 96097



68/15 Earliest view of front (east) and  
north sides. Note markings to imitate  
stone.

Date Unknown.

JUN 19 1979

1. Lewis Falkenstein House  
Sarter House

DEC. 3 1979

2. Yreka Siskiyou County / California 96097

3. Don Carey Jan 6, 1979

908 Park Place, Yreka, Calif. 96097



~~7/15~~ Later view, looking directly west.

# ~~70/15~~

1934.

JUN 19 1979

# 70/15

1. Lewis Falkenstein House  
Sarter House

DEC 31 1979 <sup>DOE</sup>

2. Yreka Siskiyou County California

3. Don Carey  
908 Park Place, Yreka, California 96097  
Jan. 6, 1979



Taken 1947

East (front) side of house with the original porch before the addition was added on the south side of house.





This is the East side of the upper story which shows detail of the Italianate Architecture under the eave of the roof. It is also on the North side of the house.



BERRY & Son  
1865

# 4

East side of house (front) when the addition was added to the South side, the original porch was removed and this stoop was placed in front of the entrance.

DOE

DEC -3 1 1979

#10/15

Falkenstein, Lewis, House  
Siskiyou County, California



I-6-79

South side of house where the addition was added on--also shows south end of porch that is under construction.



Date taken, unknown.

Shows front (east) and North side of  
house with the original porch.





I-6-79

This shows the porch being replaced according to the original design on both the East and North sides.



I-6-79

East side of house, porch is same length as the original, does not cover addition. According to City regulations, the porch would have been too close to the side walk, had it gone to the south end of the house.

005



I-6-79

East and North side of house (a closer view) shows porch under construction.