



H-1

From Entry

-N-

SM #1



H-2 Dining space

NW 5m#3



H-3 Dining Room, east
wall - NE SM#5



H-4 dining room,
east wall - E - SM#5



4-5 Remodeled kitchen

SW - SM#6



H-6 Parach - internal
screen enclosure

NE SIM# 7



H-7 Porch, external
screen enclosure - W-

SM #7



A-8 Main house
Orientation to guest house

n - sm #8



H-9 Entry gate with
sign - NE - SM#11

ANTOYO
DEL
AJO

H-10

Entry gate with sign,

Closeup - NE - SM#L1



A-11 grape stake fence
bordering Greenwood Lane

SE ... SM # L2



#1 front entry - E - SM #1



2 front entry - NW - SM # 1



#3 brick path: bedroom, south wall - NW - SM#2



* * bedroom converted to dining room - S - SM#2



#5 dining space: entry - NW - SM #3



#6 workroom - W - SM #4



#7

WORKROOM

-

S

-

SM#4



#8 living room, south wall - S - SM#5






#9 living room, east wall - SE - SM#5



ON THE TERRACE

#10 living room, north wall - N - SM # 5



#11 Kitchen, looking toward former bathroom - SW - SM#6



#12 porch, interior glass enclosure - NE - SM#7



#13 porch, exterior glass enclosure - W - SM#7



#14 main house orientation to guest house - N - SM #8



#15 guest house - E - SM # 8



#16 guest house, bedroom #1 - SW - SM# 2a



#17 guest house. kitchen converted to bathroom - SE - SMM# 86



#18 guest house, bedroom #2 - NW - SM# 8c



#19 carport converted to garage - NE - SM#9



#20 gazebo converted to pool equipment enclosure - NW - SM# 10



#21 entry gate with sign - NE - SM # L1



ANTONIO
DEL
AJO

#22 entry gate with sign. close up - NE - SM#L1



#23 grape stake fence: garage driveway - E - SM# L2