

#1 of 20

MILLTOWN INDIA RUBBER CO. 11/85
Milltown, Middlesex Co.,NJ
Projecting original rear wing,
South elevation, view to north
Photo by Wyatt. Negs. on file
at 78 Essex St., Jersey City NJ



#2 of 20
MILLTOWN INDIA RUBBER CO. 11/85

MILLTOWN INDIA RUBBER CO. 11/85
Milltown, Middlesex Co., NJ
Streetscape, Washington Avenue,
View looking north.

Streetscape, Washington Avenue, View looking north. Photo by Wyatt. Neg. on file at 78 Essex St., Jersey City NJ



#3 A 20
MILLTOWN INDIA RUBBER CO. 11/85
Milltown Middlesey Co. NJ

Milltown, Middlesex Co.,NJ Streetscape, Washington Avenue, View looking north.

Photo by Wyatt. Neg. on file at 78 Essex St., Jersey City NJ



1 of 20 MILLTOWN INDIA RUBBER CO. 11/85 Milltown, Middlesex Co., NJ

Detail of central tower. View looking NNE.

Photo by Wyatt. Negs. on file at 78 Essex St., Jersey City NJ



MILLTOWN INDIA RUBBER CO. 11/85 Milltown, Middlesex Co., NJ North end of west elevation.

View looking NNE.

Photo by Wyatt. Negs. on file



#/ of 20
MILLTOWN INDIA RUBBER CO. 11/85
Milltown, Middlesex Co.,NJ

Rear yard area, view to modern factory on original grounds. View to NNE.
Photo by Wyatt. Negs. on file at 78 Essex St., Jersey City NJ



MILLTOWN INDIA RUBBER CO. 11/85
Milltown, Middlesex Co.,NJ
S end of Front elevation,
View looking ENE.

Photo by Wyatt. Negs. on file at 78 Essex St., Jersey City NJ

17 of 20



MILLTOWN INDIA RUBBER CO. 11/85 Milltown, Middlesex Co., NJ

West elevation, center & north are

View looking East Photo by Wyatt. Negs. on file



MILLTOWN INDIA RUBBER CO. 11/85
Milltown, Middlesex Co.,NJ
North elevation, view look east
Photo by Wyatt. Negs. on file

Photo by Wyatt. Negs. on file at 78 Essex St., Jersey City NJ

of 20



MILLTOWN INDIA RUBBER CO. 11/85 Milltown. Middlesex Co., NJ North elevation of 1930s wing

view looking ESE Photo by Wyatt. Negs. on file at 78 Essex St., Jersey City NJ #10 of 20



#11 of 20 MILLTOWN INDIA RUBBER CO. 11/85 Milltown, Middlesex Co., NJ

North face of central tower, view looking south.

Photo by Wyatt. Negs. on file



417 of 20 MILLTOWN INDIA RUBBER CO. 11/85 Milltown, Middlesex Co., NJ Projecting original rear wing, view looking west Photo by Wyatt. Negs. on file at 78 Essex St., Jersey City NJ



#13 of 20 MILLTOWN INDIA RUBBER CO. 11/85 Milltown, Middlesex Co., NJ

East (rear) elevation, view looking West.

Photo by Wyatt. Negs. on file at 78 Essex St., Jersev Citv NJ



#/4 of 20
MILLTOWN INDIA RUBBER CO. 11/85
Milltown, Middlesey Co. NJ

MILLTOWN INDIA RUBBER CO. 11/85
Milltown, Middlesex Co.,NJ
Stack and powerhouse on south
elevation. View looking west.
Photo by Wyatt. Negs. on file



MILLTOWN INDIA RUBBER CO. 11/85 Milltown, Middlesex Co.,NJ Rear elevation, south and central portions. View looking WNW. Photo by Wyatt. Negs. on file

at 78 Essex St., Jersey City NJ

15 of 20



4/6 of 20 MILLTOWN INDIA RUBBER CO. 11/85 Milltown. Middlesex Co., NJ Projecting original rear wing, view looking WNW Photo by Wyatt. Negs. on file at 78 Essex St., Jersey City NJ



MILLTOWN INDIA RUBBER CO. 11/85 Milltown, Middlesex Co.,NJ Detail of arched loading dock door

#17 of 20

on south end of rear elevation. Photo by Wyatt. Negs. on file at 78 Essex St., Jersey City NJ



#18 of 20 MILLTOWN (NJ) INDIA RUBBER CO. Photo #

. Typical floor, looking to north end of bldg.

Neg on file: CWA, 78 Essex St.

Jersey City N.J.



#19 A 20
MILLTOWN (NJ) INDIA RUBBER CO.
Photo # . Rear hall in "T"
of building.

of building.
Neg on file: CWA, 78 Essex St.

Jersey City N.J.



#20 f 20

MILLTOWN (NJ) INDIA RUBBER CO. Photo # . Tower Stairway.

Neg on file: CWA, 78 Essex St.

Jersey City N.J.