APPENDIX B REEF BAY GREAT HOUSE HISTORIC DISTRICT

DESCRIPTION

The site of Reef Bay Great House Historic District is on a small spur extending into Reef Bay Valley from Bordeaux Mountain to the east, approximately 1,000 yards inland from the shoreline of the bay. The district contains the Great House, a servants house, a stable, a privy and a well. The elevation is about 250 feet above sea level and it is reached by a trail that branches off the Reef Bay-Lameshur Trail.

The Great House is still partially roofed but several bearing masonry walls show signs of failure and on the interior all woodwork is badly deteriorated as are exterior and interior masonry finishes. The masonry walls of the servants quarters and the stable still stand to plate height in a deteriorated condition. The cookhouse, the privy and the walls of the semi-circular terrace on the north side of the Great House have collapsed as has the once roofed terrace to the south of the Great House.

Reef Bay Great House is the most important architectural monument within the Virgin Islands National Park and a significant example of West Indian architecture. Considered in connection with the remains of Reef Bay Sugar Factory and its historical association with the various ruins within the confines of Reef Bay Valley, it ranks as the most complete exhibit of the plantation economy of the West Indies within the Virgin Islands. Its spectacular and well-planned setting makes it a noteworthy example of historic landscaping, both for the quality of the design and its rarity. Reef Bay Great House was originally the Great House of Par Force. The existing building dates from the early 19th century but it contains within its shell the masonry base of an earlier wood building.

In its present form the Great House is an excellent example of a severely formal classical revival design with well conceived and sophisticated detailing that is carried through on the service buildings and in the retaining walls and fences. The incongruity between the formality and controlled symmetry of the architecture and the irregular topography of the setting has by the builder or the designer been turned to an advantage. Retaining walls, fences and steps direct the approaches and provide changing views of both the buildings and of the surroundings that soften and enrich the severity of the architecture. The original planting of the terraced landscaping has been choked out by bush and can only be guessed at, but sufficient remains of the terraces to provide an idea of the formalized landscape intended.

STATEMENT OF SIGNIFICANCE

Reef Bay Great House complex is significant as a distinguished architectural expression in a neo-classical manner, that within a time frame of contemporary buildings, is of a highly sophisticated design as well as a true adaptation to the West Indies and to its setting.

Latitude Latitude Longitude 18⁰ 19' 54" 64⁰ 44' 25"

Acreage: 5 acres

Longitude

There are no UTM references on any published maps of the U.S. Virgin Islands

VERBAL BOUNDARY DESCRIPTION

Except for a small flat approximately 150 feet by a 100 feet northwest of the Reef Bay Great House, the terrain around the complex is very steep and without any distinctive natural or man-made features. As it is located in a protected area the boundaries of the Historic District have been arbitrarily set as the area bounded towards the west and east as longitude 64° 44' 23" and 64° 44' 27" and towards the north and south as latitude 180 19' 56" and 180 19' 52".

	Hillian and Hillian III	Aidunn			
endix B, Historic Distr	LAS SIFIED STR	RUCTURE FIELD	INVENTORY F	REPORT	
	(Att	ach 4"x5" B&	W Photo)	NPS ORGANIZ	ZATION
REGION Southeast	_ PARK/AREA 1	IAME <u>Virgin Isl</u>	ands 'Nat'l I		
STRUCTURE NAME Reef Ba	ay Great Hou	se		STRUCTURE NO. H.	15.1.
				, , , , , , , , , , , , , , , , , , , ,	7
ORDER OF SIGNIFICANCE:	National	1	State	. Tocal	•
			•		
•					
LOCATION OF STRUCTURE:	la miles sou	th of Center	line Rd Re	ef Bay Valley on	trail 1
	-2	- Conternation		Lameshur	
UTM REFERENCE:		1 1 1 1	1	LAND ACREAGE (if a complex or dist	
Zone Eastin	Nor	thing		- <u>E</u>	cres.
•					
STRUCTURE: Type of, as	nd compositio	n: Plastered	Brick and I	Rubble masonry o	lwellin
rectangula	r in plan one	-story high b	pasement.	, , ,	
Physical Description: T	he building i	s one story v	with a partia	d basement under	the
north and west side of grade. On the south a	the structur	the grade is	ver west sic	or level. The har	ilding
measures 35 feet by 5	6 feet It is	constructed:	in rubble m	sonry with brick	lining
of corners and around	masonry ope	nings. Exce	pt for payer	nents and steps,	all
masonry surfaces are	plastered or	stuccoed. 7	The roof is	partially a flat br	ick ro
on wood beams and par					
wood on wood beams. front of the main entra					
porch is supported on					
similar design shields severely symmetrical					
south and north flank a					
core is 4 by5 bays with leading from the interi	or to the sou	s on either s	gallery res	nectively. On the	doore
exterior base, flooran	d rail levels	as well as	window and	door openings h	2
stucco banding. A den	til course ar	d a very sim	nole cyma re	cta moulding form	'n
		(continue on	reverse if necess	ary)
	Excellent	Good_	 4	Deteriorate	
Ruins Una	ltered x	Altered	1 Origina	1 Site X Moved	1 1

the classical revival cornice. The parapet wall alone e cornice is divided into panels by stucco banding and the corners carry acroterions. The flanking galleries have stucco banding of corners and base, stucco panels above and below the arches, keystones, spring mouldings, parapet mouldings and on the parapet, domed finials and acroterions. A similar detailing is given the porches. The plaster work is well executed and the design very sophisticated. The interior has trim around door and window openings and cornice mouldings in plaster.

The Great house is still under roof and with all walls standing. All woodwork, however, including rafters and beams have deteriorated beyond repair and within recent years, structural failure of the masonry can be observed in the front and south section of the building. Finishes inside and out are fragmentary only. Roofing throughout has deteriorated.

Latitude 18019'54" Long de 64044'25"

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT (Attach 4"x5" B&W Photo)

REGION Southeast PARK/AREA NAME Virgin Islands Nat'l Park CODE NO. 5360
STRUCTURE NAME Cook House, Reef Bay Great House Complex STRUCTURE NO. H-15.2
ORDER OF SIGNIFICANCE: National State X Local
•
LOCATION OF STRUCTURE: / mile south of Centerline Rd, Reef Bay Valley on trail to UTM REFERENCE: CLASS VI LAND ACREAGE (if not
A part of a complex or district:
Zone Easting Northingacres.
\cdot
STRUCTURE Type of and composition: Plastered Brick and rubble masonry rect-
angular in plan one-story. Physical Description: The Cook House is located in front and to the west of the
main house, ten feet below its first floor level. It is a one-story rubble masonry structure 24'2x14'2" with a Dutch oven built into the soutwest corner. The
exterior walls vary in thickness from 2'3" to 2'6"; the interior is divided into two
almost equal sized rooms. The room to the north contained the kitchen with a masonry range along the west wall. Two doors in the east and north wall respect
ively provided light and additional ventilation to the interior. The south room has
one door in the east wall. The south end wall of the cook house now stands only 2'6" above the original floor level, while the back west wall of the cook house
2'6" above the original floor level, while the back west wall of the cook house stands to a height of 8' measured from outside grade level, or 6'6" from interior
pavement level. The cook house was plastered throughout and had the same banding of corners and openings as the other buildings of the Great House complex
Latitude 18°19'54" Longitude 64°44'25"
(continue on reverse if necessary)
PRESENT CONDITION: Excellent Good Fair Deteriorated Ruins X Unaltered X Altered Original Site X Moved

<u>CL.</u>	ASSIFILM ATRUCT	URE FIFE BOW	INVENTURY R			
REGION Southeast	PARK/AREA NAME	Virgin Isla	ınds Nat'l F		PS ORGA	NIZATION 5360
STRUCTURE NAME Servants	' Quarters, Re	ef Bay Gre	at House	STRUCT	URE NO.	H-15.
ORDER OF SIGNIFICANCE:	National	•	State X	, ·	Local	
	,					
LOCATION OF STRUCTURE: 1	$\frac{1}{2}$ mile south of	Centerline	Rd, Reev	Bay Va	lley on	esnur trail to
UTM REFERENCE: A Zone Easting	North	ing	CLASS VI part of			•
	, ,	•				
•	•					
STRUCTURE: Type of, and	d composition: I	Plastered I	Brick and R	ubble r	nasonr	V
	in plan one-st	ory.				
utility buildings. It me	asures 18'5 by	14'4" and	is northwes	t of the	main l	uilding
It was constructed to ling one-story masonry buil	ding, standing of	on an acce	ntuated bas	e. The	buildir	ig was
plastered throughout an	d with an exteri	ior decorat	tive banding	of win	dows.	corners
and eaves. All walls st of the original finishes.	Wood frames	nt although for the doc	or and one of	nd with	indows	racesare
	woodwork, inc					
		Latitude 18	3 ⁰ 19'54'' L	ongitud	e 64º44	12511
		· · · · · · · · · · · · · · · · · · ·	ant fame		16	
PRESENT CONDITION: Ex	ccellent	Good	ontinue on r	1-0-1	ir nec	
		ltered	Original	**************************************		,

endix B, Historic Dis	rict		dr.f.		
•	CLASSIFIED STRUC	TURE FIEL	D INVENTORY RI	erort	
REGION Southeast	•	ch 4"x5" B	aw Pnoto) slands Nat'l I		RGANIZATIO NO. 5360
STRUCTURE NAME Privy	. Reef Bay Grea	t House	, `	STRUCTURE 1	NO. <u>H-15</u>
ORDER OF SIGNIFICANCE	. National	٦.	State X	Loca	al 🔲
LOCATION OF STRUCTURE	$\frac{1}{2}$ miles south	of Centerl	ine Rd, Reef	Bay Valley	on trail to
UTM REFERENCE: A Zone Eastin	g Nort	1 l l h i n g	*	LAND ACREAG	•
		. •			
		•			
	and composition:	Plastere	d rubble masc	onry, one s	tory and
Physical Description: with a door on the nor	The privy was a	10' by 10 probably a	'6", one-stor a small windo	y masonry w in each o	structure ne of the
hree other sides. T and slightly projectin	g stucco bands.	as did the	other building	gs of the si	te. The
south corner stands to cootings and wall frag		', but othe	er walls have	tumbled and	d only
		Latitude	18 ⁰ 19'54'' Lo	ngitude 64°	744 25 11
	,		•		

(continue on reverse if necessary) PRESENT CONDITION: Excellent Good Fair Deteriorated

Ruins X

Unaltered X

Altered

Original Site X Moved

(Attach 4"x5" B&W . noto)
NFS ORGANIZATION
REGION Southeast PARK/AREA NAME Virgin Islands Nat'l Park CODE NO. 5360
STRUCTURE NAME Stable. Reef Bay Great House STRUCTURE NO. H-15.
ORDER OF SIGNIFICANCE: National State X Local I
LOCATION OF STRUCTURE: 1 miles south of Centerline Rd, Reef Bay Valley on
UTM REFERENCE: CLASS VI LAND ACREAGE (II not
A part of a complex or district: Zone Easting Northing acres.
bone . But of I mg N.O.I that I mg
\cdot
STRUCTURE: Type of, and composition: Plastered rubble masonry, one-story
rectangular in plan. Physical Description: The stable is a one-story masonry building measuring 14'4"
by 39'1". It was built into the side of the hill and its rear, southeast wall also
served as a retaining wall. Both end walls have a centered window opening 3'0"
by 3'9" high. The front wall that has collapsed, appears to have had either two or three large openings. The exterior was stuccoed and corners, window openings,
base and top of walls were accentuated by slightly projecting stucco bands. The
two remaining walls stand partially to their full height and the roof appears to
have been hipped.
Latitude 18 ⁰ 19'54'' Longitude 64 ⁰ 44'25''
(continue on reverse if necessary)
Ruins X Unaltered X Altered Original Site X Moved

· <u>C</u> I	LASSIFIED TRUCTURE FIEL (Attach 4"x5" B	&W Photo)
REGION Southeast	PARK/AREA NAME Virgin	NPS ORGANIZATION Islands Nat'l Park CODE NO. 5360
STRUCTURE NAME Retainin	g Walls and Fences. Rec	f Bay Great STRUCTURE NO. H-15.
ORDER OF SIGNIFICANCE:	National	State X Local
LOCATION OF STRUCTURE: UTM REFERENCE: A		CLASS VI LAND ACREAGE (if not part of a complex or district:
walls, fence Physical Description: P	ces and gate posts and st art of Reef Bay Great H	ouse quality lies in its carefully
These features are now	almost obscured by ve	ining walls, steps, fences, etc. getation and in some cases, parti-
ally destroyed. A terra house and servants quare bounded to the west by repillars that once were the north by three steps posts. The front terractraised gazebo. A retain yards south and east of corner of the east yard access to the stable and	ters built to the west and retaining walls up to 12' he posts for the iron fend and a gate between two see continues 45 feet beyoning wall and steps sepathe building from the from lead down to the area no outhouse. The retaining	d at a lower level. The terrace is high topped by circular masonry ce. Access to the terrace is from 10'3" ornamental masonry gatend the Great House and ends in a rated the narrow and irregular ont terrace. Steps in the northeast rth of the Great House and provider g walls and staircases, where they
are still standing, have	the same stucco band de	ecoration as observed on the building
	Latitude	18 ⁰ 19'54'' Longitude 64 ⁰ 44'25''
		(continue on reverse if necessary)
PRESENT CONDITION: E	Excellent Good	Fair Deteriorated X
	tered X Altered	Original Site X Moved