

JUL 13 1976

R. L. Durning May 1975 Louisville, Kentucky.

Photo 2.0/8
Photo taken from the south of the main block. Because of the original window under the first-floor entrance, the stoop was

restored with an open arch below it.

DEC 2 1977



R.L. Durning JUL 13 1976

May 1975

Louisville, Kentucky. 1977

Photo 3. %
Photo taken from the southwest.
Note unusual arrangement of

windows in the west side.



R. L. Durning
May 1975
Louisville, Kentucky. DEC 2

Photo taken from the west showing

Photo 4. 7 18

the side fenestration.

2 1977



Distillery Site. Taylorsville, Spencer County. JUL 13 1976 R.L. Durning May 1975 Louisville, Kentucky. Photo 5. 9/8

Bourne-Anderson House and

Photo taken from the north showing the frame addition on the left. Notice the flat horizontal siding around the opening of the back door.



R. L. Durning
May 1975
Louisville, Kentucky.

Photo 6. % 18
Interior photo of the stairs in the

JUL 13 1976

central hall. The back door of the house is on the left, seen through the opening of the lateral passage behind the entrance hall. Notice the original pendant under the landing and graceful "gooseneck"

balustrade.



R. L. Durning
May 1975

Louisville, Kentucky.

Photo 7. % | 8 View of east end of lateral passage behind stairhall. Note shallow vaulted ceiling, typical

door frame and chair-railing.

JUL 13 1976



R. L. Durning

May 1975 Louisville, Kentucky. JUL 13 1976

Photo 8. 3 18 Interior photo of mantel in a downstairs room. The other three mantels on the first-floor are similar.



R.L. Durning JUL 13 1976
May 1975
Louisville, Kentucky.

Photo 9. 6 8 Interior photo showing the detail of the paneling made under the window. Notice the window trim and raked moldings.



R. L. Durning May 1975 Louisville, Kentucky-JUL 13 1976

Photo 10. \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(\) \(

later.



R. L. Durning
May 1975

Louisville, Kentucky.

as shown in photo 10.

DEC 2 1977 en tucky.

Photo 11. % (§
Photo taken from the north showing the stone springhouse which is located underneath the brick building



R. L. Durning
May 1975
Louisville, Kentucky.

13 1976

Photo 12.9 | 8 DEC 2 1977

Photo taken from the south showing

the log (covered with clapboard)
smokehouse. It is located northeast.



R. L. Durning

May 1975 DEC 2 1977 Louisville, Kentucky.

Photo 13. (?)
View of the log barn with the stone foundation in the ravine north of the house. The logs can be seen through the cracks of the

left front corner.

JUL 1.3.1976

barn siding, particularly at the



Daurne-Anderson House Taylorsville Spencer Co. Kentucky DEC 2 1977 Mary Cronan Oppel July. 1977 Kentucky Heritage Commission Frankfort, Kentucky Photo 14. 7) 18 Photo taken from the southwest showing the facade after the AUG 9 1977 restoration.



Bourne-Anderson House Taylorsville Spencer Co. AUG 9 1977 Kentucky Mary Cronan Oppel July, 1977 Kentucky Heritage Commission Frankfort, Kentucky DEC 2 1977 Photo 15. %/8 Photo taken from the northwest showing the back of the house after

the restoration.



Taylorsville
Spencer Co. AUG 9 1977
Kentucky

Mary Cronan Oppel
July 1977

Bourne-Anderson House

Photo 16.% | Rentucky

Photo 16.% | Rentucky

Interior photo of the central hall

and rear entrance after the restoration

Kentucky Heritage Commission



R. L. Durning DEC 2 1977 May 1975 Louisville, Kentucky.

Photo 7.0 18
View of interior of Palladian
window in upper central gable hall.
Note elliptical vault and simplified

chair-rail upstairs.



R. L. Durning
May 1975

Louisville, Kentucky.

Photo 18.0 18
Photo taken from the south showing the main block and the new frame kitchen addition on the right, with restoration not yet complete; notice

lack of entrance stoop.