



McCartan ~~Gilman~~ / Turner House
Newton Co. ~~Goodland~~ IN

Doren Green (ph)

Ph. with this application

Fall 1991

2 story bay window in center, round-topped
with flashed glass (cathedral) in cobalt
blue.

Company formal veranda left, partial veranda
29' long right and ornamental screen doors,
porch trim + the east wing, also pilasters all
original.

1

(looking north)



McCAIRN ~~Gitman~~ / Turner House
NEWTON Co. ~~Goodland~~ IN

Doren Green (ph)

Fall 1991

Sent in w/ the application

Removal of second-story brackets (). There was not room for them when the box eaves were removed, bringing soffit close to the tops of windows.

Done c. 1946 the soffit was added the same time that the cupola was removed from above the front hall.

Upper & downstairs kitchen windows changed & bathroom window added.

(Looking northwest)

#10

#12



^{McCartan}
~~St man~~ / Turner House

Newton
Co. ~~Goodland~~ IN

Doren Green, (P.H.)

Jul 1991

Incl. w/ The Application

East side of house. Newer part is left side with vertical stick windows. At right, the only 6 over 6 window that remains. (Old glass). From an old picture there was at least one 6 over 6 in the east wing front elevation. This 6 over 6 window has been moved from closer to the center of the wall to facilitate basement stairs.

Notice the gable and eave crown molding that is found on this closed-eave wing. Note the little lip over each opening.

(Looking west)

~~#17~~ #3



McManis/Gottman / Turner House
NEWTON CO.,

Goodland IN

Doren Green (Phot.)

Fall 1991

Sent w/ the application

Back of the House

- a. Most interesting feature: you can see the north-facing gable at right which was part of simple front gabled house $1\frac{1}{2}$ c/1871.
- b. 4 of these openings have changed. Bathroom window had been a full-length battery window as I grew up. The kitchen window had been a long dining room window. (A door to a 12' x 15' back kitchen built c/1908 was where there is nothing now. An outline of where this room had been can be seen in the grass.)
- c. Pump can barely be seen
- d. Present rear property line is about where steel post is.
- e. Back door to the original house was likely where bathroom window is now.
- f. House was raised -- all of it -- was raised when full basement was dug 1908 or so, with horse & slip scoop through this basement-way entry. (Looking South)



^{McCann}
~~Wittman~~ / Turner House
NEWTON Co.,
~~Goodland~~ IN

Doran Green (ph.)

Fall 1991

Incl. in the Application

Depicts well the use of parapet to disguise the slanted roof as it extended the north wall of the bedroom (center) beyond the upper-floor inset.

(Looking east.)



^{McCANN}
~~Gilman~~ / Turner House
~~Goodland IN Newton Co., IN~~

Doren Green (Ph.)

1991

Incl. w/ the Application

West side of 1886 addition

Shows the vertical stick double-hung windows

Double stairway goes up this wall toward the left.

Before the cupola was removed c/1946, there was a

4th window on this wall where a little stairway
went up to the cupola where the
hall came around at the place
where the window is now.

Little porch trim appears to be about perfect.

(Looking north east)



~~McCAIRN~~ 1

McCAIRN - TURNER HSE.

NEWTON CO., IN

DORIS GREEN (pl.)

1993

VELMA DART - ADDRESS OF NOMINATED PROP.

STAIR NEWEL POST

LOOKING NORTH

#7



McCrann-Gitman / Turner House
Newport Goodland IN
Co.

Doren Green (Photog.)

Fall 1991

Incl. in Application

Walnut banister (4 1/2" wide) with the center grip feature, balusters 2 to a step, and newel post (not shown 10" at the bottom, 12" at the thickest part.) Photographer chose to dramatize the curving aspect at the top turning back along the upper hall. Stairway has 17 steps.

(Looking north.)

~~#8~~ #8



McCrain ~~Gitman~~ / Turner House

Newman Co. Goodland IN

Doren Green (photog.)

Fall 1991

% Velma Dart

Bay window, 4 part moldings under windows.

Shows thickness of woodwork. 10'4" ceiling.

(Looking south)

~~#8~~ #9



McCAFFREY Gitman / Turner House
Newport Co., Goodland IN

Doren Green, photographer
Fall 1991

Incl. with the Application

White pine double doors on a 10' 4" wall.
10-inch grooved onefboard. Door opening $9\frac{1}{2}' \times 7'$.
The deep molding Trims are "rounded" at the ends in
imitation of the round-top window themes.
8" woodwork.

(Looking North in parlor)



McCormick / Turner House
Horton Co. Goodland IN

Doren Green, phag.

Fall 1991

Incl. w/ Application

Cobalt blue transom light and 5-panel door on
10' 4" wall. Woodwork had roundness. (Outer
part thought to be pew bench rail, attached so well
that the seam cannot be seen, only detected by
fingernail in some places.)

10" mopboard

(Looking west in the parlor)

~~#10~~ #11



McClain ~~Gilman~~ / Turner House
Newton Co., ~~Goodland~~ IN

Doren Green (photog)

Fall 1991

Incl. w/ Application

Sittingroom, mostly sharp angles to the 5".
woodwork (in great quantities: 8 doors & 3 windows).
Oldest part (perfectly plain woodwork on other
side of the door right).

there used to be an eye-level board with
hooks for hanging your clothes on the wall.
See a bit of the old chandelier

(Looking Northwest)

~~10~~ 12