



1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. Historic photograph c. 1900 looking northwest showing appearance of Mineral Springs complex under Antonio Joseph's operation. The first floor of the recreation building (center with second floor balcony) remains today.
7. Photo no. 1



1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. Historic photograph c. 1918 looking northeast showing outdoor pool (foreground) and 1917 hotel (background). Photograph was taken prior to construction of existing bath house. Gable end of one story recreation building shows on extreme left.
7. Photo no. 2



HOTEL

1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. Historic photograph (date unknown - probably late 1920's) looking northwest showing south elevation of 1917 hotel and quadrangle.
7. Photo no. 3





1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. Partial view of complex looking southeast showing hotel from back (lower center), quadrangle (center) and bath house (upper right).
7. Photo no. 4





1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. Partial view of complex looking south showing hotel from back (lower left), quadrangle (center left), bath house (center) and recreation building (center right).
7. Photo no. 5



1. OJO CALIENTE MINERAL SPRINGS
2. Ojo caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. View looking northeast showing south elevation of hotel.
7. Photo no. 6




1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. View looking east showing hotel veranda detail.
7. Photo no. 7





1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. View looking west showing north (rear) elevation of hotel.
7. Photo no. 8



1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. View of west wall of hotel dining room showing typical mission detailing.
7. Photo no. 9



1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. View looking west showing east elevation of recreation building.
7. Photo no. 10



1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs, Ojo Caliente, New Mexico 87549
6. View looking southeast showing north gable end of recreation building.
7. Photo no. 11





1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs  
Ojo Caliente, New Mexico 87549
6. View looking northeast showing rear roof of recreation building and iron spring bath enclosure.
7. Photo no. 12



194  
LITHIA

1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente, New Mexico 87549
6. View looking southeast showing lithia spring fountain with bath house in background.
7. Photo no. 13



1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente, New Mexico 87549
6. View looking southwest showing north and east elevations of bath house.
7. Photo no. 14





1. OJO CALIENTE MINERAL SPRINGS
2. Ojo Caliente, New Mexico
3. James A. Caufield
4. 2/85
5. Negative on file in Ojo Caliente Mineral Springs records, Ojo Caliente Mineral Springs  
Ojo Caliente, New Mexico 87549
6. View looking northeast showing south (rear) elevation of bath house and outdoor swimming pool.
7. Photo no. 15