13. Part of Estab. Yes

Hist. Dist.?

No x

15. Name of Established District

Potent'l?

14. District

OHIO HISTORIO	<u> INV</u>	VENTORY JUMBIE CO.	Ohio Historical Center Columbus, Ohio 43211	
1. No. /7	4. Pres	resent Name(s) ck No. 27 ("Johnny Cake Lock")		17
2.0001117		ner Name(s)		1
3. Location of Negatives OHS				
6. Specific Location		16. Thematic Category	28. No. of Stories	S
on private road approx. 400 ft. east of intersection of Riverview & Everett Rds. 7. City or Town If Rural, Township & Vicinity Everett 8. Site Plan with North Arrow 9. Coordinates Lat. Long.		F, H, I 17. Date(s) or Period	29. Basement? Yes ☐ No ☐	
		1825-1827	30. Foundation Material	j t
		18. Style or Design	31. Wali Construction load-bearing masonry	
		19. Architect or Engineer 20. Contractor or Builder	32. Roof Type & Material	1
			33. No. of Bays Front Side	Ļ
		21. Original Use, if apparent canal lock	34. Wail Treatment	СK СK
		22. Present Use	cut stone/concrete 35. Plan Shape rectangle	N O
		23. Ownership Public 22X Private	36. Changes Addition ☐ (Explain Altered ☑	ر ا
		24. Owner's Name & Address,	in #42) Moved 🗆	7
Lat. Long. U.T.M. Reference		if known Akron Metro. Park District	37. Condition	J
1 7 4 5 2 1 4 0 4 5 6 1 2 4 0		976 Treaty Line Rd., Akron	XENNO fair	ဝှ
Zone Easting North		25. Open to Yes f k Public? unrestricted No □	38. Preservation Yes ☐ Underway? No ☒	ohnny
10. Site □ St Building □	ructure 🗗 Object 🗆	26. Local Contact Person or Organization	39. Endangered? Yes □	a
11. On National Yes ☐ 12. is it Register? No 攵 Eligible	Yes 💆	Summit Co. Hist. Soc.	By What? No XX	ake

27. Other Surveys in Which included

included in "Ohio & Erie Canalto.

historic civil engineering

landmark, Ohio Council ASCH

Approx. Acreage: less than 1

42. Further Description of Important Features Lock is standard mitered gate type. The lock chamber is 90 feet long by 15 feet wide. Of cut sandstone construction, it was repaired with concrete c. 1905. Both gates Some water in lock chamber, canal itself is are missing. dry south of Peninsula. There is an original piece of hardware--probably the wrought iron collar bearing that held the oak gate post--in the east lock wall at south end

Yes 🗷

No C



Visible from

Public Road?

41. Distance from and

Frontage on Road

Lock"

Yes 🗆 No 🖄

43. History and Significance According to tradition, in the spring of 1828 a flood in Furnace Run swept into the canal and stopped navigation. "...the crews and passengers were compelled to live, water-bound, as best they could. They were at last reduced to johnnycake, which constituted their diet for a number of days." origin of the name for this lock at Everett, a canal stopover then known as 44. Description of Environment and Outbuildings Unionville.

In the small residential neighborhood that constitutes the village of Everett.

45. Sources of Information 46. Prepared by
45. Sources of Information History of Summit County, ed. William Henry Perrin (Chicago: Carol Poh Miller Baskin & Battey Historical Publishers 1881) n 5/10/2
Baskin & Battey, Historical Publishers, 1881), p. 54047. Organization
Frank Wilcox, The Ohio Canals, selec. and ed. William A.
Macial (Vant Chata Walanta A.
McGill (Kent, O.: Kent State University Press, 1969), 48. Date 49. Revision Date(s)
see esp. p. 21 on lock hardware.