356

United States Department of the Interior National Park Service

# National Register of Historic Places Registration Form



This form is for use in nominating or requesting determinations for individual properties and districts. See instructions in National Register Bulletin, How to Complete the National Register of Historic Places Registration Form. If any item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions. Place additional certification comments, entries, and narrative items on continuation sheets if needed (NPS Form 10-900a).

1. Name of Property		
historic name Kellogg, Enos, House		
other names/site number Comstock-Newell Hou	se	
2. Location		
street & number 210 Ponus Avenue Extension		NA not for publication
city or town Norwalk		NA vicinity
state Connecticut code CT Co	unty Fairfield code 01	zip code 06850
3. State/Federal Agency Certification		
As the designated authority under the National Histor	ic Preservation Act as amended	
nationalvstatewidelocal	5.9.12 Date ATTON OFFICE	
In my opinion, the property meets does not meet the Natio	onal Register criteria.	
Signature of commenting official	Date	-
Title	State or Federal agency/bureau or Tribal Governmen	nt .
4. National Park Service Certification		
I hereby certify that this property is:	determined eligible for the National	Register
determined not eligible for the National Register other (explain:)	removed from the National Register	
Signature of the Keeper	Date of Action	<u> </u>

(Expires 5/31/2012)

Kellogg, Enos, House Fairfield, Connecticut lame of Property County and State				
5. Classification				
Ownership of Property (Check as many boxes as apply.)  Category of Property (Check only one box.)		Number of Resources within Property (Do not include previously listed resources in the count.)		
Tun Institute	Landers		ntributing	
x private public - Local	x building(s)		buildings	
public - State	site	11	sites	
public - Federal	structure		structures	
public - redetar	object	2	objects Total	
			- 55.001	
Name of related multiple prop (Enter "N/A" if property is not part of a	perty listing multiple property listing)	Number of contributing rein the National Register	sources previously listed	
N/A		0		
6. Function or Use				
Historic Functions (Enter categories from instructions.)		Current Functions (Enter categories from instructions)	)	
DOMESTIC/single dwelling		DOMESTIC/single dwelling		
AGRICULTURE/SUBSISTEN	CE	-		
COMMERCE/TRADE/Nursery	<u> </u>	*		
		-		
		-		
7. Description				
Architectural Classification (Enter categories from instructions.)		Materials (Enter categories from instructions.)	(K	
NEW ENGLAND COLONIAL				
Other: Saltbox		foundation: STONE		
		walls: WOOD/Shingle		
		roof: ASPHALT		
		other: STONE (chimney)		

(Expires 5/31/2012)

Kellogg,	Enos,	House
Name of P	roperty	

Fairfield, Connecticut
County and State

Narrative Description

(Describe the historic and current physical appearance of the property. Explain contributing and noncontributing resources if necessary. Begin with a summary paragraph that briefly describes the general characteristics of the property, such as its location, setting, size, and significant features.)

#### Summary Paragraph

The Enos Kellogg House, a two and one half story, 2,800 square foot saltbox farmhouse, is a classic second half of the 18th century southwestern Connecticut farm property, with many remaining original, illustrative architectural details. The building was constructed circa 1784 by Enos Kellogg, and remained home to his direct descendents until 1917. Oriented to the west, the dwelling has four bays across the front, with the front entrance located in the second bay in from the south side of the house. The likely original architectural layout consisted of three primary rooms on the first floor, and an additional four rooms on the second floor, with a large fieldstone central chimney occupying the core of the structure. Defined by its classic saltbox profile, the structure is an integral lean-to, with rear rafters running continuously from the roof peak to the rear floor line of the second story. A series of 19<sup>th</sup>, 20<sup>th</sup> and 21<sup>st</sup> century additions are attached to north (side) and east (rear) of the original structure, but have had little impact on the original fabric of the house. The building is located close to the street on the western edge of a very gently sloping 1.7 acre lot. Contributing resources on the property include an 18<sup>th</sup> or early 19<sup>th</sup> century timber framed English barn that lies downhill to the north of the house, and a series of fieldstone walls. Landscaping includes a variety of mature trees, although none are from the era of the home's construction.

#### Narrative Description

The Enos Kellogg House is a two story (plus attic), 2,800 square foot saltbox farmhouse. The house faces the terminating end of Ponus Avenue Extension, a road that has evolved from a Native American trail between Norwalk and New Canaan known as "Ponasses Path", into a street connecting the two towns, and finally into a dead-end as a result of construction of the Merritt Parkway adjacent to the property. Oriented to the west, the dwelling (Photo 1) has four bays across the front, with the front entrance located in the second bay in from the south side of the house. The roof is currently comprised of asphalt shingles, although historic photographs and remaining roof sheathing show it to have been wood shingled originally. While no original windows remain on the first or second floors, the likely original front door remains. This single board thick Dutch door, containing two small raised panels over two large raised panels on the top and two large raised panels over two small raised panels on the bottom, is hung on likely original pintled strap hinges, and features an elaborate, likely original iron thumb latch. (Photos 2, 3, 4)

A stone path leads up to the front door from Ponus Avenue Extension, terminating in a large granite entry step directly in front of the front door. A number of mature trees are dispersed across the property. Stone walls of varying sizes remain in multiple locations around the property. The lot drops off to the north of the house, with the barn at a grade substantially lower than that of the house. Elsewhere, the lot is very gently sloping and open.

The exterior of the house is currently wood shingled. The use of modern nails makes it clear that these shingles are not original. There is evidence that the house may originally have been covered in beaded clapboards. Underneath the current shingles on all sides of the house, red painted, beaded clapboards have been recycled as sheathing. (Photo 5) Although clearly not located in their original positions, these boards contain wrought nails, and are present in such quantity as to indicate that the original covering of the house may have been re-used as sheathing beneath the shingling, once it was determined that the old boards were no longer fit to serve as a visible finish surface for the house. Victorian era photographs of the house clearly show the house shingled, so it is likely that the original covering was removed at some point in the 19<sup>th</sup> century.

#### Framing

The house is of timber framed construction, with posts and beams comprised primarily of oak. Floor joists throughout the house show milling saw marks, but major timbers appear to have been hand-cut and shaped. All joints are held fast with wooden pegs, and the major visible framing timbers are scribe ruled. Roman numeraled raising marks are evident on rafter peaks, and at other exposed timber unions throughout the house (Photo 6).

<sup>&</sup>lt;sup>1</sup> Elsie Nicholas Danenburg. The Romance of Norwalk. (The States History Company, New York, 1929) 50.

(Expires 5/31/2012)

Kellogg, Enos, House

Name of Property

Fairfield, Connecticut
County and State

#### Interior - First Floor

In an unusual, but not unprecedented, configuration, entry from the front door leads directly into a relatively plain public room (referenced in Enos Kellogg's will and hereafter as the South Room), rather than into an entryway. This room, currently used as a family room, contains a large fieldstone fireplace (Photo 7) with an original granite hearth stone. The corner of the hearth is clipped, perhaps to provide a less constrained pathway for those passing deeper into the house from the front door. The room also contains a wall of built-in bookshelves on the north side, which were installed in the mid-20<sup>th</sup> century. One major ceiling beam and several vertical posts are exposed, although it is clear from nail marks and two pieces of wood casing that remain in place that all framing elements were previously cased. The floor in this room is uniform width wide plank pine, although this is a later replacement for the original. A likely original raised panel door, also seen in Photo 7, leads from this room into the kitchen.

To the north of the South Room is a second, more formal room (referenced in Enos Kellogg's will and hereafter as the North Room), which now serves as a master bedroom. This room contains a wall of likely original raised paneling surrounding a fieldstone fireplace (Photo 8). There is evidence that, subsequent to initial construction, this wall was relocated further into the room by approximately 6 inches in order to make additional room for a closet. As noted by architectural historian James Sexton, while the South Room shows evidence of wood casings on the framing elements, in the North Room the "major timbers were scored to create a matrix for plaster. This combination of casing everywhere except the best room in the house suggests a last quarter of the 18<sup>th</sup> century construction date. It was at this time that casings were going out of style and plaster covered timbers were becoming the norm." The flooring in this room is a modern replacement. Exposed joists in the ceiling show evidence of a previous plaster and lath covering. (Photos 9, 10)

A large Kitchen (now a living room) occupying the majority of the rear of the original first floor is dominated by a massive hearth containing a beehive oven located somewhat antiquatedly for the late 18th century in the rear right corner of the firebox (Photo 11). Unlike the other three fireplaces in the house, the firebox here is built of dressed stone, rather than random sized fieldstone. The faint remnants of a red wash are visible on the masonry. A likely original granite hearth stone fronts the firebox, and an extremely large wooden lintel tops the firebox opening. Nails driven into small strips of wood on the either side of the firebox opening provide a location to hang cooking implements. While nail hole patterns indicate that there was originally wood trim on the lintel, the stonework above the fireplace may have been exposed since construction. (Photo 12) Two doors lead off of the north wall of the Kitchen. The first leads into what is now a small dressing room that may originally have been part of the North Room. The second door opens into a small closet that is referenced in Enos Kellogg's will and hereafter as the Milk Room. Shadow marks on the original beaded paneling dividing the Kitchen and the Milk Room indicate shelving that was present in the Kitchen in the home's early years, prior to application of the first coat of paint. As elsewhere on the first floor, modern sub-flooring has been installed in both the Kitchen and the Milk Room. A 1961 study of the house states that the wide plank oak flooring in the living room was moved to that room from the attic when the sub-flooring was installed in 1937. As in the North Room, exposed ceiling joists in the Kitchen show evidence of a previous plaster and lath covering. The massive rear posts of the original house stand fully exposed, having been revealed when a later addition was placed on the rear of the Kitchen. (Photo 13)

#### Staircase

From behind a board-and-batten door in the southwest corner of the Kitchen, a narrow staircase (Photo 14) winds upward to the second floor, opening into a large hall. The banister and newel at the top of the stairs are 20<sup>th</sup> century replacements.

The staircase presents something of a mystery, as there are indications that the stairs may have been originally designed, and perhaps partially or completely installed adjacent to the front door of the house, directly in front of the chimney stack. Over the present staircase, an empty pocket for a floor joist is visible in the exposed beam, indicating that flooring was once intended to cover the opening between the first and second floor. Moreover, unusual horizontal planks run alongside a portion of the staircase, and are inconsistent with the plastering elsewhere along the staircase, and with the more refined vertical sheathing elsewhere in the house. This appears to be a patch of some sort, although its purpose is unclear. Despite this evidence of possible reconfiguration, the stair risers are affixed to the walls with wrought nails, and the stair treads are similarly affixed to the risers with period nails. The horizontal planks in the stairway are also affixed with wrought nails, indicating a likely 18<sup>th</sup> century installation. With this inconclusive evidence, it is impossible to establish whether the location of the stairs may have been changed during the initial

<sup>&</sup>lt;sup>2</sup> James Sexton, Ph.D., Establishing a Date of Construction for 210 Ponus Avenue, Norwalk, Connecticut. (In possession of the Norwalk Historical Society, Norwalk, CT. 2003) 2.

<sup>&</sup>lt;sup>3</sup> J.S. Cook, A Study of the Comstock-Newell House, Norwalk, Connecticut. Thesis. (Yale University, New Haven, 1961. Print. In possession of John Harrington, Norwalk, CT) 15.

(Expires 5/31/2012)

Kellogg, Enos, House

Name of Property

Fairfield, Connecticut
County and State

construction of the house, or whether they were moved for some reason shortly after construction. James Sexton, an architectural historian who has inspected the house, is of the opinion that the location of the staircase is original to the house. (Photo 15)

#### Interior - Second Floor

Reflecting the home's construction as an integral lean-to saltbox, the ceiling in the second floor hallway slopes dramatically to the floor line at the back of the house (Photo 16). This hall appears to have originally run the length of the house, from north to south, although it was divided circa 1910 (as indicated by the manufacture dates of the sink, tub and faucets) to create space for a bathroom. Flooring in the hall is a modern replacement. Currently used as a seating and play area, the hall likely served as a multi-purpose space for work and sleep in the 18<sup>th</sup> century. The early 20<sup>th</sup> century bathroom remains in use, and original wide plank oak flooring has been re-exposed in this area.

From the hall, there are doorways leading into two bed chambers on either side of the massive chimney stack. Evidence in the remaining wall paneling and nail marks on the floor and ceiling beams indicate that a small third chamber was originally located between and connecting to these larger rooms. This space, however, has since been incorporated into the room nearest the staircase, and into small closets opening off of each bed chamber.

The less formal of the chambers (South Chamber), located directly at the top of the stairs, has vertically installed, single board, beaded wood interior dividing walls (Photo 17). The exterior walls are plaster-skimmed drywall, which replaced collapsing plaster and lath walls in 2001. The flooring, wide plank oak attached with wrought nails, may be original. Beaded flat case moldings surrounding the door from the hallway into the chamber are attached with wrought nails, and appear to be original. Although much of the casing has since been removed, there is clear nail pattern evidence that all beams and posts in the South Chamber were previously encased in wood.

The more formal bed chamber (North Chamber), located farthest from the staircase, contains a fireplace with brick hearth and raised panel surround (Photo 18). Like the South Chamber, this room has vertically installed, single board, wood interior dividing walls and plaster-skimmed drywall exterior walls installed in 2001. The flooring in this room is uniform width pine, attached with wrought nails. It is unclear if this is original to the house or not. The beams and posts surrounding the fireplace wall are cased in original beaded wood casings. The two posts on the opposite wall are plaster covered, as in the North Room on the first floor. As in the South Chamber, beaded flat case moldings surrounding the door from the hallway into the North Chamber are attached with wrought nails, and appear to be original.

#### Interior - Basement

The basement of the house is accessed by stairs located behind a likely original beaded board-and-batten door in the original Kitchen. While the stair treads are modern replacements, the rough hewn stringers may be original. The floor, which was likely dirt at the time of construction, has since had a concrete surface installed. Made of fieldstone, evidence indicates that the basement was also earlier accessible from an exterior entrance on the south side of the house. This entrance was subsequently moved to the north side of the basement, probably when the coal furnace was installed near the north entrance in the late 19<sup>th</sup> century. The massive chimney stack is centered in the basement. Located at the base of the chimney stack on the south side is a small opening to an unusually large beehive oven. Floor joists, which consist primarily of cedar logs, span the basement. According to a 1961 study of the house, many of these joists are replacements, installed in 1937. One major joist is clearly original and inspection of the top of this timber reveals a series of unusual slits intended to direct dust and debris from the floor above into the basement (Photo 19). All chimney masonry in the basement, as well as all of the original woodwork on the basement stairs and the remaining original floor joists retain varying degrees of whitewash.

#### Interior - Attic

The attic is reached by means of a ladder contained behind an access door in the second floor hall. Pegged corner six over six windows located on the north and south sides of the attic are likely 19<sup>th</sup> century replacements. The roof rafters, likely original, are carried on raised plates (Photo 20). The attic floor has been elevated to create a cavity for insulation, but it appears that wide-plank flooring remains in place underneath. As the original attic floor was supposed to have been re-laid in the living room in the 1930s, it is unclear if this is original sub-flooring, or a later replacement.

<sup>4</sup> James Sexton, Ph.D., Personal Interview, 2003.

J.S. Cook, A Study of the Comstock-Newell House, Norwalk, Connecticut. Thesis. (Yale University, New Haven, 1961. Print. In possession of John Harrington, Norwalk, CT) 11.

Sexton, Interview, 2003.

Cook, Comstock-Newell House, 15.

(Expires 5/31/2012)

Kellogg, Enos, House

Name of Property

Fairfield, Connecticut
County and State

#### Hardware

Although much of the hardware in the house has been replaced over the years, there are several pieces that appear to be original. These include:

Exterior front door latch: Large wrought iron thumb latch, bar, keeper and drive catch. Latch with double spade design on top and bottom. Attached to door by wrought nails (Photo 21).

Front door hinges: Large spade tipped wrought iron strap hinges showing a bulbous flair at termination before pintle collar, indicative of a Hudson Valley design influence. Hung on likely original driven wrought iron pintles (Photo 3).

Basement door hinges: Small spade tipped wrought iron strap hinges showing a bulbous flair at termination before pintle collar, indicative of a Hudson Valley Dutch design influence. Hung on likely original driven wrought iron pintles.

Basement door thumb latch: Wrought iron thumb latch located on board and batten door from Kitchen to basement stairs.

Interior door thumb latch: Wrought iron thumb latch located on raised panel interior door between Kitchen and South Room.

Exterior door thumb latch: Large wrought iron thumb latch, bar, keeper and drive catch. Latch with triangular top and bottom. Attached to Greek Revival side entrance by wrought nails.

#### **Additions to Original Structure**

Like many 18<sup>th</sup> century houses, the Enos Kellogg House has been repeatedly expanded over the years through a series of additions. The additions to the Enos Kellogg House are as follows:

#### Addition 1

Early in the history of the house, an addition was made across the back (east) of the kitchen, effectively bumping out the rear wall of that room by just over 6.5 feet (Photo 23). The old rear wall was removed, exposing the framing posts that had previously marked the back wall of the house, and a new exterior wall was installed. This new wall was timber framed. The marks of a screw point auger in an open mortise on a rear post indicate that the addition was likely added at some point after 1800. The net addition to the house was approximately 162 square feet.

#### Addition 2

At an indeterminate point in time, but after or concurrent with Addition 1, an addition was made across the back (north) of the Milk Room. The existing rear wall of the Milk Room was left intact, but a new room was added behind the Milk Room, with access from Addition 1 space in the Kitchen. Addition 2 was timber framed, using square rule framing techniques. The net addition to the house was approximately 80 square feet. The original function of this room is impossible to determine with certainty, although it is currently used as a bedroom. A rounded, charred depression in the rear beam of this addition indicates the presence of a heating source with a stove pipe, and this evidence is further confirmed by Victorian era photographs.

#### Addition 3

At an indeterminate point in time, but after Addition 2, an addition was made on the north side of Addition 2, effectively bumping out the side wall of that room by 8 feet. The old side wall of addition 2 was removed, and a new exterior wall was installed. Addition 3 was timber framed, using square rule framing techniques. The net addition to the house was approximately 80 square feet.

#### Addition 4

At an indeterminate point in time, but after Addition 2, an addition was made to the south side of Addition 1. This addition serves as an entry hall into the house. Photographic evidence indicates that Addition 4 was constructed at some point prior to the twentieth century, and based upon what appears to be an original Greek Revival door and artifacts found in the fill beneath this structure, it is likely that Addition 4 was constructed sometime around the 1840s. Addition 4 was timber framed, using square rule framing techniques. The net addition to the house was approximately 40 square feet. (Photo 24)

<sup>&</sup>lt;sup>8</sup> Keith C. Wilbur, Home Building and Woodworking in Colonial America, (The Globe Pequot Press, Guilford, CT, 1992) 65.

<sup>9</sup> Ibid. 65.

<sup>10</sup> Ibid. 4.

(Expires 5/31/2012)

Kellogg, Enos, House

Name of Property

Fairfield, Connecticut
County and State

#### Addition 5

At an indeterminate point in time, but after Addition 2, an addition was made to the east (rear) of the house, with access from Addition 1 in the Kitchen. Addition 5 was timber framed, although framing is not currently visible other than from the crawl space below. The net addition to the house was approximately 143 square feet. The original function of this room is impossible to determine with certainty, although it is currently used as a dining room.

#### Addition 6

At some point in the late 19<sup>th</sup> or early 20<sup>th</sup> century, a timber framed agricultural building from elsewhere on the property was moved and butted against the house on the north side of Addition 5. The net addition to the house was approximately 500 square feet. The original function of this addition is impossible to determine. Presently used as a kitchen and garage, the building may have continued to serve an agricultural purpose, may have been used as a carriage house or automobile garage, or may have been converted to domestic use as a kitchen or other public space. It is also conceivable that the building served a commercial purpose, as the property functioned as a nursery in the late 19<sup>th</sup> century. Victorian era photographs of the house show a similarly sized and shaped building located to the rear of the house, and it is likely that this structure is Addition 6.

#### Addition 7

At an indeterminate point in time, an addition was made to the north wall of the original house, with access from the entry way to the North Room. Addition 7 was timber framed, using square rule techniques, and was set on an insubstantial fieldstone foundation and a series of logs which served as sleepers for the floor. The net addition to the house was approximately 64 square feet. While it is known that this space was used in the 20<sup>th</sup> century as a bathroom, the original purpose of this addition is impossible to determine with certainty.

#### Addition 8

In 2006, Addition 7 was demolished. Extensive rot to the log sleepers and framing timbers and a deteriorating foundation made the structure irreparable. To replace Addition 7, a new, two story addition was attached to the house. Addition 8 was balloon framed. On the first floor, 135 square feet of space was constructed, to be used as a master bathroom. Salvaged timbers from Addition 7 were recycled for use as decorative elements in the finished space. While clearly of modern construction, beaded vertical paneling, salvaged wide plank oak flooring, board and batten doors and salvaged and reproduction wrought iron hinges and thumb latches were installed to reflect the historic design elements found elsewhere in the house.

On the second floor, Addition 8 is accessed by a new doorway created in the place of a side window in the circa 1910 bathroom. On the second floor, approximately 135 square feet was added to extend the bathroom, providing space for a shower stall, and storage closets. As on the first floor section of Addition 8, salvaged wide plank oak flooring, board and batten doors and reproduction wrought iron hinges and thumb latches were installed to reflect the historic design elements found elsewhere in the house. The south wall of this space, previously the exterior (north) wall of the house, is clad in horizontal beaded paneling copied from the beaded sheathing found beneath the shingles around the structure.

#### Contributing Resources

#### English Barn 1

A timber framed structure (Photo 25) located to the west of the dwelling house was constructed in the late 18<sup>th</sup> century or early 19<sup>th</sup> century, as evidence by its raised plate construction and evidence of spoon bit augering in open mortises. Victorian era photographs of the property show the structure in use as a barn. The structure has undergone various changes over the years, including the addition and removal of a cupola, the replacement of the front facade, and the replacement of various framing elements. Three cattle stanchions remain in place, anchored into a concrete pad inscribed 1917. The barn has remained in continuous use as an outbuilding on the Enos Kellogg House property to the present day.

#### Stone Walls

The property is crossed by a series of substantial fieldstone walls, delineating what were once fields and pastures.

(Expires 5/31/2012)

Fairfield, Connecticut
County and State

Kellogg, Enos, House Name of Property

#### Other Associated Structures and Resources

#### English Barn 2

A timber framed structure located directly across the street from the house was part of the farm at least as early as 1832, when the estate inventory of Enos Kellogg references the "Barn West Side of Road". Victorian era photographs of the property show the structure in use as an outbuilding, likely as barn. Since converted to a private residence, framing details of the structure are unknown. In a personal interview with the current owner of the Enos Kellogg House, an employee of previous owners, who worked as a gardener on the property in the 1930s and 40s recalls his employers driving their Model T Ford through the large barn doors on the front of the structure, which they used as a barn and garage.

Carriage House

A fieldstone structure located across the street from the house and adjacent to English Barn 2 was part of the farm property at least as early as 1832, when the estate inventory of Enos Kellogg references the "Carriage house West side of road". Victorian era photographs of the property show the structure in use as an outbuilding of indeterminate function. The structure has undergone significant renovations, and framing details are not visible. The building is currently used as a rental residence.

#### Cemetery

The Kellogg Comstock Cemetery, located at the southernmost edge of the original property, was the family burial ground from at least as early as 1832. Among those interred in the cemetery are Enos Kellogg (1832) and his wife Lydia Fitch Kellogg (1832), their daughter Esther Kellogg Comstock (1857), her husband, Aaron Comstock (1827), and at least six other individuals.

William Napolitano, Personal interview, 2009.

Kellogg, Enos, House Name of Property

Fairfield, Connecticut County and State

8. Statement of Significance		
Applicable National Register Criteria (Mark "x" in one or more boxes for the criteria qualifying the property for National Register listing.)	Areas of Significance (Enter categories from instructions.) Architecture	
A Property is associated with events that have made a significant contribution to the broad patterns of our history.		
B Property is associated with the lives of persons significant in our past.		
C Property embodies the distinctive characteristics of a type, period, or method of construction or represents		
the work of a master, or possesses high artistic values, or represents a significant	Period of Significance	
and distinguishable entity whose components lack individual distinction.	1784	
D Property has yielded, or is likely to yield, information important in prehistory or history.	Significant Dates	
Criteria Considerations (Mark "x" in all the boxes that apply.)		
Property is:	Significant Person (Complete only if Criterion B is marked above.)	
A Owned by a religious institution or used for religious purposes.	(complete only if effection is is marked above.)	
B removed from its original location.	Cultural Affiliation	
C a birthplace or grave.		
D a cemetery.		
E a reconstructed building, object, or structure.	Architect/Builder	
F a commemorative property.		
G less than 50 years old or achieving significance within the past 50 years.		

### Period of Significance (justification)

The house was constructed circa 1784.

(Expires 5/31/2012)

Kellogg, Enos, House Name of Property Fairfield, Connecticut
County and State

Criteria Considerations (explanation, if necessary)

NA

Statement of Significance Summary Paragraph (Provide a summary paragraph that includes level of significance and applicable criteria.)

The Enos Kellogg House is significant statewide under Criterion C as it embodies the distinctive characteristics of an 18<sup>th</sup> century Connecticut integral lean-to saltbox farmhouse, possesses high artistic value, and is the work of master framers and carpenters. In addition, many of the original elements of the structure provide unique insight into the construction and aesthetic changes that took place in the architecture of Connecticut in the second half of the 18<sup>th</sup> century

Narrative Statement of Significance (Provide at least one paragraph for each area of significance.)

#### Architecture

Taken as a whole, the Enos Kellogg House is an outstanding example of a New England farmhouse that was designed and constructed in the saltbox form. As described by J. Fredrick Kelley, the development of this "integral lean-to" design reflected the attainment in Connecticut of a more pervasive level of wealth and security that allowed families "to devote much more attention to the physical home." Originally, the saltbox form reflected the evolution of a house over time, as a gabled one and a half or two story structure was expanded at some point after construction by the addition of a lean-to attached to the rear of the first story. The emergence of the integral lean-to form, which integrates space that had previously been a deferrable luxury into the initial construction of the house, indicates that additional domestic space had ceased being a luxury, and had, in fact, become, "owing to changes in the mode of living, a sheer necessity." 13

The Enos Kellogg House retains, to an impressive degree, the architectural elements that define the saltbox style in Connecticut in the second half of the 18<sup>th</sup> century. In addition to the extended sloping rear roofline that gives this style its colloquial name, the building is centered around a characteristic massive fieldstone chimney stack from which open three fireplaces on the first floor, and a fourth fireplace on the second floor. The floor plan matches that typically associated with a lean-to and described by J. Fredrick Kelley as "two large front rooms, one of which is a parlor, the other being variously known as the living room, hall or keeping room," and a kitchen that is "centrally located, behind the great chimney." The major framing elements of the house are of hand hewn oak, the dominantly used species in 18<sup>th</sup> century Connecticut significant using the scribe rule technique that prevailed in Connecticut through the close of the 18<sup>th</sup> century.

While the Enos Kellogg House is, in many ways, representative of the integral lean-to form in Connecticut in the second half of the 18<sup>th</sup> century, there are certain unique elements that make the structure particularly worthy of note. Of primary interest from an architectural perspective is the transitional nature of the house. In terms of its basic construction techniques, the structure, in the words of architectural historian James Sexton, "appears to be clearly late 18<sup>th</sup> century." Raised plates support the rafters on both the front and rear of the house, a technique that became common in the area in the last quarter of the 18<sup>th</sup> century. In addition, certain timbers in the building's most formal rooms were scored and covered in plaster, a stylistic detail that was uncommon the area before 1775. In contrast to these late-18<sup>th</sup> century construction details, there are aspects of the house that are rooted in an earlier design sensibility. Raised paneling and beaded wood casings in various areas of the house are typically associated with the mid-18<sup>th</sup> century. Similarly, the beehive oven in the kitchen hearth is located to the rear of the firebox, a location that was antiquated by the last quarter of the 18<sup>th</sup> century, with ovens constructed after 1775 typically placed adjacent to the firebox, rather than within it.

<sup>12</sup> Kelley, 12.

<sup>13</sup> Ibid. 12.

<sup>&</sup>lt;sup>14</sup> Ibid. 14.

<sup>&</sup>lt;sup>15</sup> Ibid. 21.

<sup>&</sup>lt;sup>16</sup> James Sexton, Ph.D., Establishing a Date of Construction for 210 Ponus Avenue, Norwalk, Connecticut. (In possession of the Norwalk Historical Society, Norwalk, CT. 2003) 3.

<sup>17</sup> Ibid. 3.

<sup>18</sup> Ibid. 2.

(Expires 5/31/2012)

Kellogg, Enos, House Name of Property Fairfield, Connecticut
County and State

While these details, independently, are not unique, in aggregate they help to illustrate the construction and aesthetic changes that took place in the architecture of Connecticut in the second half of the 18<sup>th</sup> century. In the instance of the Enos Kellogg House, the evidence would indicate that the dwelling was constructed using framing techniques that were current for the period from 1775 through 1800. Aesthetically, however, the structure captures a moment in time when homeowners in rural Connecticut were in stylistic transition, still holding on to certain elements that they had long lived with, such as the rear oven, raised panels, and cased timbers, while easing into more modern design elements such as plastered framing members. As summarized by Sexton, "what emerges is a house where conservative elements of form and style were used in conjunction with more progressive technological approaches. In other words, the client-driven choices (those based on appearance) are backward looking while the craftsman-driven ones (those related to technology) are forward looking. The result is a stylistically conservative house of the late 18<sup>th</sup> century." <sup>19</sup>

Developmental history/additional historic context information (if appropriate)

#### Ownership History

Deed research indicates that the farmhouse was constructed circa 1784 on 16 acres of land in Norwalk that was purchased by Enos Kellogg on March 29, 1784 from Mary Fitch. By the time of its construction, Enos had been married to Lydia Fitch Kellogg for ten years, and had three surviving children: Aaron, born February 10, 1775, Esther 2d, born October 30, 1779, and Hannah, born May 29, 1784. Another daughter, also named Esther, born January 12, 1778, had died in infancy. One more child, Rebeckah, was born March 16, 1787. In addition, it appears that Enos Kellogg's orphaned nephew, Matthew Kellogg, was raised by Enos and Lydia, and lived with the family. Enos Kellogg died in May 1832, and his wife Lydia quickly followed, dying on December 14, 1832. Both are interred at the Kellogg Comstock cemetery located on the southernmost edge of the original property and now owned by the city of Norwalk. Inheriting the property, which included the "Dwelling House, Barn, Hogg House, Wood House, I Barn West Side of Road, I Carriage House West Side of Road" was Enos and Lydia's daughter, Esther Comstock. Esther's husband, who died in 1827, is also buried at the family cemetery.

Concurrent with her inheritance of the property, Esther purchased, for \$1,000, an additional abutting 20 acres of land, with buildings, from her cousin, Matthew Kellogg, who presumably inherited that property from his uncle upon his death. The two parcels of land would remain Esther's property until her death 34 years later. In 1864, in accordance with the provisions of Esther's February 15, 1852 will, the property passed to Esther's grandchildren, the five heirs of her eldest son, George E. Comstock, Sr. George E. Comstock, Sr. had also purchased an adjoining 33 acres of land in 1835, and this land passed initially to George E. Comstock's oldest son, Walter. In 1868, Walter sold this land, along with his interest in his grandmother's 25 acres, to his brothers George E. Comstock, Jr. (known as Edwin) and William McCuctheon Comstock. Between 1868 and 1878, George E. and William M. Comstock's sisters, Agnes and Rebecca Comstock, also sold their interests in the inherited property to their two brothers. The 1870 census shows George E. Comstock Sr.'s widow, Mary, "keeping house" and four of her adult children, including Edwin and William, living in the home. By the 1880 census, Edwin is listed as "Head of Family", and both he and his brother William are listed as living in the house and employed as farmers. Their older sister Rebecca also remained a resident, and is now identified as "keeping house".

On what was ultimately 66 acres of land, George E. and William McCuctheon Comstock established Comstock Brothers Nursery. On February 11, 1886, William M. Comstock sold his half interest in the property to Edwin Comstock's father-in-law, Harvey Lyon, and the Norwalk Directory subsequently lists the business as Comstock and Lyon, Nurserymen of Ponus Avenue and Nursery Street. The 1910 census lists George E. Comstock as a "Nurseryman", living with his wife, Emma, their adopted daughter Nettie Comstock, his father-in-law and business partner Harvey Lyon, and several boarders.

On April 27, 1917, the Enos Kellogg House and 32 acres passed out of the hands of Enos Kellogg's descendents, as George Lyon and Emma R. Comstock, Edwin's widow, sold the property, and presumably the nursery business, to a group of four individuals. Subsequent owners sold off various pieces of the land for development, and in the late 1930s, construction of the Merritt Parkway resulted in the State of Connecticut's ownership of land to the north of the original dwelling house and barn. As of 2011, 1.67 acres of land, containing the original dwelling house and barn remain intact at 210 Ponus Avenue Extension. Two additional outbuildings from the farm, located across Ponus Avenue from the house, also remain, although they have since been converted to residences.

<sup>19</sup> Ibid. 4.

<sup>20</sup> Estate of Enos Kellogg. 1832. Print. Recorded copy in possession of Probate Court of City of Norwalk, CT.

Kellogg, Name of P	Enos, House roperty					Fairfield, Connecticut County and State
	Bibliographical					
Bibliogra	phy (Cite the books, a	articles, and other sources used in p	preparing this f	orm.)		
Cook, J.S Print, In p	S. A Study of the possession of John	Comstock-Newell House, N Harrington, Norwalk, CT.	Norwalk, Co	nnecticu	t. Research Pape	r. Yale University, New Haven, 1961
Danenbur	g, Elsie Nicholas.	The Romance of Norwalk.	New York:	The Sta	tes History Compa	ny, 1929.
Kellogg, I	Enos. Estate of En	os Kellogg. 1832. Print. F	Recorded co	oy in pos	session of Probate	Court of City of Norwalk, CT.
Kelly, J. F	Fredrick. Early Do	mestic Architecture of Con	necticut. No	ew York:	Dover Publication	ns, Inc. 1924.
Napolitan	o, William. Person	nal interview, summer 2009				
Sexton, Ja Norwalk I	ames, Ph.D. Estab Historical Society,	olishing a Date of Construct Norwalk, CT.	tion for 210	Ponus A	venue, Norwalk, C	Connecticut. 2003. In possession of the
Sexton, Ja	ames, Ph.D. Person	nal Interview, 2003.				
Wilbur, C	. Keith. Home Bu	ilding and Woodworking in	Colonial A	merica.	Guilford, CT: The	Globe Pequot Press, 1992,
previou previou designa recorde	ted) usly listed in the Nation usly determined eligible ated a National Historic ed by Historic America	by the National Register Landmark Buildings Survey # Engineering Record #	een	Nam	State Historic Preserv Other State agency Federal agency Local government University Other e of repository:	ation Office
Historic R	desources Survey N	lumber (if assigned):				
10. Geog	raphical Data					
	of Property 1	.67 source acreage.)				
UTM Ref	erences					
		n a continuation sheet.)				
1 18T	629473	4554564	3			
Zone	Easting	Northing	_ 3	Zone	Easting	Northing
2 Zone	Easting	Nouthing	_ 4	7	Pawin	V-di-
Zone	Lasting	Northing		Zone	Easting	Northing

Kellogg, Enos, House Name of Property			airfield, Connecticut ounty and State
Verbal Boundary Description (De		A	
The boundaries of the property are	shown on a City of Norwalk	x, CT parcel map attached as Figur	e 2.
Boundary Justification (Explain who The boundaries represent the total r		sociated with the Enos Kellogg Ho	ouse.
11. Form Prepared By			
name/title John Harrington			
organization		date August 1,	2011
street & number 210 Ponus Ave	nue Extension		-845-9181
city or town Norwalk		state CT	zip code 06850
e-mail Johnharrington1972	@gmail.com		
map.  Continuation Sheets	with the SHPO or FPO for		ources. Key all photographs to this
Photographs:			
Submit clear and descriptive photog Key all photographs to the sketch n	graphs. The size of each image.	age must be 1600x1200 pixels at 3	00 ppi (pixels per inch) or larger.
Name of Property:			
City or Vicinity:			
County:	State:		
Photographer:			
Date Photographed:			
Description of Photograph(s) and n	umber:		

(Expires 5/31/2012)

Kellogg, Enos, House	
Name of Property	

Fairfield, Connecticut
County and State

Property Owner:	
(Complete this item at the request of the SHPO or FPO.)	
name	
street & number	telephone
city or town	state zip code

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C.460 et seq.).

Estimated Burden Statement: Public reporting burden for this form is estimated to average 18 hours per response including time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Office of Planning and Performance Management. U.S. Dept. of t he Interior, 1849 C. Street, NW, Washington, DC.

Kellogg, Enos, House Name of Property



Figure 1. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Earliest know photo of the house. View south, no date, photographer unknown.

Kellogg, Enos, House Name of Property

Figure 2. Property map – 210 Ponus Avenue Extension, Norwalk, CT 06850




Figure 3. Floorplan






Photo 1. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View north, July 28, 2011, Tod Bryant



Photo 2. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View east showing original front door and hardware, July 29, 2011, Tod Bryant



Photo 3. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior, view west, showing original front door and hardware. July 29, 2011, Tod Bryant.



Photo 4. Enos Kellog House, Norwalk, Fiarfield County, Connecticut. First floor interior, view west, showing original front door hardware. July 29, 2011, Tod Bryant.



Photo 5. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Attic showing original siding used as sheathing. July 29, 2011, Tod Bryant



Photo 6. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Attic showing rafter framing detail and raising marks. July 29, 2011, Tod Bryant



Photo 7. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view northeast showing hall fireplace, framing and original interior door. July 29, 2011, Tod Bryant



Photo 8. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor North Rom, view southeast showing paneling, framing and fireplace. July 29, 2011, Tod Bryant



Photo 9. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor North Room, view northeast showing, framing detail. July 29, 2011, Tod Bryant



Photo 10. Enos Kellog House, Norwalk, Fairfield County, Connecticut, First floor North Room, view southeast showing paneling and framing detail. July 29, 2011, Tod Bryant



Photo 11. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view southwest showing fireplace and framing. July 29, 2011, Tod Bryant



Photo 12. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view southwest showing fireplace. July 29, 2011, Tod Bryant



Photo 13. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view northeast showing framing July 29, 2011, Tod Bryant



Photo 14. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view east showing stairs. July 29, 2011, Tod Bryant



Photo 15. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View north, showing horizontal paneling and stairs. July 29, 2011, Tod Bryant.



Photo 16. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Second floor, view south showing saltbox cieling slant. July 29, 2011, Tod Bryant



Photo 17. Enos Kellog House, Norwalk, Fiarfield County, Connecticut. Second floor South Chamber, view east, showing slanted paneling. July 29, 2011. Tod Bryant.



Photo 18. Enos Kellog House, Norwalk, Fiarfield County, Connecticut, Second floor North Chamber, view south, showing paneling, fireplace, door and flooring. July 29, 2011. Tod Bryant.



Photo 19. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Basement showing dust slits in floor joist. July 29, 2011, Tod Bryant



Photo 20. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Attic, view east showing raised plate framing detail. July 29, 2011, Tod Bryant

Kellogg, Enos, House Name of Property



Photo 21. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Front door latch. July 29, 2011, Tod Bryant



Photo 22. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View West, showing additions. July 28, 2011, Tod Bryant



Photo 23. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View east, showing additions. July 28, 2011, Tod Bryant



Photo 24. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View north showing Greek Revival side door and hardware, July 29, 2011, Tod Bryant

Kellogg, Enos, House Name of Property



Photo 25. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Barn, view east. July 29, 2011, Tod Bryant

## NR Nomination Photograph Log Page

Name of Property:

**Enos Kellog House** 

City or Vicinity:

Norwalk

County:

**Fairfield County** 

State:

CT

Name of Photographer:

Tod Bryant July, 2011

Date of Photographs: Location of Original Digital Files:

23 Morgan Avenue, Norwalk, CT 06851

Photo 1. View northeast showing facade and southeast elevation.

Photo 2. View southeast showing front door.

Photo 3. First floor interior, view west, showing framing and original front door with original hardware.

Photo 4. First floor interior, view west, showing original front door hardware.

Photo 5. Attic showing original siding used as sheathing,

Photo 6. Attic showing rafter framing detail and raising marks.

Photo 7. First floor interior, view northeast showing front hall fireplace, framing and original interior door.

Photo 8. First floor interior, north room, view southeast showing paneling, fireplace and framing.

Photo 9. First floor interior, north room, view northeast showing framing detail.

Photo 10. First floor interior, north room, view southeast showing paneling and framing detail.

Photo 11. First floor interior, view southwest showing fireplace and framing.

Photo 12. First floor interior, view southwest showing fireplace.

Photo 13. First floor interior, view northeast showing framing.

Photo 14. First floor interior, view south showing framing, paneling and stairs to second floor.

Photo 15. First floor interior, view west showing horizontal framing in stairway to second floor.

Photo 16. Second floor interior, view east, showing framing.

Photo 17. Second floor South Chamber, view east, showing slanted paneling.

Photo 18. Second floor North Chamber, view south, showing paneling, fireplace, door and flooring.

Photo 19. Basement showing dust slits in floor joist.

Photo 20. Attic, view east showing raised plate framing detail.

Photo 21. Front door latch.

Photo 22 View west showing northeast elevation and additions.

Photo 23. View east showing west elevation and additions.

Photo 24 View north showing Greek Revival side door and hardware.

Photo 25. Barn, view west showing west showing north elevation and facade.

# UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: NOMINAL	LION		
PROPERTY Kellogg, Enos, NAME:	House		
MULTIPLE NAME:			
STATE & COUNTY: CONNECTION	CUT, Fairfield		
DATE RECEIVED: 5/11, DATE OF 16TH DAY: 6/26, DATE OF WEEKLY LIST:		OF PENDING LIST: OF 45TH DAY:	6/11/12 6/27/12
REFERENCE NUMBER: 120003	56		
REASONS FOR REVIEW:			
APPEAL: N DATA PROBLEM: OTHER: N PDIL: REQUEST: N SAMPLE:	N LANDSCAPE: N PERIOD: N SLR DRAFT:	N PROGRAM UNAPPRO	EARS: NOVED: N
COMMENT WAIVER: N		A 25 12	
✓ACCEPTRETURN	REJECT	6-27-12DATE	
ABSTRACT/SUMMARY COMMENTS	:		
	Entered in The National Regis of Historic Places		
,			
RECOM./CRITERIA			
REVIEWER_	DISCIE	PLINE	
TELEPHONE	DATE_		
DOCUMENTATION see attache	d comments Y/1	N see attached SLR	Y/N
If a nomination is return	ed to the nom	inating authority,	the



Photo 1. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View north, July 28, 2011, Tod Bryant



Photo 2. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View east showing original front door and hardware, July 29, 2011, Tod Bryant



Photo 3. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior, view west, showing original front door and hardware. July 29, 2011, Tod Bryant.



Photo 4. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior, view west, showing original front door hardware. July 29, 2011, Tod Bryant.



Photo 5. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Attic showing original siding used as sheathing. July 29, 2011, Tod Bryant



Photo 6. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Attic showing rafter framing detail and raising marks. July 29, 2011, Tod Bryant



Photo 7. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view northeast showing hall fireplace, framing and original interior door. July 29, 2011, Tod Bryant



Photo 8. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor North Rom, view southeast showing paneling, framing and fireplace. July 29, 2011, Tod Bryant



Photo 9. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor North Room, view northeast showing, framing detail. July 29, 2011, Tod Bryant



Photo 10. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor North Room, view southeast showing paneling and framing detail. July 29, 2011, Tod Bryant



Photo 11. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view southwest showing fireplace and framing. July 29, 2011, Tod Bryant



Photo 12. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view southwest showing fireplace. July 29, 2011, Tod Bryant



Photo 13. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view northeast showing framing July 29, 2011, Tod Bryant



Photo 14. Enos Kellog House, Norwalk, Fairfield County, Connecticut. First floor interior view east showing stairs. July 29, 2011, Tod Bryant



Photo 15. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View north, showing horizontal paneling and stairs. July 29, 2011, Tod Bryant



Photo 16. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Second floor, view south showing saltbox cieling slant. July 29, 2011, Tod Bryant



Photo 17. Enos Kellog House, Norwalk, Fiarfield County, Connecticut. Second floor South Chamber, view east, showing slanted paneling. July 29, 2011, Tod Bryant.



Photo 18. Enos Kellog House, Norwalk, Fiarfield County, Connecticut. Second floor North Chamber, view south, showing paneling, fireplace, door and flooring. July 29, 2011, Tod Bryant.




Photo 19. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Basement showing dust slits in floor joist. July 29, 2011, Tod Bryant



Photo 20. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Attic, view east showing raised plate framing detail. July 29, 2011, Tod Bryant



Photo 21. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Front door latch. July 29, 2011, Tod Bryant



Photo 22. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View west, showing additions. July 28, 2011, Tod Bryant



Photo 23. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View east, showing additions. July 28, 2011, Tod Bryant



Photo 24. Enos Kellog House, Norwalk, Fairfield County, Connecticut. View north showing Greek Revival side door and hardware, July 29, 2011, Tod Bryant



Photo 25. Enos Kellog House, Norwalk, Fairfield County, Connecticut. Barn, view east. July 29, 2011, Tod Bryant



TO:	J. Paul Loether, Chief National Register of Historic Places
FROM:	Stacey Vairo, National Register Coordinator
SUBJECT:	National Register Nomination
The followin	g materials are submitted on this <u>9</u> day of <u>May</u>
2012, for no	mination of the Kellogg, Enos House, Norwalk, CT
Connecticut	
to the Nation	nal Register of Historic Places:
	Original National Register of Historic Places nomination form
	Multiple Property Nomination form
	Photographs
	Original USGS maps
	Sketch map(s)/figure(s)/exhibit(s)
	Pieces of correspondence
	Other CD of images
COMMENT	S:
	Please insure that this nomination is reviewed
	This property has been certified under 36 CFR 67
	The enclosed owner objections do do not constitute a majority of property owners.
	Other: