



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

1 of 11

Historic view, 1931, showing house  
newly-completed. South and east  
elevations. Note shutters.

Collection of Louise Clark Patterson.

Copy Negative: Kay Atwood  
102 So. Pioneer  
Ashland, OR 97520



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

2 of 11

South (front) elevation shutters were removed in intervening years; may be replaced.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

3 of 11

Close-up view of portico in the Greek  
Ionic order. Note shadow pilasters.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

4 of 11

West end elevation, showing stone  
chimney.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520





Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

5 of 11

North (rear) elevation.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

6 of 11

Detail of east end elevation.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

7 of 11

Typical interior trim in Colonial vein.  
Broken pediment with urn finial frames  
entrance to study as well as built-in  
bookshelf.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

8 of 11

View of side yard on west side of  
house, planted in lawn, oaks and  
evergreens.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520





Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

9 of 11

Detail of staircase in entry stairhall.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

10 of 11

Detail of livingroom fireplace.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520



Clark, Frank Chamberlain, House  
1917 East Main Street  
Medford, Jackson County, Oregon

11 of 11

Detail of French doors giving access  
from main hallway to diningroom with  
built-in sideboard in Arts and Crafts  
tradition.

Kay Atwood Photo, 1981  
102 So. Pioneer  
Ashland, OR 97520