

Photo No. 1
By: Ralph J. Christian, AASLH
Negative at: HSS, HCRS
Date: August 1978

View: From southwest, showing southwest end and southeast facade.



Photo No. 2

By: Ralph J. Christian, AASLH

Negative at: HSS, HCRS

Date: August 1978

View: From southeast, showing southeast facade and southwest end.



Photo No. 3
By: Ralph J. Christian, AASLH
Negative at: HSS, HCRS
Date: August 1978

View: From northwest, showing northwest facade and portion of northeast end.



Photo No. 4
By: Ralph J. Christian, AASLH
Negative at: HSS, HCRS
Date: August 1978

View: From southwest, showing southwest end and northwest facade.



Photo No. 5
By: Ralph J. Christian, AASLH
Negative at: HSS, HCRS
Date: August 1978

View: From northeast, showing northeast end.




Photo No. 6
By: Ralph J. Christian, AASLH
Negative at: HSS, HCRS
Date: August 1978

View: From southeast, showing "get-aways" on southeast facade.




Photo No. 7
By: Ralph J. Christian, AASLH
Negative at: HSS, HCRS
Date: August 1978

View: Interior, showing original crane and present electrical equipment.







