

DESCRIPTION: Exterior View, North Facade from NE

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 1 of 14



DESCRIPTION: Exterior View, East Facade from NE

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, DREGON 97209

Heritage Photo - 1995

Photo 2 of 14



DESCRIPTION: Exterior View, South Facade from S

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 3 of 14



DESCRIPTION: Exterior View, West Facade from SW

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 4 of 14



DESCRIPTION: Exterior Detail, North Facade Brickwork from N

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 5 of 14




DESCRIPTION: Exterior Detail, North Facade Doorway from N

HERITAGE INVESTMENT CORPORATION
123 N.W. SECOND AVENUE, SUITE 200
PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 6 of 14



DESCRIPTION: Exterior Detail, Main Entry (North Facade) from NW

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 7 of 14




DESCRIPTION: Interior View, Lobby

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 8 of 14



DESCRIPTION: Interior Detail, Lobby Light Fixture and Medallion

HERITAGE INVESTMENT CORPORATION
123 N.W. SECOND AVENUE, SUITE 200
PORTLAND, GREGON 97209

Heritage Photo - 1995

Photo 9 of 14



DESCRIPTION: Interior View, Upper Floor Lobby (typical)

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 10 of 14



DESCRIPTION: Interior View, Upper Floor Reception Room (typical)

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, GREGON 97209

Heritage Photo - 1995

Photo 11 of 14



DESCRIPTION: Interior View, Lodge Room

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, DREGON 97209

Heritage Photo - 1995

Photo 12 of 14



DESCRIPTION: Interior View, Lodge Room/Dining Room

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 13 of 14



DESCRIPTION: Interior Detail, Doorway (typical)

HERITAGE INVESTMENT CORPORATION 123 N.W. SECOND AVENUE, SUITE 200 PORTLAND, OREGON 97209

Heritage Photo - 1995

Photo 14 of 14