



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking West towards front
(East) facade



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking West towards front
(East) facade



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking West towards Main

Entrance and tower



Lang Anderson House

Maysville Ky 41056

Looking towards West facade

Jul 26/84



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking South towards
columns of front portico



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking Southwest toward
front portico (toward North
of tower)



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking North towards side
(South) facade



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking Southeast towards
side (North) facade



7/26/84

Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking South towards side
(North) facade and bracketed
eaves



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking East toward rear

(West facade) showing (a.)

1950 garage addition



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking West (from rear of
house) towards original ice
house.




Lang Anderson House

Maysville KY 41056

Looking towards East facade

collected



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher.)

Looking South (from house)

down entrance lane to estate



Point Au View Estate

Maysville, Ky.

Photo: 7/84 (Doug Loescher)

Looking North towards Ohio
River (View from house)

Note one of 8 original stone
markers