

SEP 12 1985 AUG 13 1985

City, Village or Town: <b>Village of Whitefish Bay</b>		County: <b>Milwaukee</b>	Surveyor: <b>Virginia A. Palmer</b>	Date: <b>May 27, 1985</b>	Street <b>E. Lexington Blvd.</b>  Number <b>1028</b>
Street Address: <b>1028 E. Lexington Blvd, originally noted as 224 Bellevue Blvd.</b>		USGS Quad and UTM Reference: <b>16/426930/4773600</b>		Acreage: <b>less than 1</b>	
Current Name & Use: <b>private residence</b>		Current Owner: <b>E. Campion Kersten</b>			
Film Roll No.	Affix Contact Prints		Current Owner's Address: <b>1028 E. Lexington Blvd.</b>		
Negative No.					
Facade Orient.			Legal Description: <b>E 1/2 of Lot 6 and all of Lot 3, Block 7, Stone &amp; Thomas' Idlewild Subdivision # 2, N.E. 1/4 S 33, T 8 N, R 22 E, Village of Whitefish Bay.</b>		

Original Name & Use: <b>Halbert D. Jenkins home</b>	Source <b>A</b>	Previous Owners	Dates	Uses	Source	Town <b>8 N</b>  Range <b>22 E</b>
Dates of Construction/Alteration <b>1924</b>	Source <b>A</b>					
Architect and/or Builder: <b>Arnold F. Meyer &amp; Company, Inc.</b>	Source <b>A</b>					

<b>3</b> Architectural Significance <input type="radio"/> Represents work of a master <input type="radio"/> Possesses high artistic values <input checked="" type="radio"/> Represents a type, period, or method of construction <input type="radio"/> Engineering <input type="radio"/> None	<b>4</b> Historical Significance <input type="radio"/> Assoc. with lives of significant persons <input type="radio"/> Assoc. with significant historical events <input type="radio"/> Assoc. with development of a locality <input type="radio"/> Other: _____ <input checked="" type="radio"/> None      Period of significance: _____	Section <b>33</b>  Map Name <b>Milwaukee Quadrangle</b>
Architectural Description and Significance: <b>This two story Flagg System house is U shaped and has limestone exterior walls. The house faces south and window and door openings are regular. There are two shed gables and two chimneys. The original garage is attached but a family room has been added to the second story of it. The marble mantle has been added to the living room fireplace. There is a beam and girder ceiling in living room and dining room. Casement windows open inward. There is a partial basement and laundry room on the first floor. The bathroom floor is one step above the level of the hallway.</b> Interior visited? <input checked="" type="radio"/> Yes <input type="radio"/> No      (Over)		

<b>5</b> Sources of Information (Reference to Above) <b>A</b> Building Inspectors office, Village of Whitefish Bay <b>B</b> <b>C</b> <b>D</b> <b>E</b> <b>F</b>	<b>6</b> Representation in Previous Surveys <input type="radio"/> HABS <input type="radio"/> LDMK <input checked="" type="radio"/> WIHP <input type="radio"/> NRHP <input type="radio"/> other: _____ <b>7</b> Condition <input checked="" type="radio"/> excellent <input type="radio"/> good <input type="radio"/> fair <input type="radio"/> poor <input type="radio"/> ruins <b>8</b> District: _____ <input type="radio"/> pivotal <input type="radio"/> contributing <input type="radio"/> non-contributing <b>9</b> Opinion of National Register Eligibility date: _____ initials: _____ <input type="radio"/> eligible <input type="radio"/> not eligible <input type="radio"/> unknown <input type="radio"/> national <input type="radio"/> state <input type="radio"/> local	Map Code <b>7.5 minute</b>
---	--	-------------------------------

There is an attic with access through a pull-down stairway.

This house is architecturally significant because it is one of a group of stone masonry houses built by Arnold F. Meyer & Company, Inc. according to the construction methods of Ernest Flagg.

