

Form No. 10-301a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC Hollenburg Pony Express Station

AND/OR COMMON

Hollenburg Pony Express Station

2 LOCATION

CITY, TOWN Hanover X VICINITY OF

COUNTY Washington STATE Kansas

PHOTO NO

3 PHOTO REFERENCE

PHOTO CREDIT

Stephen Lissandrello

DATE OF PHOTO

May, 1975

NEGATIVE FILED AT Historic Sites Survey, National Park Service, 1100 L. Street, NW Washington, D.C. 20240

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

Facing north to front entrance, Hollenburg Pony Express Station

(driveway in foreground).

INT: 2983-75



Form No. 10-301a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Hollenburg Pony Express Station

AND/OR COMMON

Hollenburg Pony Express Station

2 LOCATION

CITY, TOWN Hanover X VICINITY OF

COUNTY Washington STATE Kansas

3 PHOTO REFERENCE

PHOTO CREDIT Stephen Lissandrello

DATE OF PHOTO May, 1975

NEGATIVE FILED AT Historic Sites Surveu, National Park Service, 1100 L. Street, NW. Washington, D.C. 20240

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET
Facing east to rear of Pony Express Station.

PHOTO NO

Cottonwood Station (Hollenberg Ranch Pony Express Station), Hanover, Kansas, Landmark Inspection, June 21, 1977

W exposure - Note variety of siding - cedar (?) lower, redwood - middle, original walnut - upper. Note deterioration of original siding as well as a sagging roof. This wall was apparently damaged in a hail storm a few years ago





E exposure - detail of siding, window and door condition