

HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

North end, view southeast



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

South end of east building, view north



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Main entrance, east elevation, east building, view northwest



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford


Typical windows, west side of east building, view east



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Dyehouse and west building, view north

5



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Boiler house, view northwest



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Ruins of oil/coal storage building, view north



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Office building, view south



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Waste house, view northwest




HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Typical interior; north half of
east building, 1st floor,
view north # 10



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Interior, under monitor roof
(north half of east building),
view east # 1



HRC Photo, 7/86
Negative filed with Conn.
Hist. Comm., Hartford

Interior, dyehouse, showing vat foundation and concrete construction, view north

# 12