

Map # 14

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. L-W-SW-410

1. Historic Name(s)  Parkland Evangelical Church  
 Original Owner Parkland Evangelical Church

2. Present Name Greater Good Hope Baptist Church

3. Owner's Name Greater Good Hope Baptist Church

4. Owner's Address 1102 South 26th Street 40210

5. Location  1102 South 26th Street

6. Open to Public  Yes  No

7. Visible from road  Yes  No

8. Ownership  Private  Local  State  Federal

9. Local Contact/Organization Landmarks Commission

22. ADD/County JF 056

23. Zoning Classification Magisterial District

24. U.S.G. S. Quadrant (15'/75') Louisville West 079

25. UTM Reference 16 605340 4232960  
 Zone Easting Northing

26. Prehistoric Site Object  
 Historic Site Structure  
 Building

27. District Yes  No   
 Name:

10. Site Plan with North Arrow  
 Block 466 Lot 72  
 less than 1 acre. Structure occupies majority of site.

Grand 1951 72 26th St

11. Architect

12. Builder

13. Date 1915 6

14. Style A. Stick 15 B.

15. Original Use religious 8

16. Present Use religious

17. Condition excellent 1

28. Significance Evaluation meets NR criteria d

29. Status National Landmark  National Register  Landmark Certificate  Kentucky Survey  Local Landmark  HABS/HAER

30. Theme Primary architecture 3 Secondary Other

31. Endangered Yes No

18. Description  
 The Parkland Evangelical Church is a small calpboard structure which retains most of its original exterior features. The structure is L-shaped. The facade consists of a gable wing which has a small tower. A gable entry section projects with a double door (altered) set in a lancet wood surround. Lancet stained-glass windows with wood surrounds flank the entry (over)

No. Stories one 1

Single Pile NA Double Pile

Floor Plan

Structural Fabric e frame d

Decorative Fabric A. glass p B. sawn weatherboard j

Roof Form gable end



19. History  
 This structure was built in 1915 for the Parkland Evangelical Congregation.

33. Tape No. Negative No.  
 34. Prepared by: Marty Hedgepeth Director of Research

20. Significance  
 This church is one of a very few frame churches in the city which has not been clad in aluminum siding or

35. Organization Landmarks Com.  
 36. Date March 23, 1981

21. Source of Information  
 Caron Directory of the City of Louisville.

37. Revision Dates 38. Staff Review

18. section. Both gable roofs have deep overhanging eaves with wood braces. To the right of the wing is a wing which is set back. This contains a lancet stained glass window and another entry with a wood surround. The north facade of this wing contains a large lancet window and entry. The structure still retains a seamed metal roof. The detailing of the building is simple yet charming.
  
20. destroyed to make way for a larger church building. The church is an excellent example of a Shingle style treatment with Gothic Revival motifs.