

Huntington, Indiana George Bachnivsky 1982 Camera facing northwest, before aluminum siding was removed

Moore/Corlew Building


Photo #1 of 5

#1 ARIAL VIEW OF MOORE BUILDING BEFORE ALUMINUM SKIN WAS REMOVED





Moore/Corlew Building
Huntington, Indiana
George Bachnivsky 1982
After siding removel, camera facing
northwest
Photo #2 of 5







Moore/Corlew Building Huntington, Indiana George Bachnivsky 1982 After siding removal, camera facing northwest Photo #3 of 5



Moore/Corlew Building Huntington, Indiana George Bachnivsky 1982 East elevation of Moore Building. camera facing west Photo #4 of 5



Moore/Corlew Building
Huntington, Indiana
G. Bachnivsky 1983
Interior view, camera facing southeast
Photo #5 of 5

Moore Building Interior.

Beam at right will be covered with tin material existing at left. Note the masonry at the right hand corner. These bricks were taken from a building that had been torn down. The bricks were made in 1859 or 1860, the building stood 200 feet to the west of the Moore Building.