Property Name Hiwasse Bank Building Property Owner Douglas Banks Location Main Street of Hiwasse, Hww 279 Address Hiwasse, AR 72739 Construction Date c, 1890 Survey No. 0694 DESCRIPTION The Hiwasse Bank Building is a modest one-story brick commercial building with an all-glass front divided into three parts by cast iron stanchions. Two of the bays are display windows with wood trim, the third being the entrance door surrounded by sidelights and a transom. The all-brick facade over the windows is dominated by a long horizontal brick panel, defined on four sides by a corbelled brick frame. The exterior of the building is otherwise without ornament. The interior is undivided except for a small brick partitioned room at the northwest rear corner, which was probably the bank's security room. The ceiling still bears its original ornamental pressed metal panels. Exterior walls are covered with deteriorating original plaster. The wood floor seems sound. STATEMENT OF SIGNIFICANCE The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. Acreage less than 1 acre Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed			
Construction Date c. 1890 Survey No. 0694 DESCRIPTION The Hiwasse Bank Building is a modest one-story brick commercial building with an all-glass front divided into three parts by cast iron stanchions. Two of the bays are display windows with wood trim, the third being the entrance door surrounded by along horizontal brick panel, defined on four sides by a corbelled brick frame. The exterior of the building is otherwise without ornament. The interior is undivided except for a small brick partitioned room at the northwest rear corner, which was probably the bank's security room. The ceiling still bears its original ornamental pressed metal panels. Exterior walls are covered with deteriorating original plaster. The wood floor seems sound. STATEMENT OF SIGNIFICANCE The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. Acreage less than 1 acre Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed		Property	Owner Douglas Banks
The Hiwasse Bank Building is a modest one-story brick commercial building with an all-glass front divided into three parts by cast iron stanchions. Two of the bays are display windows with wood trim, the third being the entrance door surrounded by sidelights and a transom. The all-brick facade over the windows is dominated by a long horizontal brick panel, defined on four sides by a corbelled brick frame. The exterior of the building is otherwise without ornament. The interior is undivided except for a small brick partitioned room at the northwest rear corner, which was probably the bank's security room. The ceiling still bears its original ornamental pressed metal panels. Exterior walls are covered with deteriorating original plaster. The wood floor seems sound. STATEMENT OF SIGNIFICANCE Criterion: C Area of significance: Architecture The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. Acreage less than 1 acre Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed	Location Main Street of Hiwasse, Hwy 279	Address	Hiwasse, AR 72739
The Hiwasse Bank Building is a modest one-story brick commercial building with an all-glass front divided into three parts by cast iron stanchions. Two of the bays are display windows with wood trim, the third being the entrance door surrounded by sidelights and a transom. The all-brick facade over the windows is dominated by a long horizontal brick panel, defined on four sides by a corbelled brick frame. The exterior of the building is otherwise without ornament. The interior is undivided except for a small brick partitioned room at the northwest rear corner, which was probably the bank's security room. The ceiling still bears its original ornamental pressed metal panels. Exterior walls are covered with deteriorating original plaster. The wood floor seems sound. STATEMENT OF SIGNIFICANCE The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. Acreage less than 1 acre Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed	Construction Date c. 1890 Survey No. 0694		
The Hiwasse Bank Building is a modest one-story brick commercial building with an all-glass front divided into three parts by cast iron stanchions. Two of the bays are display windows with wood trim, the third being the entrance door surrounded by sidelights and a transom. The all-brick facade over the windows is dominated by a long horizontal brick panel, defined on four sides by a corbelled brick frame. The exterior of the building is otherwise without ornament. The interior is undivided except for a small brick partitioned room at the northwest rear corner, which was probably the bank's security room. The ceiling still bears its original ornamental pressed metal panels. Exterior walls are covered with deteriorating original plaster. The wood floor seems sound. STATEMENT OF SIGNIFICANCE The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. Acreage less than 1 acre Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed			
all-glass front divided into three parts by cast iron stanchions. Two of the bays are display windows with wood trim, the third being the entrance door surrounded by sidelights and a transom. The all-brick facade over the windows is dominated by a long horizontal brick panel, defined on four sides by a corbelled brick frame. The exterior of the building is otherwise without ornament. The interior is undivided except for a small brick partitioned room at the northwest rear corner, which was probably the bank's security room. The ceiling still bears its original ornamental pressed metal panels. Exterior walls are covered with deteriorating original plaster. The wood floor seems sound. STATEMENT OF SIGNIFICANCE The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. Acreage less than 1 acre	DESCRIPTI	ON	
all-glass front divided into three parts by cast iron stanchions. Two of the bays are display windows with wood trim, the third being the entrance door surrounded by sidelights and a transom. The all-brick facade over the windows is dominated by a long horizontal brick panel, defined on four sides by a corbelled brick frame. The exterior of the building is otherwise without ornament. The interior is undivided except for a small brick partitioned room at the northwest rear corner, which was probably the bank's security room. The ceiling still bears its original ornamental pressed metal panels. Exterior walls are covered with deteriorating original plaster. The wood floor seems sound. STATEMENT OF SIGNIFICANCE The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. Acreage less than 1 acre			
The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. **Acreage less than 1 acre** Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed.	all-glass front divided into three parts by a are display windows with wood trim, the third by sidelights and a transom. The all-brick is by a long horizontal brick panel, defined on frame. The exterior of the building is other is undivided except for a small brick partitioning or which was probably the bank's security original ornamental pressed metal panels.	cast iron stand being the extended facade over the four sides be the four sides be the four at the foom. The exterior walls	enchions. Two of the bays entrance door surrounded the windows is dominated by a corbelled brick to ornament. The interior the northwest rear a ceiling still bears its are covered with
The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. **Acreage less than 1 acre** Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed.			
The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. **Acreage less than 1 acre** Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed.			
The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. **Acreage less than 1 acre** Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed.			
The Hiwasse Bank Building, built c. 1890, is a surviving significant reflection of the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. **Acreage less than 1 acre** Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed.	STATEMENT OF SIG	NIFICANCE	
the scale, material, and simplicity of small-town commercial architecture of the period. Standing beside it is a similar brick commercial front, built perhaps a generation later and less well preserved. The two buildings also share a concrete platform which raises their entrances above the level of the street. The Bank Building's appealing modularity remains unchanged except for the scars of neglect. A sheet metal canopy, probably as crude and unsophisticated as the one still attached to the neighboring building, has been removed. The building, although it once housed the Bank of Hiwasse and subsequently many other commercial enterprises, is now unoccupied and deteriorating. **Acreage less than 1 acre** Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed	Criterion: C	Area of	significance: Architecture
Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed	the scale, material, and simplicity of small- period. Standing beside it is a similar brid generation later and less well preserved. The platform which raises their entrances above Building's appealing modularity remains unchat A sheet metal canopy, probably as crude and attached to the neighboring building, has been once housed the Bank of Hiwasse and subsequent	-town commercial he two buildi the level of anged except unsophisticaten removed.	rial architecture of the front, built perhaps a lags also share a concrete the street. The Bank for the scars of neglect. The building, although it
Verbal Boundary Description From the intersection of State Highways 79 & 279, proceed			
	Acreage less than 1 acre		
	Verbal Boundary Description From the interse	ction of Stat	ce Highways 79 & 279, proceed
	Quadrangle Name Hiwasse, ArkMo.		
UTM Reference: Zone 15 Easting 380440 Northing 4032410			

MRA	No.	51	

INDIVIDUAL DATA SHEET

Property Name <u>Hiwasse Bank Building</u>	Property Owner
Location	Address
Construction Date Survey No 0694	
DESCRIPT	ION
VERBAL BOUNDARY DESCRIPTION CONT.	
south on Highway 279 100 feet to the northeas of beginning. Proceed west 135 feet, then proceed north 100 feet to the	oceed south 100 feet, then proceed east
STATEMENT OF SI	GNIFICANCE
Criterion:	Area of significance:
Acreage	-
Verbal Boundary Description	
Quadrangle Name_	Quadrangle Scale
UTM Reference: Zone Eas	tingNorthing

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only

eceived 12/14

date entered

Continuation sheet

Item number

Page

Multiple Resource Area Thematic Group

	e Benton County, ARKAN	NOAD		
Nom	ination/Type of Review			Date/Signature
1.	HaglerCole Cabin	Batared in dia Vational Register	Keeper	Allows Byen 1/28/
			Attest	- 1
2.	HenryThompson House	Reternd in the Retained Register	Keeper	Stelous Byen 1/28
			Attest	•
3.	Hiwassee Bank Building	Petsonel Register	Keeper	Allows Byen 1/28
			Attest	-
4.	House at 305 E. Ashley	National Register	*Reeper	Allow Byen 1/2
		2-2-647	Attest	
5.	Illinois River Bridge	Patered in the National Register	frKeeper	DelousByen 1/2.
			Attest	
6.	Jackson House	National Register	Keeper	Helous Byen 1/28
			Attest	
7.	James House	Entered in the National Register	Keeper	Selous Byen 1/2.
			Attest	
8.	Jones House	National Register	Keeper	Selous Byer 1/28,
		national megister	Attest	
9.	Kefauver House	Between in the	Keeper	Selonoffigur 1/28
		National Register	Attest	
0.	Kindley House	Mathemat for the	Keeper	Selver Gyens 1/28

WASO Form - 177 ("R" June 1984)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE



NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Benton County ARKANSAS resubmission	ilding (Benton Cou	nty MRA)	Batacad in t	Working No	1-28-88
appeal Substantive Review:	□ sample □	□ request	appeal	☐ NR decision	
Reviewer's comments:	sample		appear		
				Recom./Criteria Reviewer Discipline Date see continuation s	
Nomination returned for:	technical correct		w		
1. Name				noisent sui pas nois	chusth valibriuod Jadne V
2. Location					
3. Classification					
Category	Ownership Public Acquisition		Status Accessible	Present Use	
4. Owner of Property			te state is:	li niki liv yhaqosa sinti ra a	otts: Pingle be suleve ad T
5. Location of Legal Desc	cription		lipod	01832	socurer
6. Representation in Exis	ting Surveys			e snorengia replitti ng	sonneari shateH ette
Has this property been de	termined eligible?	□ yes □	no		
7. Description					
Condition excellent good fair	deteriorated ruins unexposed	Check o	Itered	Check one original site moved	late
Describe the present and	original (if known) phys	ical appearance			
summary paragraph completeness clarity alterations/integrity dates boundary selection	Phono:				

8. Signif	icance		
Period	Areas of Significance—Check and justify below		
Specific	dates Builder/Architect at of Significance (in one paragraph)		
Staterner	it of Significance (in one paragraph)		
sumr	nary paragraph		
	pleteness		
☐ clarit			
	cable criteria		
	ication of areas checked		
	ng significance to the resource		
cont	onship of integrity to significance		
	ication of exception		
othe			
	- Recom/Cuteria		
9. Majo	r Bibliographical References		
10. Geo	graphical Data		
Acreage	of nominated property		no cred becautes neirammel/
	gle name	worled been spailt at the Petivip regret	
	ferences		
Vorbalt	oundary description and justification		Waste J
V CI Dai L	ouridary description and justinoution		
			Salesi Feet 2 S
11. For	m Prepared By	euter8 greene	Ceregory
	te Historic Preservation Officer Certification		
The eva	uated significance of this property within the state	is:	
	nationalstatelocal		
State Hi	storic Preservation Officer signature		
title	date		
13. Oth			
□ Мар	and source		
-	s tographs		
Othe			
Questio	ns concerning this nomination may be directed to _	imagen) physical aspearage	Describe the proximt and corquisi (d
Signed_		Date Phon	ne:
WILLIETT		PULL FIRST	



Hiwasse Bank Building - 0694
Benton County MRA
Photographed by Benton County Survey Staff-1983
Negatives on file at AHPP

Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000022