






ADENA Fig 1  
Chillicothe, Ohio  
North (entrance) Front  
Photo by David R. Barker, April 2001



ADENA Fig 2  
Chillicothe, Ohio  
East Elevation  
Photo by David R. Barker, April 2001



ADENA Fig 4  
Chillicothe, Ohio  
South (garden) Front  
Photo by David R. Barker, April 2001



ADENA

Fig 5


Chillicothe, Ohio

West Elevation

Photo by David R. Barker, April 2001







ADENA

Chillicothe, Ohio

Entrance Hall (center north room, first floor)

Photo by David R. Barker, April 2001



ADENA

Chillicothe, Ohio

Parlor (southeast room, first floor)

Photo by David R. Barker, April 2001






ADENA  
Chillicothe, Ohio  
Smokehouse  
Photo by David R. Barker, April 2001



ADENA  
Chillicothe, Ohio  
Washhouse  
Photo by David R. Barker, April 2001



ADENA

Chillicothe, Ohio

General view of grounds, from north lawn, looking east

Photo by David R. Barker, April 2001



ADENA  
Chillicothe, Ohio  
Flower Garden  
Photo by David R. Barker, April 2001















ADENA  
Chillicothe, Ohio  
Springhouse  
Photo by David R. Barker, April 2001



ADENA  
Chillicothe, Ohio  
Barn

Photo by David R. Barker, April 2001



ADENA  
Chillicothe, Ohio  
Tenant House  
Photo by David R. Barker, April 2001