


- A. 1904 Stone Schoolhouse
- B. Hominy, Osage County, Oklahoma
- C. Arthur Shoemaker
- D. 9/8/87
- E. Hominy Heritage Assn. files
- F. Oblique view showing front and side.
 Camera pointed southwest.
 G. Photo #1



A. 1901 Stone Schoolnouse B. Hominy, Osage County, Oklahoma C. Arthur Shoemaker D. 9/8/87 E. Hominy Heritage Assn. files F. Side view. Camera pointed west G. Photo #2



- A. 1904 Stone Schoolhouse B. Hominy, Osage County, Oklahoma C. Arthur Shoemaker D. 9/8/87 E. Hominy Heritage Assn. files
- F. Front Entrance. Camera pointed south.
- G. Photo #3



A. 1904 Stone Schoolhouse

- B. Hominy, Osage County, Oklahoma
- C. Arthur Shoemaker
- D. 9/8/87
- E. Hominy Heritage Assn. files
- F. Restored (1980) bell tower with original
- bell. Camera pointed south. G. Photo #4



A. 1904 Stone Schoolhouse

- B. Hominy, Osage County, Oklahoma
- C. Arthur Shoemaker
- D. 9/8/87
- E. Hominy Heritage Assn. files
- F. Ornamental trim on top of building.
 Restored 1980. Camera pointed southwest.
 G. Photo #5



A. 1904 Stone Schoolhouse B. Hominy, Osage County, Oklahoma C. Shirley Pettengill D. 8/15/87 E. Hominy Heritage Assn. files F. Side view. Camera pointed east. G. Phota #6



- A. 1904 Stone Schoolhouse
- B. Hominy, Osage County, Oklahoma
- C. Unknown photographer
- D. 1904
- E. Hominy Heritage Assn. Files
- F. Earliest known photo of 1904 building. Camera pointed southeast.
- G. Photo #7



A. 1904 Stone Schoolhouse

- B. Hominy, Okage County, Oklahoma
- C. Sutton
- D. 1907
- E. Hominy Heritage Assn. files
 F. Shows construction of Horace Mann School (now demolished). Camera aimed southwest.
- G. Photo #8



A. 1904 Stone Schoolhouse B. Hominy, Osage County, Oklahoma C. Shirley Pettengill D. 8/15/87 E. Hominy Heritage Assn. files F. Interior shot showing portion of original ceiling during remodeling. G. Photo #9



A. 1904 Stone Schoolhouse B. Hominy, Osage County, Oklahoma C. Shirley Pettengill D. 8/15/87 E. Hominy Heritage Assn. files F. Interior shot showing a portion of original plaster "blackboard" during remodeling. G. Photo #10



- A. 1904 Stone Schoolhouse
- B. Hominy, Osage County, Eklahoma
- C. Unknown
- D. 1906
- E. Hominy Heritage Assn. files F. Front entrance showing original "fan-shaped" glass panel over door. Original was replaced by a wooden panel, but has now been restored to glass. G. Photo #11



- A. 1904 Stone Schoolhouse
- B. Hominy, Osage County, Oklahoma
- C. Unknown
- D. 1906
- E. Hominy Hebitage Assn. files
- F. Closer view of frontentrance showing original
 - "fan shaped" glass panel over door. See photo #11. G. Photo #12