



H. H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Dec. 15, 1991

S.H. P.O. neg.

East (front) facade, camera facing West

1 of 12



H. H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Dec. 15, 1991

S. H. P. O. neg.

South facade, camera facing NE

2 of 12





H. H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Dec. 15, 1991

S.H. P.O. neg.

North facade, camera facing SW

3 of 12



H. H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Dec. 15, 1991

S. H. P. O. neg.

Greenhouse attached to storage building

Camera facing NW

4 of 12





H. H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Dec. 15, 1991

S. H. P. O. neg.

West (rear) facade, camera facing E

5 of 12



H. H. Champlin House

Enid, Oklahoma


Dianna Everett, photo.

Dec. 15, 1991

S.H.P.O. neg.

Main (East) entrance, camera facing W

6 of 12





H. H. Champlin House

Enid, Oklahoma

Dianina Everett, photo.

Dec. 15, 1991

S. H. P. O. neg.

Southwest tower, camera facing N

Leaded windows

7 of 12



A. H. Champlin House

Enid, Oklahoma


Dianna Everett, photo.

Dec. 15, 1991

S. H. P. O. neg.

Detached carport (left), attached 3-car garage (right),  
camera facing NE

8 of 12



H. H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Jan. 10, 1992

S. H. P. o. neg.

Leaded windows, Sun room, camera facing S

9 of 12





H. H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Jan. 10, 1992

S. H. P. O. neg.

Main Hall, carved staircase and soffit beams

Camera facing SW

10 of 12



H. H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Jan. 10, 1992

S. H. P. O. neg.

Library, camera facing NW

11 of 12





H.H. Champlin House

Enid, Oklahoma

Dianna Everett, photo.

Jan. 10, 1992

S.H.P.O. neg.

Kitchen, camera facing SW

12 of 12