#### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

### NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS USE	all v		21 E 1800	
ron ara oat				
DECEMEN				
RECEIVED AL	IG 2 T 191			
100000				
DATE ENTERED	3	HIM:	C IOOA	30

Russian Orthodox Church Buildings and Sites in Alaska

**CONTINUATION SHEET** 

ITEM NUMBER

7 PAGE 14 of 53

The main front entranceway vestibule combines an ornamented canopy with an overhead bell tower. The cross motif, noted above over the window sashes, is repeated over each opening in the front entryway, but here the design similarity ceases, and the design of the front entryway is from some source other than that which inspired the details of the main building. A virtually identical arched entranceway is to be seen in a contemporary addition to Sandringham Castle, a country home of the British Royal Family in East Anglia, England. The entryway to this church is open at ground level through three arch-surmounted doorways, on its north, west, and south facades, with the east face being congruent to the church west wall. The upper level, or bell tower, of the entryway or vestibule, echos these three outer openings with smaller versions of the same arch-forms. The whole is surmounted by a low-angle gable roof, which is abrasive to the design element of the main building roof angle, and is surmounted by a cross added at a later date. This later dated cross is identified by the small ball at its base. This reflects the widespread use of three-dimensional curvelinear forms as a basis for the elevated crosses, in the tradition of those churches built and ornamented in the eclectic Byzantine-Russian-Alaskan-R.O. tradition. (Ibid.).


The interior of the church is as finished as the exterior, wainscoted throughout, even into the overhead octagonal dome and the cupola into which it telescopes. Unique among such small R. O. Churches is the choir loft, at the west end of the church, above the inner entrance door. This is built above an entrance vestibule that is 10'1" and extends completely across the width of the building. The stairway to the choir loft runs up the south side of the vestibule. The choir loft is distinguished by an arched convex-shaped gallery railing of graceful design. (Ibid.)

QUAD: Cordova

- 1. St. Michael the Archangel Church (AHRS SITE NO. COR-021)
- 2. LOCATION
  - a. NA
  - b. Cordova
  - c. NA
  - d. Alaska
  - e. 02
  - f. Cordova-McCarthy
  - g. 080

#### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



Russian Orthodox Church Buildings and Sites in Alaska

**CONTINUATION SHEET** 

ITEM NUMBER

7

PAGE 15 of 53

3. AHRS DATE: May 18, 1973

4. CONDITION: Good

UNALTERED

6. ORIGINAL SITE

The present building was built in 1925. As the building approached its fiftieth anniversary, early in this decade, the entire interior was reconstructed inside the 1925 shell, providing insulation and strength against the high winds and inclement weather common to this area. This church building exemplifies a virtually unadorned exterior, due to constant wind damage. Consequently, virtually all ornamentation is reserved for interior decoration. The exterior is rectangular shape with a medium gable roof, and a modest entry vestibule echoing the main roof line angle. Each of the longitudinal (north and south) walls is fenestrated by three double hung 12-pane window sashes. Two additional windows in the east (altar) wall have been boarded up. (Kreta, Notes; Wallace, 1974, 111, Plate 143; Kreta/Merculief, Photos).

The only overt adornment to the outside is a modest squared cupola surmounted by a pyramidal roof. From the peak of the pyramidal roof rises the high cross of the church. A second cross rises a foot above the peak of the west (entranceway) gable, and a third cross adorns the space above the front (west) exterior entranceway door.  $(\underline{\text{Ibid}}.)$ 

The present interior, inside the shell of the 1925 church, measures 44' in length and 23' in width. The exterior austerity is modest, due to necessity. The lack of onion or bulb-shaped apertenances indicates that the tradition is that of the Belkofski R. O. Church, rather than the Byzantine tradition of exterior ornamentation and symbolism. The interior of this church, however, is in keeping with the tradition of the R. O. Church in Alaska, which is taken up below, in Item #8.

QUAD: Iliamna

1. St. Nicholas Chapel (AHRS SITE NO. ILI-042)

FHR-8-300A (11/78)

UNITED STATES DEPARTMENT OF THE INTERIOR HERITAGE CONSERVATION AND RECREATION SERVICE

### NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR HCRS USE ONLY
RECEIVED MAR 1 9 1980
DATE ENTERED. UN 6

**CONTINUATION SHEET** 

ITEM NUMBER

PAGE

1 of 6

OUAD: AFOGNAK (A-3)

Nativity of Holy Theotokos Church, Afognak (AHRS SITE NO. AFG-080)

VERBAL BOUNDARY DESCRIPTION: Building is sited on U.S. survey map sheet 454a-d, enclosed. Sited on point of land jutting southeastward beyond general waterfront line on U.S. Department of the Interior, Bureau of Land Management, Photographic Atlas of Alaskan Communities (Anchorage, Alaska State Office, Bureau of Land Management, U.S. Department of the Interior, n.d.), "Afognak 1962".

QUAD: BETHEL (C-8)

St. Jacob's Church, Napaskiak, Alaska (AHRS SITE NO. BTH-009)

VERBAL BOUNDARY DESCRIPTION: Building is the largest man-built structure in the community, occupies the southernmost building site in the community, which is the entire south boundary of the graveyard, as sited on <a href="Photographic Atlas">Photographic Atlas</a>, "Napaskiak (sic) 1962". Sited also on "City of Napaskiak and Oscarville, Alaska," aerial photo map (Douglas, Alaska, State of Alaska, Department of Highways, 1972, 1973).

OUAD: COLD BAY

Holy Resurrection Church, Belkofski (AHRS SITE NO. XCB-020)

VERBAL BOUNDARY DESCRIPTION: Building is sited on U.S. Survey map sheet 758, enclosed.

QUAD: CORDOVA (C-5)

St. Michael the Archangel Church, Cordova (AHRS SITE NO. COR-021)

VERBAL BOUNDARY DESCRIPTION: Building is the first structure on the east side of an untitled north-south road running south from Chase Avenue, parallel to and 200 feet west of LeFever Street, as sited on U.S. Survey map sheet 656, enclosed. Also sited on BLM Photographic Atlas, "Cordova, 1963" and, on State of Alaska, "City of Cordova, Alaska," aerial photo map, (1972).

Form No. 10-300a (Hev. 10-74)

### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

ı	COD	LINA	100	ONLY
ł	[ ~ 1 ] <del>[</del> ~	N M	150	THE P
ı			~~.	~

RECEIVED

AUG 2 1 1979


# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

DATE ENTERED

<del>JUN 6 igan</del>

Orthodox Russian Church Buildings and Sites in Alaska

CONTINUATION SHEET . ITEM	NUMBER 10 PAGE 2 of 15
QUADRANGLE NAME: Cold Bay	
LOCATION: Belkofski	
NAME OF PROPERTY AND AHRS NUMBER:	Holy Resurrection Church (AHRS SITE NO.
QUADRANGLE SCALE: 1: 250, 000	
UTM REFERENCE:	
ZONE: <u>0 3</u> EASTING: <u>6 9 0 2 4 9</u>	
NORTHING: 6 1 0 8 1 8 7	
QUADRANGLE NAME: Cordova (C-5)  LOCATION: Cordova	
	St. Michael the Archangel Church (AHRS
QUADRANGLE SCALE: 1: 63, 360  UTM REFERENCE:	
ZONE: <u>0 6</u> EASTING: <u>5 6 9 2 4 8</u> NORTHING: 6 7 1 2 2 9 0	



Cordova C-5

Odiak (Cordova)

#31

