

HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Fixed span, east portal view SW



HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Fixed span, upper portal joint, view SE




HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Fixed span, mid-web
diagonal, with welded repair
view E # :




HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Fixed span, floor system view W




HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Side view of both spans view SE



HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Swing span, floor system view NE



HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Side view of swing span view NE




HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Swing pier, rollers and pivot bracing, view NE



HRC Photo, 4/86
Negative filed with Conn.
Hist. Comm., Hartford

Swing span, portal of east truss and central upper eyebars, view SE



HRC Photo, 4/86 Negative filed with Conn. Hist. Comm., Hartford

Swing span, west portal view E