

M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Facade, view northeast



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

East elevation, view southwest



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Detail of bay window, facade, view north 3



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Close-up of entry, view



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Detail, interior of entry portico, looking upward to soffit, view east 5



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Interior, lobby, view west



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Interior, east office off
 lobby, mantel, view
 northeast



view east

M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Hist. Comm., Hartford
Interior, east stairway,



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Hist. Comm., Hartford
Interior, west stairway,
view north



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Vaulted ceiling of ballroom, now hidden from view, view north 10



M. Roth Photo, 10/82 Negative filed with Conn. Hist. Comm., Hartford

Typical interior office, original cornice and window moldings, view

south, second floor



F.A. Stone Photo, 1906 Original at Mattatuck Museum, Waterbury

Facade and West Main Street, start of auto tour, view west 12



F.A. Stone Photo, 1906 Original at Mattatuck Museum, Waterbury

Detail of entrance, view north



F.A. Stone Photo, 1906 Original at Mattatuck Museum, Waterbury

West stairway, ballroom visible through door, view northeast



Lobby, view west

F.A. Stone Photo, 1906 Original at Mattauck Museum, Waterbury