

PMIS 187452 --- Restoring Larry Damm Creek
Site Condition Photos



Figure 1: Entrance to the Lower B500 from the Lost Man Creek picnic area.

PMIS 187452 --- Restoring Larry Damm Creek
Site Condition Photos



Figure 2: Example of the removed portion of the Lower B500 and Larry Damm Creek. Site was excavated in 2004.

PMIS 187452 --- Restoring Larry Damm Creek
Site Condition Photos




Figure 3: Corridor of the Lower B500 through surrounding old growth forest.

PMIS 187452 --- Restoring Larry Damm Creek
Site Condition Photos



Figure 4: Modular steel bridge installed to enable equipment to access upper portion of the Larry Damm watershed for restoration work. Bridge was installed in 1999 to cross a failing log stringer bridge. (See Figure 5.) Bridge will be removed and staged for use in other locations within the park of region.

PMIS 187452 --- Restoring Larry Damm Creek
Site Condition Photos



Figure 5: Side photo of modular bridge and failing log stringer bridge crossing the main stem of Larry Damm Creek. Original surface of the log bridge was at the base of the modular bridge but the right abutment has been gradually failing. Collapse of the existing log stringers poses a threat to fish passage to upstream portion of Larry Damm Creek.