

3101

United States Department of the Interior
National Park Service

MAR 15 1994

NATIONAL REGISTER OF HISTORIC PLACES
REGISTRATION FORM

NATIONAL
REGISTER

=====

1. Name of Property

=====

historic name: Bridgeville Historic District

other name/site number: CRS No. S-8735

=====

2. Location

=====

street & number: Various Streets not for publication: n/a

city/town: Bridgeville, Northwest Fork Hundred vic: n/a

state: DE county: Sussex code: 005 zip code: 19933

=====

3. Classification

=====

Ownership of Property: private and public-local

Category of Property: district

Number of Resources within Property:

Contributing	Noncontributing	
<u>166</u>	<u>26</u>	buildings
<u>0</u>	<u>13</u>	sites
<u>70</u>	<u>117</u>	structures
<u>0</u>	<u>0</u>	objects
<u>236</u>	<u>156</u>	Total

Number of contributing resources previously listed in the National Register: 2

Name of related multiple property listing: n/a

=====

4. State/Federal Agency Certification

=====

X See continuation sheet.

=====

8. Statement of Significance

=====

Certifying official has considered the significance of this property in relation to other properties: locally.

Applicable National Register Criteria: A, B, C

Criteria Considerations (Exceptions) : n/a

Areas of Significance: ARCHITECTURE
COMMUNITY PLANNING AND DEVELOPMENT

Period(s) of Significance: ca. 1830-1945

Significant Dates: 1856; 1871

Significant Person(s): William Cannon

Cultural Affiliation: n/a

Architect/Builder: unknown

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

X See continuation sheet.

=====

9. Major Bibliographical References

=====

X See continuation sheet.

Previous documentation on file (NPS):

- preliminary determination of individual listing (36 CFR 67) has been requested.
- previously listed in the National Register
- previously determined eligible by the National Register
- designated a National Historic Landmark
- recorded by Historic American Buildings Survey # _____
- recorded by Historic American Engineering Record # _____

Primary Location of Additional Data:

- State historic preservation office
- Other state agency
- Federal agency
- Local government
- University
- Other -- Specify Repository: _____

=====
10. Geographical Data
=====

Acreage of Property: approximately 75 acres

USGS quad: Seaford East, DE

UTM References: Zone Easting Northing Zone Easting Northing

A _____ B _____
C _____ D _____

X See continuation sheet.

Verbal Boundary Description: See continuation sheet.

The boundaries of the Bridgeville Historic District are shown on the tax parcel maps which accompany this documentation. Boundaries follow existing property lines, as recorded in the Land Records of Sussex County, Delaware.

Boundary Justification: See continuation sheet.

The nominated property comprises approximately 75 acres. The boundaries of the Bridgeville Historic District were drawn to encompass the strongest concentration of historic resources, while excluding properties which are not related to the period or themes of the district's significance. Within the defined boundaries, the resources exhibit a high degree of cohesiveness as to type, date, and level of integrity; at the edges of the district, a noticeable erosion of this quality is apparent. The area south of the district was transformed by suburban residential development in the World War II period; the area beyond the western boundary has been affected by recent site clearance and commercial and industrial redevelopment. The intersections of Market and Main streets, and Market and Laws streets, exhibit recent clearance and new construction. Boundaries were determined in consultation with the Delaware State Historic Preservation Office.

=====
11. Form Prepared By
=====

Name/Title: Peter E. Kurtze, Architectural Historian with Gabrielle Lanier

Organization: Bridgeville Historical Society Date: August 17, 1993

Street & Number: 109 Brandon Road Telephone: (410) 296-7538

City or Town: Baltimore State: MD ZIP: 21212
=====

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C. 470 et seq.).
Estimated Burden Statement: Public reporting burden for this form is estimated to average 18.1 hours per response including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Chief, Administrative Services Division, National Park Service, P.O. Box 37127, Washington, DC 20013-7127; and the Office of Management and Budget, Paperwork Reductions Project (1024-0018), Washington, DC 20503.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 4 Page # 1

4. State/Federal Agency Certification

As the designated authority under the National Historic Preservation Act of 1986, as amended, I hereby certify that this X nomination request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60. In my opinion, the property X meets does not meet the National Register Criteria. See continuation sheet.



March 9, 1994

Signature of certifying official

Date

State or Federal agency and bureau

In my opinion, the property meets does not meet the National Register criteria. See continuation sheet.

Signature of commenting or other official

Date

State or Federal agency and bureau

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 1

7. Description

Description Summary:

The Bridgeville Historic District comprises a cohesive collection of resources within the limits of the town of Bridgeville, a community located at the intersection of U. S. Route 13A (Main Street) and State Route 404 (Market Street) in the northwestern corner of Sussex County, Delaware. The architectural resources comprising the Bridgeville Historic District primarily reflect the period from the second quarter of the 19th century through the Depression era of the 1930s. During this period, the town achieved its present plan and experienced its principal period of growth as a center of agricultural commerce. Resources within the district are primarily residential in character, and reflect a broad range of architectural styles and vernacular building forms characteristic of the region and period. Several of the earliest resources within the district may incorporate elements of 18th-century construction. Vernacular forms represented in Bridgeville include the "I-house" type, two stories high, two rooms wide by one room deep, often with a service ell to the rear; this type is widely encountered in the Tidewater region both in towns and in rural contexts during the eighteenth, nineteenth and early twentieth centuries. Another vernacular building type represented in the district is the one-room wide, two-story, gable-fronted house, sometimes called "shotgun" for its similarity to the one-story form of that name which commonly occurs in the Southern states; this form was often used for workers' housing in rural towns in the region around the turn of the twentieth century. In addition to these types, Bridgeville is characterized by houses reflecting the progression of popular and academic architectural styles during the nineteenth and early twentieth centuries; examples show the influence of Greek Revival, Queen Anne, and Colonial Revival, Dutch Colonial, and Tudor Revival trends. Popular turn-of-the-20th-century forms including the American Foursquare and Bungalow house types are also represented. Few commercial or industrial resources survive, due to extensive redevelopment of the commercial and industrial areas of the town.

General Description:

The Bridgeville Historic District is primarily residential in character, with a few commercial resources and one former religious building. The district comprises most of the land within the town of Bridgeville, as laid out by William Cannon ca. 1856. Main Street (U. S. Route 13A) runs north-south and basically defines the eastern limit of the district; Market Street (State Route 404) extends to the west from Main Street. Both of these thoroughfares were in place well before the 1850s, when the land southwest of their intersection was subdivided by William Cannon. Cannon's plat established a grid pattern of roughly uniform-sized lots fronting on principal avenues running east-west;

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 2

=====
narrow alleys bisect the blocks, running between and parallel to the avenues. Houses are located toward the fronts of the lots, with a consistent slight setback from the street. The rear yards frequently contain domestic outbuildings including various sheds, stables, or garages.

Generally, the earliest, largest and most prominent buildings are located in the eastern section of the district, from William Street east to Main Street; the remainder of the district is characterized primarily by more modest, vernacular examples of late 19th and early 20th century house types. A few historic commercial buildings survive with good integrity near the east end of Market Street; much of the commercial area of town, however, has been subjected to redevelopment and extensive remodeling. Housing is primarily located south of Market Street; a small group of late 19th and early 20th century dwellings is located at the northwest corner of the district, in the area of North Cannon and Mill streets.

As the town grew through the nineteenth and early twentieth centuries, a broad variety of architectural forms chronicled its development. Although several resources within Bridgeville apparently incorporate elements of 18th and early 19th century construction, these elements have been obscured by subsequent alterations; as a result, the architectural character of Bridgeville primarily reflects the period from approximately the second quarter of the 19th century through the early 1930s. Several houses constructed in Bridgeville during the early part of this period conform to traditional building types characterized by single-pile, hall-parlor or center-passage plans. In addition, the influence of popular architectural styles is well represented by examples expressing the Greek Revival and Queen Anne styles of the nineteenth century, as well as Colonial Revival, Foursquare, and Bungalow types which achieved wide popularity after the turn of the twentieth century.

Throughout the Bridgeville Historic District, regional vernacular building types are interspersed among houses reflecting more academic influences. Common among these is the one-room-deep, three to five-bay-wide, two to 2½-story "I house." This form remained constant from the eighteenth century well into the twentieth; a noteworthy early example in Bridgeville is None Such Farms, located at 201 South Main Street, a frame two-story I-house with exterior gable end chimney incorporating late 18th century construction. The property is especially significant for its complement of early outbuildings including a privy and washhouse, and for its retention of 6 acres of what originally was an 80-acre parcel; it reflects Bridgeville's early history as an agricultural community, prior to the increasing density of the mid-19th century. Another early example of the I-house form is the Rawleigh House, located at 109 North Main Street (.322). The present building is the culmination of at least three periods of construction, beginning in the late 18th century as a log cabin. The house was expanded around the second quarter of the 19th century and raised to 2½ stories, with typical Greek Revival attic windows in the frieze. In the late 19th

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 3

=====

century, the several additions were unified under a jerkinhead roof with a central cross gable and decorative stickwork. The building has recently benefited from a thorough restoration, and is currently operated as a bed-and-breakfast inn. Late 19th century I-houses in the Delmarva region often display a front-facing central cross-gable, derived from the Gothic Revival style of the post-Civil War period; in Bridgeville, particularly noteworthy groupings of such buildings occur on the south side of Delaware Avenue, west of Cannon Street and at 102 and 106/108 Edgewood Street (.287, .285). Another important vernacular form is the two-story, one-room-wide gable-fronted house, often used for workers' housing in rural towns in the region after the Civil War; several examples of this type are located on the north side of Walnut Street, west of Cannon Street.

Several houses in Bridgeville express the influence of the Greek Revival style, which spread rapidly across America between 1830 and 1850, as migrants from the northeastern states built houses in new territories. It is especially common in areas that were settled rapidly during this period, notably the Western Reserve, Kentucky and Tennessee. Archaeological excavations during this period increased public awareness of ancient Greece, and citizens of the new American republic sympathized with modern Greece's involvement in a war for independence (1821-30). Distinguishing characteristics of this style include a low-pitched gable or hipped roof, sometimes with a front-facing gable; a porch across the entrance or the entire facade, supported by square posts or classical columns; and pilasters or board trim at the corners of the building. The entrance is usually framed with a rectangular transom and sidelights, and the roofline may feature a broad frieze below the cornice, sometimes with rectangular attic windows. A regionally distinctive variation on the attic window is a pair of small rectangular windows at the gable ends; this feature persists through the late 19th century. Examples of Greek Revival buildings in Bridgeville include 115 Delaware Avenue, built ca. 1832 (.16); in 1860, it became the parsonage for the Union Methodist Episcopal Church, the oldest Methodist congregation in Northwest Fork Hundred. A five-bay-wide, symmetrical I-house with an original service ell, the building reflects a regional response to the emerging Greek Revival style of the mid-19th century in its Classical detailing including a broad cornice, corner pilasters, and small rectangular windows in the gable ends lighting the attic. The Dr. Lawrence Cahall House, 119 North Main Street, is another noteworthy example of mid-19th century, Classical-influenced domestic architecture in Bridgeville (.316); in addition to the elements identified for the parsonage, this building features a slightly projecting gabled pavilion encompassing the two northernmost bays of its five-bay west facade.

The Gothic Revival, which drew upon the architecture of Medieval English country houses, was popularized in America through a series of publications by Alexander Jackson Davis and Andrew Jackson Downing beginning in the 1830s. The style achieved its peak of popularity between the 1850s and 1870s. It was a manifestation of a broader movement in architecture and landscape design, which rejected the classical ideals of symmetry and order and sought instead to create

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 4

=====

a "picturesque" effect through the use of exotic forms and romantic compositions. The Gothic Revival style was considered particularly appropriate for church buildings, and for houses in rural settings. In Bridgeville, the former Presbyterian Church (now the Bridgeville Public Library) exemplifies the style through its steep gabled roof forms and lancet-arched windows (.359). Gothic influence is also manifested in the central cross-gables which are found on many vernacular I-houses in Bridgeville.

The Queen Anne style of the late 19th century is derived from medieval English architectural forms. Houses in this style are characterized by asymmetrical plan and massing; variety of surface treatments, textures, and colors; elaborate decorative trim, shingles, and brickwork; an irregular roofline with multiple steep gables; often, a conical-roofed tower at a corner of the facade; the facade may have various projecting bays; a porch may span the facade, sometimes wrapping around a corner of the building; double-hung windows often have multiple small lights in the upper sash, sometimes forming a border around a single large pane. Later Queen Anne houses usually appear somewhat simplified in comparison with earlier examples of the style; they retain the characteristic irregular massing, but their surface decoration tends to be less elaborate. Constructed in 1894 for Wilbert Layton, the house at the northwest corner of South Main Street and Delaware Avenue is a well-restored example of the Queen Anne style featuring a large conical-roofed turret, a steeply sloping gable roof, an integral entrance porch with a broad arched opening, and a variety of wall cladding materials including beveled weatherboards and patterned shingles creating a richly textured surface (.1). The turret motif is also seen on several other properties in Bridgeville, including 203 South Main Street (.33) and 121 Market Street (.337); the latter property achieved its Queen Anne appearance in a ca. 1890s remodeling of a mid-19th century structure. Other buildings in Bridgeville reflect vernacular interpretations of the Queen Anne influence, primarily through steeply pitched, multiple gable roof forms and polygonal projecting bays; these buildings range in complexity from large, elaborate examples on South Main Street through simplified expressions located throughout the western section of the district. Examples include the house at the northeast corner of North Cannon and Mill streets (.124), and 202 Delaware Avenue (.92).

The American Centennial of 1876 prompted a revival of interest in the nation's heritage, and architects began to study the building forms and detailing of the Colonial period. The return to these historical precedents was partly a reaction against the unrestrained exuberance which characterized Victorian period architecture. Colonial Revival houses often combine "modern" turn-of-the-20th-century building forms with decorative elements derived from eighteenth-century architecture. Some examples are relatively accurate copies of historical sources, and may be categorized accordingly, as Georgian Revival, Spanish Colonial, Dutch Colonial, etc., but in many cases decorative detailing may be mixed from various colonial traditions. This detailing is often overscaled, and

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 5

=====
sometimes incorporates features of the Queen Anne style, whose period of popularity overlapped with that of the Colonial Revival. The ca. 1900 George W. Willin House, located at the southwest corner of Delaware Avenue and William Street, is an exceptionally large building reflecting the combined influence of the Queen Anne and Colonial Revival styles (.86): Queen Anne elements include the overall massing, with projecting bays, broad gable forms, and a large wraparound porch; wall coverings combine beveled siding with patterned shingles, and decorative cresting defines the roof ridges. Other aspects of the building's detailing are drawn from the Colonial Revival, including such features as arched Palladian windows and a bold modillion cornice. Such interaction of these two styles occurred frequently at the turn of the twentieth century, but is seldom as clearly evident as in this example. Another building showing similar design influences is 200 Market Street (.349).

Most of the Colonial Revival houses in Bridgeville are based on Georgian prototypes. Their characteristic features include a central or side entrance framed with a transom and sidelights, often of leaded glass; multi-pane sash windows; various Classical decorative details such as molded cornices enriched with modillions or dentils; frame buildings are usually sheathed in bevel-profile wood siding, or wood shingles; porches may have heavy tapered columns and balustrades with square or turned balusters. Several houses on the east side of South Main Street in Bridgeville reflect the influence of the Colonial Revival. The Wright House, built in 1915 at 210 South Main Street, is an unusual structure combining Bungalow massing with extensive Neoclassical detailing, featuring Palladian windows in the gables and a wraparound porch with a modillion cornice (.41).

The Bridgeville Historic District also contains several Dutch Colonial houses. A subtype of the Colonial Revival, the design of Dutch Colonial houses is derived from buildings constructed by Dutch settlers in New York and New Jersey in the 17th and 18th centuries. Houses of this style are generally 1½-stories in height with a broad, sloping gable or gambrel roof; the front slope of the roof extends to create a porch across the facade. Examples include 207 Delaware Avenue (.134), 203 Market Street (.341), and 104 South Main Street (.64). The house at 115 Walnut Street is a unique example of a vernacular I house to which a steep, bell-cast gambrel roof was added, probably early in the 20th century (.77).

The Tudor Revival style was popular from about 1900 up to the World War II era. Houses in this style exhibit a combination of forms and details derived from late Medieval English architecture, most particularly steep, front-facing gables, false "half-timbering" (geometric board patterns simulating exposed structural elements), stucco or masonry exterior walls, and casement windows. In Bridgeville, 206 Market Street (.355) and 104 Walnut Street (.69) are typical examples.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 6

=====

A very popular house type in the early twentieth century, the American Foursquare reflects turn-of-the-century trends toward increased economy and efficiency. The square plan enclosed large living spaces, and the relatively plain exteriors reduced the costs of construction and maintenance. These houses were built throughout America, from designs published in popular magazines, architectural pattern books, and mail-order plans; entire prefabricated buildings were manufactured and distributed nationwide by companies such as the Aladdin Company of Bay City, Michigan, Montgomery Ward, and Sears, Roebuck. The basic characteristics of this house type include a boxy, "Foursquare" shape; a steeply-pitched, near-pyramidal hipped roof with dormers; deep overhanging eaves; and a porch across the facade. Foursquares were built in a wide range of materials, including frame with weatherboard siding or wood shingles, brick, and ornamental concrete block (a new material in the period); sometimes several materials will occur in combination. Frame or masonry structures often were finished with stucco. Compared to their Victorian predecessors, Foursquares are relatively plain, but their basic form supported the use of decorative detailing derived from a variety of styles. Colonial Revival motifs are found most commonly, with sash windows (6 over 6, 6/1, or 1/1 lights are common configurations, but there are many other variations), heavy turned "Tuscan" porch columns, and other details. An outstanding example of the American Foursquare type in Bridgeville is Trinity House, located at 201 Market Street, a large masonry dwelling built in 1907 (.340). It exemplifies the Foursquare house type in its blocky, cubical proportions and steep hipped roof, and features Neoclassical decorative detailing characteristic of the turn of the 20th century. The building derives additional significance from its construction material: it is built of locally produced rock-faced concrete bricks, a highly unusual material. Distinct from the larger, cast concrete block frequently employed in early 20th century construction, the masonry units employed in Trinity House are approximately the size and shape of customary clay bricks, and are gray-brown in color with a granular texture. The property also has an outbuilding of the same material. Numerous other examples of the Foursquare house type contribute to the streetscapes of the Bridgeville Historic District; several especially large and elaborate examples are located in the area of South Main Street, and smaller, simpler versions of the type are scattered throughout the western part of the district, particularly along Walnut Street and North Cannon Street.

The Bridgeville Historic District contains several examples of the early 20th century Bungalow house type, 1-½ stories in height with a broad overhanging gable roof. This style is derived from prototypes in India, where the shading eaves and veranda open to the breeze were adapted to the tropical climate; it became widespread in America in the first quarter of the twentieth century. Bungalows are usually of frame construction, with bevel siding, wood shingles, or stucco covering the exterior. The posts supporting the porch roof are usually square in section and tapered, and simple stickwork brackets or rafter ends may appear under the eaves. One or more dormers commonly occur on the roof slopes. Houses of this type, like Foursquares, often were built from published plans or

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 7

=====

prefabricated kits. An exceptionally large example is located at 403 South Main Street (.280); instead of the customary dormer, this building has a large cross gable spanning the entire width of the west (front) slope of its roof, creating a broad porch. Numerous smaller bungalows are located in the western section of the district, along Delaware Avenue, Walnut Street, and North Cannon Street.

The district includes an exceptional example of the early 20th century Craftsman style, which is unique among the resources of Bridgeville and highly unusual in the broader Delmarva region: Cannon Manor, 106 North Main Street (.327), was built in 1904 by a grandson of the late Gov. William Cannon for his bride; it is a large 2-1/2 story frame building with broad overhanging eaves and a wraparound porch supported on battered posts. The building has been carefully restored, and retains a high degree of integrity.

The only religious structure within the Bridgeville Historic District is the former First Presbyterian Church of Bridgeville (1866), which has been reused as the Bridgeville Public Library and is individually listed in the National Register (.359).

Mid-twentieth century redevelopment has resulted in the removal or extensive remodeling of most of Bridgeville's historic commercial structures. Early store buildings remain at the intersection of Market and William streets; these buildings are of frame construction, two stories high, with a gable roof oriented perpendicular to the street; on the ground story, a recessed central entrance is flanked by large display windows. Examples of this building type which retain substantial integrity are 106 and 111 Market Street (.329, .333).

The ca. 1904 bank building on the north side of Market Street east of Cannon Street is the most prominent surviving historic commercial structure in Bridgeville (.362). Old photographs of the bank show a two-bay Queen Anne facade with a projecting entrance; the slate-roofed brick building was remodeled in the 1920s with the addition of a symmetrical Neoclassical front in cast stone. Doric columns flank the central entrance, with a three-part, semicircular-arched fanlight; the outer bays hold 1/1 sash with decorative transoms, below recessed panels. Doric pilasters mark the corners of the facade; the building has a simple entablature and brick parapet. The bank recently was renovated for use as the headquarters of the Bridgeville Police.

Prior to the renovation of the bank building, the police department was housed in the former water works building on Railroad Avenue at the west end of the district (.179). This is a one-story frame building with a steeply pitched hipped roof. It is rectangular in plan, three bays wide with a central entrance sheltered by a small gabled hood; a shed addition spans the south elevation. The water works building was constructed ca. 1909, in connection with the provision of public water service to Bridgeville.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 8

=====

Another important community service building is the old Bridgeville Fire House, now the headquarters of the Bridgeville Historical Society, a two-story gable-roofed building of rock-faced concrete bricks located at the southwest corner of William Street and Union Alley (.91). Constructed in 1911 to house the town's newly-organized volunteer fire department, the building was individually listed in the National Register in 1984.

Integrity: The properties within the Bridgeville Historic District generally demonstrate a high level of integrity. Alterations are generally minor, reversible, and not significantly destructive of historic fabric. The most common alteration in the district is the installation of synthetic siding; in most cases, historic architectural features remain undisturbed, and the basic form and construction remain intact. In some cases, additions have been constructed to the rear or side of a building; this type of additive growth is commonly encountered in the region, and usually does not obscure the basic form of the structure. The overwhelming majority of the principal buildings within the Bridgeville Historic District contribute to the significance of the district; they are related to the themes and period of significance defined for the district, and retain sufficient integrity to convey their associations. Most of the structures which are considered non-contributing are minor domestic outbuildings whose construction dates fall outside the period of significance; these structures are not intrusive on the overall visual and historic character of the district.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 9

Bridgeville Historic District
Sussex County, DE

INVENTORY

- .1 100 Delaware Avenue, Dwelling, late 19th century
[map 1-31-10.16-51; CRS No. S-4293] Contributing building.

This late 19th century, Queen Anne style dwelling is a south-facing, two-and-one-half story, five-bay, gable-roofed frame building. The house is distinguished by an ornamental front porch with an arched opening, a pedimented dormer directly above the front entrance, and a conical roofed circular tower to the east of the primary entrance; it has been enlarged with a one-story leanto addition off of the west elevation and a two-story addition on the north (rear) elevation. Built on a brick foundation, the house is clad in weatherboard on the first story and fishscale shingles on the second story, dormer, and porch facade; there are molded trim boards between stories. The roof is covered with asphalt shingles with a molded verge; there is a single brick chimney with a corbelled top located on the north side of the house, at the junction between the main block and the rear addition. Fenestration consists of one-over-one double-hung sash throughout most of the main block and small two-over-two double-hung sash in the upper story of the tower. The west gable elevation is lit by three side-by-side two-over-two double-hung windows at attic level. The primary door, located to the west of the tower, is ornamented with a single, stained-glass sidelight on the east side. The house is in good condition.

- .2 102 Delaware Avenue, Dwelling, late 19th century
[map 1-31-10.16-52; CRS No. S-4294] Contributing building.

This is a rectangular plan, five-bay, two-story center-hall frame dwelling dating to the late 19th century. The house, which faces south, is symmetrical with a pillared frame screened porch on the east gable and a similarly-designed, open-sided carport on the west gable. Built on a brick foundation, the house is clad in weathered wood shingles and topped with an asphalt-shingled gable roof with molded verge and cornice and molded cornice return. There is a single brick end chimney on the east gable. Fenestration is symmetrical, with four six-over-six double-hung sash windows on the first floor and five on the second; the center window on the second floor is slightly smaller than the others. The front door surround consists of a broken arch pediment with flanking fluted pilasters; there is a fixed four-light transom over the door. Tapered wood columns support the porch and carport roofs. The house is in good condition.

- .3 102 Delaware Avenue, Outbuilding, early 20th century
[map 1-31-10.16-52; CRS No. S-4294] Contributing building.

This is a one-story, gable-roofed, rectangular plan frame outbuilding with double sliding wood doors. The building is sided with wood shingles and roofed with asphalt shingles.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 10

=====
.4 104 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-53; CRS No. S-4295] Contributing building.

This is a rectangular plan, five-bay, two-story, gable-roofed frame dwelling with an arched Colonial Revival portico around the front entrance. There is a two-story wing attached to the northwest elevation with a one-story wing extending to the rear of the two-story addition on the northeast side. The house, which faces south, is built on a brick foundation and clad in wood shingles. There are two brick chimneys with corbelled tops, one located at the ridge on the east gable, and one at the rear of the two-story addition. The roof, which is covered with asphalt shingles, features a flush molded verge and a molded box cornice with returns. Windows, embellished only with plain board surrounds, are symmetrically placed on the front facade with four located on the first story and five on the second; windows consist of two-over-two double-hung sash. There is a single, arched-top, two-over-two, double hung window in the west gable. A frame front porch is supported by tapered wooden columns. The house is in fair condition.

.5 104 Delaware Avenue, Outbuilding, early 20th century
 [map 1-31-10.16-53; CRS No. S-4295] Contributing building.

This is a one-story, gable-roofed, rectangular frame outbuilding sheathed in beaded vertical board siding with a gable entrance.

.6 106 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-54; CRS No. S-4296] Contributing building.

This two-story frame Queen Anne-style dwelling features a three-bay main block with a circular tower on the southeast corner and a cross gable above the front entrance on the south facade. A two-story addition and two one-story additions extend from the north (rear) elevation. The house is built on a brick foundation and clad in weatherboard-style aluminum siding with vertical board and batten-type aluminum siding on the tower. The roof is hipped with cross gables and a conical roof over the corner tower. The cornice and underside of the eaves are ornamented with molded decorative trim. There are two brick chimneys with corbelled tops, one on the west side of the main block and one at the north side of the north addition. Fenestration on the front facade consists of three bays on the first floor fitted with two one-over-one, double-hung windows and a center door; on the second floor there is a projecting bay on the west side with a single double-hung, twelve-over-one-light sash and a double-hung, one-over-one-light sash in the other window. There is one large double-hung stained glass window on the second floor of the west elevation. Windows are finished with simple board surrounds. A wood frame front porch is supported by tapered cylindrical columns. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 11

.7 106 Delaware Avenue, Outbuilding, late 19th century
[map 1-31-10.16-54; CRS No. S-4296] Contributing building.

This rectangular, one-story, gable-roofed outbuilding is clad in vertical wooden board-and-batten siding and is located at the rear of the property.

.8 108 Delaware Avenue, Dwelling, early 20th century
[map 1-31-10.16-55; CRS No. S-4297] Contributing building.

This two-story, three-bay, frame dwelling is rectangular in plan with a bay on the west side. The house, which faces south, is sheathed in weatherboard, supported by a brick foundation, and topped with a gambrel roof with a full three-bay dormer on both front and back elevations; additional ornamentation includes a molded verge and beaded siding under the eaves. There are two brick chimneys, one, with a corbelled top, is located on the west gable at the ridge; the other is situated on the north (rear) elevation. One three-part window is located on either side of the front door on the first floor; these are each nine-over-one, twelve-over-one, and nine-over-one, double hung sash. There are three twelve-over-one double-hung sash windows on the second floor. Window trim consists of plain board surrounds. The wood frame front porch is supported by tapered wooden columns. The house is in good condition.

.9 108 Delaware Avenue, Shed, late 20th century
[map 1-31-10.16-55; CRS No. S-4297] Non-contributing building.

This is a small, modern, prefabricated wooden storage shed with a gambrel roof.

.10 110 Delaware Avenue, Dwelling, early 20th century
[map 1-31-10.16-56] Contributing building.

A two-story, five-bay, hip-roofed, frame dwelling built on a rusticated concrete block foundation, this house dates to the early 20th century. It is sheathed in weatherboard and roofed with asphalt shingles. There is a single pedimented dormer with three fixed four-light sash windows directly over the primary south-facing entrance. The remaining fenestration on the front facade consists of two paired eight-over-one-light, double-hung sash windows with plain board surrounds on either side of the front door and three single eight-over-one-light double-hung sash windows with plain board surrounds on the second floor. A south-facing, frame front porch is supported with tapered wooden columns. The house is in good condition.

.11 112 Delaware Avenue, Dwelling, late 19th century
[map 1-31-10.16-57] Contributing building.

This is a three-bay, rectangular, single-pile, gable-roofed, south-facing frame house with three dormers on the front elevation, two dormers on the rear

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 12

=====

elevation, a two-story addition on the north side and a one-story addition with single-pitched roof on the northeast side. The house is built on a brick foundation and sided with rough weatherboards. The roof, which is covered with asphalt shingles, is ornamented with a boxed, molded cornice with returns. Fenestration consists of six-over-six-light, double-hung sash throughout. The three front and two rear dormers are also ornamented with molded boxed cornices and cornice returns. The tripartite windows located on either side of the front door also consist of six-over-six-light, double-hung sash. Modern shutters flank all first and second story windows. The center door is flanked by five-light sidelights. The roof of the wood frame front porch is supported by straight boxed wooden pillars. The house is in good condition.

- .12 112 Delaware Avenue, Garage, late 20th century
[map 1-31-10.16-57] Non-contributing building.

This is a three-bay, one-story, gable-roofed, weatherboarded rectangular garage built on a concrete block foundation.

- .13 112 Delaware Avenue, Shed, late 20th century
[map 1-31-10.16-57] Non-contributing building.

This is a one-story, gable-roofed, weatherboarded rectangular shed built on a concrete block foundation with a single gable roof.

- .14 114 Delaware Avenue, Dwelling, late 19th century
[map 1-31-10.16-58; CRS No. S-4298] Contributing building.

This large frame, five-bay, two-story dwelling is built with two projecting two-story bays, one on the front (south) elevation and one to the west. A one-story addition is built adjacent to a two-story wing on the rear (north) elevation. Built on a foundation composed of brick-sized rusticated concrete blocks, the house has recently been sheathed in aluminum siding and is capped with a hipped roof covered with asphalt shingles. Cornice details which may be present have been concealed beneath aluminum siding. Fenestration consists of two main bays on the first floor with a projecting tripartite bay window located to the right of the front door. Windows are shuttered one-over-one, double-hung sash throughout; existing window trim has also been concealed beneath aluminum siding. Two dormer windows, each hung with two-over-two, double-hung sash, project from the south and east elevations. The front entrance consists of a wood panel door with stained glass light on top. A covered frame front porch, built on a rusticated concrete block foundation, is supported with round, tapered wooden columns. The house is in good condition, although its integrity has been compromised by the application of aluminum siding.

- .15 114 Delaware Avenue, Outbuilding, early 20th century
[map 1-31-10.16-58; CRS No. S-4298] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 13

Bridgeville Historic District
Sussex County, DE

=====

This is a one-and-one-half-story, frame, gable-roofed garage built on a concrete block foundation. The building is clad with vertical board-and-batten siding and roofed with asphalt shingles. There are three entrance bays located on a lateral elevation; one six-over-six, double-hung sash window is located at attic level in each gable.

- .16 115 Delaware Avenue, Dwelling, mid 19th century
 [map 1-31-10.16-91] Contributing building.

This two-story, five-bay, gable-roofed rectangular frame building faces north. The house has a single-pile, two story addition located on the south side of the main block with a second, one-story leanto addition attached to the east side of the rear addition. There are two, corbelled brick gable-end chimneys; a third corbelled brick chimney is located in the center of the rear ell at the ridge. Built on a brick foundation, the house is sided with painted weatherboard and roofed with asphalt shingles. The house features a center hall with wood panel door and four-light fixed transom above, a molded box cornice with returns, and a two-story frame front porch consisting of a roofed first story with a balustraded second story above. The porch roof is supported by straight, square wooden columns. There is a two-story porch of similar design located on the west elevation. Windows are six-over-six-light, double-hung sash throughout; there are two fixed three-light sashes at attic level in each gable. Window trim consists of molded board surrounds and louvered shutters. The house is in fair condition.

- .17 115 Delaware Avenue, Shed, late 19th century
 [map 1-31-10.16-91] Contributing building.

This is a one-story rectangular, gable-roofed frame shed with a leanto addition topped with a single-pitched roof on the south side. The building is sided with vertical boards and the roof of the main block is covered with standing seam metal.

- .18 111 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-92; CRS No. S-4287] Contributing building.

This two-and-one-half-story, three bay, frame Foursquare dwelling is built on a brick foundation and has been recently sheathed in aluminum siding. The house faces north. A newly-built two-story wing extends eastward from the southeast corner of the main block; the addition features a single projecting bay on the first floor and two bays on the second floor. The pyramidal roof of the main block is covered with asphalt shingles and is finished with a boxed cornice. A corbelled brick chimney is located at the peak of the roof. Windows consist of two-over-two, double-hung sash throughout the main block and a single, arch-topped window opening fitted with louvered vents on the west gable at attic level. Windows are trimmed with plain board surrounds and louvered shutters. A

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 14

Bridgeville Historic District
Sussex County, DE

=====

double wood panel door with overhead transom is located at the front entrance. A roofed frame front porch is supported by chamfered wooden columns. The house is in good condition, although its integrity has been compromised by the application of aluminum siding.

- .19 111 Delaware Avenue, Shed, early 20th century
 [map 1-31-10.16-91; CRS No. S-4287] Contributing building.

This is a one-story, frame, rectangular shed sided with vertical board-and-batten siding and roofed with wood shingles.

- .20 111 Delaware Avenue, Garage, late 20th century
 [map 1-31-10.16-91; CRS No. S-4287] Non-contributing building.

This is a one-and-one-half-story, concrete block, two-bay garage with gable end chimney.

- .21 109 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-93; CRS No. S-4288] Contributing building.

This frame house consists of a north-facing, rectangular, two-story, three-bay, single-pile main block with a two-story addition on the south elevation and a one story addition on the east elevation. The house is built on a brick foundation and clad in asbestos shingle. The hipped roof is covered with asphalt shingles and embellished with a boxed, molded cornice with pedimented gables. A single brick chimney stands at the ridge in the center of the two-story rear addition. A single dormer, located on the north side over the center entrance, has had its original sash removed and replaced with a louvered vent for an air conditioner. Windows consist of two-over-two, double-hung sash on the front of the main block, three-over-three double-hung sash on the gables, and two-over-two double-hung sash in the addition. Windows throughout are trimmed with molded board surrounds. The house is in good condition.

- .22 109 Delaware Ave, Shed, late 20th century
 [map 1-31-10.16-93; CRS No. S-4288] Non-contributing building.

This is a prefabricated, gambrel-roofed, frame one-story shed.

- .23 109 Delaware Ave, Outbuilding, late 20th century
 [map 1-31-10.16-93; CRS No. S-4288] Non-contributing building.

This is a one-story, frame, gable-roofed garage built on a concrete block foundation and clad in aluminum siding.

- .24 107 Delaware Ave, Dwelling, late 19th century
 [map 1-31-10.16-94; CRS No. S-4289] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 15

=====
This is a rectangular, two-story, three-bay, gable-roofed house with the gable entrance facing the street. There is a two-story, gable-roofed addition attached to the south elevation. The frame house, which faces north, is built on a rusticated concrete block foundation, sided with asbestos shingles, and topped with an asphalt-shingled roof. The primary entrance is to the west of the two first-floor window bays and features a four-light transom over the door. Ornamentation includes carved scrollwork at the verge and eaves, plain wood window and door surrounds with dentilated decorative crowns, and louvered wooden window shutters. There is a balustraded and roofed front porch supported by chamfered wooden posts trimmed with jigsawed wooden brackets. The house is in good condition.

.25 105 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-95; CRS No. S-4290] Contributing building.

This is a rectangular, three-bay, single pile house with a projecting front entry and pedimented cross gable. There is a two-story addition located on the southeast side of the main block with a one-story wing to the west of the addition. The house is built on a brick foundation, sheathed in weatherboard, and roofed with asphalt shingles. Details include a molded boxed cornice with returns, a corbelled brick chimney on the west gable, and an arch-topped window and balustraded porch over the front door. There is a similar arch-topped window on the east gable at attic level; there are two quarter-round attic windows on either side of the chimney on the west gable. First-floor windows are eight-over-eight-light, double-hung sash; second floor windows are six-over-six-light, double-hung sash. The centrally-placed, wood panel door is embellished with an elaborate door surround with flanking wooden pilasters. The house is in good condition.

.26 105 Delaware Avenue, Garage, early 20th century
 [map 1-31-10.16-95; CRS No. S-4290] Contributing building.

This is a two-story, gable-roofed, gable-entrance frame garage on a brick foundation with sliding doors on the south gable and a second entrance door on the east gable. The roof is covered with asphalt shingles.

.27 103 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-96; CRS No. S-4291] Contributing building.

A center hall, three-bay, single pile frame dwelling with a central entry and a one-story rear wing, this two-story house is sheathed in asbestos shingles to the level of the foundation. The asphalt-shingled gable roof features a flat boxed cornice; there is a single, corbelled brick chimney on the east gable of the main block. Window and door trim consist of simple board surrounds. Windows in the main block are one-over-one, double-hung sash on the first floor and six-over-

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 16

=====
six-light, double-hung sash on the second floor; there are two three-light fixed-sash windows at attic level on each gable. The house is in fair condition.

- .28 103 Delaware Avenue, Outbuilding, late 20th century
 [map 1-31-10.16-96; CRS No. S-4291] Non-contributing building.

This is a concrete-block outbuilding with a corrugated metal roof; it is attached to the main block with a covered breezeway located at the rear of the house.

- .29 101 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-97; CRS No. S-4292] Non-contributing building.

This two-story, three-bay, single-pile frame house has a single-pile, two-story rear addition; there is a second one-story addition with a single-pitched roof attached to the east side of the addition. The house faces north. Built on a rusticated concrete block foundation and topped with an asphalt-shingled gable roof, the house is sided with cedar shingle over old weatherboard. Details include a flush molded verge and a boxed cornice with returns. A single corbel-topped brick end chimney is located on the west gable; a second cement-covered brick chimney is located in the center of the rear addition at the ridge line. While the window and door locations appear to be original, the first period sash on the north and west elevations has been replaced with louvered windows. Several of the original second-floor window surrounds have also been removed, although several molded wood window surrounds remain on the first floor. The entry door, located in the easternmost bay, is a modern panel door. A covered frame porch built on a rusticated concrete block foundation and supported by turned wooden posts extends across the entire front facade. The porch posts are ornamented with wooden brackets. The house is in fair condition but lacks integrity.

- .30 101 Delaware Avenue, Outbuilding, late 19th century
 [map 1-31-10.16-97; CRS No. S-4292] Contributing building.

This is a large, two-story, gable-roofed frame outbuilding measuring approximately 16 by 38 feet. Sheathed with a combination of vertical boards and board-and-batten siding and covered with an asphalt shingle roof, the building has two large sliding doors located on the west gable end as well as three second-story loading doors on the north, west, and south sides. Fenestration consists of six-light fixed sash throughout.

- .31 Layton House, 200 S. Main Street, Dwelling, late 19th century
 [map 1-31-10.16-98; CRS No. S-4393] Contributing building.

This two-story, five-bay frame Queen Anne-style dwelling features a hipped roof with molded boxed cornice, an east-facing and a north-facing dormer, two projecting bays, a wraparound front porch and a one-story addition that extends

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 17

across the entire rear (west) facade. The house, which faces east, is built on a brick-sized rusticated concrete block foundation and sheathed in aluminum siding. Additional decoration includes fish scale shingles on the dormers and in the projecting gables. A brick chimney with a corbelled top is located at the center of the roof over the main block. Window sash, which is double hung, consists of four vertical panes over one single pane; window trim consists of plain board surrounds. The covered porch is supported by tapered columnar pillars on the first floor; both the first and second floor porches are balustraded. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

- .32 200 S. Main Street, Garage, early to mid 20th century
 [map 1-31-10.16-98; CRS No. S-4393] Contributing building.

This is a one-story frame garage with an asphalt shingled pyramidal roof, sliding entrance doors on the north facade, and a corbelled brick chimney located at the center of the roof. The two sliding entrance doors have 6-light fixed sash at the top. The building is sheathed in vertical boards.

- .33 203 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-177] Contributing building.

This two-and-one-half-story, five-bay, Queen Anne-style dwelling is built with a projecting tower to the left of the primary entrance, a second story porch tower to the right, projecting bays on the north and south sides, and a projecting pedimented dormer located above the front entrance. Built on a brick foundation, the house is of frame construction with a roof of mixed wood shingle and asphalt. The roof over the main block is gabled with a molded verge; over the tower, it is a hexagonal cone shape. The house is sheathed in plain weatherboard on the first floor and decorative fish scale shingles on the tower and projecting dormer. A dormer embellished with drop pendants at the corners is located over the front entrance. There are two chimneys visible; one is built of brick and stands on the north side behind the front tower, and one is constructed of concrete block and is located on the southeast corner. Windows--which consist primarily of one-over-one-light, double-hung sash throughout except on the tower which is lit with three-over-three, double-hung sash--are trimmed with plain board surrounds. There is one leaded glass window on the south gable. The front door, which is centrally-placed, is embellished with three-light fixed sidelights and an overhead transom. The roofed frame front porch, under construction at the time of field work, was probably originally supported by chamfered wooden posts. The projecting second-story porch tower is presently supported by turned wood posts. The house is in fair to poor condition, and although it appears to be vacant, is currently undergoing renovation.

- .34 205 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-178; CRS No. S-4372] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 18

=====
This two-story, six-bay frame dwelling is a rectangular-shaped building with a center hall plan, a projecting two-story bay, and a pedimented cross gable on the northwest side. The house, which faces west, is built on a brick foundation, sheathed with asbestos shingle, and topped with an asphalt shingled, gable roof with boxed, molded cornice. There are two cement-covered brick interior end chimneys with corbelled tops. Windows consists primarily of two-over-two, double hung sash to the right of the projecting bay with one-over-one, double-hung sash on the first floor and in the projecting bay. Windows are trimmed with plain board surrounds. A roofed frame front porch, which wraps around to the south side of the building, is supported by tapered circular wooden columns and embellished with a simple balustrade. The house is in good condition.

.35 205 South Main Street, Outbuilding, 20th century
 [map 1-31-10.16-178; CRS No. S-4372] Non-contributing building.

This one-story frame outbuilding is sided with asbestos shingles and topped with a single-pitched roof. The foundation is not visible.

.36 207 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-179] Contributing building.

A two-story, frame building facing west, this dwelling is constructed on a rectangular plan with a projecting one-story wing topped with a balustrade extending from the south facade and a two-story rear wing attached to the east side. A roofed Colonial Revival front portico surrounds the front entrance. While the foundation is not visible, the building is sheathed with modern aluminum siding; the gable roof is covered with asphalt shingles and features a boxed cornice with flush molded verge and returns. There are two brick chimneys: one is an exterior end chimney located on the north gable of the main block; the other is located at the east end of the two-story addition. Three paired nine-over-one-light, double-hung sash windows are located at first floor level on either side of the front entrance; on the second floor of the main block, there are three evenly-spaced, twelve-over-one-light, double-hung windows. Windows in the rear wing consist of eight-over-eight, double-hung sash on the first floor and twelve-over-one, double-hung sash on the second. Window and door trim throughout consists of plain molded surrounds. The primary entrance is lit by fixed, six-light side lights. A covered, asphalt-shingled frame portico at the front door features a molded cornice with returns and tapered circular wooden columns. The house is in good condition.

.37 209 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-180; CRS No. S-4391] Contributing building.

The house at 209 South Main Street is a three-bay, two-story, main block with a two-story rear addition and a one-story wing extending beyond the first addition. Facing west, the house is of frame construction, built on a brick foundation, and

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 19

covered with an asphalt-shingled, gable roof with boxed cornice. The house is sheathed with asbestos shingles. A single interior end chimney, built of brick, is located on the north gable. There are two two-over-two, double-hung windows finished with plain board surrounds located to the right of the main entrance door on the first floor; similar windows are located directly above the first floor bays on the second floor. The frame front porch is built on a brick foundation and covered with an asphalt shingled roof that is supported by chamfered wooden posts trimmed with decorative sawn wood corner brackets and pendants. The house is in fair condition.

.38 211 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-181; CRS No. S-4370] Contributing building.

The frame dwelling located at 211 South Main Street faces west. The two-story, three-bay, rectangular main block has been expanded with a two-story rear wing furnished with a projecting north-facing bay. Built on a brick foundation, the house is sheathed in asbestos shingle and covered with an asphalt-shingled, gable roof. The original cornice and verge have been concealed beneath a later application of aluminum siding. A single brick interior end chimney is located on the south gable. The primary entrance is located to the left of the two remaining bays; second floor openings are placed directly above those on the first floor. Windows, finished with plain molded board surrounds, consist of six-over-six, double-hung sash throughout except at attic level on each gable facade, where there are two fixed four-light windows. The front door is trimmed with flanking four-light sidelights and a three-light transom. A frame, asphalt-roofed front porch is supported by plain, square wooden posts. The house is in fair condition.

.39 300 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-156; CRS No. S-4399] Contributing building.

This is a two-story, frame dwelling facing east. While the five-bay main block is constructed in an overall L-plan, the house is also furnished with a projecting, two-story, cross-gabled bay, a projecting two-story addition at the juncture of the two portions of the "L," and two separate one-story additions located on the west (rear) and south facades. Built on a brick foundation and sheathed with asbestos siding, the dwelling is covered with an asphalt shingled, gable roof finished with a full molded boxed cornice with pedimented gables. A single interior brick chimney is located at the junction of the "L." Additional details include two-over-two, double-hung, arched windows with arched hoods in both pedimented cross gables and sawn scrollwork with decorative drop pendants under the eaves of the west-facing cross gable. Windows, finished with molded board surrounds throughout, are primarily one-over-one, double-hung sash. A single, covered frame porch supported by plain, squared wooden posts wraps around the east and north facades. The house is in good condition.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 20

=====
.40 300 South Main Street, Outbuilding, 20th century
 [map 1-31-10.16-156; CRS No. S-4399] Non-contributing building.

This is a one-story frame outbuilding sheathed with vertical board and batten siding and covered with a single-pitched, corrugated metal roof.

.41 Wright House, 210 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-103; CRS No. S-4399] Contributing building.

This is a two-story, T-plan frame dwelling with a projecting cross gable and a wraparound front porch. Built on a brick foundation, the house is sheathed in asbestos shingles and covered with a gable roof with interrupted pent eave on the second floor. The roof is further embellished with a boxed, molded cornice. A single brick interior chimney is located on the northeast side. Windows consist primarily of one-over-one, double-hung sash throughout and are finished with plain board surrounds. The front porch, which wraps around the south, east, and north facades, is built on a brick foundation. The porch roof is supported by round tapered wooden columns. Additional ornamentation includes scrolled brackets at the porch eaves and fish scale shingles in the cross gables. The house is in good condition.

.42 210 South Main Street, Shed, late 20th century
 [map 1-31-10.16-103; CRS No. S-4398] Non-contributing building.

This is a frame prefabricated storage shed with an asphalt shingled gambrel roof.

.43 208 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-102; CRS No. S-4397] Contributing building.

This late 19th century frame dwelling, which faces east, is primarily rectangular in shape with a four-bay main block, a projecting two-story pedimented bay with cross gable, and a second-story projecting pedimented flat bay located over the front entrance. A modern one-story addition is attached to the southeast corner. The house is built on a brick foundation, sided with a combination of wavy-edged asphalt shingles and aluminum siding, and covered with an asphalt-shingled, gable roof trimmed with a molded, boxed cornice and flush molded verge. There is a single, central interior brick chimney located on the west side of the ridge. Windows, fitted primarily with one-over-one, double-hung sash throughout, are finished with plain board surrounds. The wood panel door is embellished with a fixed fanlight above. The house is in fair condition; its integrity has been compromised by the application of aluminum siding as well as the addition to the front facade.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 21

.44 208 South Main Street, Outbuilding, 20th century
[map 1-31-10.16-102; CRS No. S-4397] Non-contributing building.

This is a one-story, gable-roofed, asbestos-sided frame outbuilding.

.45 200 Cherry Lane (behind 200 South Main Street), Dwelling, late 20th century
[map 1-31-10.16-102] Non-contributing building.

This is a two-story, two-bay, gable-roofed concrete block dwelling and garage sided with wavy-edged, asphalt shingles near the top of the second story.

.46 206 South Main Street, Dwelling, late 19th century
[map 1-31-10.16-101; CRS No. S-4396] Contributing building.

This L-plan, five-bay, center hall frame dwelling with asymmetrically placed front cross gable is two stories tall and faces east. The single pile house is built on a brick foundation, sheathed in wavy-edged asbestos shingles, and roofed with asphalt shingles. The roof is trimmed with a boxed cornice with returns and a flush molded verge. A single brick interior chimney with corbelled top is located at the ridge on the north end of the house. Windows consist primarily of two-over-two, double-hung sash finished with molded board surrounds, although there are also arch-topped, two-over-two, double-hung windows in the end gables as well as the front cross gable. The front door, which is centrally placed, is trimmed with a pedimented wood surround with fluted pilasters. The house is in good condition.

.47 206 South Main Street, Outbuilding, late 20th century
[map 1-31-10.16-101; CRS No. S-4396] Non-contributing building.

This is a one-story, prefabricated, gambrel-roofed frame outbuilding with a gable entrance.

.48 204 South Main Street, Dwelling, early 20th century
[map 1-31-10.16-100; CRS No. S-4395] Contributing building.

Rectangular in plan, this east-facing, gable-roofed frame dwelling features a projecting, two-story, flat-roofed bay on the north gable and a projecting flat bay on the south gable. A two-story wing is attached to the rear. The house is built on a brick foundation, sheathed with weatherboard, and roofed with asphalt shingles. The roof is further finished with a boxed cornice with returns and a molded verge. There are two front-facing dormers. Window openings on the first floor are mostly fitted with one-over-one, double-hung sash; on the second floor and in the dormers, they are furnished with six-over-one, double-hung sash. There is a single Palladian window located in the north gable at attic level. The primary entrance door is flanked with four-light fixed side lights. An asphalt-roofed, frame porch extends the full length of the front facade. The

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 22

=====

porch features brick column supports, tapered round wooden columns, and a dentilated cornice. The house is in good condition.

- .49 204 South Main Street, Garage, 20th century
 [map 1-31-10.16-100; CRS No. S-4395] Non-contributing building.

This is a frame, one-story, hip-roofed garage with a rear gable entrance built on a concrete foundation. The building is sheathed in vertical narrow-width beaded siding.

- .50 204 South Main Street, Shed, early 20th century
 [map 1-31-10.16-100; CRS No. S-4395] Contributing building.

This is a one-story, frame, gable-roofed shed with a gable entrance. The building is sheathed in weatherboards; the roof is covered with asphalt shingles.

- .51 202 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-99; CRS No. S-4394] Contributing building.

This frame, two-story, single-pile, late 19th century, L-plan dwelling faces east. The house features a projecting two-story bay with front-facing pedimented cross gable above. Built on a brick foundation and sheathed with asphalt shingles, the building is capped with an asphalt-shingled, gable roof with boxed cornice and flush molded verge. The pedimented double cross gable is further embellished with turned pendant drops and sawn, scrolled brackets under the eaves. A single brick chimney is centrally located on the ridge of the main block. The primary entrance door, placed at the far left end of the front facade, is trimmed only with plain board surrounds. The windows are similarly finished, and consist of one-over-one, double-hung sash throughout. The house is in poor condition and did not appear to be occupied at the time field work was undertaken.

- .52 202 South Main Street, Garage/Barn, late 19th century
 [map 1-31-10.16-99; CRS No. S-4394] Contributing building.

This two-story, frame, gable-roofed garage and storage building is equipped with two sliding wooden doors on the gable entrance as well as single-width, second-story doors on the east and north facades and a fixed-sash window in the front attic gable. The five bays on the west (lateral) facade are filled with fixed, six-light sash. The building is sheathed in a mixture of board-and-batten and plain vertical board siding and is covered with an asphalt-shingled roof.

- .53 None Such Farms, 201 South Main Street, Dwelling, late eighteenth/19th century; [map 1-31-10.16-176; CRS No. S-4373] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 23

=====

This two-story, three-bay, T-plan, frame dwelling with front-facing, two-story gable faces west and is set back a considerable distance from the main road. The house is built on a brick foundation, sheathed in wood shingles, and covered with an asphalt-shingled, gable roof with boxed cornice. A screened porch has been added to the west gable, a projecting, one-story bay is located on the north facade, and a new, frame, one-and-one-half-story wing is located on the north side. A single exterior end chimney with a corbelled top is located on the front-facing west gable. Windows throughout are furnished with six-over-six, double-hung sash and finished with molded surrounds and a mixture of paneled and louvered shutters. The primary entrance door is lit with a four-light fixed transom and three-light fixed sidelights. The screened porch on the south side of the house is covered with an asphalt-shingled roof that is supported by plain, square wooden posts. The house is in good condition.

- .54 201 South Main Street, Shed, early 20th century
 [map 1-31-10.16-176; CRS No. S-4373] Contributing building.

This is a two-story, gable-roofed frame storage building with wood siding and a metal roof.

- .55 201 South Main Street, Shed, early 20th century
 [map 1-31-10.16-176; CRS No. S-4373] Contributing building.

This is a second two-story, gable-roofed frame storage building with wood siding and a metal roof.

- .56 201 South Main Street, Shed, early 20th century
 [map 1-31-10.16-176; CRS No. S-4373] Contributing building.

This is a third two-story, gable-roofed frame storage building with wood siding and a metal roof.

- .57 201 South Main Street, Shed, late 20th century
 [map 1-31-10.16-176; CRS No. S-4373] Non-contributing building.

This is a small, one-story, modern frame shed.

- .58 109 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-175; CRS No. S-4374] Contributing building.

This a rectangular, two-story, five-bay, single-pile frame dwelling has a center entrance and faces west. The house is built on a brick foundation, sheathed with weatherboard, and topped with an asphalt-shingled, gable roof. The eave line is further embellished with an ornamental verge finished with raised vertical boards. There are two interior gable-end brick chimneys finished with corbelled tops. Windows consist of two-over-two, double-hung sash; there are two fixed,

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 24

=====

three-light sash windows located in the gables at attic level. Windows are simply finished with plain board surrounds. The centrally-placed door is finished with plain board surrounds and lit with a four-light transom. A roofed front porch extends across the three central bays; its original supports have been removed and have been replaced with plain, square wooden posts. The house is in fair condition.

- .59 109 South Main Street, Garage, early 20th century
 [map 1-31-10.16-175; CRS No. S-4374] Contributing building.

This is a one-story, frame, gable-roofed garage with two sliding wooden doors located in the gable end.

- .60 107 South Main Street, Dwelling, late 19th to early 20th century
 [map 1-31-10.16-174; CRS No. S-4375] Contributing building.

This rectangular, two-story, four-bay, frame dwelling faces west. The house is furnished with a projecting clipped front cross gable and a projecting two-story bay with pedimented gable on the north facade. The foundation is brick, sheathing is asbestos shingle, and the gable roof is covered with asphalt shingles. Additional ornamentation includes fish scale shingles and a Palladian window in the front cross gable. The roof is finished with a flush molded verge and a boxed, molded cornice with returns. There is a single brick chimney located in the center of the main block at the ridge line. Windows, finished with plain board surrounds with molded drip caps, are fitted with one-over-one, double-hung sash throughout. The front door, also finished with plain board surrounds, is located to the left of the front-facing bay. An asphalt-roofed, frame front porch extending the length of the front facade is supported on a brick and concrete block foundation; the roof is also embellished with a boxed cornice and supported with tapered circular wooden columns. The house is in fair condition.

- .61 107 South Main Street, Garage, late 20th century
 [map 1-31-10.16-174; CRS No. S-4375] Non-contributing building.

This is a gable-roofed, frame garage with a gable entrance.

- .62 105 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-173] Contributing building.

The single pile frame dwelling at 107 South Main Street has a rectangular main block with a projecting front two-story bay and a roofed portico over the front door. The building is further extended with a two-story rear wing with an attached one-story wing. The house, which faces west, is built on a concrete or concrete-covered brick foundation, sheathed in modern aluminum siding, and covered with an asphalt shingled, gable roof. Original cornice details have been

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 25

concealed beneath the aluminum siding. Windows consist of one-over-one, double-hung sash throughout. The gable roofed portico, which extends just over the front door, is supported by turned wooden posts. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

.63 105 South Main Street, Dwelling, mid 20th century
[map 1-31-10.16-173] Non-contributing building.

This is a one-and-one-half-story, frame dwelling set back from the main house. It has a center entrance, is sheathed in aluminum siding, and is covered with an asphalt-shingled, gable roof.

.64 104 South Main Street, Dwelling, early 20th century
[map 1-31-10.16-50; CRS No. S-4392] Contributing building.

This is an east-facing, three-bay, two-story, gambrel-roofed early 20th century frame house with a center hall, a covered pedimented portico over the front entrance and a one-story porch wing on the northeast corner. The main block is rectangular in shape. Built on a brick foundation, the house is clad in weatherboard and covered with an asphalt shingled roof with two full dormers. There is a single interior brick end chimney on the north gable. The door is centrally placed between two three-part windows on the first floor. Window sash consists of nine-over-nine, double-hung sash throughout except for the flanking parts of each three-part window; these are six-over-six sash. Window and door trim consist of plain board surrounds. The frame front porch, which extends over the main entrance, is built on a brick foundation. The asphalt-shingled porch roof is supported by tapered circular wooden columns and further ornamented with a plain wooden balustrade. The house is in good condition.

.65 104 South Main Street, Shed, late 20th century
[map 1-31-10.16-50; CRS No. S-4392] Non-contributing building.

This is a frame, gable-roofed, late 20th century outbuilding.

.66 100-102 Mechanic Street, Dwelling, late 20th century
[map 1-31-10.16-50.1 (behind parcel #50); CRS No. S-4727]
Non-contributing building.

This small two-story, two-bay, single-pile concrete block building has a flat metal roof and currently serves as a dwelling.

.67 102 Walnut Street, Dwelling, early 20th century
[map 1-31-10.16-104; CRS No. S-4246] Contributing building.

This two-story, three-bay, center-entrance, frame dwelling features a rectangular

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 26

=====

main block and a two-story, gable-roofed rear wing. The house, which faces south, is built on a brick foundation, sheathed in aluminum siding, and covered with an asphalt-shingled, gable roof. Original cornice details have been concealed beneath the aluminum siding. A single interior brick chimney with a corbelled top is located on the east gable. Windows are two-over-two, double-hung sash throughout. A front porch extending the full length of the south facade is built with a concrete floor, square wooden posts, and an asphalt-shingled, hipped roof. The house is in good condition, but its integrity has been somewhat compromised by the use of aluminum siding.

.68 102 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-104; CRS No. S-4246] Non-contributing building.

This is a prefabricated gable-roofed metal storage shed.

.69 104 Walnut Street, Dwelling, early to mid 20th century
 [map 1-31-10.16-105; CRS No. S-4247] Contributing building.

This is a four-bay, one-and-one-half-story Tudor-style frame dwelling. Facing south, the main block of the house is rectangular in plan with a projecting bay on the east facade. The foundation is not visible; the house is sheathed with wood shingles and topped with an asphalt-shingled, gable roof with a boxed cornice. There is a single brick interior chimney located just east of center at the ridge line. Windows consist primarily of six-over-six, double-hung sash with plain board surrounds. The house is in good condition.

.70 104 Walnut Street, Outbuilding, early to mid 20th century
 [map 1-31-10.16-105; CRS No. S-4247] Contributing building.

This is a one-story, frame, gable-roofed outbuilding sheathed in wavy-edge, asbestos shingles. The building is in deteriorated condition.

.71 104 Walnut Street, Garage, late 20th century
 [map 1-31-10.16-105; CRS No. S-4247] Non-contributing building.

This is a one-story concrete block garage with a gable entrance and a metal roof.

.72 106 Walnut Street, Dwelling, late 19th to early 20th century
 [map 1-31-10.16-106] Contributing building.

This two-story, four-bay, single-pile frame house has a rectangular main block with a two-story rear addition. The house, which faces south, is built on a concrete foundation, sheathed in wood shingles, and covered with an asphalt-shingled, gable roof with boxed cornice. A single, interior, corbelled brick chimney is located at the ridge line just west of center. Windows are fitted with six-over-six, double-hung sash; windows and doors are trimmed with plain

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 27

=====

board surrounds. A frame front porch extends the length of the front facade. The porch, which has been enclosed with screens, is covered with an asphalt shingled roof and supported by chamfered wooden posts embellished with turned wooden spindle work in the corners. The house is in good condition.

.73 106 Walnut Street, Outbuilding, late 20th century
[map 1-31-10.16-106] Non-contributing building.

This is a one-story, three-bay, aluminum-sided frame garage built on a concrete block foundation and covered with an asphalt-shingled, gable roof.

.74 106 Walnut Street, Outbuilding, 20th century
[map 1-31-10.16-106] Contributing building.

This is a one-story frame shed with a gable entrance. The building is supported on concrete block piers, sided with vertical boards, and covered with an asphalt shingled roof. A one-story leanto with a single-pitched roof is attached to the south side.

.75 108 Walnut Street, Dwelling, early 20th century
[map 1-31-10.16-107; CRS No. S-4249] Contributing building.

This south-facing, three-bay, two-story frame dwelling has a rectangular main block with symmetrical front facade. There is a one-story, gable-roofed wing attached to the east facade and a one-story screened porch on the north side. Built on a brick foundation, the house is clad in wood shingles and topped with an asphalt shingled, gable roof. There are two brick exterior end chimneys with corbelled tops. Windows, finished with molded board surrounds, are fitted with eight-over-eight, double-hung sash and further embellished with a mixture of louvered and paneled shutters. The front door, which is centrally placed, is trimmed with a pedimented surround ornamented with fluted pilasters and triglyphs. The house is in good condition.

.76 108 Walnut Street, Garage, early 20th century
[map 1-31-10.16-107; CRS No. S-4249] Contributing building.

This is a two-story, frame, gable-roofed, gable-entrance garage. Supported on mixed brick and concrete block piers, the building is sheathed with wood shingles and roofed with corrugated metal. The original swinging wooden doors on the gable entrance are missing.

.77 115 Walnut Street, Dwelling, early 20th century
[map 1-31-10.16-151; CRS No. S-4243] Contributing building.

This north-facing, two-story, six-bay, frame dwelling has a rectangular main block with two rear wings. There is a projecting one-story bay embellished with

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 28

=====

ornamental paired wooden brackets on the northeast end of the front facade. Built on a rusticated concrete block foundation, the house is clad in wood shingles. The roof is a gambrel type with a concave lower pitch; the upper portion of the roof is covered with standing seam metal, while the lower pitch is clad in wood shingles. The roof is further embellished with a molded cornice with returns. There are three chimneys in all; two brick interior chimneys with corbelled tops are located on the gable ends, and a single plain-topped exterior brick chimney is located at the south end of one rear wing. There are three dormers with two-over-two, pointed arch-topped windows on the front facade. Windows are finished with molded board surrounds and fitted with two-over-two, double-hung sash.

.78 115 Walnut Street, Garage, 20th century
 [map 1-31-10.16-151; CRS No. S-4243] Non-contributing building.

This is a one-story, frame, gable-roofed, gable-entrance garage with sliding wooden doors and an asphalt-shingled roof. The building is sheathed in beaded vertical board siding.

.79 115 Walnut Street, Shed, 20th century
 [map 1-31-10.16-151; CRS No. S-4243] Non-contributing building.

This is a one-story, frame, board-and-batten-sided shed with a gable entrance. The building is covered with an asphalt-shingled, gable roof.

.80 111 Walnut Street, Dwelling, late 20th century
 [map 1-31-10.16-153] Non-contributing building.

This is a small, late 20th century, L-shaped frame ranch house with a one-story wing attached. Built on a poured concrete foundation, the house is covered with aluminum siding and topped with an asphalt-shingled, gable roof.

.81 111 Walnut Street, Outbuilding, late 20th century
 [map 1-31-10.16-153] Non-contributing building.

This is a late 20th century, gable-roofed, frame outbuilding.

.82 107 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.16-155; CRS No. S-4244] Contributing building.

This is a two-story, three-bay, single-pile frame dwelling with a rectangular main block, a center entrance, and a two-story rear wing with an exterior concrete block chimney on the south gable. The house faces north. Built on a rusticated concrete block foundation, the original sheathing, cornice, and window and door surrounds have been concealed by a more recent application of aluminum siding. The building is covered with an asphalt-shingled, gable roof. Windows

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 30

=====
weatherboards embellished with fish scale shingles in the side gables as well as the two projecting front dormers. The gable roof is covered with slate shingles and further embellished with ornamental roof cresting as well as a boxed cornice with returns and scrolled brackets on the main block. The two projecting front dormers are also gable-roofed and are ornamented with Palladian windows and fish scale shingles. There are two chimneys; one is a corbelled brick, interior chimney located on the east gable end; the other is an interior brick chimney with corbelled top located on the rear addition at the center of the second story. Windows are fitted primarily with one-over-one, double hung sash throughout, although there is a tripartite leaded glass window on the first floor front facade and Palladian windows in the front dormers. Window trim consists of plain board surrounds. A wraparound frame front porch with tapered wood columns and an ornamental balustrade is supported on a roughly dressed granite foundation. The house is in good condition.

- .87 201 Delaware Avenue, Shed, early 20th century
 [map 1-31-10.16-90] Contributing building.

This is a one-story, weatherboarded frame shed with an asphalt-shingled gable roof. The building is set on brick piers and has a gable entrance.

- .88 210 Delaware Avenue, Garage, early 20th century
 [map 1-31-10.16-90] Contributing building.

This is a one-story, rusticated concrete block shed with an asphalt-shingled gable roof. There are three sliding garage doors in a lateral entrance.

- .89 Lawrence Cahill III Park, Delaware Avenue, Gazebo, late 20th century;
 [map 1-31-10.16-60] Non-contributing building.

This is a 20th century octagonal asphalt-roofed gazebo surrounded by concrete benches laid out in a radiating circular pattern.

- .90 Lawrence Cahill III Park, Delaware Avenue, Outbuilding, late 20th century;
 [map 1-31-10.16-60] Non-contributing building.

This is a modern, prefabricated gable-roofed, aluminum sided frame outbuilding on a concrete block foundation.

- .91 Old Bridgeville Firehouse, 102 William Street, 1911
 [map 1-31-10.16-59; CRS No. S-809] Contributing building.

This two-story, two-bay, gable entrance firehouse is constructed of brick-sized, rusticated concrete blocks and topped with an asphalt-shingled, gable roof. The building, which faces east, is rectangular in plan with projecting corner pilasters and a single brick interior end chimney. Additional ornamentation

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 31

=====
weatherboards embellished with fish scale shingles in the side gables as well as the two projecting front dormers. The gable roof is covered with slate shingles and further embellished with ornamental roof cresting as well as a boxed cornice with returns and scrolled brackets on the main block. The two projecting front dormers are also gable-roofed and are ornamented with Palladian windows and fish scale shingles. There are two chimneys; one is a corbelled brick, interior chimney located on the east gable end; the other is an interior brick chimney with corbelled top located on the rear addition at the center of the second story. Windows are fitted primarily with one-over-one, double hung sash throughout, although there is a tripartite leaded glass window on the first floor front facade and Palladian windows in the front dormers. Window trim consists of plain board surrounds. A wraparound frame front porch with tapered wood columns and an ornamental balustrade is supported on a roughly dressed granite foundation. The house is in good condition.

- .87 201 Delaware Avenue, Shed, early 20th century
 [map 1-31-10.16-90] Contributing building.

This is a one-story, weatherboarded frame shed with an asphalt-shingled gable roof. The building is set on brick piers and has a gable entrance.

- .88 210 Delaware Avenue, Garage, early 20th century
 [map 1-31-10.16-90] Contributing building.

This is a one-story, rusticated concrete block shed with an asphalt-shingled gable roof. There are three sliding garage doors in a lateral entrance.

- .89 Lawrence Cahill III Park, Delaware Avenue, Gazebo, late 20th century;
 [map 1-31-10.16-60] Non-contributing building.

This is a 20th century octagonal asphalt-roofed gazebo surrounded by concrete benches laid out in a radiating circular pattern.

- .90 Lawrence Cahill III Park, Delaware Avenue, Outbuilding, late 20th century;
 [map 1-31-10.16-60] Non-contributing building.

This is a modern, prefabricated gable-roofed, aluminum sided frame outbuilding on a concrete block foundation.

- .91 Old Bridgeville Firehouse, 102 William Street, 1911
 [map 1-31-10.16-59; CRS No. S-809] Contributing building.

This two-story, two-bay, gable entrance firehouse is constructed of brick-sized, rusticated concrete blocks and topped with an asphalt-shingled, gable roof. The building, which faces east, is rectangular in plan with projecting corner pilasters and a single brick interior end chimney. Additional ornamentation

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 32

=====
includes a roofed, balustraded, shingle-sided cupola or bell tower as well as segmental arches over the second story windows and the main entry door. Doors include one pair of wide swinging double doors and a modern wood-panel door on the east (front) side. Built in 1911, the firehouse is listed on the National Register of Historic Places. The building is in good condition and is currently used as a museum.

.92 202 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-61; CRS No. S-4299] Contributing building.

The dwelling at 202 Delaware Avenue is a large, two-story, five-bay, T-plan, frame house with a projecting two-story bay topped with a pedimented cross gable and a two-story rear addition. The house, which faces south, is built on a brick foundation, sheathed in weatherboard and topped with an asphalt-shingled, gable roof with boxed, molded cornice. There are two brick chimneys; one is corbelled at the top and is located at the ridge line in the center of the main block; the other is an interior gable chimney located at the rear of the north addition. Windows, finished with plain board surrounds with molded drip caps, are fitted with one-over-one, double-hung sash throughout. There are arch-topped, one-over-one, double-hung windows in the front-facing cross gable and both side gables at attic level. A frame front porch, located on the left side of the south facade, is topped with an asphalt shingled roof and supported by turned wooden posts; additional ornamentation includes decorative sawn wooden brackets. The house is in fair condition.

.93 202 Delaware Avenue, Garage, late 20th century
 [map 1-31-10.16-61; CRS No. S-4299] Non-contributing building.

This is a one-story, gable-roofed, gable-entrance modern frame garage. Double garage doors provide access to the interior. The building is sheathed in weatherboards and roofed with asphalt shingles.

.94 204 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-62] Contributing building.

This is a rectangular plan, two-story frame house with a center hall, symmetrical fenestration, and a front cross gable embellished with a round-arched, two-over-two, double-hung window. A frame front porch ornamented with scrolled wooden brackets further embellishes the front facade. Separate one-story and two-story wings extend from the rear facade. The dwelling is built on a brick foundation, sheathed with modern aluminum siding, and topped with an asphalt-shingled, gable roof. The aluminum siding does not conceal the original molded boxed cornice and flush molded verge. There are two brick interior chimneys located at the gable ends of the main block; an additional brick interior chimney is located at the end of the rear addition. Windows are fitted with two-over-two, double-hung sash; there are two two-light, fixed-sash windows in each gable at attic level.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 33

=====

The center door is trimmed with molded board surrounds and topped with a one-light, fixed transom. The frame front porch is supported by square, chamfered wooden posts trimmed with scrolled wooden brackets and roofed with asphalt shingles. The house is in good condition, although its integrity has been compromised by the application of aluminum siding.

.95 204 Delaware Avenue, Garage, late 20th century
 [map 1-31-10.16-62] Non-contributing building.

This is a one-story, frame, gable-roofed garage built in two sections, one of which is roofed with a standing seam metal roof.

.96 206 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-63; CRS No. S-4300] Contributing building.

This is a rectangular-shaped, two-story, three-bay, frame building with an asymmetrically-placed front door and a gambrel roof with two full dormers. The house faces south. There is a one-story rear entrance wing projecting from the north facade. Built on a brick foundation, the house is sheathed in aluminum siding and roofed with asphalt shingles. A single brick chimney is centrally-placed at the ridge. The front door is located to the left of the first floor windows; there are two sets of paired windows on the second floor. Windows consist of six-over-one, double-hung sash throughout; there are semicircular fixed windows in the attic gables. A front porch is built on a brick foundation and embellished with a roofed portico. The house is in good condition, but its integrity has been compromised by the application of aluminum siding.

.97 206 Delaware Avenue, Garage, late 20th century
 [map 1-31-10.16-63; CRS No. S-4300] Non-contributing building.

This is a frame, gable-roofed, one-story, gable-entrance garage. Double garage doors in the gable provide access to the interior. The house is covered with an asphalt shingled roof.

.98 302 Delaware Avenue, Dwelling, early to mid 20th century
 [map 1-31-10.16-68; CRS No. S-4301] Contributing building.

The dwelling at 302 Delaware Avenue is a one-and-one-half-story, five-bay, gable-roofed, rectangular plan frame house with a screened front porch and two second-story dormers with exposed rafter ends. The building faces south. It is built on a brick foundation, sheathed in aluminum siding, and roofed with asphalt shingles; the house is further embellished with ornamental triangular brackets at the eaves. A single brick chimney with drip cap is located in the center of the main block. Windows, trimmed with plain board surrounds, are fitted with six-over-one, double hung sash. The center door is furnished with a six-light

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 34

=====

transom. A front screened porch is built on a brick foundation and covered with asphalt shingles.

.99 302 Delaware Avenue, Outbuilding, early 20th century
 [map 1-31-10.16-68; CRS No. S-4301] Contributing building.

This is a one-story, gable-roofed frame outbuilding. Constructed on a rusticated concrete block foundation, the building is sheathed with vertical boards and covered with a metal roof. The primary entrance is on the north gable.

.100 304 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-69; CRS No. S-4302] Contributing building.

This is a one-story frame gable-entrance, gable-roofed bungalow with a front porch extending nearly the full length of the front facade. The building, which faces south, is a three-bay, house with a one-story wing on the north side. Built on a rusticated concrete block foundation, the house is sheathed in aluminum siding and covered with an asphalt shingle roof. Additional ornamentation includes a flush verge board with exposed rafter ends at the eaves of the main block and on the porch. A single corbelled brick chimney is centrally-placed toward the back of the building on the west side. Windows, trimmed with flat board surrounds, are fitted with one-over-one, double-hung sash. The front porch, also erected on a rusticated concrete block foundation, is ornamented with tapered wooden columns that support the porch roof. The house is in good condition, although its integrity has been compromised by the application of aluminum siding.

.101 306 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-70; CRS No. S-4303] Contributing building.

This one-story, gable-entrance bungalow is identical to the house at 304 Delaware Avenue except for the siding; this house retains its original weatherboards, while the dwelling at 304 Delaware has been sheathed in aluminum siding. All other features are identical. This is a one-story frame gable-entrance, gable-roofed bungalow with a front porch extending nearly the full length of the front facade. The building, which faces south, is a three-bay house with a one-story wing on the north side. Built on a rusticated concrete block foundation, the house is sheathed in weatherboards and covered with an asphalt shingle roof. Additional ornamentation includes a flush verge board with exposed rafter ends at the eaves of the main block and on the porch. A single corbelled brick chimney is centrally-placed toward the back of the building on the west side. Windows, trimmed with flat board surrounds, are fitted with one-over-one, double-hung sash. The front porch, also erected on a rusticated concrete block foundation, is ornamented with tapered wooden columns that support the porch roof. The house is in good condition.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 35

- =====
- .102 306 Delaware Avenue, Garage, 20th century
 [map 1-31-10.16-70; CRS No. S-4303] Contributing building.

This is a gable-roofed, frame one-story garage with a leanto shed attached to the west facade. There are two entrance bays on the north gable. The building is sheathed with vertical beaded board siding.

- .103 308 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-71; CRS No. S-4304] Contributing building.

A rectangular, three-bay, two-story, single-pile frame dwelling facing south, this house is built on a brick foundation, clad with asbestos shingles and covered with an asphalt shingled roof with boxed, molded cornice. There is a single brick interior end chimney. An enclosed front porch with jalousie windows extends the length of the front facade. Windows, where visible, are trimmed with plain board surrounds and fitted with one-over-one, double-hung sash. The house is in fair condition, but its integrity has been compromised by the enclosure of the front porch.

- .104 308 Delaware Avenue, Garage, 20th century
 [map 1-31-10.16-71; CRS No. S-4304] Contributing building.

This is a frame, gable-roofed, gable entrance garage. The building has been sheathed in vertical board siding and covered with an asphalt shingle roof. There is a single sliding door in the north gable.

- .105 310 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-72; CRS No. S-4305] Contributing building.

This dwelling consists of a three-bay, two-story, frame main block with a two-story wing and attached one-story leanto located at the rear. The house, which faces south, is built on a rusticated concrete block foundation, clad with wavy-edged asbestos shingles and covered with an asphalt-shingled, gable roof with boxed cornice. A single cement-covered brick exterior chimney is located on the north side of the rear addition. Windows, finished with molded board surrounds, are fitted with six-over-six, double-hung sash. The front door, located to the left of the two first-floor windows, is lit with a one-light fixed transom. A glass-enclosed frame front porch that extends the full length of the front facade is built on a concrete block foundation. The house is in good condition, but its integrity has been compromised by the enclosed front porch.

- .106 310 Delaware Avenue, Garage, late 20th century
 [map 1-31-10.16-72; CRS No. S-4305] Non-contributing building.

This is a one-story, frame, gable-entrance garage on a concrete block foundation with a corrugated metal roof.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 36

Bridgeville Historic District
Sussex County, DE

=====
.107 312 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-73; CRS No. S-4306] Contributing building.

This two-story, four-bay, single-pile frame dwelling consists of a rectangular main block with a two-story wing and an attached one-story leanto located at the rear. The house faces south. The foundation is not visible; the building has been sheathed in aluminum siding and covered with an asphalt-shingled, gable roof. There are two interior brick chimneys on the gable ends. Original cornices as well as window and door surrounds have been concealed beneath aluminum siding. Windows are fitted with one-over-one, double-hung sash throughout. A screened frame porch that extends the full length of the front facade is built on a concrete foundation, supported by wooden posts and roofed with asphalt shingles. The house is in good condition, but its integrity has been compromised by the use of aluminum siding and the screened front porch.

.108 312 Delaware Avenue, Garage, mid 20th century
 [map 1-31-10.16-73; CRS No. S-4306] Non-contributing building.

This is a frame, weatherboarded, gable-roofed, gable entrance garage with a cupola and an asphalt shingled roof.

.109 312 Delaware Avenue, Outbuilding, mid 20th century
 [map 1-31-10.16-73; CRS No. S-4306] Non-contributing building.

This is a frame, weatherboarded, gable-roofed building with an asphalt shingled roof and entrances in both gable and lateral sides.

.110 312 Delaware Avenue, Outbuilding, mid 20th century
 [map 1-31-10.16-73; CRS No. S-4306] Non-contributing building.

This is a frame shed with a single-pitched roof.

.111 302 Emory Street, Dwelling, late 19th century
 [map 1-31-10.15-15.1] Contributing building.

The house at 302 Emory Street consists of a two-story, single-pile, rectangular main block with an aluminum-sided one-story addition extending to the rear. The house, which faces west, was originally a two-bay building; one bay is now concealed by a one-story front porch. Built on a concrete foundation, the house is sheathed with a combination of asbestos shingles and aluminum siding and covered with an asphalt-shingled, gable roof with exposed, rounded rafter feet. A single brick interior chimney with corbelled top is located on the south gable end. The house is in fair condition; its integrity has been somewhat compromised by the addition of aluminum siding.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 37

- =====
- .112 112A/B North Cannon Street, Dwelling, early 20th century
 [map 1-31-10.15-11; CRS No. S-4741] Contributing building.

This is a two-story, two-bay, frame Foursquare house with a pyramidal roof. A one-story leanto has been added to the rear (west) facade; a two-story entrance porch is attached to the north side. Built on a brick foundation, the dwelling is clad in lapped asphalt shingles and covered with an asphalt shingled roof with exposed, scooped rafter ends. Windows, finished with molded board surrounds, are fitted with three-over-one, double-hung sash. The house, which is in fair to poor condition, has been divided into two apartments with two separate entrances.

- .113 113 North Cannon Street, Dwelling, late 19th century
 [map 1-31-10.15-17; CRS No. S-4737] Contributing building.

This house consists of a two-story, two-bay, frame rectangular main block with a street-facing gable entrance, a two-story rear wing, and a one-story leanto addition attached to the front elevation. The house faces west. The foundation material is concealed beneath aluminum textured to simulate rusticated concrete block, the walls are clad in aluminum siding, and the gable roof is covered with asphalt shingles. There is a single brick chimney centrally located at the ridge line. Window trim is concealed beneath aluminum siding; windows throughout are fitted with two-over-two, double-hung sash. An enclosed front porch, sided to match the rest of the house, extends the full length of the front facade. The house is in fair condition; its integrity has been compromised by the enclosure of the front porch as well as the addition of aluminum siding.

- .114 111 North Cannon Street, Dwelling, late 19th century
 [map 1-31-10.15-18; CRS No. S-4736] Contributing building.

This house is nearly identical to the neighboring house at 113 North Cannon Street [map 1-31-10.15-18] except that this building retains its original wood shingle siding and its front porch has not been fully enclosed. The building consists of a two-story, two-bay, rectangular, frame main block with a street-facing gable entrance and a one-story rear wing. The house faces west. The building is raised on brick piers; the walls are clad with wood shingles, and the gable roof is covered with asphalt shingles. A single brick chimney is centrally located at the ridge line. Window trim consists of plain molded surrounds; windows throughout are fitted with two-over-two, double-hung sash except at attic level, where there is a six-over-six, double-hung window. A screened front porch with frame shingle-covered half-wall extends the full length of the front facade. The house is in fair to poor condition, but it has more integrity than the related building at 113 North Cannon Street.

- .115 111 North Cannon Street, Shed, early 20th century
 [map 1-31-10.15-18] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 38

=====

A one-story frame shed with an asphalt-shingled roof appears to be attached to the main block of the house with a breezeway; this building is sheathed with vertical board siding.

- .116 110 North Cannon Street, Dwelling, early 20th century
[map 1-31-10.15-12; CRS No. S-4742] Contributing building.

This is a one-and-one-half-story, five-bay, frame, gable-roofed bungalow with a centrally-placed entrance, a projecting front dormer, and a porch that extends across the entire front facade under the front eave. The house, which faces east, is built on a rusticated concrete block foundation, clad in aluminum siding, and covered with an asphalt shingled, gable roof. The original cornice and window surrounds have been concealed beneath aluminum siding. There is one exterior brick chimney located on the north gable; the chimney top has been removed and the roof eave now extends over the remaining stack. Windows are primarily fitted with six-over-one, double-hung sash. The frame front porch is supported by a rusticated concrete block foundation and tapered wooden columns. The house is in good condition; its integrity has been somewhat compromised by the application of aluminum siding.

- .117 110 North Cannon Street, Shed, late 20th century
[map 1-31-10.15-12; CRS No. S-4742] Non-contributing building.

This is a one-story, gambrel-roofed, prefabricated frame storage building.

- .118 110 North Cannon Street, Shed, late 20th century
[map 1-31-10.15-12; CRS No. S-4742] Non-contributing building.

This is another one-story, gambrel-roofed, prefabricated frame storage building.

- .119 110 North Cannon Street, Shed, late 20th century
[map 1-31-10.15-12; CRS No. S-4742] Non-contributing building.

This is a two-story, gable-roofed, frame storage building partially covered with aluminum siding over weatherboard.

- .120 108 North Cannon Street, Dwelling, early 20th century
[map 1-31-10.15-13; CRS No. S-4743] Contributing building.

This is a frame, two-story, four-bay, Foursquare dwelling with a pyramidal roof. The house is further embellished with a projecting front dormer and paired windows on the second-story front facade. A one-story, leanto addition is attached to the rear facade. Built on a dressed, squared concrete block foundation, the house is walled with asphalt shingles. The roof is covered with asphalt shingles and finished with a boxed, molded cornice. There is a single, centrally-located brick chimney. Windows are finished with molded surrounds and

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 39

=====

fitted with six-over-one, double-hung sash. A roofed frame front porch, built on concrete block supports with straight wooden columns, extends the length of the front facade. The house is in fair condition.

- .121 108 North Cannon Street, Shed, late 20th century
[map 1-31-10.15-13; CRS No. S-4743] Non-contributing building.

This is a prefabricated one-story, gable-roofed frame storage shed.

- .122 109 North Cannon Street, Dwelling, late 19th century
[map 1-31-10.15-20; CRS No. S-4735] Contributing building.

This is a two-story, L-shaped frame building with a two-story rear wing. The house is characterized by a pyramidal-roofed main block, a projecting two-story bay on the front (west) and south elevations, and a projecting two-story flat bay on the west elevation. All projecting bays are furnished with pedimented cross gables. Built on a brick foundation, the house is sided with wavy-edged asbestos shingle and covered with an asphalt shingle roof with a boxed, molded cornice with flush molded verge. A single corbelled brick chimney is located at the apex of the roof. Windows are finished with molded board surrounds and fitted with one-over-one, double-hung sash. The house is in fair condition.

- .123 109 North Cannon Street, Outbuilding, 20th century
[map 1-31-10.15-20; CRS No. S-4735] Non-contributing building.

This is a flat-roofed, frame, rectangular outbuilding sheathed with a combination of aluminum siding and asphalt shingles.

- .124 North Cannon and Mill Streets, Dwelling, late 19th century
[map 1-31-10.15-21; CRS No. S-4734] Contributing building.

This is a two-story, three-bay, frame T-plan building with a two-story rear wing and attached one-story wing. The house faces west. Built on a concrete block foundation, the dwelling is sheathed with asbestos shingles and covered with an asphalt-shingled, gable roof finished with a molded, boxed cornice. No chimneys are visible. Windows are trimmed with molded board surrounds and fitted with two-over-two, double-hung sash. A frame screened porch on the west elevation is supported by turned wooden posts with sawn brackets. The house is in good condition.

- .125 North Cannon and Mill Streets, Shed, late 20th century
[map 1-31-10.15-21; CRS No. S-4734] Non-contributing building.

This is a prefabricated, gambrel-roofed frame shed.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 40

- =====
.126 Mill Street, Dwelling, late 19th to early 20th century
[map 1-31-10.15-22; CRS No. S-4733] Contributing building.

This is a two-story, five-bay, gable-roofed frame house with a one-story rear wing. The house faces south. The main block is rectangular in plan with a projecting bay on the front elevation, a wraparound front porch extending around the south and east elevations, and a projecting two-story bay with a pedimented cross gable on the east elevation. Built on a concrete block foundation, the building has been sheathed in aluminum siding and covered with an asphalt shingled roof with molded boxed cornice. There is a central brick chimney as well as a newer end chimney built of stacked concrete blocks. Windows are primarily one-over-one, double-hung sash. The wraparound front porch is supported by turned wooden posts and further embellished with a turned wooden balustrade. The house is in good condition, but its integrity has been somewhat compromised by the concrete block chimney and the use of aluminum siding.

- .127 Mill Street, Shed, late 20th century
[map 1-31-10.15-22; CRS No. S-4733] Non-contributing building.

This is a one-story, frame, prefabricated shed with a gable entrance.

- .128 Mill Street, Outbuilding, late 20th century
[map 1-31-10.15-22; CRS No. S-4733] Non-contributing building.

This is a one-story, frame, prefabricated, gambrel-roofed dog kennel.

- .129 203 Delaware Avenue, Dwelling, early to mid 20th century
[map 1-31-10.16-89; CRS No. S-4284] Contributing building.

This is a two-story, three-bay, frame dwelling that faces north. The main block is rectangular in plan and features a center entrance flanked by recessed bays. There is a one-story frame addition on the east gable that forms a separate apartment. Built on a brick foundation, the house is sided with asbestos shingles and covered with an asphalt-shingled, gable roof. The cornice and window surrounds have been concealed beneath aluminum siding. There is a single brick exterior end chimney on the north gable. Windows throughout are fitted with six-over-six, double-hung sash. The house is in good condition.

- .130 203 Delaware Avenue, Garage, mid 20th century
[map 1-31-10.16-89; CRS No. S-4284] Non-contributing building.

This is a large, three-bay, one-story frame garage with a single-pitched roof.

- .131 205 Delaware Avenue, Dwelling, early 20th century
[map 1-31-10.16-88; CRS No. S-4283] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 41

=====

This is a north-facing, rectangular-plan, two-story, three-bay, gable-roofed frame dwelling with an asymmetrically-placed front door. A screened porch with balustraded porch above is attached to the west gable. Built on a brick foundation, the house is sheathed with weatherboards and roofed with asphalt shingles. Additional ornamentation includes a boxed, molded cornice with returns and a flush molded verge. A single brick exterior end chimney is located on the east gable. The front door, which is ornamented with a broken arch pediment with flanking pilasters, is located to the right of the two first floor windows; the second story windows are placed directly over the first story openings. Windows are finished with molded board surrounds and fitted with six-over-one, double-hung sash. A screened porch built on a brick foundation and supported by square wooden columns is located on the west gable. The house is in good condition.

- .132 205 Delaware Avenue, Garage, late 20th century
 [map 1-31-10.16-88; CRS No. S-4283] Non-contributing building.

This is a one-story, two-bay, gable-roofed frame garage.

- .133 205 Delaware Avenue, Shed, 20th century
 [map 1-31-10.16-88; CRS No. S-4283] Contributing building.

This is a one-story, frame storage shed with an asymmetrically-pitched, asphalt-shingled roof.

- .134 207 Delaware Avenue, Dwelling, early to mid 20th century
 [map 1-31-10.16-87; CRS No. S-4282] Contributing building.

This is a two-story, frame dwelling with a center entrance, two flanking projecting first-floor bays and a one-story addition on the west gable. The house faces north, is built on a brick foundation, and is covered with stucco. The gable roof is covered with asphalt shingles and finished with a molded, boxed cornice with returns. There are two brick end chimneys. Windows are finished with plain board surrounds and fitted with six-over-one, double-hung sash. A frame pedimented portico extends over the front door. The house is in good condition.

- .135 207 Delaware Avenue, Garage, early 20th century
 [map 1-31-10.16-87; CRS No. S-4282] Contributing building.

This is a one-story, hip-roofed, concrete block garage with ornamental pebble-form concrete block corner quoins. There are three entrance bays fitted with sliding wooden doors.

- .136 207 Delaware Avenue, Shed, early 20th century
 [map 1-31-10.16-87; CRS No. S-4282] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 42

=====

This is a one-story frame storage shed with a single-pitched roof. The building is sheathed with weatherboards.

.137 201 Laws Street, Dwelling, late 19th century
 [map 1-31-10.16-86; CRS No. S-4724] Contributing building.

This is a two-story, four-bay, rectangular plan, gable-roofed frame dwelling. The asymmetrical arrangement of window and door openings and the character of the window surrounds suggest that its present form may have resulted from a series of building campaigns. The house, which faces west, is built on a brick foundation, sheathed with wooden shingles and covered with an asphalt-shingled, gable roof finished with a molded boxed cornice with returns. There is a single corbelled brick interior chimney located at the ridge. Windows are six-over-one, double-hung sash throughout. The original molded wood surrounds on the gables have been replaced on the front facade. A covered portico supported on a brick foundation is embellished with scrolled iron supports. The house is in fair condition.

.138 201 Laws Street, Garage, mid 20th century
 [map 1-31-10.16-86; CRS No. S-4724] Non-contributing building.

This is a one-story, gable-roofed frame garage sheathed with wavy-edged asbestos shingles and covered with an asphalt shingled roof.

.139 301 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-84; CRS No. S-4281] Contributing building.

This two-story, three-bay, frame house is rectangular in plan with symmetrical fenestration, a front-facing cross gable, and a front porch that extend the full length of the front facade. The building faces north. There are two two-story rear wings, one with a one-story leanto addition attached to it. There is a porch wing located on the west gable. Built on a foundation that has been covered with concrete, the house is clad in wooden shingles and covered with an asphalt shingled, gable roof. Additional ornamentation includes a boxed, molded cornice with a flush beaded verge, fish scale shingles in the front gable and exposed, Stick-style trusses in the side gables. The two chimneys, both brick, are located on the exterior of the gable of the main block and at the rear of the two-story addition, respectively. Windows, finished with molded board surrounds, are fitted with two-over-two, double-hung sash throughout. There is a two-over-two window with a pointed-arch top located in the front cross gable. The center door is ornamented with a stained glass overhead transom. A frame porch with a concrete floor extends the entire length of the front facade; the porch is supported by squared wooden posts with decorative turned spindlework corner brackets. The house is in good condition. The adjacent lot is empty.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 43

Bridgeville Historic District
Sussex County, DE

=====

.140 305 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-81; CRS No. S-4280] Contributing building.

This is a two-story, three-bay, frame dwelling with a center entrance, symmetrical window and door placement, and a front-facing cross gable. The house faces south. Built on a brick foundation, the house is sheathed in weatherboards and topped with an asphalt shingled, gable roof with boxed molded cornice with returns and a flush molded verge. A single, cement-covered brick interior end chimney is located on the west gable. Windows are embellished with flat board surrounds topped with molded drip caps and are fitted with two-over-two, double-hung sash throughout. A frame front porch has been screened; the asphalt shingled porch roof is supported by turned wooden posts and ornamented with sawn wooden corner brackets. The house is in good condition, although the screened porch diminishes its overall integrity somewhat.

.141 307 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.16-79; CRS No. S-4279] Contributing building.

This is a late 19th century two-story, four-bay frame dwelling with a modified cruciform plan, a covered front portico and a projecting two-story bay on the front elevation. The building faces north, is built on a brick foundation, sheathed in asbestos shingles and covered with an asphalt-shingled, gable roof. The roof features a molded boxed cornice and a molded flush verge with decorative scrollwork and pendant drops under the eaves of a projecting pedimented cross gable. Windows and doors are trimmed with molded board surrounds; windows throughout are fitted with one-over-one, double-hung sash. The gable-roofed front portico is covered with asphalt shingles and supported by square wooden posts. The house is in good condition.

.142 307 Delaware Avenue, Garage, 20th century
 [map 1-31-10.16-79; CRS No. S-4279] Non-contributing building.

This is a one-and-one-half-story, weatherboarded frame garage with a gable entrance. The building is covered with an asphalt shingled gable roof and has two windows on the front gable at attic level.

.143 311 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.16-78; CRS No. S-4279] Contributing building.

This is an early 20th century two-story, two-bay Foursquare frame dwelling with a pyramidal roof and projecting roof dormers. The building, which faces north, is built on a brick foundation, sheathed in aluminum siding, and topped with an asphalt-shingled roof with molded, boxed cornice and flush verge. Dormers are located in the center of each side of the pyramidal roof; a single corbelled brick chimney is situated at the center of the roof. Windows, finished with plain board surrounds, are fitted with one-over-one, double-hung sash. A frame

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 44

porch with a concrete block foundation and square wooden porch posts extends the full length of the front facade. The house is in fair condition; its integrity has been somewhat compromised by the application of aluminum siding.

- .144 311 Delaware Avenue, Shed, early 20th century
[map 1-31-10.16-78; CRS No. S-4279] Contributing building.

This is a one-story frame shed with asymmetrically-pitched metal roof, south entrance, and weatherboard siding.

- .145 313 Delaware Avenue, Dwelling, late 19th century
[map 1-31-10.16-77; CRS No. S-4277] Contributing building.

This is a late-19th century, two-story, three-bay frame dwelling with symmetrical front facade, front facing cross gable, and a porch that spans the full length of the front facade. The house faces north, is built on a brick foundation, sheathed from wall to cornice with aluminum siding, and roofed with asphalt shingles. Cornice and eave details have been concealed beneath the aluminum siding. There are two brick interior end chimneys on the east and west gables; one has a corbelled top. Original window and door trim has been concealed beneath the aluminum siding. The frame front porch, which has been fitted with screens, is built on a concrete block foundation and supported by square wooden posts. The house is in good condition, but its integrity has been compromised by the application of aluminum siding.

- .146 313 Delaware Avenue, Shed, 20th century
[map 1-31-10.16-77; CRS No. S-4277] Contributing building.

This is a one-story frame shed with a gable roof and gable entrance. Sheathed in asbestos siding, the shed is covered with an asphalt-shingled roof.

- .147 313 Delaware Avenue, Shed, late 20th century
[map 1-31-10.16-77; CRS No. S-4277] Non-contributing building.

This is a one-story frame shed with an asymmetrical gable roof. Sheathed in asbestos siding, the shed is covered with an asphalt shingle roof.

- .148 315 Delaware Avenue, Dwelling, late 19th century
[map 1-31-10.16-76; CRS No. S-4276] Contributing building.

This is a two-story, four-bay, T-plan frame dwelling with front and side-facing pedimented cross gables and a wraparound front porch embellished with sawn ornamental corner brackets and turned wooden posts. There is also a second-story balustraded porch located directly above the first floor porch. The house, which has been extended on the east gable elevation with a modern one-story aluminum-sided wing, faces north. Built on a brick foundation and sheathed with asbestos

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 45

shingles, the dwelling is covered with an asphalt-shingled, gable roof with a molded, boxed cornice and molded verge. It is ornamented with two paired arch-topped one-over-one, double-hung sash windows in the front cross gable, a single arch-topped window in the side gables, and sawn scalloped trim with turned pendant drops under the projecting cross gables. A single, corbelled brick chimney is centrally located. Windows are finished with flat board surrounds with molded drip caps and fitted with one-over-one, double-hung sash throughout. There is a single, lozenge-shaped multipaned stained glass window on the east facade. The front door, which is located in the far left bay, is a wood panel door with an elliptical glass pane above. The frame front porch wraps around the north and west sides and is supported by turned wooden posts; the porch is further embellished with a turned balustrade with sawn corner brackets. The house is in good condition.

.149 315 Delaware Avenue, Garage, early 20th century
 [map 1-31-10.16-76; CRS No. S-4276] Contributing building.

This is a one-story frame garage with two garage-sized bays in the lateral entrance. The building is weatherboarded and covered with an asphalt shingled gable roof.

.150 Lot 80, Pine Alley, Warehouse, early 20th century
 [map 1-31-10.16-80] Non-contributing building.

This is a large, gable-roofed frame building with a concrete block addition to the west and a series of metal shed additions to the right. The main block is covered with an asphalt shingled gable roof; the metal addition is covered with a metal roof. The foundation is not visible; the center section is sheathed in vertical boards. While the warehouse has a late 20th century exterior appearance, interior details indicate a late-19th century core. The building is in good to fair condition; its integrity has been compromised by the addition of the two wings.

.151 Lot 82, Pine Alley, Shed, late 20th century
 [map 1-31-10.16-82] Non-contributing building.

This is a gable-roofed frame garage with a gable entrance. Sheathed in aluminum siding, the building is currently used for storage.

.152 Lot 82, Pine Alley, Shed, late 20th century
 [map 1-31-10.16-82] Non-contributing building.

This is a gable-roofed frame garage with an asphalt shingled roof and a lateral entrance. Sheathed in vertical siding, this building is used for storage.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 46

=====

.153 202 Laws Street, Funeral Home, late 20th century
 (Hardesty Funeral Home); [map 1-31-10.16-85] Non-contributing
 building.

This is a one-story, three-bay brick building with a flat roof and a two-story front entry portico with brick pillars. The building, which faces east, is lit by two large paired windows located at either side on the centrally-placed front door.

.154 401 Delaware Avenue, Dwelling, early 20th century
 [map 1-31-10.15-58; CRS No. S-4275] Non-contributing building.

This is an early 20th century, Foursquare frame dwelling that has been heavily modernized and fully encased in aluminum siding. The two-story, two-bay house, which faces north, features a fully enclosed front porch, a rusticated concrete block foundation, and a pyramidal roof. Original cornice details and window and door surrounds are concealed beneath aluminum siding; windows are one-over-one, double-hung sash throughout. The front porch has a brick half-wall below and aluminum siding above. The house is in excellent condition, but its integrity has been thoroughly compromised by later alterations.

.155 401 Delaware Avenue, Playhouse, late 20th century
 [map 1-31-10.15-58; CRS No. S-4275] Non-contributing building.

This is a raised, frame, prefabricated playhouse with an asphalt-shingled, gable roof.

.156 401 Delaware Avenue, Shed, late 20th century
 [map 1-31-10.15-58; CRS No. S-4275] Non-contributing building.

This is a frame prefabricated storage shed with an asphalt-shingled, gable roof.

.157 403 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.15-57; CRS No. S-4274] Contributing building.

This is a rectangular plan, three-bay, two-story, single-pile frame dwelling with a modern enclosed front porch, center entry, and a rear wing. The building, which faces north, is built on a brick foundation, sheathed in aluminum siding and covered with an asphalt-shingled, gable roof. Window and door surrounds as well as cornice and verge details are concealed beneath the envelope of aluminum siding. A single exterior end chimney, built of concrete block, is located on the west gable. Windows are fitted with one-over-one, double-hung sash throughout. The front porch, which is covered with an asphalt shingled gable roof, is enclosed and sheathed in aluminum siding. The house is in good condition, but its integrity has been compromised by the addition of aluminum siding and the enclosure of the front porch.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 47

- =====
- .158 403 Delaware Avenue, Garage, mid to late 19th century
 [map 1-31-10.15-57; CRS No. S-4274] Contributing building.

This is a one-story, gable-roofed, gable entrance, frame garage in deteriorated condition. The building is sheathed in asphalt shingles over vertical board siding; the roof is covered with asphalt shingles over wood shingles. The size of some exposed framing members suggest a timber frame core.

- .159 405 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.15-56; CRS No. S-4273] Contributing building.

This dwelling is a two-story, two-bay gable-roofed building with a two-story rear wing with attached one-story rear wing. An enclosed front porch extends across the entire front facade. The house faces north, is built on a dressed, squared concrete block foundation, and is sheathed with weatherboard. The roof is covered with asphalt shingles and has a flat verge. Windows are trimmed with molded board surrounds and fitted with three-over-one, double-hung sash. The enclosed frame front porch, which is also built on a concrete block foundation, has been fitted with jalousie windows. Although the house is in good condition, its integrity has been compromised by the enclosure of the front porch.

- .160 405 Delaware Avenue, Shed, early 20th century
 [map 1-31-10.15-56; CRS No. S-4273] Contributing building.

This is a one-story frame shed with an asphalt shingled gable roof and a gable entrance; the building is sheathed in narrow vertical boards.

- .161 405 Delaware Avenue, Garage, mid 20th century
 [map 1-31-10.15-56; CRS No. S-4273] Non-contributing building.

This one-story frame garage also has an asphalt shingled gable roof and a gable entrance; the building faces south and is sheathed in narrow beaded vertical boards.

- .162 407/407B Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.15-54, 55; CRS No. S-4272] Non-contributing building.

This late 19th century, two-story frame dwelling with front-facing cross gable has been divided down the middle into two separate apartments; each half of the building is maintained separately. The house, which faces north, was designed as a three-bay, building. Built on a brick foundation, the building is sheathed in asbestos shingles on the left and vertical board siding on the right. The entire roof has been covered with asphalt shingles. The roof is further ornamented with a flush verge. There are three chimneys, one interior corbelled brick end chimney is located on the west gable; two additional exterior concrete block chimneys are located on the west and east gables. Window trim consists of molded

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 48

board surrounds; windows are fitted with two-over-two, double-hung sash. The original arch-topped window in the front gable has been covered over. A frame and concrete porch extends across the left front facade. The house is in poor condition and has lost integrity as a result of the divisions and alterations noted above.

- .163 407/407B Delaware Avenue, Shed, late 20th century
 [map 1-31-10.15-54, 55; CRS No. S-4272] Non-contributing building.

This is a one-story, gable-roofed, prefabricated metal shed.

- .164 407/407B Delaware Avenue, Shed, late 20th century
 [map 1-31-10.15-54, 55; CRS No. S-4272] Non-contributing building.

This is a one-story, gable-roofed, aluminum-sided frame shed roofed with asphalt shingles.

- .165 407/407B Delaware Avenue, Shed, 20th century
 [map 1-31-10.15-54, 55; CRS No. S-4272] Contributing building.

This is a one-story, gable-roofed, gable entrance frame shed roofed with asphalt shingles and sheathed with vertical board siding.

- .166 409 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.15-53; CRS No. S-4271] Contributing building.

This gable roofed frame dwelling, built in an overall rectangular shape, is characterized by a symmetrical arrangement of bays, a center entrance, and a front-facing cross gable. The two-story, three-bay, single-pile house, which faces north, is extended by a two-story rear wing that dates to the construction of the main block and two later one-story wings located on the south and west sides of the house. The building is constructed on a brick foundation and is sheathed with jaggedly laid asbestos shingles. Additional ornamentation includes a round arched window in the front cross gable. The roof is covered with asphalt shingles; there is a molded boxed cornice with returns. The front door is centrally placed. Windows are trimmed with flat molded surrounds with molded drip caps and fitted with two-over-two, double-hung sash. An open porch with a concrete block foundation and plain, unfinished wood posts extends the full length of the front facade. The house is in good to fair condition; its integrity has been somewhat compromised by the addition of the front porch.

- .167 409 Delaware Avenue, Shed, early 20th century
 [map 1-31-10.15-53; CRS No. S-4272] Contributing building.

This is a one-story, frame, gable-roofed shed sheathed in vertical board siding and covered with a corrugated metal roof.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 49

=====

- .168 409 Delaware Avenue, Garage, early 20th century
 [map 1-31-10.15-53; CRS No. S-4271] Contributing building.

This is a one-story, frame, gable-roofed, gable entrance garage sheathed in vertical beaded board siding.

- .169 411 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.15-52; CRS No. S-4270] Contributing building.

A two-story, three-bay, single-pile gable roofed frame dwelling with a front cross gable and symmetrical fenestration, this house faces north. The main block has been extended with the addition of two rear wings. Built on a brick foundation, the dwelling is sheathed in jaggedly lapped, simulated wood-grain asphalt shingles and covered with an asphalt shingled roof with boxed, molded cornice. Two brick interior chimneys are located on the gable ends. The front door is centrally placed; windows are trimmed with molded board surrounds and fitted with two-over-two, double-hung sash. The house is in fair to poor condition.

- .170 411 Delaware Avenue, Outbuilding, late 20th century
 [map 1-31-10.15-52; CRS No. S-4270] Non-contributing building.

This is a small gable-roofed plywood dog house.

- .171 413 Delaware Avenue, Dwelling, late 20th century
 [map 1-31-10.15-51] Non-contributing building.

This is a late 20th century, one-story, four-bay, frame gable-roofed ranch house clad in aluminum siding. The house is constructed on a concrete block foundation and roofed with asphalt shingles. The windows are modern one-over-one, double-hung sash.

- .172 415 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.15-50; CRS No. S-4269] Contributing building.

This two-story, three-bay, gable-roofed house is characterized by a two-story, rectangular main block with a front cross gable, a symmetrical arrangement of bays, and a two-story rear wing. The house faces north, is built on a brick foundation, and is clad with wavy-edged asbestos shingles. There is a two-over-two, double-hung pointed arch-topped window in the front cross gable; there are two fixed four-light sash windows in each end gable. The roof, covered with asphalt shingles, is finished with a molded boxed cornice. There are two interior gable end chimneys; the one on the east gable is corbelled brick; the chimney on the west gable is built of concrete block. Windows, finished with molded board surrounds, are fitted with two-over-two, double-hung sash. A frame porch built on a concrete block foundation and supported by turned wooden posts

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 50

Bridgeville Historic District
Sussex County, DE

ornamented with sawn scrolled corner brackets extends the length of the front facade. The house is in fair condition.

.173 417 Delaware Avenue, Dwelling, late 19th century
 [map 1-31-10.15-49; CRS No. S-4268] Contributing building.

This two-story house is built with its gable facing the street; the building is further distinguished by an angled front entrance at the street corner and a cross gable on the lateral side facing Railroad Avenue. The two-story, two-bay frame house faces north-northwest. Built on a brick foundation, the dwelling is sided with asbestos shingles on the first story and wood shingles with several layers of fish scale shingles on the second story and the gables. The asphalt-shingled, gable roof is finished with a molded, boxed cornice with molded verge. Windows, trimmed with flat wooden surrounds and molded drip caps, are primarily one-over-one, double-hung sash, although there is a single two-over-two double-hung window in the cross gable facing Railroad Avenue; there is also a single, double-hung window with plain lower pane and patterned upper pane facing Delaware Avenue. The house is in good condition.

.174 417 Delaware Avenue, Outbuilding, early 20th century
 [map 1-31-10.15-49; CRS No. S-4268] Contributing building.

This is a one-story frame outbuilding with an asymmetrically-pitched roof. The building faces Railroad Avenue. On the south facade, there are three sliding wooden garage doors. On the west facade, there is a first floor entry door as well as a second-story loading door flanked by two earlier sealed openings. Built on a rusticated concrete block foundation and sheathed with vertical board siding, the building is covered with a corrugated metal roof.

.175 417 Delaware Avenue, Shed, late 20th century
 [map 1-31-10.15-49; CRS No. S-4268] Non-contributing building.

This is a late 20th century, prefabricated one-story frame storage shed with a gable entrance and a gambrel roof. The building is sheathed in vertical board siding.

.176 Former Water Works, Railroad Avenue, Office, early 20th century [map
 1-31-10.15-68; CRS No. S-4310] Contributing building.

Constructed in 1909 as the office of the municipal water company and later converted to the headquarters of the local police department, this is a one-story, hip-roofed frame building with a one-story leanto attached to the south facade. The building faces west, is built on a concrete block foundation, and sheathed with aluminum siding. The roof is covered with asphalt shingles. There is a single prefabricated metal stove chimney. Windows are fitted with late 20th century double-hung sash.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 51

- =====
- .177 Former Water Works, Railroad Avenue, Outbuilding, late 20th century;
[map 1-31-10.15-68; CRS No. S-4310] Non-contributing building.

This is a late 20th century gable-roofed metal one-story outbuilding.

- .178 northeast corner Railroad Avenue and Walnut Street, Dwelling, early
20th century; [map 1-31-10.15-69; CRS No. S-4311] Contributing
building.

This is a pyramidal-roofed Foursquare house built entirely of rusticated concrete block; it is further distinguished by a rusticated concrete block porch that extends the full length of the front facade as well as a front-facing dormer fitted with paired windows and topped with an overhanging roof. A two-story, three-bay house with a one-story frame wing on a rusticated concrete block foundation, the building faces west. The overhanging roof is covered with asphalt shingles and finished with a flush verge; the underside of the roof is finished with narrow beaded boards. There are three dormers, each with paired nine-paned, fixed-sash windows. Windows throughout are trimmed with plain board surrounds and fitted with nine-over-one, double-hung sash. The front door is located in the leftmost bay. A front porch, built with a rusticated concrete block foundation and pillars, is ornamented with an unusual rusticated concrete block balustrade. The house is in good condition, and is a fine example of rusticated concrete block construction.

- .179 northeast corner Railroad Avenue and Walnut Street, Garage, early 20th
century [map 1-31-10.15-69; CRS No. S-4311] Contributing building.

This is a one-story, gable-roofed frame garage with two entrance bays on a lateral side. The building is sheathed in vertical board siding and roofed with asphalt shingles. A rusticated concrete block leanto addition on the west gable is similar in style to the main house, suggesting that this building dates to the construction of the house. The building is in deteriorated condition.

- .180 northeast corner Railroad Avenue and Walnut Street, Garage, late 20th
century; [map 1-31-10.15-69; CRS No. S-4311] Non-contributing
building.

This is a one-story, flat-roofed garage built of concrete blocks.

- .181 northeast corner Railroad Avenue and Walnut Street, Garage, late 20th
century; [map 1-31-10.15-69; CRS No. S-4311] Non-Contributing
building.

This is a large one-story gable-roofed garage built of a mixture of frame and concrete blocks. Roofed with asphalt shingles, it is partially sheathed on the upper level with asbestos shingles.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 52

.182 northeast corner Railroad Avenue and Walnut Street, Outbuilding, early to mid 20th century; [map 1-31-10.15-69; CRS No. S-4311] Contributing building.

This is a small privy-sized frame building with a single-pitch asphalt shingle roof.

.183 416 Walnut Street, Dwelling, late 19th century [map 1-31-10.15-67; CRS No. S-4267] Contributing building.

This is a late-19th century two-story, three-bay, gable-roofed frame dwelling with a center hall, a symmetrical arrangement of bays, and a two-story frame rear wing. Built on a brick foundation, the house is sided with asbestos shingles and topped with an asphalt-shingled roof with molded, boxed cornice. There are two interior brick chimneys, one is corbelled and is located in the center of the main block at the ridge; the second, also built of brick, is located at the end of the rear wing. Windows are finished with flat surrounds with molded drip caps and fitted with two-over-two, double-hung sash. A frame porch, extending nearly the length of the front facade, is supported by turned wooden posts embellished with sawn scrolled corner brackets. The house is in good condition.

.184 416 Walnut Street, Outbuilding, early 20th century [map 1-31-10.15-67; CRS No. S-4267] Contributing building.

This is a one-story, gable-roofed frame building with a gable entrance. The roof is covered with asphalt shingles.

.185 416 Walnut Street, Outbuilding, early 20th century [map 1-31-10.15-67; CRS No. S-4267] Contributing building.

This is a second one-story frame building with a gable entrance and a gable roof covered with asphalt shingles.

.186 414 Walnut Street, Dwelling, early 20th century [map 1-31-10.15-66; CRS No. S-4266] Contributing building.

This is an early 20th century two-story, two-bay, frame house with its gable entrance facing the street. Extending the house is a two-story rear wing with two one-story rear wings attached. The foundation is built of brick-sized rusticated concrete block; the house is sheathed in aluminum siding and covered with an asphalt-shingled, gable roof. Cornice details as well as any details at verge or eaves have been concealed by a complete application of aluminum siding. An enclosed frame front porch conceals the arrangement of bays on the first floor. Windows consist of two-over-two, double-hung sash throughout. The house is in good condition, but its integrity has been compromised by the addition of

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 53

Bridgeville Historic District
Sussex County, DE

aluminum siding as well as the enclosure of the front porch. There are no outbuildings.

- .187 412 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.15-65; CRS No. S-4265] Contributing building.

This early 20th century dwelling is identical in plan to its neighbor at 414 Walnut with the exception of the enclosed front porch; still, because this building is covered with a recent application of aluminum siding, it has lost some integrity. An early 20th century two-story, two-bay, frame house with its gable entrance facing the street, the house has been extended by a two-story rear wing with two one-story rear wings attached. The foundation is built of brick-sized rusticated concrete block; the house is sheathed in aluminum siding and covered with an asphalt-shingled, gable roof. Cornice details as well as any details at verge or eaves have been concealed by a complete application of aluminum siding. A frame porch with turned wooden supports extends across the entire front facade. The house is in fair condition.

- .188 412 Walnut Street, Outbuilding, late 20th century
 [map 1-31-10.15-65; CRS No. S-4265] Non-contributing building.

This is a one-story, frame building with an asphalt-shingled gable roof and a gable entrance.

- .189 412 Walnut Street, Garage, late 20th century
 [map 1-31-10.15-65; CRS No. S-4265] Non-contributing building.

This is a one-story frame garage with an asphalt shingled gable roof. The building is sheathed in horizontal board siding; there are two entrance bays in the north gable.

- .190 410 Walnut Street, Dwelling, late 19th century
 [map 1-31-10.15-64; CRS No. S-4264] Contributing building.

This two-story, three-bay frame building is characterized by a gable entrance that faces the street and a frame porch that extends the full length of the front facade. The house is extended by a two-story rear wing with two attached one-story rear wings. Built on a foundation of brick-sized concrete blocks, the house is sheathed in asbestos shingles and topped with an asphalt shingled gable roof with a flat boxed cornice. A single brick chimney is located at the center of the building at the ridge. Windows are finished with flat surrounds with molded drip caps and are fitted with two-over-two, double-hung sash. A frame front porch, built on a brick and concrete foundation, is supported by turned wooden posts ornamented with sawn scrolled corner brackets. The house is in fair condition.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 54

.191 410 Walnut Street, Outbuilding, 20th century
[map 1-31-10.15-64; CRS No. S-4264] Non-contributing building.

This is a one-story, gable-roofed frame shed sided and roofed with asphalt shingles.

.192 408 Walnut Street, Dwelling, late 19th century
[map 1-31-10.15-63; CRS No. S-4263] Contributing building.

This is a rectangular-plan, two-story, three-bay, frame house with an enclosed front porch and a two-story rear wing with a one-story wing attached. The house faces south. The foundation is constructed of brick-sized concrete blocks; the house is sheathed in an envelope of aluminum siding which also conceals the cornice, verge, and window and door trim. There are two chimneys; one is an interior chimney located at the east end of the rear addition; the other is in an exterior location at the end of the one-story rear addition. Both are built of concrete block. Windows are fitted with one-over-one, double-hung sash. The enclosed frame front porch, which extends the full length of the south facade, is also sheathed in aluminum siding. Although the house is in good condition, its integrity has been compromised by the enclosure of the front porch as well as the application of aluminum siding.

.193 408 Walnut Street, Garage, early 20th century
[map 1-31-10.15-63; CRS No. S-4263] Contributing building.

This is a one-story frame garage sheathed in vertical board siding and covered with an asphalt-shingled, gable roof.

.194 408 Walnut Street, Shed, early 20th century
[map 1-31-10.15-63; CRS No. S-4263] Contributing building.

This is a one-story, frame shed sheathed in vertical board siding; it is also covered with an asphalt-shingled gable roof.

.195 406 Walnut Street, Dwelling, early 20th century
[map 1-31-10.15-62; CRS No. S-4262] Contributing building.

This early 20th century dwelling is a frame Foursquare plan building with a hipped roof, a projecting front dormer, and a porch extending the length of the front facade. The house, which faces south, is a two-story, two-bay building with a one-story rear wing. Built on a rusticated concrete block foundation, it is sheathed in wavy-edged asbestos shingles and roofed with asphalt shingles. The roof is further finished with a molded cornice and narrow beaded board siding under the eaves. Windows are trimmed with molded board surrounds and fitted with one-over-one, double-hung sash. The front porch is also built on a rusticated concrete block foundation and topped with an asphalt shingled roof; it is

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 55

supported with square tapered wooden columns. The house is in good condition.

- .196 406 Walnut Street, Garage, late 20th century
[map 1-31-10.15-62; CRS No. S-4262] Non-contributing building.

This is a one-story, prefabricated frame garage with a gable entrance. The building is sheathed in vertical board siding and covered with an asphalt-shingled gable roof.

- .197 406 Walnut Street, Shed, late 20th century
[map 1-31-10.15-62; CRS No. S-4262] Non-contributing building.

This is a one-story, prefabricated frame storage shed sheathed in vertical board siding and covered with an asphalt-shingled gable roof.

- .198 406 Walnut Street, Outbuilding, late 20th century
[map 1-31-10.15-62; CRS No. S-4262] Non-contributing building.

This is a weatherboarded frame, one-story outbuilding that appears to be used as a club house or play house; it has a gable roof covered with asphalt shingles.

- .199 406 Walnut Street, Shed, late 20th century
[map 1-31-10.15-62; CRS No. S-4262] Non-contributing building.

This is a frame storage shed sheathed in vertical board siding and topped with an asymmetrically-pitched, asphalt-shingled gable roof.

- .200 404 Walnut Street, Dwelling, early 20th century
[map 1-31-10.15-61; CRS No. S-4261] Contributing building.

Built in the early 20th century, this is a Foursquare frame house with a pyramidal, asphalt-shingled roof, a projecting pedimented two-story bay on the west side and a front porch that extends across the entire south facade. The house is a two-story, two-bay building constructed on a foundation of brick-sized concrete blocks and sheathed with wavy-edge asbestos shingles. There is a one-story rear wing. The roof features a molded cornice with molded verge. The single brick chimney is centrally located at the peak of the roof. Windows, primarily fitted with one-over-one, double-hung sash, are trimmed with molded board surrounds. There is a single lozenge-shaped multipaned stained glass window in the east gable. The front porch is screened and partially enclosed; like the house, it is built on a foundation of brick-sized concrete blocks. The porch is supported on turned wooden posts embellished with sawn scrolled corner brackets. The house is in good condition.

- .201 404 Walnut Street, Shed, late 20th century
[map 1-31-10.15-61; CRS No. S-4261] Non-contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 56

=====

This is a one-story, prefabricated corrugated metal storage shed with a gable roof.

.202 402 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.15-60; CRS No. S-4260] Contributing building.

This is an early 20th century, one-story, three-bay rectangular frame dwelling with a steeply-pitched gable roof, overhanging front and back eaves, and a large gabled front dormer. The building, which faces south, has been enlarged with a one-story rear wing. Built on a concrete block foundation, the house is sided with asbestos shingles and covered with an asphalt-shingled gable roof embellished with a flat verge and exposed rafter ends. The undersides of the eaves are finished with narrow beaded siding. A single cement-covered brick chimney is centrally located at the ridge line. Windows are trimmed with flat board surrounds and fitted with one-over-one, double-hung sash. The front porch, which extends approximately three quarters of the length of the south facade, is built on a concrete block foundation; it has a wooden floor and scrolled iron supports. The house is in fair condition.

.203 402 Walnut Street, Shed, late 20th century
 [map 1-31-10.15-60; CRS No. S-4260] Non-contributing building.

This is a prefabricated, gambrel-roofed frame storage shed. Covered with an asphalt shingled roof, the shed is sided with vertical board siding.

.204 206 South Cannon Street, Storage Building, 20th century
 [map 1-31-10.15-59] Non-contributing building.

This is a one-story, frame, gable-roofed storage building with a one-story leanto addition on the south facade. The building, which faces east, is built on a concrete block foundation, sheathed in vertical board siding, and covered with an asphalt-shingled, gable roof with a flat verge. There are sliding garage doors in the gable end.

.205 206 South Cannon Street, Fabrication Shop, early to mid 20th century;
 [map 1-31-10.15-59; CRS No. S-4726] Contributing building.

This is one-story, four-bay, concrete block shop used for metal fabrication. The building has a gable entrance and is topped with an asphalt shingled gable roof; there is a single interior brick chimney located on the west gable. A sign on the shop reads "Miller Metal Fabrication."

.206 206 South Cannon Street, Shed, late 20th century
 [map 1-31-10.15-59; CRS No. S-4726] Non-contributing building.

This is a one-story, prefabricated storage shed sheathed in corrugated metal.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 57

=====
.207 southeast corner South Cannon Street and Pine Alley, Dwelling, mid 20th century [map 1-31-10.16-??; CRS No. S-4259] Non-contributing building.

This is a three-bay, one-story, rectangular concrete block building with a gable entrance and an asphalt-shingled gable roof. The building faces west. There is a single, centrally-located brick chimney at the ridge line. A frame front porch supported by square wooden columns extends nearly the full length of the west facade.

.208 312 Walnut Street, Dwelling, early 20th century [map 1-31-10.16-??; CRS No. S-4258] Contributing building.

This is a two-bay, two-story, Foursquare dwelling with a pyramidal roof and projecting second-story bay and cross gable. The house faces south. Built on a brick foundation, it is enveloped in aluminum siding and topped with an asphalt shingled roof. On the front facade, the brick foundation has been reworked with a recent brick veneer with curvilinear front steps. Cornice and verge details as well as window and door surrounds are concealed beneath aluminum siding. There is one centrally-located brick chimney. Windows are fitted with one-over-one, double-hung sash. There is a single lozenge-shaped window on the east gable that was probably once fitted with a multipaned fixed sash; it is now fitted with a single-paned sash. A frame front porch extends across the entire south facade and wraps around to the west; covered with an asphalt-shingled roof, it is supported by scrolled iron posts. Although the house is in fair condition, its integrity has been somewhat compromised by the application of aluminum siding and the brick veneer on the front foundation.

.209 312 Walnut Street, Outbuilding, late 20th century [map 1-31-10.16-??; CRS No. S-4258] Non-contributing building.

This is a small frame gambrel-roofed dog house covered with an asphalt shingle roof.

.210 310 Walnut Street, Dwelling, early 20th century [map 1-31-10.16-118; CRS No. S-4257] Contributing building.

This is a two-story, three-bay, frame Foursquare house with a hipped roof, a front dormer and a one-story rear wing. The building faces south. Built on a foundation of brick-sized concrete blocks, the house is sheathed with aluminum siding and topped with an asphalt-shingled roof. Any details at the cornice, verge, or eaves have been concealed by aluminum siding; window and door surrounds have also been covered. The projecting front dormer has also been altered; originally fitted with a sash window, the dormer now houses a louvered roof vent. A single corbelled brick chimney is centrally located. Windows are fitted with one-over-one, double-hung sash throughout. The front door is a wood panel door

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 58

Bridgeville Historic District
Sussex County, DE

with an elliptical upper light. A front porch supported by round tapered wooden columns extends the entire length of the south facade. Although the house is in good condition, its integrity has been altered significantly by the reworking of the front dormer as well as the application of aluminum siding.

.211 306 Walnut Street, Dwelling, late 19th century
 [map 1-31-10.16-117.1; CRS No. S-4256] Contributing building.

This is a rectangular, two-story, three-bay, single-pile frame dwelling with symmetrical fenestration and a two-story rear wing; a one-story rear wing is attached to the two-story addition. The original foundation has been covered with a later application of concrete. The house is sheathed in asphalt shingles and covered with an asphalt-shingled gable roof with a molded boxed cornice. There are two three-light fixed sash windows in each gable at attic level. Windows and doors are trimmed with flat board surrounds; windows are fitted with two-over-two, double-hung sash throughout. The house is in fair condition.

.212 306 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-117.1; CRS No. S-4256] Non-contributing building.

This is a prefabricated one-story frame shed with a gable entrance and an asphalt-shingled, gable roof.

.213 306 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-117.1; CRS No. S-4256] Non-contributing building.

This is a prefabricated one-story frame shed with a gable entrance and an asphalt-shingled, gambrel roof.

.214 304 Walnut Street, Dwelling, late 19th century
 [map 1-31-10.16-116; CRS No. S-4255] Contributing building.

This is a two-story, three-bay, single-pile, south-facing frame dwelling with a center entrance, a symmetrical arrangement of bays and two front dormers. A two-story rear wing with an attached one-story wing are appended to the main block. Built on a brick foundation, the house is sheathed in asbestos shingles and covered with an asphalt-shingled, gable roof with a molded boxed cornice and molded verge. There are two fixed, three-light windows in each attic gable. One corbelled brick chimney is centrally located at the ridge line; a second exterior brick chimney is located at the rear of the two-story addition. Windows and doors are trimmed with flat surrounds with molded drip caps; windows throughout are fitted with three-over-one, double-hung sash. A frame porch extends the full length of the front facade. Topped with an asphalt shingled roof, it is supported by tapered circular wooden columns and embellished with a square balustrade. The house is in fair condition.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 59

=====
.215 304 Walnut Street, Garage, mid to late 20th century
 [map 1-31-10.16-116; CRS No. S-4255] Non-contributing building.

This is a one-story, frame garage with a gable entrance and an asphalt-shingled, gable roof.

.216 302 Walnut Street, Dwelling, mid 20th century
 [map 1-31-10.16-115; CRS No. S-4254] Non-contributing building.

This rectangular plan, two-story, three-bay frame house has a symmetrical placement of bays with the front door located in the left bay. The building has a modern roofed portico over the front door, a carport with a metal balustrade extending from the west gable, a one-story wing with a similar metal balustrade extending from the east gable and a one-story rear wing. Built on a brick foundation, the house is enveloped in aluminum siding and covered with an asphalt-shingled gable roof. Aluminum siding conceals any original details at the cornice, verge, or eaves. There is a single brick chimney centrally located at the ridge line. Windows are fitted with modern sash with snap-out "six-over-six" muntins. The front portico is supported on turned wooden posts. The building is in good condition, but its integrity has been significantly compromised.

.217 302 Walnut Street, Garage, late 20th century
 [map 1-31-10.16-115; CRS No. S-4254] Non-contributing building.

This is a long, one-story frame garage with a gable entrance. the building is sheathed in aluminum siding and topped with an asphalt-shingled, gable roof.

.218 300 Walnut Street, Post Office, late 20th century
 [map 1-31-10.16-114] Non-contributing building.

This is a 20th century rectangular one-story, brick building with a flat roof. Facing south, the four-bay building is constructed of yellow brick. There is a single brick interior chimney located near the center of the building. Windows are fitted with fixed panes.

.219 Pine Alley, Warehouse, late 20th century
 [map 1-31-10.16-117.1] Non-contributing building.

This is a one-story, one-bay, gable-roofed metal warehouse. The foundation is not visible; the walls and roof are metal.

.220 200 Walnut Street, Dwelling, mid 20th century
 [map 1-31-10.16-108; CRS No. S-4250] Non-contributing building.

This is a rectangular, two-story, three-bay frame dwelling with a center

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 60

=====

entrance, symmetrical placement of bays, and a rear wing with attached garage. Built on a brick foundation, the house is sheathed in aluminum siding and topped with an asphalt shingled, gable roof. The cornice, verge, and eaves as well as window and door surrounds have been concealed beneath aluminum siding. Windows are fitted with eight-over-eight, double-hung sash throughout. There are single, semi-circular windows in each attic gable. The central front door is embellished with a covered portico supported by scrolled iron posts. The attached garage is a one-story, gable-roofed frame addition covered with an asphalt-shingled, gable roof and topped with a cupola.

.221 202 Walnut Street, Dwelling, mid to late 20th century
 [map 1-31-10.16-109] Non-contributing building.

This is a rectangular two-story, three-bay brick house with a center entrance and a two-bay, two-story addition on the east gable. The house faces south and is covered with an asphalt shingled gable roof with a scalloped wooden frieze. There is a single exterior brick chimney on the west gable. Windows are fitted with six-over-six, double-hung sash throughout; the center door has flanking fixed four-light sidelights as well as a surround fitted with flanking pilasters and a scalloped frieze. The house is in good condition.

.222 202 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-109] Non-contributing building.

This is a frame, one-story storage shed with an asphalt-shingled gable roof.

.223 202 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-109] Non-contributing building.

This is a small gable-roofed frame shed that appears to have been designed to cover a well or earlier cistern.

.224 204 Walnut Street, Dwelling, late 20th century
 [map 1-31-10.16-110] Non-contributing building.

This is an L-shaped, one-story, south-facing frame ranch house with an attached rear garage wing. Built on a brick foundation, the house is sheathed in asbestos shingles and covered with an asphalt-shingled gable roof. There is a single interior brick chimney near the east gable. Windows are trimmed with molded surrounds.

.225 204 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-110] Non-contributing building.

This is a one-story, prefabricated frame storage shed with an asymmetrically-pitched asphalt-shingled gable roof.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 61

Bridgeville Historic District
Sussex County, DE

=====

This is an L-plan, one-story, three-bay frame house with two one-story rear wings and a one-story rear screened porch. Built on a rusticated concrete block foundation, the house is completely enveloped in aluminum siding and topped with an asphalt shingled, gable roof. Windows are fitted with three-over-one, double-hung sash. A front porch is built on a brick foundation and supported by scrolled iron posts.

.231 413 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.15-71; CRS No. S-4227] Contributing building.

This is a two-story, two-bay, Foursquare frame dwelling with a pyramidal roof and an enclosed porch extending the length of the front facade. The building faces north and is sheathed in aluminum siding and covered with an asphalt shingle roof with a flat boxed cornice. There is a single central brick chimney. Windows are trimmed with flat board surrounds and fitted with one-over-one, double-hung sash. The frame front porch is fully enclosed and fitted with jalousie windows. The house, while in fair condition, has lost integrity as a result of the enclosure of the front porch and the application of aluminum siding.

.232 413 Walnut Street, Shed, early to mid 20th century
 [map 1-31-10.15-71; CRS No. S-4227] Contributing building.

This is a one-story frame storage shed with an asphalt-shingled gable-roof. The building is sheathed in weatherboards.

.233 411 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.15-72; CRS No. S-4228] Contributing building.

This is a two-story, two-bay, frame Foursquare with a pyramidal roof, an enclosed frame front porch, and two projecting wings on the east and west facades. The building faces north. Built on a brick foundation and sheathed with asbestos shingles on the main block and aluminum siding on the porch, the house is covered with an asphalt-shingled roof finished with a molded cornice. The roof is further ornamented with beaded board siding on the underside of the eaves. A single brick chimney is centrally located at the peak of the roof. Windows are finished with flat board surrounds with molded drip caps. The frame front porch extends across the entire facade and is fully enclosed. Although the house is in fairly good condition, its integrity has been compromised by the enclosure of the front porch and the addition of aluminum siding.

.234 411 Walnut Street, Shed, late 20th century
 [map 1-31-10.15-72; CRS No. S-4228] Non-contributing building.

This is a one-story, prefabricated frame storage shed with vertical board siding and an asphalt-shingled gable roof.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 62

=====

.235 409 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.15-73; CRS No. S-4229] Contributing building.

This is a rectangular one-story, three-bay, gable-roofed dwelling with a front porch extending the full length of the front facade, a one-story rear wing, and a front-facing dormer with paired windows. The front porch is formed by a shallowly-pitched extension of the roof over the main block. The building, which faces north, is constructed on a concrete block foundation, clad in aluminum siding, and roofed with asphalt shingles. The roof is further finished with narrow beaded siding under the eaves. There are two chimneys; one is located at the end of the rear wing; the other is an exterior chimney placed on the west gable. Both are brick. Windows are finished with molded board surrounds and fitted with three-over-one, double-hung sash. A frame, partially enclosed screened front porch is supported by tapered squared wooden columns. The house has lost integrity due to the enclosure of the front porch and the addition of aluminum siding.

.236 409 Walnut Street, Shed, late 20th century
 [map 1-31-10.15-73; CRS No. S-4229] Non-contributing building.

This is a one-story, frame shed with an asymmetrically-pitched gable roof. Sheathed in board and batten siding, the building is covered with a corrugated metal roof.

.237 407 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.15-74; CRS No. S-4230] Contributing building.

This early 20th century, two-story, two-bay, frame Foursquare has a pyramidal roof with a projecting hipped front dormer, a porch that extends the length of the front facade, and a one story rear wing. The house faces north, is built on a foundation of brick-sized concrete blocks, and is sheathed with aluminum siding. The roof is covered with asphalt shingles and finished with a boxed molded cornice. The front dormer has been reworked into a louvered roof vent. A single brick chimney is centrally located at the peak of the roof. Windows are finished with flat board surrounds and fitted with one-over-one, double-hung sash. A frame front porch is partially enclosed, also with aluminum siding, and is supported on turned wooden posts. The house is in good condition, but its integrity has been compromised by the enclosure of the front porch and the application of aluminum siding.

.238 407 Walnut Street, Garage, late 20th century
 [map 1-31-10.15-74; CRS No. S-4230] Non-contributing building.

A late 20th century, one-story frame garage with a gable entrance, this building is sheathed in vertical board siding and covered with an asphalt-shingled gable roof.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 63

- =====
.239 407 Walnut Street, Shed, mid 20th century
 [map 1-31-10.15-74; CRS No. S-4230] Non-contributing building.

This is a one-story frame shed with an overhanging gable roof.

- .240 405 Walnut Street, Dwelling, late 19th century
 [map 1-31-10.15-74.1; CRS No. S-4231] Contributing building.

This is a late 19th century, two-story, three-bay, L-plan dwelling with a central entrance, a gable roof, and a one-story rear wing with a single-pitched roof. The house faces north, is built on a brick-sized concrete block foundation, and is sheathed in aluminum siding. The asphalt-shingled roof is trimmed with a molded boxed cornice with returns. A single, corbelled brick chimney is centrally placed. Windows are fitted with two-over-two, double-hung sash throughout; window and door surrounds have been concealed beneath aluminum siding. A frame front porch topped with an asphalt-shingled roof is supported by iron posts. The house is in good condition, although its integrity has been somewhat compromised by the application of aluminum siding.

- .241 403 Walnut Street, Dwelling, late 19th century
 [map 1-31-10.16-120; CRS No. S-4232] Contributing building.

This is a two-story, three-bay, gable-roofed, rectangular plan dwelling with a one-story wing on the west gable, a two-story rear addition, a one-story rear addition, and a pent eave across the front. Built on a concrete block foundation, the house is clad in asbestos shingles and topped with an asphalt shingled roof finished with a molded boxed cornice. There are two exterior concrete block chimneys; one is located at the rear of the two-story addition, and the other at the back of the one-story addition. Windows, finished with flat surrounds with molded drip caps, are fitted with two-over-two, double-hung sash. The house is in good condition.

- .242 403 Walnut Street, Outbuilding, late 20th century
 [map 1-31-10.16-120; CRS No. S-4232] Non-contributing building.

This is a tiny gable-roofed frame dog house.

- .243 401 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.16-121; CRS No. S-4233] Contributing building.

This is a Foursquare, two-story, two-bay frame dwelling with a wraparound front porch, a projecting front dormer, a one-story rear wing, and a projecting two-story bay on the east gable. The house faces north. Set on a foundation of brick-sized concrete block, the building is sheathed in asbestos shingles and topped with an asphalt shingled, pyramidal roof with molded boxed cornice. The front dormer is also trimmed with a molded boxed cornice with returns. The

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 64

projecting bays are ornamented with sawn work and turned pendant drops under the eaves. A single brick chimney is centrally located at the peak of the roof. Windows, trimmed with flat surrounds with molded drip caps, are fitted with one-over-one, double-hung sash. There is a single lozenge-shaped window in the west gable. The wraparound frame front porch is built on a foundation of brick-sized concrete blocks and supported by turned wooden posts embellished with sawn scrolled wooden brackets. The house is in good condition.

.244 401 Walnut Street, Outbuilding, early 20th century
[map 1-31-10.16-121; CRS No. S-4233] Contributing building.

This is a one-story frame outbuilding with an asphalt shingled gable roof. The building is set on concrete block piers.

.245 401 Walnut Street, Garage, early 20th century
[map 1-31-10.16-121; CRS No. S-4233] Contributing building.

This is a one-story frame garage with an asphalt-shingled gable roof, a gable entrance, and weatherboard siding.

.246 315 Walnut Street, Dwelling, late 19th century
[map 1-31-10.16-122; CRS No. S-4234] Contributing building.

A two-story, three-bay, rectangular plan frame dwelling with a symmetrical arrangement of bays and a two-story rear wing, this house faces north. It is built on a brick foundation, sheathed in asbestos siding and topped with an asphalt-shingled gable roof. The cornice, verge, and window and door trim have been covered with aluminum siding. The front door is located in the left bay; windows are fitted with one-over-one, double-hung sash. A frame porch roofed with asphalt shingles extends the length of the front facade; built on a concrete block foundation, it is supported with scrolled metal posts. The house is in fair condition.

.247 315 Walnut Street, Garage, mid 20th century
[map 1-31-10.16-122; CRS No. S-4234] Non-contributing building.

This is a one-story frame garage sheathed with weatherboards and covered with an asphalt-shingled gable roof.

.248 315 Walnut Street, Shed, late 20th century
[map 1-31-10.16-122; CRS No. S-4234] Non-contributing building.

This is a one-story frame shed sheathed with plywood and covered with a single-pitched roof.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 65

=====

.249 311 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.16-124; CRS No. S-4235] Contributing building.

This is an early 20th century two-story, two-bay frame four square with a hipped roof, a projecting front dormer, and a porch that extends the length of the front facade. The house has been enlarged with a two-story wing on the west gable and a one story rear wing. The house, which faces north, is built on a brick foundation, clad in aluminum siding, and topped with an asphalt shingled roof. The cornice, verge, and window and door surrounds have been covered with aluminum siding. Windows are fitted with one-over-one double-hung sash. The front dormer has been reworked into a louvered roof vent. The frame front porch is built on a brick foundation and covered with an asphalt shingled hipped roof with a pedimented cross gable over the front door. The porch is supported by iron posts with a zigzag decoration. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding and the reworking of the front dormer.

.250 311 Walnut Street, Garage, mid 20th century
 [map 1-31-10.16-124; CRS No. S-4235] Non-contributing building.

This is a large, two-story frame garage/storage building sheathed in metal and covered with an asphalt-shingled gable roof.

.251 311 Walnut Street, Screen House, late 20th century
 [map 1-31-10.16-124; CRS No. S-4235] Non-contributing building.

This is a one-story frame screen house.

.252 311 Walnut Street, Shed, mid 20th century
 [map 1-31-10.16-124; CRS No. S-4235] Non-contributing building.

This is a one-story weatherboarded frame garage topped with an asphalt-shingled gable roof; the entrance is on the south lateral side.

.253 307 Walnut Street, Dwelling, late 20th century
 [map 1-31-10.16-125] Non-contributing building.

This is a one-story, three-bedroom "Nanticoke Home" ranch with a balustraded front porch. The house faces north, is built on a poured concrete foundation, clad in aluminum siding and topped with an asphalt-shingled gable roof. Windows are fitted with modern "six-over-nine" double-hung sash with artificial muntins. The concrete and frame front porch is sheltered by a projecting roof gable and supported on turned wooden posts. The house was placed on this site in April, 1993.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 66

- =====
.254 307 Walnut Street, Outbuilding, late 20th century
 [map 1-31-10.16-125] Non-contributing building.

This is a one-story, prefabricated frame outbuilding with an asphalt-shingled gambrel roof and vertical board siding.

- .255 305 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.16-125; CRS No. S-4236] Contributing building.

This is a two-story, two-bay frame Foursquare dwelling with a pyramidal roof, projecting front dormer and balustraded front porch. The house faces north, is built on a rusticated concrete block foundation, and is clad in aluminum siding. The roof is covered with asphalt shingles; cornice and verge details are concealed beneath aluminum siding. A cement-covered, corbelled brick chimney is centrally located at the roof peak. Window and door surrounds are also clad in aluminum siding. Windows are fitted with one-over-one, double-hung sash. There is a single, lozenge-shaped window in the east gable. A frame porch extends the length of the front facade and is supported on turned wooden posts embellished with a square wooden balustrade. The house is in good condition.

- .256 305 Walnut Street, Garage, late 20th century
 [map 1-31-10.16-125; CRS No. S-4236] Non-contributing building.

This is a one-story frame garage with an asphalt-shingled gable roof, two entrance bays on the west gable and a leanto addition on the north side. The building is sheathed in vertical board siding.

- .257 303 Walnut Street, Dwelling, late 19th century
 [map 1-31-10.16-126; CRS No. S-4237] Contributing building.

This is a two-story, one-bay, rectangular plan frame dwelling with the gable entrance facing the street. The main block was extended with two two-story additions on the west and east gables. The house faces north. The foundation is not visible; the building is clad in asbestos shingles and covered with an asphalt-shingled gable roof. The roof is further finished with a molded boxed cornice with returns and a flat verge. A single brick chimney is centrally located at the ridge. Windows, trimmed with flat board surrounds with molded drip caps, are fitted with two-over-two, double-hung sash. There is a single, pointed arch-topped window in the front gable. A frame front porch wraps around the north and part of the east facades; the porch is screened and partially enclosed. The house is in fair condition, but its integrity has been compromised by the partial enclosure of the front porch.

- .258 303 Walnut Street, Garage, mid 20th century
 [map 1-31-10.16-126; CRS No. S-4237] Non-contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 67

=====

This is a one-story frame garage with two entrances in the east gable. The building is sheathed in corrugated metal.

.259 301 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.16-127; CRS No. S-4238] Contributing building.

This is a one-story, three-bay frame dwelling with a steeply pitched overhanging roof, a front facing cross gable, paired windows, and a one-story rear wing. The overhanging roof covers a front porch with tapered wooden columns. The house faces north, is built on a rusticated concrete block foundation, and clad in aluminum siding. The gable roof is covered with asphalt shingles. A single brick chimney is centrally located at the ridge. Cornice details and window and door surrounds have been concealed beneath aluminum siding. Windows are fitted with one-over-one, double-hung sash. The porch extends the length of the front facade and is also built on a rusticated concrete block foundation. The original tapered wooden columns have been sheathed in weatherboard-style aluminum siding. The house is in good condition, but its integrity has been compromised somewhat by the application of aluminum siding.

.260 301 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-127; CRS No. S-4238] Non-contributing building.

This is a prefabricated frame shed with an asphalt shingled gable roof.

.261 301 Walnut Street, Garage, late 20th century
 [map 1-31-10.16-127; CRS No. S-4238] Non-contributing building.

This is a one-story frame garage with two entrance bays in the south gable. The building is covered with an asphalt shingled gable roof.

.262 213 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.16-146; CRS No. S-4239] Contributing building.

This is a one story, two-bay, frame bungalow with a steeply pitched roof, a porch extending across the entire front facade, and front and rear dormers. The building faces north, is built on a concrete block foundation, and sheathed with weatherboards. The roof, which is finished with a molded boxed cornice with returns, is covered with asphalt shingles and extends forward beyond the main block to cover the front porch. There is a single central brick chimney. Windows, trimmed with flat surrounds and molded drip caps, are fitted with three-over-one, double-hung sash. A frame front porch extends the full length of the north facade and is built on concrete block supports. The porch is supported with tapered wooden columns and partially enclosed with a weatherboarded half-wall instead of a balustrade. The house is in good condition.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 68

Bridgeville Historic District
Sussex County, DE

- =====
- .263 213 Walnut Street, Garage/Shed, early 20th century
 [map 1-31-10.16-146; CRS No. S-4239] Contributing building.

This is a long, one-story frame building with two sliding garage doors in the south-facing lateral facade. The building is sheathed with beaded vertical board siding and topped with a corrugated metal gable roof.

- .264 211 Walnut Street, Dwelling, early 20th century
 [map 1-31-10.16-147; CRS No. S-4240] Contributing building.

A two-bay, two-story frame Foursquare dwelling with a pyramidal roof, a wraparound front porch, a single front hipped dormer and two two-story wings, this building faces north. The house is built on a foundation of brick-sized rusticated concrete block, sheathed with aluminum siding and roofed with asphalt shingles. Cornice and verge details as well as window and door surrounds have been concealed beneath aluminum siding. Windows are fitted with one-over-one, double-hung sash throughout. The first floor window opening on the front facade appears to have been widened. The front porch, which also wraps around to the west facade, is built on a brick-sized rusticated concrete block foundation and roofed with asphalt shingles. The porch is supported with fluted Doric columns. The house is in good condition, although its integrity has been compromised somewhat by the application of aluminum siding as well as the widening of the first floor front window.

- .265 211 Walnut Street, Shed, early 20th century
 [map 1-31-10.16-147; CRS No. S-4240] Contributing building.

This is a one-story frame shed with an asphalt-shingled gable roof and two swinging doors in the north gable. The building is sheathed with vertical board siding.

- .266 211 Walnut Street, Pool House, late 20th century
 [map 1-31-10.16-147; CRS No. S-4240] Non-contributing building.

This is a prefabricated, frame, shed-roofed pool house with vertical board siding and a roof of asphalt shingles.

- .267 207 Walnut Street, Dwelling, late 19th century
 [map 1-31-10.16-148; CRS No. S-4241] Contributing building.

This is a two-story, three-bay, rectangular plan frame dwelling with symmetrical fenestration, a screened front porch, and a two-story rear wing with an attached one-story shed wing. The house faces north. The original foundation has been coated with concrete. Sheathed with weatherboards, the building is topped with an asphalt-shingled gable roof. Cornice, verge, and window and door surrounds have been covered with aluminum siding. There is a single brick exterior chimney

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 69

=====
on the east gable. Windows are fitted with three-over-one, double-hung sash. The front door, which is located in the center of the front facade, is embellished with a fixed, one-light overhead transom. The front porch extends three-quarters of the length of the north facade. Supported on piers and topped with an asphalt shingled roof, it is of frame construction. The house is in good condition.

.268 207 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-148; CRS No. S-4241] Non-contributing building.

This is a one-story frame shed topped with a gable roof and sheathed with vertical board siding.

.269 207 Walnut Street, Shed, late 20th century
 [map 1-31-10.16-148; CRS No. S-4241] Non-contributing building.

This is a prefabricated metal one-story gambrel-roofed shed.

.270 207 Walnut Street (faces Maple Alley), Apartment Building, late 20th century; [map 1-31-10.16-148; CRS No. S-4241] Non-contributing building.

This is a two-story, five-bay apartment building constructed of stuccoed masonry and topped with a flat roof. The building appears to be divided into three apartments.

.271 205 Walnut Street, Dwelling, mid to late 20th century
 [map 1-31-10.16-149] Non-contributing building.

This is an L-shaped, one-story, three-bay, gable-roofed, frame ranch house. The house faces north. Constructed on a rusticated concrete block foundation, the building is sheathed in aluminum siding and topped with an asphalt-shingled gable roof. Windows are fitted with six-over-six, double hung sash. A front porch with a concrete floor and rusticated concrete block foundation is supported by square wooden posts. The porch is tucked into the open side of the "L" of the house and is covered by an extension of the roof over the main block.

.272 205 Walnut Street, Garage, mid to late 20th century
 [map 1-31-10.16-149] Non-contributing building.

This is a one-story frame garage with an asphalt-shingled gambrel roof and two entrance bays on the south gable. The building is sided with vertical board siding.

.273 201/203 Walnut Street, Dwelling, late 19th century
 [map 1-31-10.16-150, 150.1; CRS No. S-4242] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 70

=====
This is a two-story, three-bay, frame house with a front cross gable, symmetrical fenestration, and a porch that extends the length of the front facade. The house, which faces north, is constructed on a brick foundation and sheathed with aluminum siding. The gable roof is covered with asphalt shingles and finished with a molded, boxed cornice with returns and a flush molded verge. A single exterior corbelled brick chimney is located on the east gable. Window and door surrounds have been concealed by aluminum siding; windows are fitted with one-over-one, double-hung sash throughout. The front door is located in the center bay. The frame front porch is supported by turned wooden posts and further finished with a turned balustrade; the porch is covered with an asphalt shingle roof. The house is in good condition, although its integrity has been compromised somewhat with aluminum siding.

.274 201/203 Walnut Street, Shed, early 20th century
 [map 1-31-10.16-150, 150.1; CRS No. S-4242] Contributing building.

This is a one-story frame shed with an asymmetrically-pitched asphalt shingled gable roof and vertical board siding.

.275 304 Main Street, Dwelling, late 19th century
 [map 1-31-10.16-157; CRS No. S-4709] Contributing building.

This is a two-story, five-bay, rectangular frame building with symmetrical fenestration, a center door and a screened porch on the south gable. The building faces east, is built on a brick foundation and clad in wood shingles. The gable roof is covered with asphalt shingles with a molded boxed cornice with returns and a flush verge. There are two modern, rough-surfaced or "rusticated" brick exterior chimneys on each gable. Windows are trimmed with molded board surrounds and fitted with six-over-six, double-hung sash. The arched front door surround is ornamented with flanking pilasters and a dentilated overhang. The house is in good condition.

.276 304 Main Street, Garage, late 20th century
 [map 1-31-10.16-157; CRS No. S-4709] Non-contributing building.

This is a one-story frame garage with a gable entrance. The building is sheathed with wood shingles and topped with an asphalt-shingled gable roof.

.277 308 Main Street, Dwelling, early 20th century
 [map 1-31-10.16-158; CRS No. S-4710] Contributing building.

This is a two-story, two-bay frame Foursquare dwelling with an overhanging hipped roof, a fully enclosed front porch, and dormers on each face of the roof. The main block has been extended with a one-story rear wing and a projecting two-story bay on the south side. The house faces east. Set on a foundation of brick-sized rusticated concrete blocks, the building is clad with aluminum siding

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 71

and topped with an asphalt-shingled roof. There is a single corbelled brick chimney located at the peak of the roof. Window and door surrounds have been concealed beneath aluminum siding; the window openings have also been fitted with new, simulated "six-over-one" sash with removable muntins. The frame front porch extends the length of the east facade; like the house, it rests on a foundation of brick-sized rusticated concrete blocks and is enclosed with aluminum siding. The house is in good condition; its integrity has been compromised, however, by the enclosure of the front porch, the application of aluminum siding, and the alterations to the windows.

.278 Lot 116, South Main Street, Dwelling, late 19th century
[map 1-31-10.20-116] Contributing building.

This is a two-story, five-bay, hip-roofed rectangular frame dwelling with symmetrical fenestration, a center entrance, and a wraparound front porch. The building faces west. It is constructed on a brick foundation, clad in aluminum siding, and covered with an asphalt-shingled roof. Cornice and verge details as well as window surrounds have been concealed beneath aluminum siding. There are two hipped dormers on the front and north facades. A single interior brick chimney is located on the north gable. Windows are fitted with six-over-one, double-hung sash. The front door is lit by a fixed six-light transom and flanking fixed, four-light sidelights. A frame, concrete-floored porch built on a concrete foundation extends the full length of the front facade and wraps around to the west side; the porch is supported by circular wooden columns. The house is in good condition.

.279 Lot 116, South Main Street, Outbuilding, late 20th century
[map 1-31-10.16-116] Non-contributing building.

This is a one-story, concrete block outbuilding that was under construction in July 1993.

.280 403 South Main Street, Dwelling, early 20th century
[map 1-31-10.16-193.1; CRS No. S-4359] Contributing building.

This is a large one-story bungalow with a front-facing gable entrance, a porch that extends three-quarters of the length of the front facade, a series of paired and tripartite windows, and a one-story wing on the south side. The building faces west. Built on a rusticated concrete block foundation, the house is sheathed in weatherboards on the first story and wood shingles in the upper part of the gables. The gable roof is covered with asphalt shingles and further embellished with a molded verge and exposed triangular brackets under the eaves. There is a single exterior brick chimney located on the south facade. Windows are trimmed with flat board surrounds with molded drip caps and fitted with nine-over-one, double-hung sash. The central front door is flanked by wooden panels with four fixed sidelights above. The frame porch is built on a rusticated

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 72

=====

concrete block foundation; the porch roof is supported by tapered wooden columns with rusticated concrete block bases. The house is in good condition.

- .281 403 South Main Street, Garage, early 20th century
 [map 1-31-10.16-193.1; CRS No. S-4359] Contributing building.

This is a one-story frame garage with two entrance bays on the west lateral facade. The building is topped with an asphalt shingled gable roof and sheathed with vertical board siding.

- .282 404 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-165; CRS No. S-4715] Contributing building.

This is a two-bay, one-story, frame bungalow with a steeply pitched gable roof, a large gable dormer, and a front porch supported by tapered columns. The main block is extended by a projecting, one-story bay off of the north gable as well as a modern, one-story rear wing. The building faces east, is set on a rusticated concrete block foundation, and sheathed with aluminum siding. The roof is covered with asphalt shingles. There are single gabled dormer windows located on the front and rear facades. A single center brick chimney is located behind the ridge. Window and door surrounds have been concealed; windows are fitted with six-over-one, double-hung sash. The frame front porch extends the length of the east facade. Like the house, it is built on a rusticated concrete block foundation and supported by tapered wooden columns; it is further ornamented with a decorative angled balustrade and a scalloped overhang. The house is in good condition, but its integrity has been somewhat compromised by the addition of aluminum siding.

- .283 402 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-164; CRS No. S-4714] Contributing building.

This is a small, one-story, three-bay, frame bungalow with a steeply pitched overhanging roof and a front porch supported by tapered wooden columns. To the rear there is a one-story, hip-roofed wing. The house faces east. Set on a brick foundation, it is clad in aluminum siding and covered with an asphalt-shingled gable roof. Cornice details have been concealed beneath aluminum siding. Windows are fitted with one-over-one, double-hung sash. The front porch extends the full length of the east facade and is supported by wooden posts with an exaggerated taper. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

- .284 402 South Main Street, Garage, early 20th century
 [map 1-31-10.16-164; CRS No. S-4714] Contributing building.

This is a one-story frame garage covered with an asphalt-shingled gable roof, set on a concrete block foundation, and sheathed with vertical board siding. There

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 73

Bridgeville Historic District
Sussex County, DE

are two entrance bays on the north lateral facade.

- .285 108/106 Edgewood, Dwelling, late 19th century
 [map 1-31-10.16-163; CRS No. S-4217] Contributing building.

This is a two-story, three-bay, gable-roofed, rectangular frame dwelling with symmetrical fenestration, a center cross gable and a front porch decorated with scrolled sawn wooden brackets. The house faces south; its original foundation has been concealed beneath concrete. Sheathed with wavy-edged asbestos shingles, it is covered with an asphalt-shingled gable roof. There are two fixed two-light sash windows in each gable as well as a single double-hung window with a pointed upper sash in the front cross gable. There are two corbelled brick interior chimneys, one on the west gable, and one at the rear of the rear wing. Windows and doors are trimmed with molded board surrounds with molded drip caps and fitted with two-over-two, double-hung sash. The front door is located in the center of the front facade. A frame front porch extends three-quarters of the length of the south facade; it is supported by chamfered wooden posts ornamented by sawn scrolled wooden brackets. The house is in good condition.

- .286 108/106 Edgewood, Garage, early 20th century
 [map 1-31-10.16-163; CRS No. S-4217] Contributing building.

This is a one-story, one-bay, frame gable-entrance garage covered with an asphalt-shingled gable roof. The building is sided with asphalt shingles.

- .287 102 Edgewood, Dwelling, late 19th century
 [map 1-31-10.16-162; CRS No. S-4218] Contributing building.

This dwelling is nearly identical to the house at 108/106 Edgewood except that the asbestos shingles used for siding are straight rather than wavy-edged, there are no outbuildings, and the porch foundation is concrete block rather than poured concrete. This is a two-story, three-bay, gable-roofed, rectangular frame dwelling with symmetrical fenestration, a center cross gable and a front porch decorated with scrolled sawn wooden brackets. The house faces south; its original foundation has been concealed beneath concrete. Sheathed with asbestos shingles, it is covered with an asphalt-shingled gable roof. There are two fixed, two-light sash windows in each gable as well as a single double-hung window with a pointed upper sash in the front cross gable. There are two corbelled brick interior chimneys, one on the west gable, and one at the rear of the rear wing. Windows and doors are trimmed with molded board surrounds with molded drip caps and fitted with two-over-two, double-hung sash. The front door is located in the center of the front facade. A frame front porch extends three-quarters of the length of the south facade; it is supported by chamfered wooden posts ornamented by sawn scrolled wooden brackets. The house is in good condition.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 74 Bridgeville Historic District
Sussex County, DE
=====

.288 314 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-161; CRS No. S-4713] Contributing building.

This is a two-story hip-roofed frame dwelling with a projecting two-story bay on the south, north, and east facades, a wraparound front porch, and fish scale shingles in the upper gables. The main block has been extended with a one story as well as a two-story rear wing. The building faces east and is sheathed with asphalt shingles. The asphalt-shingled roof is irregularly shaped but hipped over the main block. The roof is further embellished with a molded boxed cornice with a flat molded verge and scalloped sawn scrollwork with turned pendant drops under the projecting cross gables. There is a front facing gabled dormer with paired one-over-one windows on the north side of the roof. Windows are fitted with one-over-one, double-hung sash throughout; there are three sets of paired, arch-topped, one-over-one windows in the three attic cross gables. A curvilinear frame porch wraps around the front and two sides. The porch is ornamented with Ionic wood columns, a turned wooden balustrade, and a pedimented gable over the main entrance. The house is in fair to poor condition.

.289 317 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-192; CRS No. S-4360] Contributing building.

This is a two-story, five-bay frame Foursquare dwelling with a pyramidal roof, a front-facing two-story projecting bay with pedimented cross gable, and a wraparound front porch. The house faces west. Set on a brick-sized rusticated concrete block foundation, the building is sheathed in aluminum siding and covered with an asphalt-shingled roof. Cornice and verge details and window and door trim have been concealed beneath aluminum siding. A single brick chimney is centrally located toward the rear of the building. Windows are fitted with one-over-one, double-hung sash. The frame front porch, which has a gabled roof over the main entry, wraps around the west and north facades; the porch is supported by circular wooden columns and ornamented with a square balustrade and turned posts. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

.290 317 South Main Street, Garage, late 20th century
 [map 1-31-10.16-192; CRS No. S-4360] Non-contributing building.

This is a one-story, metal, gable entrance garage with an asphalt-shingled gable roof.

.291 315 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-191; CRS No. S-4361] Contributing building.

This is a two-story, four-bay, T-plan dwelling with a projecting two-story bay, a two-story wing on the south facade, and a wraparound front porch. The building, which faces west, is set on a brick foundation and sheathed with aluminum siding

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 75

=====

at first floor level and fish scale shingles in the front gable. The house is covered with an asphalt-shingled gable roof with a molded boxed cornice. Further ornamentation includes sawn scrolled trim with turned pendant drops under the cross gables and arch-topped windows with molded drip caps in the gables. Window trim has been concealed by a layer of aluminum siding; window openings are fitted with one-over-one, double-hung sash. The wraparound front porch is built on a concrete foundation and supported by tapered wooden columns. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

.292 313 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-190; CRS No. S-4362] Contributing building.

This is a large, two-story, three-bay, frame Foursquare dwelling with a hipped roof, a curvilinear wraparound front porch and a hipped front dormer. Built on a foundation of brick-sized rusticated concrete block, the building is sheathed in aluminum siding and covered with an asphalt-shingled roof. Cornice and verge details as well as window surrounds have been concealed beneath aluminum siding. The front dormer is fitted with a Palladian window with a stained glass upper sash. There are two interior brick chimneys; one is centrally located toward the rear; the other is on the south gable. Windows are fitted with modern simulated "six-over-six-light" double-hung sash with snap-out muntins. The wood front door is embellished with a single large elliptical glass light. A frame porch built on a concrete block foundation wraps around the west and north sides, the porch is supported by tapered circular wooden columns and ornamented with a square wooden balustrade. The house is in fair condition, but its integrity has been somewhat compromised by the reworking of the windows as well as the application of aluminum siding.

.293 313 South Main Street, Garage, late 20th century
 [map 1-31-10.16-190; CRS No. S-4362] Non-contributing building.

This is a one-story, frame hip-roofed garage covered with an asphalt-shingled gable roof. The building is sheathed with weatherboards.

.294 311 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-189; CRS No. S-4363] Contributing building.

This is a two-story, six-bay, frame L-plan building with an angled corner entrance and projecting second story bays on the west and south facades. Set on a brick foundation, the house is clad in aluminum siding and topped with an asphalt-shingled gable roof with a boxed molded cornice and flush molded verge. Window trim has also been concealed by aluminum siding; windows are fitted with one-over-one, double-hung sash. A single porch with iron supports is located on the south facade. Extensive alterations have compromised the integrity of this building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 76

- =====
- .295 311 South Main Street, Outbuilding, mid 20th century
 [map 1-31-10.16-189; CRS No. S-4363] Non-contributing building.

This is a one-story frame outbuilding covered with an asphalt-shingled gable roof.

- .296 312 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-160; CRS No. S-4712] Contributing building.

This is a two-story, two-bay, frame dwelling with an overhanging hipped roof, a front dormer fitted with three paired windows, a one-story wing on the south facade, and a porch that extends the full length of the front facade. The building, which faces east, is constructed on a rusticated concrete block foundation, clad in aluminum siding and covered with an asphalt-shingled roof. The undersides of the roof overhang are finished with narrow-width beaded board siding. A single exterior corbelled brick chimney is located on the south facade. Windows are finished with flat board surrounds and fitted with three-over-one, double-hung sash. The front door, located in the right bay, is lit with flanking fixed, five-light sidelights. A frame front porch, set on a rusticated concrete block foundation and piers, is supported by tapered wooden columns. The house is in good condition.

- .297 312 South Main Street, Garage, early 20th century
 [map 1-31-10.16-160; CRS No. S-4712] Contributing building.

This is a hip-roofed one-story two-bay frame garage with an asphalt shingled roof and vertical board siding.

- .298 310 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-159; CRS No. S-4711] Contributing building.

This is a two-story, five-bay, T-plan frame building with a wraparound front porch and a projecting two-story bay topped with a pedimented gable; the main block has been further extended by two contiguous one-story rear wings. The house, which faces east, is built on a brick foundation and sheathed with asbestos shingles; it is covered with an asphalt-shingled gable roof with a molded boxed cornice and flush molded verge. A single arch-topped two-over-two, double-hung window with molded drip cap is located in each gable. Windows are trimmed with flat wooden surrounds with molded drip caps and fitted with one-over-one, double-hung sash. The front porch is built on a concrete block foundation and covered with an asphalt-shingled roof. The porch is supported by turned wooden posts with a square wooden balustrade. The house is in good condition.

- .299 310 South Main Street, Shed, late 20th century
 [map 1-31-10.16-159; CRS No. S-4711] Non-contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 77

=====

This is a prefabricated, one-story frame storage shed covered with an asphalt-shingled gable roof.

.300 310 South Main Street, Shed, early 20th century
 [map 1-31-10.16-159; CRS No. S-4711] Contributing building.

This is a one-story frame storage shed with an asymmetrically-pitched asphalt shingled gable roof. The building is sheathed in vertical board siding.

.301 310 South Main Street, Garage, late 19th to early 20th-century
 [map 1-31-10.16-159; CRS No. S-4711] Contributing building.

This is a two-story frame garage sheathed with vertical board siding and has a gable roof. The building is deteriorated and obscured by foliage, but appears to date to the late 19th or early 20th century.

.302 Lot 188, South Main Street, Dwelling, late 20th century
 [map 1-31-10.16-188] Non-contributing building.

This is a one-story, five-bay frame Cape Cod-style house built on a concrete block foundation and clad in aluminum siding. The house, which is covered with an asphalt-shingled gable roof, has symmetrical fenestration and a center door. Windows are fitted with one-over-one, double-hung sash.

.303 Lot 188, South Main Street, Outbuilding, late 20th century
 [map 1-31-10.16-188] Non-contributing building.

This is a one-story, prefabricated frame building covered with an asphalt-shingled gable roof.

.304 309 South Main Street, Dwelling, late 19th century
 [map 1-31-10.16-187; CRS No. S-4364] Contributing building.

This is a two-story, five-bay, frame L-plan dwelling with two projecting two-story bays on the front facade, a wraparound front porch and arch-topped windows in the front gables. The house faces west. The original foundation material has been covered by a layer of concrete. The building is sheathed in aluminum siding and covered with an asphalt-shingled hipped roof with a molded boxed cornice. The undersides of the pedimented gables are ornamented with sawn scalloped trim with turned pendant drops. There are two interior corbelled brick chimneys. Windows, trimmed with flat surrounds topped with molded drip caps, are fitted with one-over-one, double-hung sash. The front door is centrally located. A frame porch wraps around the front and side elevations and is supported by turned wooden posts; the porch is further embellished with a front cross gable sheathed with fish scale shingles. The house is in good condition.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 78

.305 309 South Main Street, Shed, early 20th century
 [map 1-31-10.16-187; CRS No. S-4364] Contributing building.

This is a one-story frame shed covered with a metal gable roof and sheathed with weatherboards.

.306 307 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-186; CRS No. S-4365] Contributing building.

This is a two-story, two-bay, frame Foursquare dwelling with a hipped roof, screened front porch, and a projecting front dormer. The house faces west and is built on a dressed concrete block foundation, sheathed with weatherboards, and topped with an asphalt-shingled roof. Windows are trimmed with flat wood surrounds and fitted with one-over-one, double-hung sash. A frame front porch built on a concrete block foundation is supported by tapered square wooden columns and ornamented with a square balustrade. The house is in good condition.

.307 307 South Main Street, Garage, early 20th century
 [map 1-31-10.16-186; CRS No. S-4365] Contributing building.

This is a one-story, frame garage with a gable entrance. The building is sheathed in vertical board siding and covered with an asphalt-shingled gable roof.

.308 305 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-185; CRS No. S-4366] Contributing building.

This is a two-story, three-bay, double pile, frame Foursquare dwelling with a wraparound front porch, a hipped roof, and a pedimented front dormer trimmed with fish scale shingles. The house, which faces west, is set on a brick-sized rusticated concrete block foundation and sheathed with a combination of weatherboard on the first floor, asbestos shingles on the upper story, and fish scale shingles in the dormers. The roof, covered with asphalt shingles, is finished with a molded boxed cornice with flush molded verge. Single dormers are located on the front and north facades. A single chimney, also constructed of rusticated brick-sized concrete block, is located on the south facade. Windows are trimmed with flat surrounds, topped with molded drip caps, and fitted with one-over-one, double-hung sash. The frame front porch wraps around the west (front) and south facades; it is built with a foundation and round columns of rusticated brick-sized concrete block and topped with an asphalt-shingled frame roof. The porch gable is trimmed with fish scale shingles. The house is in good condition.

.309 305 South Main Street, Shed, late 20th century
 [map 1-31-10.16-185; CRS No. S-4366] Non-contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 79

=====

This is a late 20th century one-story frame shed. The building is sheathed in vertical board siding and covered with an asphalt-shingled, asymmetrically-pitched gable roof.

.310 303 South Main Street, Dwelling, early 20th century
 [map 1-31-10.16-184; CRS No. S-4367] Contributing building.

This is a two-story, two-bay, frame Foursquare house with a pyramidal roof, a wraparound front porch with a corner porch "tower" and a series of projecting bay windows and attic dormers. The house faces west. The original foundation material is concealed beneath a coating of concrete, the exterior walls are clad in aluminum siding, and the roof is covered with asphalt shingles. A single exterior corbelled brick chimney is located on the south facade. Windows, trimmed with plain board surrounds with molded drip caps, are fitted with one-over-one, double-hung sash. There are paired one-over-one, double-hung sash windows in each dormer. The front door is centrally placed. The front porch, which wraps around the front (west) and north sides, is covered with an asphalt-shingled gable roof and supported by round wooden columns. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

.311 303 South Main Street, Garage/Shed, late 20th century
 [map 1-31-10.16-184; CRS No. S-4367] Non-contributing building.

This is a one-and-one-half-story, frame combination garage and shed with a metal hipped roof. The building is sided with particle board.

.312 102 John Street, Dwelling, late 19th century
 [map 1-31-10.16-7; CRS No. S-4730] Contributing building.

This is a one-and-one-half-story, five-bay, single-pile, frame dwelling with a screened front porch and two front doors. The main block has been extended with a one-story and a two-story rear wing as well as a one-story wing on the west facade. The house, which faces south, is built on a brick foundation, sheathed in a combination of wavy-edged asbestos siding and aluminum siding inside the first floor screened porch, and covered with an asphalt-shingled gable roof finished with a molded verge. Windows are finished with molded board surrounds and fitted with one-over-one, double-hung sash. A frame screened porch extends three-quarters of the length of the front facade; the porch is built on a concrete block foundation and supported on square wooden posts. The house is in good condition, but its integrity has been somewhat compromised by the apparent reworking of the original bay arrangement and the partial application of aluminum siding.

.313 100 John Street, Dwelling, late 19th century
 [map 1-31-10.16-8; CRS No. S-4729] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 80

=====

This is a two-story, four-bay, rectangular dwelling with a center door, irregular arrangement of bays, and a covered frame front portico; the main block is extended by two one-story wings on the west facade. The house faces south. The original foundation material is hidden beneath a later application of concrete. Sheathed in asbestos siding, the house is topped with an asphalt-shingled gable roof finished with a molded boxed cornice, pedimented gable, and flush molded verge. A single brick chimney is centrally located at the ridge line. Windows are finished with flat board surrounds and fitted with one-over-one, double-hung sash. A frame front portico topped with an asphalt shingled gable roof is supported on square wooden posts. The house is in good condition, but the fenestration appears to have been altered.

.314 100 John Street, Garage, early 20th century
[map 1-31-10.16-8; CRS No. S-4729] Contributing building.

This is a one-story, two-bay, square frame garage covered with an asphalt-shingled pyramidal roof and sheathed with vertical board siding.

.315 100 John Street, Garage, early 20th century
[map 1-31-10.16-8; CRS No. S-4729] Contributing building.

This is a large, two-bay, square concrete block garage with a hipped roof and a brick center chimney.

.316 Cahall House, 119 North Main Street, Dwelling, mid 19th century
[map 1-31-10.12-135] Contributing building.

This is a two-story, five-bay, frame house with an L-shaped main block, symmetrical fenestration, a front-facing gable to the left of the center entrance, and a front porch with a dentilated cornice. The main block has been extended by a two-story rear wing with an attached one-story wing and a one-story rear screened porch. The house faces west. It is set on a brick foundation, sheathed with weatherboard and covered with an asphalt-shingled gable roof finished with a molded boxed cornice with returns and a flush molded verge. There are three interior corbelled brick chimneys; two are located on the east and west gables and one is located at the back of the two-story rear wing. Windows, finished with molded surrounds, are fitted with six-over-six, double-hung sash. The central front door is ornamented with flanking fixed four-light sidelights and an overhead eight-light transom. A frame front porch, covered with an asphalt-shingled roof, is built on a concrete base and is supported by square wooden columns; the porch is further ornamented with a dentilated cornice. The house is in good condition.

.317 119 North Main Street, Shed, late 20th century
[map 1-31-10.12-135] Non-contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 81

=====

This is a one-story frame gambrel-roofed shed with a gable entrance.

- .318 117 North Main Street, Dwelling, late 19th century
[map 1-31-10.12-136; CRS No. S-4379] Non-contributing building.

This is a two-story, two-bay, gable-roofed frame dwelling with the gable entrance facing the street. The house faces west; there is a one-story shed with a single-pitched roof attached to the south facade. The foundation material is not visible, but the building is sheathed in aluminum siding and covered with an asphalt-shingled roof finished with a molded boxed cornice. There is a single, modern concrete block exterior chimney located on the south facade. Window surrounds have been concealed beneath aluminum siding; windows are fitted with six-over-six, double-hung sash in most bays and two-over-two, double-hung sash in the attic. A front porch with a concrete floor and topped with an asphalt-shingled gable roof is supported by scrolled iron posts. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

- .319 117 North Main Street, Outbuilding, late 20th century
[map 1-31-10.12-136; CRS No. S-4379] Non-contributing building.

This is a one-story, frame, shed-roofed outbuilding. The building is set on concrete block piers, sheathed in plywood, and roofed with asphalt shingles.

- .320 113 North Main Street, Dwelling, late 19th century
[map 1-31-10.12-137; CRS No. S-4378] Contributing building.

This is a two-story, two-bay, L-plan frame dwelling with a one-story rear wing and the primary gable entrance facing the street. The house faces west. The original foundation material has been covered with a later application of concrete. Clad in a combination of lapped square asphalt shingles and vertical board siding, the building is covered with an asphalt-shingled gable roof finished with a boxed molded cornice with returns and a flat molded verge. There is a single brick chimney centrally located at the ridge. Windows, trimmed with molded surrounds, are fitted with a combination of twelve-over-one and nine-over-one, double-hung sash; there is a single fixed one-light sash in the attic gable. A frame porch with iron supports extends the full length of the front facade. The house is in good condition.

- .321 113 North Main Street, Shed, late 20th century
[map 1-31-10.12-137; CRS No. S-4378] Non-contributing building.

This is a one-story, prefabricated frame shed covered with an asphalt-shingled gambrel roof and sheathed in vertical board siding.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 82

=====

.322 Rawleigh House, 109 North Main Street, Dwelling, late eighteenth to late 19th century; [map 1-31-10.16-166, 167] Contributing building.

This is a rectangular plan, two-and-one-half-story, five-bay, building with roughly symmetrical fenestration, a front cross gable with decorative sawn scrollwork in the peak and sides, a projecting bay on the north elevation, and decorative fish-scale trim at attic level and on the projecting bay. The house, which faces west, has been enlarged with two two-story rear wings as well as a one-story rear wing. Constructed on a brick foundation, the dwelling is sheathed in weatherboards and fish scale shingles and covered with a wood-shingled gable roof with clipped end gables. The roof is finished with a molded boxed cornice with flush molded verge. There are two chimneys; one is built of brick and is located on the interior at the south end of the house; the other, built of concrete block, is located on the outside wall at the end of the one-story rear wing. Windows, finished with flat board surrounds with molded drip caps, are fitted with one-over-one, double-hung sash. There are two, arch-topped, two-over-two windows in each attic gable. The central front door is also trimmed with a flat wooden surround. A frame front porch is built with a concrete floor, turned wooden posts and a turned balustrade. The house, which is in good condition, is currently operated as a bed and breakfast.

.323 107 North Main Street, Dwelling, late 19th century
 [map 1-31-10.16-168] Contributing building.

This is a two-story, three-bay, L-plan dwelling with its gable entrance facing the street. The house faces west. The original foundation has been concealed beneath a layer of concrete, the exterior walls are sheathed in aluminum siding, and the building is covered with an asphalt-shingled gable roof with a molded, boxed cornice with scrolled brackets. A single, corbelled brick exterior chimney is located on the north gable. Window trim is concealed beneath aluminum siding; windows are fitted with two-over-two, double-hung sash. A frame front porch, also sheathed in aluminum siding, is built with a concrete floor and an asphalt shingled gable roof. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

.324 107 North Main Street, Garage, late 20th century
 [map 1-31-10.16-168] Non-contributing building.

This is a prefabricated, one-story frame garage sheathed with vertical board siding and covered with an asphalt-shingled gable roof.

.325 102 North Main Street, Dwelling, late 19th century
 [map 1-31-10.16-11; CRS No. S-4391] Contributing building.

This is a two-story, four-bay, L-plan building with a center entrance and a front porch that extends three-quarters of the length of the east facade. The building

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 83

Bridgeville Historic District
Sussex County, DE

=====

has been enlarged with a two-story rear wing with a contiguous one-story wing. Built on a foundation of brick-sized rusticated concrete block, the house is sheathed in asbestos shingles and topped with an asphalt-shingled gable roof with a molded boxed cornice with returns and a flush molded verge. There are two interior end chimneys, both are corbelled brick. Windows, finished with plain surrounds and molded drip caps, are fitted with one-over-one, double-hung sash. The front door is centrally placed. A frame front porch, also built on a brick-sized rusticated concrete block foundation, is supported by circular wooden pillars and ornamented with a square balustrade. The house is in fair to poor condition.

.326 104 North Main Street, Dwelling, late 19th century
 [map 1-31-10.16-10; CRS No. S-4390] Contributing building.

This is a two-bay, two-story, rectangular, gable-roofed frame dwelling with its gable entrance facing the street. The house has been enlarged by the addition of a one-story rear wing and separate one-story bays on the north and south elevations. The building, which faces east, is constructed on a rusticated concrete block foundation, clad in asbestos shingles, and covered with an asphalt-shingled gable roof with a molded boxed cornice and molded verge. Windows, trimmed with flat surrounds and molded drip caps, are fitted with one-over-one, double-hung sash. There is a single, arch-topped, one-over-one double-hung window in the front gable. A frame porch extends the entire length of the front facade. Like the main block, it is built on a rusticated concrete block foundation and covered with an asphalt-shingled roof with a boxed cornice. The porch is supported with round wooden posts. The house is in good condition.

.327 Cannon Manor, 106 North Main Street, Dwelling, early 20th century
 [map 1-31-10.16-9; CRS No. S-4389] Contributing building.

This is a large Craftsman style two-story, six-bay, rectangular frame building with a gable roof, a wraparound front porch and three front roof dormers. The house faces east. Sheathed in wood shingles, it is covered with an asphalt-shingled roof. There are two corbelled brick chimneys located at the rear of the main block. Windows, trimmed with molded board surrounds, are fitted with six-over-six, double-hung sash; the three front and one rear dormers are fitted with swinging four-light sash. A frame front porch wraps around the east and south sides. It is covered with an asphalt-shingled gable roof and supported by square wooden columns ornamented with decorative sawn brackets. The house is in good condition.

.328 106 North Main Street, Shed, late 20th century
 [map 1-31-10.16-9; CRS No. S-4389] Non-contributing building.

This is a one-story frame shed covered with an asphalt-shingled gable roof.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 84

Bridgeville Historic District
Sussex County, DE

=====

.329 106 Market Street, Commercial Building, late 19th to early 20th century; [map 1-31-10.16-13; CRS No. S-4337] Contributing building.

This is a two-story, three-bay frame commercial building with its gable entrance facing the street. The building, which faces south, has been enlarged by a late 20th century, one-story frame addition on the east facade. Its foundation is not visible, but it is clad in aluminum siding and covered with an asphalt-shingled gable roof. Cornice and verge details are concealed beneath aluminum siding. The entrance is centrally placed and consists of a double door with flanking angled display windows of modern, fixed, four-pane sash. The building is in fair condition, but its integrity has been compromised by the application of aluminum siding and the alterations to the front facade. There are no outbuildings.

.330 Market Street, Commercial Building, mid to late 20th century
[map 1-31-10.16-17] Non-contributing building.

This is a large, one-story, south-facing, flat-roofed supermarket constructed of concrete block. The building is currently vacant. There are no outbuildings.

.331 114 Market Street, Dwelling, early 20th century
[map 1-31-10.16-18; CRS No. S-4340] Contributing building.

This is a large, two-story, five-bay, frame, Foursquare house with a hipped roof, an imposing front porch with a circular central portico and a balustraded second-story porch above, and a projecting, second-story center bay. The building was further enlarged with a one-story rear addition. The house faces south. It is built on a brick foundation, sheathed in aluminum siding, and topped with a hipped asphalt-shingled roof. Cornice and verge details have been covered by aluminum siding. A single corbelled brick chimney is located on the east facade. Windows are fitted with a combination of one-over-one, twelve-over-one, and twenty-four-over-one, double-hung sash. The front dormer is fitted with a three-part window with ornamental upper panes. The central front door is ornamented with an elliptical fanlight overhead and flanking five-light sidelights. A frame porch extends the entire length of the front facade; it is built on a brick foundation, supported by fluted wooden columns, and ornamented with a square wooden balustrade. The house is in good condition, but its integrity has been somewhat compromised by the application of aluminum siding.

.332 114 Market Street, Garage, early 20th century
[map 1-31-10.16-18; CRS No. S-4340] Contributing building.

This is a one-story frame weatherboarded garage with a pyramidal roof.

.333 111 Market Street, Commercial Building, late 19th century
[map 1-31-10.16-43.1; CRS No. S-4333] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 85

=====
This two-story, gable-roofed, north-facing frame building with its gable entrance facing the street has been reworked into a modern commercial space by means of a one-story, store-front addition with fixed, angled display windows on the front facade. The front facade was originally two bays wide. A one-story leanto further extends the space on the west side, and a one-story concrete block wing is located at the rear. The building is constructed on a brick foundation, clad in aluminum siding, and covered with an asphalt-shingled roof. Cornice and verge details have been concealed beneath aluminum siding. A single interior brick chimney is located at the center of the building on the slope of the roof. Windows on the upper stories are fitted with two-over-two, double-hung sash. The building is in good condition, but its integrity has been compromised by the alterations to the front facade as well as the application of aluminum siding. The building is currently operated as an antique shop.

.334 Mechanic Street, behind 111 Market, Apartment Building, 20th century;
 [map 1-31-10.16-43.1; CRS No. S-4332] Non-contributing building.

This is a one-story, L-shaped, three-bay apartment building with its gable entrance facing Mechanic Street. The building is constructed on a concrete block foundation, sheathed in aluminum siding, and covered with an asphalt-shingled gable roof.

.335, .375 113-115 Market Street, Commercial Building, early to mid 20th
 century; [map 1-31-10.16-42, 44; CRS No. S-4399] Two (2)
 contributing buildings.

This is a one-story, four-bay, north-facing, rectangular double commercial building constructed of brick with an extended "false" front and a flat roof. There are two separate commercial establishments housed within. The spaces are currently occupied by a video store and an antique shop.

.336, .376 117-119 Market Street, Commercial Building, early to mid 20th
 century; [map 1-31-10.16-41, 40; CRS No. S-4339] Two (2) contributing
 buildings.

This is a one-story, five-bay, north-facing, rectangular brick and concrete block double commercial building with an extended "false" front and a flat roof. There are two separate commercial establishments housed within. The spaces are currently occupied by a drug store and an insurance office.

.337 121 Market Street, Dwelling, mid to late 19th century
 [map 1-31-10.16-39; CRS No. S-4330] Contributing building.

This is a two-story, five-bay, frame L-plan dwelling with a half-hexagonal front tower topped with a hexagonal conical roof, a wraparound front porch, and a front-facing gable dormer. Enlargements to the main block include two projecting

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 86

two-story bays on the west facade and a two-story rear wing with an attached one-story wing. The house faces north. Built on a brick foundation, it is sheathed in asbestos shingles at first and second story levels with decorative fish scale shingles at the top of the tower and on the dormer. The house is covered with an asphalt-shingled gable roof with a boxed cornice and flush verge. Windows are trimmed with flat surrounds and molded drip caps and are fitted with two-over-two, double-hung sash. A frame porch supported by circular wooden columns wraps around the front and west sides. The house is in good condition.

- .338 121 Market Street, Shed, early 20th century
[map 1-31-10.16-39; CRS No. S-4330] Contributing building.

This is a one-story, frame shed sheathed in vertical board siding and covered with an asphalt-shingled, asymmetrically-pitched gable roof.

- .339 121 Market Street, Garage, late 19th century
[map 1-31-10.16-39; CRS No. S-4330] Contributing building.

This is a two-story frame garage sheathed in a combination of board-and-batten and vertical board siding and covered with a shallowly-pitched asphalt-shingled gable roof. There is a single entrance bay with a second-floor loading door above in the gable as well as two other garage door-sized entrance doors on the south lateral facade.

- .340 Trinity House, 201 Market Street, Dwelling, early 20th century
[map 1-31-10.16-39; CRS No. S-4329] Contributing building.

This is a two-story, three-bay, Foursquare dwelling constructed entirely of brick-sized rusticated concrete block. The building is further distinguished by a wraparound front porch and a front facing dormer. The main block has been enlarged by a one-story rear porch wing. The house faces north. The exterior walling consists of sand-colored brick-sized rusticated concrete block ornamented with red brick horizontal banding at first and second story levels, decorative red brick segmental arches over the windows, red brick laid in keystone shapes around a small, second-story fixed elliptical window, and red-and sand-colored lapped fish scale shingles in the side gables and front dormer. The house is topped with an asphalt-shingled pyramidal roof with a boxed cornice and flush verge. There are two interior chimneys located on the east and west sides, both also constructed of a combination of sand-colored rusticated concrete block and brick; both are stepped and corbelled. Windows are trimmed with plain molded surrounds and fitted with one-over-one, double-hung sash. A wraparound front porch, also constructed of red brick and sand-colored rusticated concrete block, is covered with an asphalt-shingled roof and supported by circular pillars constructed of smooth-faced brick-sized concrete block embellished with horizontal red brick banding. The porch roof is hipped with a cross gable over the front entrance; fish scale shingles fill the pediment above the entrance.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 87

=====
The house is in good condition, and is an outstanding example of rusticated concrete block construction.

- .341 203 Market Street, Dwelling, early to mid 20th century
[map 1-31-10.16-37; CRS No. S-4328] Contributing building.

This is a two-story, three-bay, north-facing rectangular brick dwelling in the Dutch Colonial Revival style, with a center entry and a one-story wing on the east side. The masonry is laid in Flemish bond. The gambrel roof is spanned by a broad shed dormer and covered with asphalt shingles, and has a boxed molded cornice and a flat molded verge. A single brick chimney is centrally located at the ridge. Windows are finished with flat wooden surrounds and fitted with six-over-one, double-hung sash. The center front door is ornamented with an overhead elliptical fanlight. A gabled frame front portico is built on a brick foundation and supported by circular wooden columns. The house is in good condition.

- .342 203 Market Street, Garage, early to mid 20th century
[map 1-31-10.16-37; CRS No. S-4328] Contributing building.

This is a one-story, one-bay brick garage with an asphalt-shingled gable roof.

- .343 205 Market Street, Dwelling, late 20th century
[map 1-31-10.16-36] Non-contributing building.

This is a late 20th century, one-story, frame, three-bedroom ranch house with a central front door. Facing north, the house is built on a concrete block foundation, sheathed entirely in aluminum siding, and covered with an asphalt-shingled, gable roof.

- .344 205 Market Street, Garage, late 20th century
[map 1-31-10.16-36] Non-contributing building.

This is a one-story frame garage sheathed in vertical board siding and covered with an asphalt-shingled, gable roof. There is one entrance bay in the lateral side.

- .345 207 Market Street, Dwelling, late 19th century
[map 1-31-10.16-35; CRS No. S-4327] Contributing building.

This is a two-story, three-bay, rectangular frame building with symmetrical fenestration, a front porch that extends across the entire north facade, and a two-story rear wing. Built on a brick foundation, the house is sheathed in wavy-edged asbestos siding and covered with an asphalt-shingled, gable roof with a boxed molded cornice. A single brick end chimney is located at the end of the rear addition. Windows are trimmed with molded board surrounds and fitted with two-over-two, double-hung sash. The front door, located in the left bay, is

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 88

=====
fitted with an overhead one-light fixed transom. The frame front porch is supported on turned wooden posts ornamented with sawn scrolled corner brackets. The house is in good condition.

.346 207 Market Street, Shed, late 20th century
 [map 1-31-10.16-35; CRS No. S-4327] Non-contributing building.

This is a prefabricated frame storage shed topped with an asphalt-shingled, gambrel roof.

.347 209 Market Street, Dwelling, late 19th century
 [map 1-31-10.16-34; CRS No. S-4326] Contributing building.

This is a two-story, four-bay frame L-plan dwelling featuring a projecting two-story bay with a pedimented gable on the front facade, a one-story wing on the east facade, and a side porch. The building, which faces north, is constructed on a brick foundation, sheathed with wavy-edged asbestos shingles, and covered with an asphalt-shingled, gable roof. The roof is further finished with a molded boxed cornice with returns and a flush verge. There are three corbelled brick chimneys; one is centrally located at the rear of the building, one is situated on the east side, and one is placed at the center of the rear addition. Windows are trimmed with molded board surrounds and fitted with two-over-one, double-hung sash. A frame front porch is supported by circular wooden columns and covered with an asphalt-shingled, gable roof.

.348 209 Market Street, Garage, late 20th century
 [map 1-31-10.16-34; CRS No. S-4326] Non-contributing building.

This is a one-story, three-bay, concrete block garage covered with an asphalt-shingled, gable roof.

.349 200 Market Street, Dwelling, late 19th century
 [map 1-31-10.16-19; CRS No. S-4341] Contributing building.

This is a two-story, four-bay, nearly square frame dwelling with a hipped roof and a front porch that extends the length of the south facade. The main block has been enlarged with a one-story wing on the east facade. Built on a brick foundation, the house is clad in weatherboards and covered with an asphalt-shingled roof with a molded, boxed cornice. There are two front dormers, one with a pedimented gable. A single, corbelled brick chimney is centrally located at the peak of the roof. Windows are trimmed with molded board surrounds and fitted with one-over-one, double-hung sash; the dormers are fitted with arch-topped, multi-paned, double-hung sash. There is a single stained glass window in the east gable. The primary front door is centrally located with a fixed decorative transom overhead. A second front door is located to the right of the first and is ornamented with an overhanging hood and decorative scrolled wooden

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 89

Bridgeville Historic District
Sussex County, DE

brackets. A frame front porch is supported with a series of single, paired, or tripled circular wooden columns and ornamented with a turned balustrade; there is an additional turned balustrade at second-story level over the front entrance. The house is in good condition.

.350 200 Market Street, Shed, late 20th century
 [map 1-31-10.16-19; CRS No. S-4341] Non-contributing building.

This is a one-story concrete block shed covered with an asphalt-shingled, gable roof.

.351 202 Market Street, Dwelling, late 19th century
 [map 1-31-10.16-20; CRS No. S-4342] Contributing building.

This is a two-story, hip-roofed frame dwelling that is nearly square in plan. The house, which faces south, is built on a brick foundation, clad with weatherboards, and covered with an asphalt-shingled roof with a boxed, molded cornice. There is a single front-facing dormer fitted with a Palladian window. An interior brick chimney is located in the center of the building; a second interior brick chimney is located on the west wall. Windows are trimmed with flat board surrounds with molded drip caps and fitted with one-over-one, double-hung sash. The front door is ornamented with a dentilated surround with flanking eight-light sidelights. A frame front porch wraps around the south and east sides and is supported with circular wooden columns topped with Ionic capitals. The house is in good condition.

.352 202 Market Street, Garage, early 20th century
 [map 1-31-10.16-20; CRS No. S-4342] Contributing building.

This is a one-story, two-bay frame garage with a hipped, corrugated metal roof. The building is sheathed in corrugated metal.

.353 204 Market Street, Dwelling, late 19th century
 [map 1-31-10.16-21; CRS No. S-4343] Contributing building.

This is a two-story, four-bay, L-shaped, single-pile frame dwelling with two projecting front dormers and a wraparound front porch. The building, which faces south, is constructed on a brick-sized concrete block foundation, clad in aluminum siding, and covered with an asphalt-shingled, hipped roof. Additional ornamentation includes decorative sawn scrollwork with turned pendant drops under the projecting gables. A single corbelled brick exterior chimney is built on the west facade. There are two front dormers fitted with arch-topped windows with decorative upper panes. Windows are fitted with a combination of fifteen-over-one and nine-over-one, double-hung sash. The front door is ornamented with an elliptical fanlight and flanked by leaded glass sidelights. The frame porch, which wraps around the south and east sides, is supported by circular columns and

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 90

Bridgeville Historic District
Sussex County, DE

ornamented with a square wooden balustrade. The house is in good condition.

.354 204 Market Street, Garage, early 20th century
[map 1-31-10.16-21; CRS No. S-4343] Contributing building.

This is a one-story, one-bay frame garage covered with a corrugated metal hipped roof. The building is sheathed in vertical board siding.

.355 206 Market Street, Dwelling, early to mid 20th century
[map 1-31-10.16-22; CRS No. S-4344] Contributing building.

This is a two-story, three-bay, roughly L-shaped dwelling with the gable side of the building facing the street. The building has been enlarged with two one-story rear wings. The house, which faces south, is built on a brick foundation, clad in aluminum siding, and covered with an asphalt-shingled, hipped roof. A single corbelled brick chimney is centrally located at the roof peak. A frame front porch on a brick foundation is situated on the southeast side.

.356 206 Market Street, Garage, late 20th century
[map 1-31-10.16-22; CRS No. S-4344] Non-contributing building.

This is a one-story, two-bay, concrete block garage covered with an asphalt-shingled, gable roof.

.357 208 Market Street, Dwelling, late 19th century
[map 1-31-10.16-23; CRS No. S-4345] Contributing building.

This is a two-story, three-bay frame dwelling with symmetrical fenestration and a center entrance. The house faces south. While the foundation is not visible, the exterior walls are clad in aluminum siding and covered with an asphalt-shingled, gable roof. There are two fixed one-light sash windows in each gable. Window and door surrounds have been concealed beneath aluminum siding; windows throughout are fitted with six-over-six, double-hung sash. The house is in good condition, but its integrity has been compromised somewhat by the application of aluminum siding.

.358 208 Market Street, Barn/Garage, late 19th century
[map 1-31-10.16-23; CRS No. S-4345] Contributing building.

This is a two-story frame combination barn and garage sheathed in vertical board siding and covered with a corrugated metal, gable roof. According to the owner, it incorporates heavy timber framing with pegged joinery.

.359 Bridgeville Public Library, 210 Market Street, Library, late 19th to early 20th century; [map 1-31-10.16-24; CRS No. S-4346] Contributing building.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 91

=====
Originally constructed as a church, this is a one-story, five-bay frame building with a central projecting tower; the building is oriented with the gable entrance facing the street. The library has been enlarged with a one-story wing on the west gable as well as a two-story rear wing with an attached one-story wing. Constructed on a brick foundation, the building is sheathed in aluminum siding and covered with a steeply-pitched, asphalt-shingled, gable roof with exposed rafter feet. Pointed arch-topped windows are utilized throughout; the center tower is fitted with arch-topped, two-over-two, double-hung sash windows flanked by arch-topped louvered vents. There is a one-story, gable-roofed portico with tapered wooden columns over the front entrance. In good condition, the building is individually listed in the National Register of Historic Places.

.360 northeast corner Laws and John streets, Dwelling, late 19th century
[map 1-31-10.16-2; CRS No. S-4732] Contributing building.

This is a two-story, two-bay frame L-plan dwelling with a partially enclosed front porch and two additional one-story wings. The house faces west, is built on a brick foundation and sheathed with wavy-edged asbestos shingles. The gable roof is covered with asphalt shingles and finished with a boxed, molded cornice. A brick chimney is centrally located at the ridge; a second brick chimney is situated at the south end of the south wing. Windows are trimmed with flat board surrounds and fitted with two-over-two, double-hung sash. An enclosed frame front porch is located on the west facade. The house is in good condition, but its integrity has been compromised somewhat by the partially enclosed front porch.

.361 northeast corner Laws and John streets, Shed, late 20th century
[map 1-31-10.16-2; CRS No. S-4732] Non-contributing building.

This is a one-story prefabricated frame shed covered with an asphalt-shingled, gambrel roof.

.362 Former Bridgeville Bank, Market Street, early 20th century
(Bridgeville Police Department); [map 1-31-10.16-26; CRS No. S-4347]
Contributing building.

Constructed in 1905 as a branch of the Baltimore Trust Company, this building recently was renovated to house the Bridgeville Police Department. It is a one-story, three-bay, hip-roofed rectangular brick bank building with an extended stone front, brick sides and buttresses, corbelled brick banding near the cornice line, and an arched center entrance. The building faces south. Foundation and walls are brick; the roof is covered with asphalt shingles and ornamented with cresting at the ridge. There are two brick interior end chimneys located on the west side of the building. The building is in good condition.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 92

=====
.363 308 Market Street, Dwelling, late 19th century
 [map 1-31-10.15-24; CRS No. S-4348] Contributing building.

This is a two-story, four-bay, L-plan frame dwelling with a projecting two-story bay. The house faces south, is built on a brick foundation, clad in aluminum siding, and covered with an asphalt-shingled, gable roof. Cornice and verge details have been concealed beneath aluminum siding. There are two, centrally-located interior corbelled brick chimneys. Window and door surrounds have been concealed beneath aluminum siding; windows are fitted with one-over-one, double-hung sash throughout. A frame front porch is built on a brick foundation, supported with fluted wooden columns and covered with an asphalt-shingled, gable roof. The porch floor is concrete. The house is in good condition, but its integrity has been compromised somewhat by the application of aluminum siding.

.364 308 Market Street, Garage, late 20th century
 [map 1-31-10.15-24; CRS No. S-4348] Non-contributing building.

This is a one-story frame garage sheathed in aluminum siding and covered with an asphalt-shingled, gable roof.

.365 309 Market Street, Dwelling, late 19th century
 [map 1-31-10.16-28; CRS No. S-4348] Contributing building.

This is a three-bay, two-story, frame dwelling with symmetrical fenestration, a center entrance, a front-facing dormer and a front porch that extends the full length of the north facade. The building has been enlarged with two two-story rear wings and a one-story rear wing. Built on a brick foundation, the house is sided with asbestos shingles and covered with an asphalt-shingled, gable roof. Cornice and verge details as well as window and door surrounds have been concealed beneath aluminum siding. Windows are fitted with one-over-one, double-hung sash. There are two fixed, three-light sash windows in each gable at attic level. The frame front porch is built on a brick and concrete foundation and supported with fluted metal columns. The house is in good condition.

.366 309 Market Street, Shed, late 19th to early 20th century
 [map 1-31-10.16-28; CRS No. S-4322] Contributing building.

This is a one-story, frame shed clad in vertical boards and covered with an asphalt-shingled, gable roof.

.367 307 Market Street, Dwelling, late 19th century
 [map 1-31-10.16-29; CRS No. S-4323] Contributing building.

This is a two-story, five-bay, frame L-plan dwelling with a front-facing gable and a porch that extends the length of the front facade. The house faces north. Built on a foundation of rusticated concrete block, the house is sheathed in

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 93

=====

weatherboards and covered with an asphalt-shingled, gable roof with a flat verge; the eaves are further ornamented with exposed rounded rafter ends. A single, corbelled brick chimney is located in the center of the main block. Windows are trimmed with flat surrounds and molded drip caps and fitted with a combination of nine-over-one, eighteen-over-one, and ten-over-one, double-hung sash. The frame front porch, also constructed on a rusticated concrete block foundation, is supported by circular wooden columns. There is an overhanging second story screened porch with a square balustrade on the east facade. The house is in good condition.

.368 307 Market Street, Garage, late 19th century
 [map 1-31-10.16-29; CRS No. S-4323] Contributing building.

This is a one-story, one-bay gable entrance, frame garage sheathed in vertical board siding and covered with an asphalt-shingled, gable roof. The building has an end chimney; on the east lateral side, there is a one-story leanto sheathed in corrugated metal.

.369 307 Market Street, Garage, late 19th century
 [map 1-31-10.16-29; CRS No. S-4324] Contributing building.

This is a one-and-one-half story frame garage with a gable entrance, vertical board siding, and a metal gable roof. There is a one-story leanto clad in vertical board siding attached to the west lateral side.

.370 305 Market Street, Dwelling, early 20th century
 [map 1-31-10.16-30; CRS No. S-4324] Contributing building.

This is a two-story, two-bay, gable-roofed rectangular frame building with symmetrical fenestration. The building, which faces north, has been enlarged with a two-story rear addition with a one-story wing attached. Built on a rusticated concrete block foundation, the house is clad in aluminum siding and covered with an asphalt-shingled, gable roof. A single, interior corbelled brick chimney is located on the east gable. Window and door surrounds have been concealed beneath aluminum siding; windows throughout are fitted with one-over-one, double-hung sash. The house is in good condition, but its integrity has been compromised somewhat by the application of aluminum siding.

.371 305 Market Street, Outbuilding, early 20th century
 [map 1-31-10.16-30; CRS No. S-4324] Contributing building.

This is a narrow, one-story frame building sheathed in corrugated metal and covered with an asphalt-shingled, gable roof. A corrugated metal-clad leanto is attached.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 94

=====
.372 303 Market Street, Dwelling, early 20th century
 [map 1-31-10.16-31; CRS No. S-4326] Contributing building.

This is a two-story, two-bay, frame Foursquare dwelling with a pyramidal roof and a projecting front dormer. The building faces north and has been enlarged with a one-story frame wing on the east side as well as a one-story rear brick garage wing. Constructed on a rusticated concrete block foundation, the building is sheathed with weatherboards and topped with an asphalt-shingled roof. The roof is finished with narrow-width beaded board siding under the eaves. There are two corbelled brick chimneys; one is centrally located, and the other is situated at the back of the rear wing. The front dormer is fitted with three fixed-sash, single-light windows. A front porch extends the full length of the front facade; the porch is built on a rusticated concrete block foundation, supported by paired or tripled wooden pillars, and covered with an asphalt-shingled roof. The house is in good condition.

.373 see .85

.374 see .85

.375 see .335

.376 see .336

.377 Lawrence Cahill III Park, Delaware Avenue, Landscape, late 20th
 century; [map 1-31-10.16-60] Non-contributing site.

This is a small public park created in the late 20th century on the site of a late 19th/early 20th century dwelling.

.378 400 Mill Street; Commercial building; [map 1-31-10.15-14] Non-
 contributing building.

This modern one story, gable roof, five by three bay, concrete block building has a brick veneer on the facade.

.379 400 Mill Street; Outbuilding, [map 1-31-10.15-14] Non-contributing
 building.

This one story, gambrel roof, frame outbuilding was constructed in the late-twentieth century.

.380 Southeast corner of North Cannon Street and Mill Road; Portion of
 Parcel, [map 1-31-10.15-34] Non-contributing site.

Vacant portion of parcel adjacent to 102 North Cannon Street.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Bridgeville Historic District
Sussex County, DE

Section number 7 Page # 95

.381 A&B Farmer's Supply Service Company building, 102 North Cannon Street; Commercial building; [map 1-31-10.15-28, CRS# S-4744] Contributing building.

Built in the early twentieth century, the Farmer's Supply Company building is one of Bridgeville's best examples of the use of cast concrete block in a commercial building. This building consists of two sections (A & B) which have a common wall. Building A has a larger, three bay, commercial facade. Building B has a slightly smaller three bay storage building similarly detailed to the main facade on building A. The buildings display rusticated concrete block as the main building material, both have metal covered gable roofs with parapet walls clad in asbestos shingle on the facade and are oriented toward Cannon Street. The original fenestration has been retained with the facade windows being mainly three small over two large fixed pane windows. The facades of both sections are broken between the floors by a small pent roof from under which bare light bulbs are hung. The building retains its original folding wooden doors, scaled for both foot traffic and the transport of bulk goods. The rear elevations of both buildings display the ten over ten double hung sash windows with flat concrete lintels and wooden sills. The second story, rear gable ends of both buildings are sheathed in asbestos shingles and have one set of paired six over six wood windows with simple surrounds each. Rusticated concrete block piers project at the corners of the rear elevations. The south elevation of building A has regularly spaced ten over ten double hung sash windows with a loading door toward the east end. This folding historic tongue and groove door displays six single fixed glass panes above a solid lower panel. The north elevation of building B displays regularly spaced ten over ten double hung sash windows detailed similarly to those in the rest of the building. These buildings enjoy a high degree of architectural integrity and excellent physical condition.

.382 Vacant lot; [map 1-31-10.16-27] Non-contributing site.

Vacant lot on the north side of Market Street adjacent to the former police station (.362).

.383 Vacant lot; [map 1-31-10.15-16] Non-contributing site.

Vacant lot located on the east side of North Cannon Street.

.384 Vacant lot; [map 1-31-10.15-19] Non-contributing site.

Vacant lot located on the east side of North Cannon Street.

.385 Vacant lot; [map 1-31-10.16-83] Non-contributing site.

Vacant lot located near the southwest corner of Delaware Avenue and Laws Street.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 7 Page # 96

Bridgeville Historic District
Sussex County, DE

=====
.386 Vacant lot; [map 1-31-10.16-15] Non-contributing site.

Vacant lot located on the north side of Market Street.

.387 Vacant lot; [map 1-31-10.16-166] Non-contributing site.

Vacant lot located on the east side of Main Street.

.388 Vacant lot; [map 1-31-10.16-123] Non-contributing site.

Vacant lot located on the south side of Walnut Street.

.389 Vacant lot; [map 1-31-10.16-152] Non-contributing site.

Vacant lot located on the south side of Walnut Street.

.390 Vacant lot; [map 1-31-10.16-152.1] Non-contributing site.

Vacant lot located on the south side of Walnut Street.

.391 Vacant lot; [map 1-31-10.16-154] Non-contributing site.

Vacant lot located on the south side of Walnut Street.

.392 Vacant lot; [map 1-31-10.16-117] Non-contributing site.

Vacant lot located on the north side of Walnut Street.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 8 Page # 1 Bridgeville Historic District
Sussex County, DE

8. Statement of Significance

Significance Summary:

The Bridgeville Historic District is significant under Criterion C as a largely intact representative example of the type of community which characterized southern Delaware in the late 19th and early 20th century. The town began in the 18th century as a scattered agricultural settlement at the crossing of Bridge Branch; major land routes ran north-south (present Main Street) and to the west (present Market Street). It achieved its present layout in the late 1850s, when local businessman and developer William Cannon laid out a portion of his extensive real estate holdings into a series of rectilinear blocks defined by a grid pattern of streets and alleys, containing uniform-sized lots. These lots were subsequently improved with a variety of building types reflecting vernacular forms and academic styles of the period; both the historic development pattern and the architectural resources retain a high degree of integrity, resulting in a strong sense of time and place within the district. Architectural resources within the district contribute to its significance under Criterion C; the district is characterized by well-preserved examples of houses reflecting popular architectural styles, including Greek Revival, Queen Anne, Colonial Revival, American Foursquare, Bungalow, and vernacular house forms including side-passage, I-house, and shotgun types. In addition to these principal resources, the residential lots contain a variety of secondary structures typifying domestic outbuildings of the late 19th and early 20th century, and several historic commercial buildings survive on Market Street. The district derives additional significance under Criterion B from its association with William Cannon, a local entrepreneur and effective founder of the present town, who became Governor of Delaware in 1862. Finally, it is significant under Criterion A for its reflection of the influence of rail transportation on the agricultural economy of the region in the latter half of the 19th century; the town boomed following the arrival of the railroad in 1856, and became a prominent center for the shipment of agricultural produce from the surrounding region; it retained this status well into the early 20th century.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 8 Page # 2 Bridgeville Historic District
Sussex County, DE
=====

Historical Background:

The portion of Sussex County in which Northwest Fork Hundred is located was originally part of Maryland; it became part of Delaware in 1776, when the boundary line dividing the two states was settled. The disposition of land grants in the area began as early as the 1680s, although actual settlement may not have occurred for some time.

The town of Bridgeville is the oldest community in western Sussex County. Records of land transactions which were made in the first quarter of the 18th century suggest that a significant agricultural community already existed in the area by that period. A small group of houses had been built along the present Main Street by the turn of the 19th century; this settlement was known as "Bridge Branch" for the nearby stream, which was crossed by a bridge as early as 1730. By 1804, the community had grown sufficiently to merit the establishment of a post office. The village was formally recognized in 1810, when an Act of the Assembly was passed to establish its name as "Bridgeville." Over the ensuing decade, the town grew rapidly, to become the largest community in Northwest Fork Hundred; it boasted 29 houses, two stores, a tavern, three carriage shops, a blacksmith shop, three granaries, a storehouse, and a tanyard by 1816, and served as a center of political and commercial activity. Early 19th century industries included a water-powered mill, tanyard, charcoal furnace, and fruit-drying business. [Several properties on Main Street appear to incorporate elements which were constructed during this period; these properties, however, achieved their present configuration as the result of building campaigns which took place later in the 19th century, so that their overall architectural character is primarily reflective of the latter period.]

The growth of the town accelerated greatly upon the arrival of the railroad in Bridgeville in 1856. At that time, local businessman William Cannon (1809-1865) established the pattern of development in the town by laying out his extensive land holdings south of Market Street into lots fronting on the principal east-west avenues. A series of parallel streets, named William, Laws, and Cannon streets, intersected the avenues, running north-south;

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 8 Page # 3 Bridgeville Historic District
Sussex County, DE
=====

these streets were named for the developer's son, William Laws Cannon. Development through the remainder of the century followed this plat.

A native of the Bridgeville area, William Cannon began preparing for a career in business at an early age by assisting his father, a successful merchant. In adulthood, Cannon's interests included a store in Bridgeville, lumber, grain, peaches, grist and saw mills, banking, and newspaper publishing. He also served as a director of the Delaware Railroad. He amassed land holdings totaling 3800 acres, including 16 farms. These various interests contributed to his status as the wealthiest individual in Sussex County by 1864, when his annual income was \$5000.

In addition to his business interests, Cannon pursued a career in politics, beginning in 1844 as a Democratic representative to the State House. He was reelected in 1846, and served as State Treasurer from 1849-51. He subsequently changed party affiliation, and ran as the Republican candidate for governor of Delaware in 1862. He was elected by a slim margin. As a Republican with strong Unionist views, Cannon found his term in office difficult, encountering constant opposition from a hostile legislature.

Cannon died on March 1, 1865, and was buried in the Methodist cemetery on William Street in Bridgeville. Cannon's residence, which was located on the west side of North Main Street just outside the historic district boundary, was destroyed in 1939; the street pattern of Bridgeville therefore represents the surviving resource most directly associated with his interests in the town.

Bridgeville's town plan exhibits a typical pattern of development shared by railroad-influenced communities on the Delmarva peninsula in the latter half of the nineteenth century. Preexisting through routes became the principal commercial and residential streets, and new streets were laid out in a grid pattern parallel to these thoroughfares. Railroad tracks define one edge of the town. These general characteristics are evident in towns of the period in lower Delaware and adjacent Maryland; Bridgeville presents an exceptionally well-preserved example of

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 8 Page # 4 Bridgeville Historic District
Sussex County, DE

=====
this development pattern, which remains clearly expressed with
remarkably little alteration.

A boom in building construction in Bridgeville followed the arrival of the railroad and continued through the remainder of the century. By 1868, ten years after the completion of the railroad, some 77 structures were indicated on a map of the town (Pomeroy and Beers, Atlas of the State of Delaware, 1868).

The area supported a variety of large and small industries through the 19th century. These enterprises reflected the agricultural productivity of the community. The cannery of Prettyman & Robbins, formerly located on the southwest corner of Main and Market streets, began operations in 1867. At the time the Town of Bridgeville was incorporated in early 1871, its commercial resources included six general stores, two hardware stores, one drug store, one clothing store, one shoe store, three grocery stores, three millinery stores, and a newsstand. Wroten & Morris opened a cannery in the late 1870s.

By 1881, an observer reported that "the spirit of enterprise and progress . . . now seems to pervade [the town]." It boasted about 500 inhabitants, ten stores, three steam mills, two canning factories, one fruit dryer, three mechanic shops, a phosphate factory, two hotels, three churches, and three school houses. In the same year, Henry P. and Philip L. Cannon, sons of William Cannon, established an extensive canning plant in Bridgeville; this enterprise remained in operation for a full century. [Subsequent expansion and redevelopment have resulted in the removal of the original structures associated with this facility.]

By the early 20th century, Bridgeville's importance as a center of agricultural commerce was well established, and its growing population enjoyed a number of important community services and organizations. The railroad station at Bridgeville offered an important trans-shipment point for large quantities of produce from the surrounding fields and orchards. Notable crops included peaches, apples, strawberries, cantaloupes, watermelons, and sweet potatoes. The increasing economic prosperity of Bridgeville motivated the establishment of a branch of the Baltimore Trust Company in the town in 1905; prior to that date,

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 8 Page # 5 Bridgeville Historic District
Sussex County, DE
=====

Bridgeville residents had relied on the banks of Seaford. Several fraternal societies had been organized by the 1890s; in the same period, a public reading room began operation, the predecessor of a circulating library organized in 1919. A municipal Water Works was constructed in 1909, and a volunteer fire company was organized the following year.

Later in the century, around the era of World War I, motor trucks began to replace railroads as the preferred mode of transport for agricultural products; by the Depression of the 1930s, trucks had gained clear ascendancy over railroads.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 8 Page # 6 Bridgeville Historic District
Sussex County, DE

=====

Comprehensive Planning

Zone: Lower Peninsula/Cypress Swamp

Periods: Early Industrialization and Urbanization, 1830-1880+/-
Urbanization and Early Suburbanization, 1880-1940+/-

Themes: Architecture, Engineering and Decorative Arts
Settlement Patterns and Demographic Change
Major Families, Individuals, and Events
Finance
Retailing and Wholesaling
Government
Religion
Education
Community Organizations

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 9 Page # 1 Bridgeville Historic District
Sussex County, DE

9. Major Bibliographical References

"A Short History of Bridgeville." Pamphlet, 1920.

"Bridgeville, Delaware." Pamphlet, 1930.

Carter, Richard B., "Old Bridgeville Fire House (S-809)," National Register of Historic Places nomination, 1984.

Duhadaway, Donald A., Jr., Kimberly R. Sebold, and Stephen G. Del Sordo, "Bridgeville Public Library (S-4346)," National Register of Historic Places nomination, 1989.

Hancock, Harold B. Bridgeville: A Community History of the Nineteenth Century. Bridgeville, DE: Bridgeville Historical Society, 1985.

Herman, Bernard L. Architecture and Rural Life in Central Delaware, 1700-1900. Knoxville: University of Tennessee Press, 1987.

Martin, Roger A. A History of Delaware Through Its Governors, 1776-1984. Wilmington, DE: McClafferty Printing, 1984.

McAlester, Virginia and Lee McAlester. A Field Guide to American Houses. New York: Alfred A. Knopf, 1984.

Pomeroy and Beers. Atlas of the State of Delaware. 1868.

Sanborn Map Company. Fire Insurance Maps of Bridgeville, Delaware. Philadelphia: Sanborn Map Company, 1884-1950.

Scharf, J. Thomas. History of the State of Delaware. Philadelphia: L. J. Richards & Co., 1888.

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section number 10 Page # 1 Bridgeville Historic District
Sussex County, DE

=====

UTM References:	Zone	Easting	Northing
A	18	447920	4288720
B	18	448040	4288560
C	18	448220	4287900
D	18	447320	4287080
E	18	447380	4288620

MAP #2

MAP #1



MAP #3

ERO SERVICE
 BRIDGEVILLE, PENNSYLVANIA 19315
 MAP 1-31-10
 DATE OF REVISION: 10-10-10
 SITE OF DEVELOPER: HARRY KAPPA
 DATE OF REVISION: 10-10-10
 PROPERTY DATA FROM: 1925
 DATE OF REVISION: 10-10-10
 ONLY APPLICABLE FOR THE STATE AND DISTRICTS
 WILL BEING USED BY THE DELAWARE STATE ARCHIVE

Bridgeville Historic District
 Sussex County, Delaware

Map Placement Key

1:25,000

1:25,000

DATE OF REVISION 11-8-91

DATE OF ORIGINAL SURVEY 1850

1:25,000

SUSSEX COUNTY DELAWARE

BRIDGEVILLE HISTORIC DISTRICT

TAX MAP #3 OF 3 1"=200" N


LEGEND

	Lot
	Street
	Railroad
	Utility Line
	Boundary Line
	Easement
	Right-of-Way
	Water Feature
	Monument
	Survey Point
	Building
	Fence
	Tree
	Rock
	Iron Pipe
	Iron Nail
	Iron Spike
	Iron Bolt
	Iron Washer
	Iron Nut
	Iron Cap
	Iron Ring
	Iron Band
	Iron Collar
	Iron Plate
	Iron Disk
	Iron Cylinder
	Iron Cone
	Iron Sphere
	Iron Cube
	Iron Pyramid
	Iron Prism
	Iron Cylinder with Cap
	Iron Cylinder with Ring
	Iron Cylinder with Collar
	Iron Cylinder with Plate
	Iron Cylinder with Disk
	Iron Cylinder with Cone
	Iron Cylinder with Sphere
	Iron Cylinder with Cube
	Iron Cylinder with Pyramid
	Iron Cylinder with Prism

Photograph Key

BRIDGEVILLE HISTORIC DISTRICT
Sussex County, Delaware
Tax Map #3 of 3 1"=200" N

MAP 1-31-10 20



FEDERAL SERVICE

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

1:25,000

DATE OF REVISION 11-8-91

DATE OF ORIGINAL SURVEY 1850

1:25,000

SUSSEX COUNTY DELAWARE

BRIDGEVILLE HISTORIC DISTRICT

TAX MAP #3 OF 3 1"=200" N

MAP 1-31-10 20

SEE I-31-10

SEE I-31-10



BRIDGEVILLE HISTORIC DISTRICT
 SUSSEX COUNTY, DELAWARE
 Tax Map #2 of 3 1"=200' N
 Photograph Key

SUSSEX COUNTY
 DELAWARE

DATE OF REVISION I-8-91
 VICE
 COUNTY COUNCIL, DEPARTMENT
 1 THE SALE AND DISTRIBUTION
 DATE OF COMPLETION MARCH 8, 1978. DATE OF PHOTOGRAPHY DECEMBER 1971
 PROPERTY DATA FROM DEED RECORDS, FIELD RECONNAISSANCE AND RECORDED PLATS.
 SHEET LAYOUT BASED ON THE DELAWARE STATE PLANNING COMMISSION SYSTEM.

THE DISTRICTS SHOWN ON THIS MAP WERE DERIVED FROM THE 1978 AERIAL PHOTOGRAPHY OF BRIDGEVILLE, DELAWARE. THE DISTRICTS WERE IDENTIFIED BY VISUAL INSPECTION OF THE AERIAL PHOTOGRAPHY AND THE FIELD RECONNAISSANCE DATA. THE DISTRICTS WERE NOT VERIFIED BY FIELD SURVEY.

SCALE: 1 INCH = 200 FEET

LEGEND

- County line
- Incorporated line
- City or Borough line
- Map parcel number
- Original lot number
- Map scaled dimension
- Owner's name owner
- All Dimensions Shown in Feet