

OTTO SCHLEMMER BUILDING 129-131 N. Green Street Crawfordsville, Indiana

PHOTO ONE: General exterior view, looking west. Most of what is seen here is the result of the 1889 reworking of the building.

Photo by Richard Tulley, March 1978.

Negative filed at Crawfordsville. (see form)

SEP 8 1978



OTTO SCHLEMMER BUILDING 129-131 N. Green Street Crawfordsville, Indiana

SEP 8 1978

PHOTO FIVE: Detail, front facade. Storefront in south half of building. Brick piers, wood window enframement, glazing in nearly original condition. Original 1889 doors are being reinstalled.

Photo by Bruce E. Lynch, March 1978 Negative filed at Lynch address



SEP 8 1978

OTTO SCHLEMMER BUILDING 129-131 N. Green Street Crawfordsville, Indiana

PHOTO THREE: Detail, main facade. Note iron work at cornice lines; freestanding arcade at second level.

Photo By Bruce E. Lynch, March 1978 Negative filed at Lynch address.



OTTO SCHLEMMER BUILDING 129-131 N. Green Street Crawfordsville. Indiana

SEP 8 1978

NOV 28 1978

PHoto FOUR: Detail, second floor arcade. Note wall construction, window enframement, "triple-X" iron balustrade, construction of arches.

Photo by Bruce E. Lynch, March 1978 Negative filed at Lynch address



129-131 N. Green Street Crawfordsville, Indiana

OTTO SCHLEMMER BUILDING

PHOTO TWO: General three-quarters view, looking southwest. Note change in brick in second story, indicating height of old Bennage Block.

Photo by Bruce E. Lynch, March 1978
Negative filed at Lynch address (see form)



OTTO SCHLEMMER BUILDING 129-131 N. Green Street Crawfordsville, Indiana

PHOTO SIX: Interior view, ground floor, north half.

View looking threat, shows work in

progress. Note galvanized iron pressed

metal covering walls and ceiling.

Photo by Bruce E. Lynch, March 1978 Negative filed at Lynch address