## HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES HIST-6 NEW 5. 77

450

FOR OFFICE USE ONLY Site No.: Town No.: 7.1 5: 0.0

(200, 500-500)	DISTA	ICT . IF NR. SPECI
59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106 (203) 566-3005	QUAD:	Branford
STATE OF CONNECTICUT CONNECTICUT HISTORICAL COMMISSION	$um_1$	8 68 78 8 04 5

	(203) 566-3005	DISTRICT IF NR. SPECIFY
		S NR Actual Percental
15	1. BUILDING NAME (Common) (Mint	
		Hezekiah Palmer House
	2. TOWN'CITY VILLAGE	COUNTY
₹	Branford Stony Creek	New Haven
DENTIFICATION	1. STREET AND NUMBER (and/or location)	
2	340-408 Leete's Island Road Map J8, Block 3,	Lot 1; .46 acres
Ę		Public Privere
	Robert J. Sanzero et ux 5. USE (Present) (History)	
=	One-Family Dwelling	Same
1	ACCESSIBILITY EXTERIOR VEHILE FROM PUBLIC ROAD INTERIOR ACCESSIBLE	IF YES, EXPLAIN
_	TO PUBLIC: Yes No Yes No	
ı		1800-1830
-	New England Colonial/Greek Revival  MATERIALIS (Indicate use or location when appropriate)	1800-1830
1	Clapboard Asbastos Siding Brick	(Specify)
		(Specify)
	Wood Shingle Asphalt Siding Fieldstone	
	Board & Batton Stucco Cobblestone	
	Aluminum Concrete Cut stone	
	Siding Type: Type: Type:	
	▼ Wood frame  ▼ Pest and beam  ■ belloon	
	Load bearing masonry Structural iron	er steel
į		
	Other (Specify)	
	Goble Flot Monsord Monitor	sewteeth
		Other
z	Gambrel Shed Hip Round	(Specify)
SCRIPTION	(Material)	
2 6	C Roll C	
	Wood Shingle Asphalt Tin Slate	
DE	Asphalt shingle Built up Tile Other (Specify)	
į	11. NUMBER OF STORIES APPROXIMATE DIMENSIONS	
	$2\frac{1}{2}$ 34 ft x 27 ft	
	12. CONDITION (Structural) (Exterior)	
	Excellent S Good Fair Deteriorated Excellent  13 INTEGRITY (Lin stion) WHEN? (Allerations) IF YES.	Fair Deteriorated
	On original Gable	windows altered (date unknown)
	TA RELATED OUTBUILDINGS OR LANDSCAPE FEATURES	The state of the s
	Barn Shed Garage 🕥 Other landscape feature	s or buildings (Specify)
	Carriage	• 14 1
	☐ house ☐ Shap ☐ Garden	
	15 SURROUNDING ENVIRONMENT	
	Open land Wood- X Residential Scattered	ouildings visible from site
:	Commercial Indus- Rural High build	ing density
. 4	16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS	
	Located in the village of Stony Creek at the junction of t	nree main roads; a neighborhood of
	mostly nineteenth-century buildings.	
		(OVER)

DE SCIAIT LION (Cantinued)	Constructed on a rectangular plan with its ridge parallel to the street, this structure has a moderate roof pitch and minimal overhangs at the cornices. Its brick center chimney straddles the ridge. It has a nine-window facade and a five-window gable. Windows have twelve-over-twelve sash. Its entry has Doric pilasters and a three-part entablature with a projecting cornice. A large fixed window on the south side is the only significant alteration.					
+	N/A		Unknown			
-	This house was recorded on the	WPA survey and da	ted 1830 as this was the date	carved in		
	a beam of the house. It appears from land record research that the house had been built earlier by James and Nancy Palmer, parents of Hezekiah Palmer who owned the house in 1852. James Palmer was lost in a shipwreck in 1831.					
SIGNIFICANCE	It is interesting to note that the very large boxwood by the front door, noted on the WPA survey, is still present. This well-preserved transitional Colonial/Greek Revival house is important as an example of a transitional period in Branford's collection of colonial houses.					
SOURCES	Maps: Whitford, 1852; Smith, 1856; Beers, 1868. Branford Land Records, Vol. 45, p. 83. W.P.A. Federal Writers Project. "Census of Old or Distinctive Buildings in the State of Connecticut," c.1936, No. 33					
10	PHOYOGRAPHER Jane P. Bouley	3/18/86	.,	· · · · · · · · · · · · · · · · · · ·		
PHOTO	West & North CHC-File	4 Neg 19		A		
COMPILED BY	S. Ardis Abbott& Robert B. Hu  ONGANIZATION Architectural F  Trust of Branford, Inc.  ADDRESS  226 East Main St. Branford, C	May, 1986  Treservation				
-	· · · · · · · · · · · · · · · · · · ·					