



Lava Rock Structures in South Central Idaho
Vineyard, Charles C., House, site 73

Six miles southwest of Eden
Eden vicinity, Jerome County, Idaho

Photograph by Marian Posey-Ploss
Summer 1981

Negative on file at the Idaho State Historical Society,
Boise, Idaho

View from northeast

Photograph one of two



Lava Rock Structures in South Central Idaho
Vineyard, Charles C., House, site 73

Six miles southwest of Eden
Eden vicinity, Jerome County, Idaho

Photograph by Marian Posey-Ploss
Summer 1981

Negative on file at the Idaho State Historical Society,
Boise, Idaho

View from south

Photograph two of two