



We and Our Neighbors Club

Picture c. 1912 of the south side and
stream rolled stone front porch of the
building and also showing the early
landscaping.

MAY 31 1978



We and Our Neighbors Club
Picture of southerly and easterly side
of building. Redwood grape stake
fence on property line.
1977-78 photo



We and Our Neighbors Club
Picture of rear and westerly side of
building shows composition shingles
over original Cedar shingles.
1977-78 photo MAY 31 1978



We and Our Neighbors Club

Picture showing stream rolled
stone fireplace.
1977-78 photo

MAY 8 1978



We and Our Neighbors Club
San Jose-Los Gatos, California
Front entrance; west side of
building.
MAY 31 1978
1977-78 photo