





③

③



④

④






NOTE: OVAL HOLES IN LOGS
ABOUT 1/2 WAY UP - PROBABLY
ANCHOR HOLES FOR EARLY
PORCH ROOF.



6

ORIGINAL MANTEL.

FIRE PLACE ALSO HAS
ORIGINAL WARMING OVEN



⑦

⑦

ORIGINAL PANELING —
" DOOR & STRAP
Hinges - (see 7A)

NOTE MORTISE & TENON
CONSTRUCTION (see 7B)



(11)

(11)

ORIGINAL MANTEL
& STONE in FIREPLACE