



Walden, Nicholas O., House  
1847 SE 5th Avenue  
West Linn, Clackamas Co., Oregon  
1 of 8

View from the northeast, 3/84  
Diane Awalt photo  
1847 SE 5th Avenue  
West Linn, OR 97068

Expanded view of photo B.



Walden, Nicholas O.  
1847 SE 5th Avenue  
West Linn, Clackamas Co., Oregon  
2 of 8

View from the northwest, 3/84  
Diane Awalt photo  
1847 SE 5th Avenue  
West Linn, OR 97068

View of house front face from a  
northwest orientation.

Another vintage house is visible  
between the garage and our house  
(to the right of our house) and  
another is visible through the  
porch posts.

House faces Fifth Avenue.

A.



Walden, Nicholas O., House  
1847 SE 5th Avenue  
West Linn, Clackamas Co., Oregon  
3 of 8

View from the northeast, 3/84  
Diane Awalt photo  
1847 SE 5th Avenue  
West Linn, OR 97068

Face of house from Northeast  
orientation. Note roofline.

Neighboring vintage house is  
barely visible through tree in  
right side of photograph.

B.



Walden, Nicholas O., House  
1847 SE 5th Avenue  
West Linn, Clackamas Co., Oregon  
4 n f r

South elevation, 3/84  
Diane Awalt photo  
1847 SE 5th Avenue  
West Linn, OR 97068

Rear view of house from  
alley; a somewhat southeast  
orientation. If YOU were  
standing here looking at the  
house, the Willamette River  
would be down the hill behind  
you.





Walden, Nicholas O., House  
1847 SE 5th Avenue  
West Linn, Clackamas Co., Oregon  
5 of 8

View of West Elevation, 3/84  
Diane Await photo  
1847 SE 5th Avenue  
West Linn, OR 97068

Side and rear view of the house,  
from a western orientation.

The brick foundation is barely  
visible along this side.

The bay will be in place of the  
6'x2½' widow seen below the  
upstairs window of the same size.

The garage is the structure in  
the right side of photo.



Walden, Nicholas O., House  
1847 SE 5th Avenue  
West Linn, Clackamas Co., Oregon  
6 of 8

Second floor view from the north, 3/84  
Diane Await photo  
1847 SE 5th Avenue  
West Linn, OR 97068

View of upstairs; top of stairs  
and landing. Also bannister(oak)  
and newell post(maple)  
View is looking west from the  
dormer with the round widow.

your back is to the front of the  
house.



Walden, Nicholas O., House  
1847 SE 5th Avenue  
West Linn, Clackamas Co., Oregon  
7 of 8

Second floor view from the south, 3/84  
Diane Await photo  
1847 SE 5th Avenue  
West Linn, OR 97068

View taken from the top of  
stairs (photo G.) looking  
toward front of house, into  
the dormer room that serves as  
an entry room to the bedroom to  
its left.

H.



Walden, Nicholas O., House  
1847 SE 5th Avenue  
West Linn, Clackamas Co., Oregon  
8 of 8

View of kitchen, 3/84  
Diane Await photo  
1847 SE 5th Avenue  
West Linn, OR 97068

Kitchen: looking toward the  
west ; dining room would  
be to your right if you  
were standing here.

Counter tops are slab fir.