



Lucy Hobbs Taylor Building

Lawrence, KS.

Photo credit: NP Small

Date: March, 1982

View from the east of the front facade. Wood window frames are beneath aluminum storms.



Lucy Hobbs Taylor Building

Lawrence, KS.

Photo credit: NPrSmall

Date: March, 1982

View from northeast of remaining porch.



Lucy Hobbs Taylor Building

Lawrence, Ks.

Photo credit: NP Small

Date: March, 1982

View of south facade. Note glass block window where bay window used to be.

Fire escape door on second floor was a window until recently.



PRIVATE
PARKING
NO TOLLS

Lucy Hobbs Taylor Building

Lawrence, Kansas

Photo credit: NP Small

Date: March, 1982

View of west facade



Lucy Hobbs Taylor Building

Lawrence, Kansas

Photo credit: NP Small

Date: March, 1982

Interior-detail of former bay window
on south wall.



Lucy Hobbs Taylor Building

Lawrence, KS.

Photo credit: NP Small

Date : March, 1982

View of main staircase. Note original
woodwork. Wall plaster was removed by
current owner.