



St. John the Evangelist Roman Catholic
Church

Zigzag vicinity, Clackamas County,
Oregon

^{DOE}
DEC 21 1979

Michael Gudge photo, 1978
2017 NE 19th
Gresham, OR 97030

SEP 19 1979

1 of 12 North and west elevations of
building as relocated within a mile of
original site. Original east-west ori-
entation recreated. Concrete foundation
to be covered with back-fill.



St. John the Evangelist Roman Catholic
Church

Zigzag vicinity, Clackamas County
Oregon

DOE
DEC 21 1979

Michael Gudge photo, 1978
2017 NE 19th
Gresham, OR 97030

SEP 29 1979

2 of 12 Detail of double-leaf front
door in rustic mode



St. John the Evangelist Roman Catholic
Church

Zigzag vicinity, Clackamas County
Oregon

Michael Gudge photo, 1978

2017 NE 19th
Gresham, OR 97030

SEP 29 1979

DOE
DEC 21 1979

3 of 12 West and south elevations



St. John the Evangelist Roman Catholic
Church
Zigzag vicinity, Clackamas County
Oregon

Michael Gudge photo, 1978
2017 NE 19th
Gresham, OR 97030

SEP 19 1979

002
DEC 21 1979

4 of 12 South and east elevations,
showing south transept



St. John the Evangelist Roman Catholic
Church

Zigzag vicinity, Clackamas County
Oregon

DOE
DEC 21 1979

Michael Gudge photo, 1978
2017 NE 19th
Gresham, OR 97030

SEP 18 1979

5 of 12 East and north elevations,
showing north transept




St. John the Evangelist Roman Catholic
Church
Zigzag vicinity, Clackams County
Oregon

DEC 21 1979 *DE*

Michael Gudge photo, 1978
2017 NE 19th
Gresham, OR 97030

SEP · 9 1979

6 of 12 Interior view, showing sacristy
converted to kitchen use



St. John the Evangelist Roman Catholic
Church

Zigzag vicinity, Clackamas County
Oregon

DOE
DEC 21 1979

Michael Gudge photo, 1978
2017 NE 19th
Gresham, OR 97030

SEP 19 1979

7 of 12 Interior view, showing plumbing
fixture installed in south
transept



St. John the Evangelist Roman Catholic
Church

Zigzag vicinity, Clackamas County
Oregon

Michael Gudge photo, 1978

2017 NE 19th

Gresham, OR 97030

DEC 21 1979

8 of 12 Detail of rustic stairway of
peeled log half-rounds and pole
railing leading from sacristy
to rectory in loft above.



St. John the Evangelist Roman Catholic
Church
Zigzag vicinity, Clackamas County
Oregon

Michael Gudge photo, 1978.
2017 NE 19th
Gresham, OR 97030

DEC 21 1979
DOE

SEP 19 1979

9 of 12 Detail of rustic stairway to
choir loft, west end of nave



St. John the Evangelist Roman Catholic
Church
Zigzag vicinity, Clackamas County
Oregon

Michael Gudge photo, 1978
2017 NE 19th
Gresham, OR 97030

DEC 21 1978
DOE

SEP 19 1979

10 of 12 Detail of confessional stalls
with choir loft railing of
peeled pole diagonals above



St. John the Evangelist Roman Catholic
Church

Zigzag vicinity, Clackamas County
Oregon

Michael Gudge photo, 1978
2017 NE 19th
Gresham, OR 97030

DOE
DEC 21 1979

SEP 19 1979

11 of 12 South and east elevations,
showing roof repair in progress



St. John the Evangelist Roman Catholic
Church

Zigzag vicinity, Clackamas County
Oregon

DEC 21 1979

Michael Gudge photo, 1978

2017 NE 19th
Gresham, OR 97030

SEP 19 1979

12 of 12 East and north elevations,
showing roof repair in progress
following relocation



EAST END

REPAIR WORK OF
DAMAGED FOUNDATION
WALL WITH CRAWL
SPACE TEMPORARILY
LEFT OPEN FOR
PLUMBING AND
ELECTRICAL WORK
UNDER BUILDING.

St. John the Evangelist Roman
Catholic Church
C. Lockman Co., Oregon



EAST END

NOTE THAT
EXISTING EAST GRADE
LENDERS ITSELF NICELY
TO ABOUT 19" OF
BACKFILL TO MAKE
AREA LEVEL. THIS
END AND SOUTH SIDE
WERE EXCAVATED
TO CLEAR A LEVEL
AREA FOR BUILDING.

*St. John the Evangelist Roman
Catholic Church
Clackamas Co. Oregon*



NORTH SIDE

HERE METER BASE
AND ELECTRICAL
TRANSFORMER CAN
BE SEEN SOME
DISTANCE FROM
BUILDING CONCEALED
PARTIALLY IN
BRUSH. THIS IS A
WINTER PICTURE SO
FOUAGE IS SPARSE.

*St. John the Evangelist Roman
Catholic Church
Clackamas Co. Oregon*



NORTH SIDE

GRADUAL TAPER OF
BACKFILL WILL
EXTEND PAST NORTH
SIDE OF DRIVE TO
AVOID MOUNDED
LOOK AND PROVIDE
BETTER DRAINAGE
FOR BUILDING AND
DRIVE.

St. John the Evangelist Roman
Catholic Church
© Jackson Co., Oregon




SOUTH SIDE

REPAIR WORK OR
BEAM POCKETS SHOWN
FILLED WITH TWO
VENT HOLES LEFT OPEN.

ALSO THIS SIDE WILL
TAKE BACKFILL NICELY
AS WILL THE SOUTH-
EAST AND EAST
END.

St. John the Evangelist Roman
Catholic Church
Clackamas Co, Oregon



NORTH WING

THREE OF THE
BEAM POCKETS I
POURED IN PREPARATION
FOR ROCKWORK AND
BACKFILL.

ELECTRICAL PANELS
AND PHONE CONNECTION
ARE UNDER THIS
WING.

*St. John the Evangelist Roman
Catholic Church
C Lockman Co, Oregon*



SOUTH SIDE

SHOWS APPROXIMATELY
HOW DRAINAGE TRENCH
WILL RUN. DRAIN
PIPE WILL LAY IN
TRENCH FILLED WITH
DRAIN ROCK AND THEN
APPROX 18" OF FILL
DIRT

St. John the Evangelist Roman
Catholic Church

Clackamas Co, Oregon



BATH WING.

OLD ORIGINAL
OAK CHAIN PUSH
TOILET (NOT A
REPRODUCTION).

ALSO NOTE KNOTTY
PINE WALL. NO
PLYWOOD IS USED IN
RESTORATION OR
RENOVATION WORK.

ALSO NOTE LOOP
VENT BEHIND LAV.

St. John the Evangelist Roman
Catholic Church
Clackamas Co. Oregon



BATH WING

PARTIALLY
COMPLETED BATH
AREA USING OLD
FIXTURES OF CHURCH
ERA. NOTE EXPOSED
COPPER VENT PIPE
BEHIND TUB. IT
WAS NECESSARY TO
MEET CODE BUT
TASTEFULLY DONE.

*St. John the Evangelist Roman
Catholic Church
Clackamas Co. Oregon*