1. Name of Resource:

4. Prehistoric Site

Maysville. 6. Owner's Name:

7. Owner's Address:

9. Recognition & Date: Nat.Landmark

10. N.R.Status & Date:

12. Historical Theme:

8. Evaluation:

11. N.R.Group:

13. Statement of Significance:

5. Location: 3/10 mile south of U.S. 62, 3/10 mile west of U.S. 68. outskirts of

Resource #

Mason

Ms-W 13

County

## KENTUCKY HISTORIC RESOURCES Individual Inventory Form

						_
Name of Resource:	16.	Date:				_
Tom Forman House		Original Building	1790-1800		[ 9	1
Original Owner:		Addition			Ī	j
Tom Forman	<del>17.</del>	Style:				
Other Names:		•	Federal		[21	1
						]
Prehistoric Site Building X Object	18.	Architect/Builder:				
Historic Site Structure Other			Not Known			
Location: 3/10 mile south of U.S. 62, 3/10	19.	No. of Stories: 2 p	lus attic, c	ellar	[2.0	<u> </u>
mile west of U.S. 68, outskirts of	20.	Original Floor Plan			_	_
Maysville		<u>Sid</u>	e passage		[ SP	_]
Owner's Name:			ouble Pile X		·	
. M	22.	Roof Form & Mater		iginal		_
Mrs. Harriett Cartmell [ P ]			le Not Or	iginal		_
Owner's Address:	23.	Structural Material			e e	
c/oHolton Cartmell	0.4	T-4-: M-4-:-1	Stone		<u>LS</u>	4
Washington, Kentucky 41096  Evaluation: [ G ]	<b>Z4.</b>	Exterior Material:	Stone		[ S	. !
Evaluation: [ G ] Recognition & Date:	25	Foundation Materia	_Rendering		l p	
Nat.Landmark Local Landmark	<b>4</b> 0.	roundation materia			[ c	1
Nat.Register HABS/HAER	26	Major Alterations:	Stone None		<u>. S</u>	
Highway Marker KY Inventory X	20.	Moved/Rebuilt	Other			
KY Landmark Certificate		Additions	Other			
N.R.Status & Date:	27.	Special Features:				_
N.R.Group:		Special Louisian co.				
District Name: [ ]	28.	Outbuildings:				_
Mult.Resource Area: [ ]		<b></b>	None		[ 0	]
Thematic Name: Early Stone Buildings[ ]	29.	Original Function:			<u> </u>	
Historical Theme:		J	Residence		[ 01A	. ]
Primary: Architecture [030]	30.	Present Use:				_
Secondary: Settlement [140]			Vacant		[ 99V	_]
Other: [ ]	31.	Condition:				
Statement of Significance:			Poor		[ P	]
As built, this was an especially fine house	32.	Endangered:		Yes	<u>X</u>	
for the time. It is one of several in the			By neglect	No		
area, and similar in size and plan to MS-27,	33.	Attach Photos:	<del></del>			_
the Pelham House. This one, in unfortunately		Roll: 24 Photo No	os: 3-9 No. of	Slide	S:	

## 14. History:

Built by Tom Forman, from New Jersey. Married Dolly Wood, daughter of Revolutionary soldier, George Wood.

poor condition reveals the construction system of the walls, floors, and roof.

15. Source of historical information and/or contact person: 1980 Survey Form

34.	Prepared by:	Carolyn Murray Wooley	
35.	Organization:	Kentucky Heritage Council	
36.	Date:	March 1984	
<del>37.</del>	New Survey	Resurvey X	

	Site		#	# The 412		
Page	1	of		3		Pages

## KENTUCKY HISTORIC RESOURCES INVENTORY

	17 254760	Primary Building: 4276860	37. USGS Quadrant: May Lich	38. G.I.S. Mod. 39. Coordinate Accurac	→ [ ] y → [ ]
40.	UTM Points of A. B.	Boundary: C.		E F	
		in Present Propert		age Included in Nominated	Boundary: 40/2
43. /^			:	Preprice boundary livele 150 feet in its from leater of how dependencies remain lines nearly, no to festure, no intruse  Mole (lease attacke  The access was fegured at fix  Agaares : 4356	pagraphical pagraphical ion . a): radius

## 44. Description and House Plan:

Two-story, side-passage, double-pile, dry-stone house, with cellar, and 1 1/2 story stone wing. Size 35' square, wing 22 X 29. Interior chimney on east end of main block serves five fireplaces—in cellar, and two on each floor. Chimney breasts divided below attic level. Fenestration pattern on north side compressed to accommodate stair. Double faced frames. Outside cellar entrance from south front, east bay. Fireplace in cellar.


Side passage on west end of main block has open stair with landing, open treads with scroll carving, turned balusters, square newell. Partition walls frame, lathe and plaster. Chairrail throughout. Presses built in spaces between fireplaces. Six panel doors. Enclosed corner stair to attic beside, not above, main stair, has beaded board wall surrounding it. Three rooms second floor, plus passage. Extremedown are between running.

House framing system is summer beam running from gable end to gable end; joists mortised and pegged into it with other ends of joists supported by the outside walls. Roof rafters braced by collar beams, pegged. Chairrail and plaster on end walls in attic.


Two bay wing on west end of house in poor condition; no roof. Main block has been covered with stucco, and front door made into window when approach to house was changed from south to north.

NOV 26 1985

M W 1:



First floor



Second floor