

View: from east side of Sanctuary crawl space, looking west at main beam splice

#1 of 24 - spliced main beam and stone pier, probably from the original structure, supporting the Sanctuary floor (mortar applied about 1970)



Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Photographer: Edward B. Schumacher Negatives: from color slide included in nomination


- View: from north end of Sanctuary crawl space, looking northeast
- #2 of 24 typical Sanctuary floor joist pier support of unnortared stone probably dating to original church building.



Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Photographer: Edward B. Schumacher Negatives: from color slide included in nomination

View: from north end of Sanctuary crawl space, looking north

#3 of 24 - stone foundation wall at north end of original church location (mortar applied about 1970)



Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Photographer: Edward B. Schumacher Negatives: from color slide included in nomination

View: from west side of Sanctuary crawl space, looking west

#4 of 24 - examples of ganctuary floor joist piers, a stone and oak tree trunk segment (left), and a length of locust log (right).



Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Negatives: Dankwart Koehler View: in Narthex, looking west #5 of 24 - Narthex



Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Negatives: Dankwart Koehler View: from balcony, of Sanctuary #6 of 24 - south view of Sanctuary




Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Negatives: Dankwart Koehler View: from center aisle of Sanctuary #7 of 24 - south wall of Sanctuary




Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County. N.J. Negatives: Dankwart Koehler View: from center aisle #8 of 24 - Altar and Choir



Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Negatives: Dankwart Koehler View: from southeast corner of Sanctuary #9 of 24 - north view of Sanctuary








View: from north end of Sanctuary attic, looking south

#11 of 24 - typical pinned mortise and tenon joint connecting hewn center column and rafter elements at ridge line of roof truss



View: from north end of Sanctuary attic, looking southeast

#12 of 24 - roof truss diagonal brace and center column arrangement



View: from north end of Sanctuary attic

#13 of 24 - roof truss diagonal brace and center column connection



View: looking west toward roof in Sanctuary attic


#14 of 24 - roof truss detail where diagonal brace and outboard column are connected to roof rafter




View: looking west toward eave in Sanctuary attic

#15 of 24 - roof truss bottom chord and roof rafters at eave line, showing wood strut supports for perimeter of ceiling and loose ceiling insulation













Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Negatives: Dankwart Koehler View: from across Main St. #18 of 24 - Church, front facade & steeple




Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Negatives: Dankwart Koehler View: from across Main St. #19 of 24 - Church, front facade
















Holmdel Community Church U.C.C. Complex 40 Main St., Holmdel, Monmouth County, N.J. Negatives: Dankwart Koehler View: from Church parking lot #23 of 24 - back of Church, Hall & Parsonage



