



001  
AUG 1 1974  
Magnolia Petroleum Building.

This is a shot of the east side of the building on the alley.

On the east and south sides, which do not face the streets, the brick and facade treatment are inferior to the fine workmanship and detail on the north and west sides.



Magnolia Petroleum Building.

This is a shot of the cornice detail. Notice the simulated torches cut from limestone.

This was a popular trim used in 1919.



7TH ST

BDWY

MAGNO

OCT 4 1979

Magnolia Petroleum Building.

This is a shot of the northwest corner, illustrating the embossed lettering on the belt course around the second level. This is an example of added detail and workmanship typical of the 1919-1930 era.

AUG 1 1979



Magnolia Petroleum Building.

This is full shot of the building from the northwest. Notice the trim around the cornice, the cut limestone window sills, the symmetrical arches, the sign on the roof, the cinder blocks enclosing the arches.

AUG 1 1979